

MOTORINI

BMW

BMW	RMA $\sqrt{\text{Kw}} \text{ -!}$	BMW	RMA $\sqrt{\text{Kw}} \text{ -!}$	BMW	RMA $\sqrt{\text{Kw}} \text{ -!}$
1241 7515390	M185X				
1241 7515392	M185X				

BOSCH RMA $\sqrt{\text{Kw}} - !$

0001106002	M111	0
0001106011	M143	12 0,9
0001106012	PM010	0
0001106014		0
0001106015	M143	0
0001106016	M406	0
0001106017	PM010	0
0001106018	PM538	
0001106019	PM011	0
0001106022	PM010	
0001106023	PM012	0
0001106024	PM539	
0001106405	RM001	
0001107003	M306	12 1,1
0001107004	M306	12 1,1
0001107005	M392	0
0001107006	M392	0
0001107007	M248	12 1,1
0001107008	M248	12 1,1
0001107009	M013X	12 1,1
0001107010	PM013	0
0001107011	M320X	0
0001107012	M227	12 1,1
0001107013	M227	12 1,1
0001107014	M217	12 1,4
0001107015	M099X	0
0001107016	M235	12 1,4
0001107017	M227	12 1,1
0001107018	M227	12 1,1
0001107019	M102X	12 1,1
0001107020	M248	12 1,1
0001107021	M248	12 1,1
0001107022	M236	12 1,1
0001107023	M236	12 1,1
0001107024	M379	0
0001107025	M255	12 1,1
0001107026	M255	12 1,1
0001107027	M217	12 1,4
0001107028	M217	12 1,4
0001107029	M190	12 1,0
0001107030	PM015	0
0001107031	M398	0
0001107032	PM540	0
0001107033	M388	0

BOSCH RMA $\sqrt{\text{Kw}} - !$

0001107034	M314	12 1,0
0001107037	M083X	0
0001107038	PM013	0
0001107039	M320X	0
0001107041	M190	12 1,0
0001107043	M317	12 1,4
0001107044	M099X	0
0001107045	M314	12 1,0
0001107047	M017X	12 1,2
0001107048	M083X	0
0001107049	M398	0
0001107052	M248	12 1,1
0001107053	M248	12 1,1
0001107054	M227	12 1,1
0001107055	M227	12 1,1
0001107056	M314	0
0001107058	M375	12 1,1
0001107059	M387	0
0001107062	M388	0
0001107063	M102X	12 1,1
0001107064	M291	
0001107066	M382	0
0001107067	M416	0
0001107068	M227	12 1,1
0001107069	M227	12 1,1
0001107070	PM541	0
0001107071	PM541	0
0001107072	M083X	0
0001107073	M227	0
0001107074	M227	0
0001107075	PM015	0
0001107076	PM016	0
0001107077	RM086	0
0001107078	PM542	
0001107079	PM017	0
0001107080	PM543	0
0001107082	M387	0
0001107085	M388	0
0001107087	M317	12 1,4
0001107088	PM018	0
0001107091	M393	0
0001107092	PM013	
0001107093	PM544	
0001107094	PM545	

BOSCH RMA $\sqrt{\text{Kw}} - !$

0001107095	PM545	
0001107096	M083X	
0001107097	M393	
0001107098	RM086	0
0001107100	M314	0
0001107101	M314	
0001107103	M255	
0001107104	M255	
0001107108	M314	
0001107109		
0001107401	M143X	
0001107402	M143X	
0001107403	M083X	0
0001107404	M143X	
0001107405	M143X	
0001107406	PM547	
0001107407	M317	0
0001107408	M143X	
0001107409	M143X	
0001107410	PM548	
0001107411	M382	
0001107415	PM546	
0001107417	M317	
0001107418	PM548	
0001107421	RM002	
0001107423	RM058	
0001107424	RM058	
0001107425	PM549	
0001107426	PM549	
0001107427	PM550	
0001107428	PM550	
0001107429	M143X	
0001107432	PM546	
0001107433	PM551	
0001107434	PM551	
0001107435	M143X	
0001107436	M143X	
0001107437	M143X	
0001107438	RM062	
0001107439	RM062	
0001107440	RM003	
0001107442	M185X	
0001107443	M185X	
0001107448	RM061	

BOSCH RMA $V/Kw -!$

0001107449	RM061	
0001108001	M116	12/1,4 15a
0001108001	M116	12/1,4 15a
0001108002	M116	12/1,4 15a
0001108002	M116	12/1,4 15a
0001108003	M083	12/1,4
0001108004	M261	12/1,4
0001108004	M261	12/1,4
0001108005	M386	0
0001108006	M386	0
0001108009	M116	12/1,4 15a
0001108009	M116	12/1,4 15a
0001108010	M116	12/1,4 15a
0001108010	M116	12/1,4 15a
0001108011	M062	12/1,4
0001108012	M237	12/1,4
0001108013	PM019	0
0001108016	M116	12/1,4 15a
0001108017	M116	12/1,4 15a
0001108018	M175	12/1,4 30h
0001108019	M243	0
0001108020	M260	12/1,4
0001108020	M260	12/1,4
0001108021	PM020	0
0001108022	M415	0
0001108023	PM021	0
0001108024	M062X	12/1,4
0001108025	M057	12/1,4
0001108026	M116	12/1,4 15a
0001108026	M116	12/1,4 15a
0001108027	M116	12/1,4 15a
0001108027	M116	12/1,4 15a
0001108028	M116	12/1,4 15a
0001108029	M116	12/1,4 15a
0001108029	M116	12/1,4 15a
0001108030	M240	12/1,4
0001108031	M239	12/1,4
0001108032	PM022	0
0001108033	M261	
0001108033	M261	12/1,4
0001108034	M243	0
0001108035	M243	12/1,4
0001108037	M260	12/1,4
0001108038	M237	12/1,4

BOSCH RMA $V/Kw -!$

0001108039	M260	12/1,4
0001108040	M263	12/1,4
0001108040	M263	12/1,4
0001108042	M375	12/1,4 30h
0001108043	M238	12/1,4
0001108044	M238	12/1,4
0001108045	PM022	0
0001108046	PM022	0
0001108047	M099	12/1,4
0001108048	M200	12/1,4
0001108050	M375	12/1,1
0001108051	M415	0
0001108052	M239	12/1,4
0001108053	M143	0
0001108054	M185	12/1,4 30h
0001108056	M239	
0001108057	M260	12/1,4
0001108061		0
0001108062		0
0001108063	M375	12/1,4 30h
0001108064	M175	12/1,4 30h
0001108065	M185	12/1,4 30h
0001108066	PM022	0
0001108068	PM022	0
0001108069	PM022	0
0001108070	PM023	0
0001108071	M263	12/1,4
0001108071	M263	12/1,4
0001108072	M116	12/1,4 15a
0001108072	M116	12/1,4 15a
0001108073	M116	12/1,4 15a
0001108073	M116	12/1,4 15a
0001108074	M195	12/1,4
0001108075	PM021	0
0001108076	M306	12/1,1
0001108077	M306	12/1,1
0001108078	M099	12/1,4
0001108079	M099	12/1,4
0001108080	M093	12/1,0
0001108081	M062	12/1,4
0001108082	M263	12/1,4
0001108082	M263	12/1,4
0001108083	M260	12/1,4
0001108084	M243	12/1,4

BOSCH RMA $V/Kw -!$

0001108085	M440	0
0001108086	PM024	0
0001108087	M261	12/1,4
0001108087	M261	12/1,4
0001108088	M240	12/1,4
0001108089		0
0001108090		0
0001108091	M237	12/1,4
0001108092	M381	0
0001108093	M143	0
0001108094	M386	0
0001108095	M386	0
0001108096	M392	0
0001108097	M392	0
0001108098	M182	12/1,1
0001108099	RM039	0
0001108100	PM025	0
0001108101	M116	12/1,4 15a
0001108102	M116	12/1,4 15a
0001108103	PM022	0
0001108104	PM022	0
0001108105	PM023	0
0001108106	M261	12/1,4
0001108107	M262	12/1,4
0001108108	M185	12/1,4 30h
0001108109	M243	12/1,4
0001108110	M260	12/1,4
0001108111	M263	12/1,4
0001108112	M195	12/1,4
0001108113	PM026	0
0001108114	PM026	0
0001108115	M185	12/1,4 30h
0001108117	PM025	0
0001108118	M243	12/1,4
0001108119	M243	12/1,4
0001108120	M083	12/1,4
0001108121	M235X	12/1,4
0001108122	PM027	0
0001108123	M412	0
0001108124	M083	12/1,4
0001108125	M195	12/1,4
0001108126	M200	12/1,4
0001108127	M386	0
0001108128	PM028	0

BOSCH	RMA $\sqrt{Kw - !}$
0001108129	M388 0
0001108130	M440 0
0001108131	PM029 0
0001108132	M260 12 1,4
0001108133	M243 12 1,4
0001108134	PM022 0
0001108135	PM023 0
0001108136	M200 12 1,4
0001108137	M305 0
0001108138	PM024 0
0001108139	M261 12 1,4
0001108140	M261 12 1,4
0001108140	M261 12 1,4
0001108141	PM025 0
0001108143	M415 0
0001108144	RM007
0001108145	PM030 0
0001108146	M057 12 1,4
0001108148	PM031 0
0001108149	M083 12 1,4
0001108150	PM032 0
0001108151	M099 0
0001108152	M263 12 1,4
0001108153	M262 12 1,4
0001108154	M239 12 1,4
0001108155	M260 12 1,4
0001108156	PM033 0
0001108157	M185X 12 1,4 30h
0001108158	M263 0
0001108158	M263 0
0001108159	M200 12 1,4
0001108160	PM034 0
0001108162	M195 12 1,4
0001108166	M262 12 1,4
0001108167	M262 12 1,4
0001108168	PM867
0001108169	PM030 0
0001108170	PM031 0
0001108171	M099 12 1,4
0001108172	PM035 0
0001108173	PM036 0
0001108174	PM037 0
0001108175	PM037 0
0001108176	M440 0

BOSCH	RMA $\sqrt{Kw - !}$
0001108177	PM032 0
0001108178	PM032 0
0001108180	M415 12 1,9
0001108182	M415 12 1,9
0001108183	M390 0
0001108184	M099 12 1,4
0001108186	M415 0
0001108189	M200X
0001108190	PM038 0
0001108196	PM039 0
0001108197	PM040 0
0001108199	PM035 0
0001108202	M384 0
0001108204	PM241
0001108206	PM942
0001108211	RM059
0001108212	RM059
0001108213	RM046
0001108214	RM046
0001108217	RM043
0001108218	RM043
0001108220	RM008
0001108222	RM050
0001108223	RM050
0001108224	M384
0001108225	M200
0001108228	PM943
0001108237	RM009
0001108400	M390
0001108401	M185X
0001108402	PM608
0001108403	RM045
0001108404	RM045
0001108405	PM938
0001108408	PM606
0001108409	RM051
0001108410	RM051
0001108411	RM010
0001108415	RM011
0001108423	
0001109001	M238 12 1,4
0001109002	M238 12 1,4
0001109009	M299X
0001109012	PM552

BOSCH	RMA $\sqrt{Kw - !}$
0001109014	M399 0
0001109015	M385 0
0001109017	PM553
0001109018	M058X 12 1,8
0001109021	PM042 0
0001109022	PM042 0
0001109025	M037X 12 2,2 30h
0001109026	M105 12 1,7
0001109029	M346 12 1,8
0001109030	M384 0
0001109033	PM043 0
0001109034	M397 0
0001109035	PM554
0001109036	M399 0
0001109040	PM044 0
0001109041	PM045 0
0001109045	M384 0
0001109048	PM241 0
0001109049	PM553
0001109052	M385 0
0001109055	M385
0001109059	PM944
0001109060	PM944
0001109062	M385 0
0001109066	PM042
0001109067	PM042
0001109068	M385
0001109073	M116 0
0001109200	M037X
0001109201	M037X
0001109201	RM012
0001109204	RM013
0001109205	RM014
0001109250	M399
0001109252	PM046 0
0001109253	M384
0001109258	PM935
0001109259	PM935
0001109260	PM936
0001109262	RM044
0001109263	RM044
0001109264	RM015
0001109268	M384
0001109269	M384

BOSCH RMA $V_{Kw} -!$

0001109270	RM016	
0001109300	RM017	
0001110001	M014	12/1,7
0001110002	M014	12/1,7
0001110003	M415R	12/1,9
0001110003	M120X	12/1,9
0001110005	M058	12/1,7
0001110007	PM048	0/
0001110007	PM048	0/
0001110008	PM048	0/
0001110008	PM048	0/
0001110009	M257	12/1,7
0001110010	M257	12/1,7
0001110011	M304	12/1,4
0001110012	M015	12/1,7
0001110012	M015	12/1,7
0001110013	M214	12/1,7
0001110013	M214	12/1,7
0001110014	M014	12/1,7
0001110015	M014	12/1,7
0001110016	M216	12/1,7
0001110017	M105	12/1,7
0001110018	M346	12/1,8
0001110019	M214	12/1,7
0001110019	M214	12/1,7
0001110022	M069X	12/1,4
0001110022	M069X	12/1,4
0001110023	M069X	12/1,4
0001110023	M069X	12/1,4
0001110024	PM023	0/
0001110025	M058	12/1,7
0001110026	M120X	12/1,9
0001110027	M347	
0001110028	M299X	12/1,7 30h
0001110029	PM049	0/
0001110030	PM049	0/
0001110031	PM050	0/
0001110032	PM050	0/
0001110033	M346	12/1,8
0001110039	PM051	0/
0001110041	M299X	12/1,7 30h
0001110042	M299X	0/
0001110043	M214	12/1,7
0001110043	M214	12/1,7

BOSCH RMA $V_{Kw} -!$

0001110043	M214	12/1,7
0001110044	M244	12/1,8
0001110045	M069X	12/1,4
0001110045	M069X	12/1,4
0001110046	M069X	12/1,4
0001110046	M069X	12/1,4
0001110047	RM018	
0001110048	PM555	0/
0001110049	PM555	0/
0001110051	M244	12/1,8
0001110053	PM051	0/
0001110054	PM556	
0001110055	M015X	12/1,7
0001110055	M015X	12/1,7
0001110056	M105	12/1,7
0001110057	M383	0/
0001110058	M383	0/
0001110059	PM052	0/
0001110061	M256	12/1,8
0001110062	M256	12/1,8
0001110063	PM053	0/
0001110064	M214	12/1,7
0001110064	M214	12/1,7
0001110065	M244	12/1,8
0001110066	M069	12/1,4
0001110067	M069	12/1,4
0001110069	M282	12/1,7
0001110070	M282	12/1,7
0001110071	PM054	0/
0001110072	PM055	0/
0001110075	M216	12/1,7
0001110076	M310	12/1,8
0001110077	M310	12/1,8
0001110079	PM056	0/
0001110081	PM052	0/
0001110082	M058	12/1,7
0001110084	M383	0/
0001110085	M383	0/
0001110086	M282	12/1,7
0001110087	M282	12/1,7
0001110088	M214	
0001110088	M214	12/1,7
0001110088	M214	12/1,7
0001110089	M120X	12/1,9

BOSCH RMA $V_{Kw} -!$

0001110090	PM044	0/
0001110091	M216	12/1,7
0001110092	M058X	0/
0001110095	M120X	12/1,9
0001110098	M310	12/1,8
0001110099	M310	12/1,8
0001110100	PM057	0/
0001110101	PM057	0/
0001110102	M058X	12/1,7
0001110104	M214	12/1,7
0001110104	M214	12/1,7
0001110105	M214	12/1,7
0001110105	M214	12/1,7
0001110106	M069	12/1,4
0001110107	M069	12/1,4
0001110108	M069	0/
0001110110	PM058	0/
0001110111	M304	
0001110112	M216	12/1,7
0001110113	PM051	0/
0001110114	M120X	12/1,9
0001110115	M015X	12/1,7
0001110115	M015X	12/1,7
0001110116		
0001110118	M282	12/1,7
0001110119	M282	12/1,7
0001110120	PM044	0/
0001110122	M069	12/1,4
0001110123	M069	12/1,4
0001110124	M058X	12/1,7
0001110125	M058	12/1,7
0001110126	M069	12/1,4
0001110127	M069	12/1,4
0001110128	M069	0/
0001110129	M069	0/
0001110130	PM557	
0001110132	M397	0/
0001110133	M014	0/
0001110134	M014	0/
0001110136	M069	
0001110137	M069	
0001110138	M069	
0001110139	M069	
0001110143	M120X	

BOSCH	RMA $V_{Kw} -!$
0001111164	PM024
0001112003	M111
0001112003	M111 $12/0,8$ 15a
0001112004	M111 $12/0,8$ 15a
0001112004	M111 $12/0,8$ 15a
0001112005	M112 $12/0,9$ 15a
0001112006	M112 $12/0,9$ 15a
0001112007	M176 $12/0,9$
0001112008	M095 $12/0,9$
0001112009	M190 $12/1,0$
0001112010	M191 $12/1,0$
0001112011	M191 $12/1,0$
0001112012	M137 $12/0,8$
0001112013	M112 $12/0,9$ 15a
0001112014	M112 $12/0,9$ 15a
0001112015	M143 $12/0,9$
0001112016	M137 $12/0,8$
0001112017	PM013 0
0001112018	M320 $12/0,8$
0001112018	M320 $12/0,8$
0001112019	M222 $12/1,0$
0001112020	PM558 0
0001112020	PM558 0
0001112021	M034 0
0001112022	M034 0
0001112024	M131 $12/0,8$
0001112025	M017E $12/0,8$
0001112027	M255 0
0001112028	M255 0
0001112029	M222 $12/1,0$
0001112030	M191 $12/1,0$
0001112031	M191 $12/1,0$
0001112032	M327 $12/0,7$
0001112032	M327 $12/0,7$
0001112033	M137 $12/0,8$
0001112035	M143 $12/0,9$
0001112037	M136 $12/0,8$
0001112038	M111 $12/0,8$ 15a
0001112038	M111 $12/0,8$ 15a
0001112039	M111 $12/0,8$ 15a
0001112039	M111 $12/0,8$ 15a
0001112041	M222 $12/1,0$
0001112044	M255 0
0001112045	M255 0

BOSCH	RMA $V_{Kw} -!$
0001113001	M034 $12/0,8$
0001113002	M034 $12/0,8$
0001113003	M134 $12/0,8$
0001113003	M134 $12/0,8$
0001113003	M134 $12/0,8$
0001113004	M013 $12/0,7$
0001113005	M134 $12/0,8$
0001113005	M134 $12/0,8$
0001113006	M268 $12/0,8$
0001113007	M034 $12/0,8$
0001113007	M034 $12/0,8$
0001113008	M034 $12/0,8$
0001113008	M034 $12/0,8$
0001113009	M134 $12/0,8$
0001113009	M134 $12/0,8$
0001113009	M134 $12/0,8$
0001113010	M389 0
0001113011	M111 $12/0,8$ 15a
0001113011	M111 $12/0,8$ 15a
0001113012	M111 0
0001113012	M111 0
0001113013	M255 0
0001113014	M255 0
0001113017	M389 0
0001114003	M115 $12/1,0$ 15a
0001114004	M115 $12/1,0$ 15a
0001114005	M150 $12/0,9$ 15a
0001114005	M150 $12/0,9$ 15a
0001114005	M150 $12/0,9$ 15a
0001114006	M150 $12/0,9$ 15a
0001114006	M150 $12/0,9$ 15a
0001114006	M150 $12/0,9$ 15a
0001114008	M190 $12/1,0$
0001114009	M191 $12/1,0$
0001114010	M191 $12/1,0$
0001114012	M150 $12/0,9$ 15a
0001114012	M150 $12/0,9$ 15a
0001114012	M150 $12/0,9$ 15a
0001114014	M137 $12/0,9$
0001114014	M137 $12/0,9$
0001114015	M115 $12/1,0$ 15a
0001114016	M115 $12/1,0$ 15a
0001114017	M190 $12/1,0$
0001114020	M138 $12/0,9$

BOSCH	RMA $V_{Kw} -!$
0001114020	M138 $12/0,9$
0001114021	M190 $12/1,0$
0001114022	M217 0
0001114023	PM061 0
0001114025	M255 0
0001115001	M415R $12/1,9$
0001115001	M120X $12/1,9$
0001115002	PM062 0
0001115005	PM063 0
0001115006	PM064 0
0001115007	PM065 0
0001115008	PM066 0
0001115011	PM052
0001115012	PM067 0
0001115015	PM068 0
0001115016	PM559
0001115017	PM559
0001115020	PM068
0001115022	PM560
0001115024	PM067
0001115031	PM941
0001115035	M299X
0001115047	RM055
0001115048	RM055
0001115049	RM052
0001115050	RM052
0001115051	RM053
0001115052	RM053
0001116001	M319 $12/0,7$
0001116003	M391 0
0001116005	M268 $12/0,8$
0001116006	PM069 0
0001116008	PM013 0
0001116009	PM544
0001117008	M014
0001120400	PM561
0001120401	PM561
0001120402	PM562
0001120403	PM562
0001120406	PM563
0001120407	PM563
0001120408	PM564
0001120409	PM564
0001120410	PM565

BOSCH RMA $\sqrt{\text{Kw}} -!$

0001120411	PM565	
0001121001	PM566	0
0001121002	PM566	0
0001121006	PM070	0
0001121007	PM070	0
0001121008	PM071	12 1,1
0001121009	PM071	0
0001121010	PM072	0
0001121011	PM072	0
0001121016	PM073	0
0001121017	PM073	0
0001121018	PM567	
0001121019	PM567	
0001121022	PM074	0
0001121023	PM074	0
0001121024	PM567	
0001121025	PM567	
0001121026	PM071	
0001121027	PM071	
0001121028	PM070	
0001121029	PM070	
0001121030	RM020	
0001121034	RM021	
0001121402	PM568	
0001121403	PM568	
0001121408	PM569	
0001121409	PM569	
0001121410	PM565	
0001121411	PM565	
0001121422	RM022	
0001122400	RM023	
0001122402	RM024	
0001123001	PM570	
0001123002	PM571	
0001123003	PM571	
0001123012	PM572	
0001123013	PM572	
0001123014	PM573	
0001123015	PM573	
0001123016	PM574	
0001123017	PM574	
0001123018	PM575	
0001123019	PM575	
0001123020	PM576	

BOSCH RMA $\sqrt{\text{Kw}} -!$

0001123021	PM576	
0001123024	RM025	
0001123026	RM026	
0001124001	M289X	12 1,8
0001124002	M289X	12 1,8
0001124003	M313	12 1,8
0001124004	M313	12 1,8
0001124005	M396	0
0001124006	M396	0
0001124007	M315	12 1,8
0001124008	M315	12 1,8
0001124011	M315	12 1,8
0001124012	M315	12 1,8
0001124013	PM076	0
0001124014	PM076	0
0001124018	PM077	0
0001124019	PM077	0
0001124020	PM078	0
0001124021	PM078	0
0001124022	M315	
0001124023	M315	
0001124024	PM945	
0001124026	PM946	
0001125001	M396	0
0001125002	M396	0
0001125003	M315	0
0001125004	M315	0
0001125005	M313	12 1,8
0001125006	M313	12 1,8
0001125007	M289X	12 1,8
0001125008	M289X	12 1,8
0001125009	PM577	
0001125010	PM577	
0001125011	M396	0
0001125012	M289	12 1,8
0001125013	M289	12 1,8
0001125014	M313	12 1,8
0001125015	M313	12 1,8
0001125016	PM079	0
0001125017	PM079	0
0001125018	PM080	0
0001125019	PM080	0
0001125021	PM081	0
0001125022	PM081	0

BOSCH RMA $\sqrt{\text{Kw}} -!$

0001125031	M396	
0001125032	M396	
0001125035	M313X	
0001125036	M313X	
0001125039	PM577	
0001125040	PM577	
0001125042	M289X	
0001125043	M289X	
0001125043	M289X	
0001125046	PM079	
0001125046	RM027	
0001125048	PM080	
0001125049	PM080	
0001125051	PM081	
0001125052	PM081	
0001125053	PM578	
0001125054	PM578	
0001125055	PM940	
0001125501	PM082	0
0001125502	PM082	0
0001125503	PM083	0
0001125504	PM083	0
0001125507	PM084	0
0001125508	PM084	0
0001125511	PM082	
0001125512	PM082	
0001125517	PM084	0
0001125518	PM084	0
0001125519	PM937	
0001125600	PM939	
0001125605	PM579	
0001125606	PM579	
0001125607	RM028	
0001131112		
0001141101	PM085	0
0001141107	PM085	0
0001155009	M094	12 0,6
0001155010	M094	12 0,6
0001155016	M094	12 0,6
0001155017	M094	12 0,6
0001157001	M094	12 0,6
0001157002	M094	12 0,6
0001157003	M094	12 0,6
0001157004	M094	12 0,6

BOSCH RMA $V/Kw -!$

0001157008	0
0001157009	M094 12/0,6
0001157010	M094 12/0,6
0001157012	M094 12/0,6
0001157013	M094 12/0,6
0001157020	M081 0
0001157021	12/0,8
0001157022	M081 12/0,6
0001157022	M081 12/0,6
0001157023	M376 0
0001157024	M095 12/0,7
0001157025	M094 12/0,6
0001157028	M095 12/0,7
0001157029	M094 12/0,6
0001157030	M095 12/0,7
0001160002	
0001180025	0
0001204102	
0001204103	0
0001207001	0
0001207005	0
0001207016	0
0001207017	0
0001207018	0
0001207019	0
0001208001	0
0001208003	0
0001208004	0
0001208005	0
0001208006	0
0001208009	M197 12/0,8
0001208017	0
0001208019	M152 12/0,8 15a
0001208020	M152 12/0,8 15a
0001208025	0
0001208026	M197 12/0,8
0001208026	M197 12/0,8
0001208027	M152 12/0,8 15a
0001208028	M152 12/0,8 15a
0001208029	M152 0
0001208030	M152 12/0,8 15a
0001208031	M152 12/0,8 15a
0001208032	M158 12/0,8
0001208033	M197 12/0,8

BOSCH RMA $V/Kw -!$

0001208033	M197 12/0,8
0001208038	M096 12/0,8
0001208038	M096 12/0,8
0001208039	M096 12/0,8
0001208039	M096 12/0,8
0001208040	M152 12/0,8 15a
0001208041	M152 12/0,8 15a
0001208044	12/0,8
0001208046	0
0001208050	M152 12/0,8 15a
0001208052	12/0,8
0001208053	M096 12/0,8
0001208053	M096 12/0,8
0001208054	M096 12/0,8
0001208054	M096 12/0,8
0001208055	M152 0
0001208056	12/0,8
0001208058	12/0,8
0001208059	0
0001208060	12/0,8
0001208061	12/0,8
0001208100	0
0001208101	0
0001208151	0
0001208172	M082 12/0,8
0001208172	M136 0
0001208200	12/0,8
0001208201	12/0,8
0001208202	M096 12/0,8
0001208202	M096 12/0,8
0001208203	M118 0
0001208204	M158 12/0,8
0001208205	M118 12/0,8
0001208206	M152 0
0001208208	0
0001208209	M021 12/1,0
0001208210	M118 12/0,8
0001208211	M010 12/0,8
0001208213	M100 12/0,8
0001208214	M118 12/0,8
0001208216	12/0,8
0001208217	12/0,8
0001208218	M114 12/0,8
0001208218	M114 12/0,8

BOSCH RMA $V/Kw -!$

0001208219	M030 12/0,7
0001208220	0
0001208221	0
0001208223	M137 12/0,8
0001208223	M137 12/0,8
0001208224	M180 12/0,8
0001208224	M180 12/0,8
0001208225	0
0001208226	M075X 12/0,8
0001208226	M075X 12/0,8
0001208227	M021 12/1,0
0001208228	M075X 12/0,8
0001208228	M075X 12/0,8
0001208229	M096 12/0,8
0001208229	M096 12/0,8
0001208232	M136 12/0,8
0001208232	M082 12/0,8
0001208233	M013X 12/1,1
0001208233	M013X 12/1,1
0001208240	
0001208241	
0001208335	
0001208400	M280 12/1,1
0001208405	0
0001208406	M118 12/0,8
0001208407	PM019 0
0001208408	M011 12/0,9
0001208409	M136 12/0,9 15a
0001208409	M136 12/0,9 15a
0001208411	M022 12/0,9
0001208412	M022 12/0,9
0001208413	PM019 0
0001208414	M022 12/0,9
0001208415	M022 12/0,9
0001208416	M150 12/0,9 15a
0001208416	M150 12/0,9 15a
0001208416	M150 12/0,9 15a
0001208417	M150 12/0,9 15a
0001208417	M150 12/0,9 15a
0001208417	M150 12/0,9 15a
0001208418	M150 12/0,9 15a
0001208418	M150 12/0,9 15a
0001208418	M150 12/0,9 15a
0001208419	M150 12/0,9 15a

BOSCH	RMA $\sqrt{Kw - I}$
0001208419	M150 $\frac{12}{0,9}$ 15a
0001208419	M150 $\frac{12}{0,9}$ 15a
0001208420	$\frac{0}{/}$
0001208421	$\frac{0}{/}$
0001208422	M046 $\frac{12}{0,9}$
0001208423	M136 $\frac{12}{0,9}$ 15a
0001208423	M136 $\frac{12}{0,9}$ 15a
0001208425	M251 $\frac{12}{0,9}$
0001208426	M251 $\frac{12}{0,9}$
0001208428	M251 $\frac{12}{0,9}$
0001208429	M251 $\frac{12}{0,9}$
0001208501	M152 $\frac{0}{/}$
0001208506	M100 $\frac{12}{0,8}$
0001208507	M010 $\frac{12}{0,8}$
0001208508	M118 $\frac{12}{0,8}$
0001208510	M029 $\frac{12}{1,0}$
0001208513	M030 $\frac{12}{0,7}$
0001208513	M030 $\frac{12}{0,7}$
0001208514	$\frac{0}{/}$
0001208515	M017 $\frac{12}{0,8}$
0001208516	M102 $\frac{12}{0,8}$
0001208517	M017 $\frac{12}{0,8}$
0001208518	M075X $\frac{12}{0,8}$
0001208518	M075X $\frac{12}{0,8}$
0001208519	$\frac{0}{/}$
0001208520	$\frac{0}{/}$
0001208520	$\frac{0}{/}$
0001208521	M030 $\frac{12}{0,7}$
0001208521	M030 $\frac{12}{0,7}$
0001208524	$\frac{0}{/}$
0001208524	$\frac{0}{/}$
0001208526	M017 $\frac{12}{0,8}$
0001208527	M017 $\frac{0}{/}$
0001208528	M017 $\frac{12}{0,8}$
0001208702	M118 $\frac{12}{0,8}$
0001208706	M030 $\frac{12}{0,7}$
0001208706	M030 $\frac{12}{0,7}$
0001208707	M102 $\frac{12}{0,8}$
0001208709	M148 $\frac{12}{0,9}$
0001208709	M148 $\frac{12}{0,9}$
0001208710	M148 $\frac{12}{0,9}$
0001208710	M148 $\frac{12}{0,9}$
0001208711	M148 $\frac{12}{0,9}$ 15a
0001208711	M148 $\frac{12}{0,9}$ 15a

BOSCH	RMA $\sqrt{Kw - I}$
0001208712	M148 $\frac{12}{0,9}$ 15a
0001208712	M148 $\frac{12}{0,9}$ 15a
0001208713	M068 $\frac{12}{0,9}$
0001208713	M148 $\frac{12}{0,9}$
0001208714	M068 $\frac{12}{0,9}$
0001208714	M148 $\frac{12}{0,9}$
0001208715	M030 $\frac{12}{0,7}$
0001208715	M030 $\frac{12}{0,7}$
0001208717	M202 $\frac{12}{0,9}$
0001208717	M202 $\frac{12}{0,9}$
0001208718	M030 $\frac{12}{0,7}$
0001208718	M030 $\frac{12}{0,7}$
0001208719	M030 $\frac{12}{0,7}$
0001208719	M030 $\frac{12}{0,7}$
0001209014	$\frac{0}{/}$
0001209227	M021 $\frac{0}{/}$
0001210213	$\frac{0}{/}$
0001211005	$\frac{12}{0,8}$
0001211006	M152 $\frac{0}{/}$
0001211007	M152 $\frac{0}{/}$
0001211010	M152 $\frac{12}{0,8}$ 15a
0001211011	M152 $\frac{0}{/}$
0001211012	$\frac{0}{/}$
0001211013	$\frac{0}{/}$
0001211014	$\frac{0}{/}$
0001211016	$\frac{12}{0,9}$
0001211017	$\frac{12}{0,8}$
0001211018	M152 $\frac{0}{/}$
0001211019	M152 $\frac{12}{0,8}$ 15a
0001211020	$\frac{0}{/}$
0001211022	$\frac{12}{0,8}$ 15a
0001211025	M012 $\frac{12}{0,7}$
0001211027	M172 $\frac{0}{/}$
0001211200	$\frac{0}{/}$
0001211201	$\frac{0}{/}$
0001211204	M016 $\frac{12}{0,8}$ 15a
0001211204	M016 $\frac{12}{0,8}$ 15a
0001211205	M016 $\frac{12}{0,8}$ 15a
0001211205	M016 $\frac{12}{0,8}$ 15a
0001211206	M159 $\frac{12}{0,7}$ 15a
0001211206	M159 $\frac{12}{0,7}$ 15a
0001211207	M012 $\frac{12}{0,7}$
0001211208	M012 $\frac{12}{0,7}$
0001211209	M016 $\frac{12}{0,8}$ 15a

BOSCH	RMA $\sqrt{Kw - I}$
0001211209	M016 $\frac{12}{0,8}$ 15a
0001211210	M016 $\frac{12}{0,8}$ 15a
0001211210	M016 $\frac{12}{0,8}$ 15a
0001211211	M016 $\frac{12}{0,8}$ 15a
0001211211	M016 $\frac{12}{0,8}$ 15a
0001211212	M016 $\frac{12}{0,8}$ 15a
0001211212	M016 $\frac{12}{0,8}$ 15a
0001211213	M107 $\frac{12}{0,8}$ 15a
0001211213	M107 $\frac{12}{0,8}$ 15a
0001211214	M107 $\frac{12}{0,8}$ 15a
0001211214	M107 $\frac{12}{0,8}$ 15a
0001211215	M013 $\frac{12}{0,7}$
0001211216	M107 $\frac{12}{0,8}$ 15a
0001211216	M034 $\frac{12}{0,8}$ 15a
0001211217	M107 $\frac{12}{0,8}$ 15a
0001211217	M107 $\frac{12}{0,8}$ 15a
0001211218	M016 $\frac{12}{0,8}$ 15a
0001211218	M016 $\frac{12}{0,8}$ 15a
0001211219	M016 $\frac{12}{0,8}$ 15a
0001211219	M016 $\frac{12}{0,8}$ 15a
0001211220	M016 $\frac{0}{/}$
0001211221	M031 $\frac{12}{0,7}$
0001211222	M031 $\frac{12}{0,7}$
0001211223	M106 $\frac{12}{0,8}$ 15a
0001211223	M106 $\frac{12}{0,8}$ 15a
0001211224	M106 $\frac{12}{0,8}$ 15a
0001211224	M106 $\frac{12}{0,8}$ 15a
0001211225	$\frac{0}{/}$
0001211227	M082 $\frac{12}{0,8}$
0001211227	M076 $\frac{12}{0,8}$
0001211228	M159 $\frac{12}{0,7}$ 15a
0001211228	M159 $\frac{12}{0,7}$ 15a
0001211229	M152 $\frac{12}{0,8}$ 15a
0001211230	M149 $\frac{12}{0,8}$
0001211231	M149 $\frac{12}{0,8}$
0001211232	M076 $\frac{12}{0,8}$
0001211232	M076 $\frac{12}{0,8}$
0001211233	M107 $\frac{12}{0,8}$ 15a
0001211233	M107 $\frac{12}{0,8}$ 15a
0001211234	M107 $\frac{12}{0,8}$ 15a
0001211234	M107 $\frac{12}{0,8}$ 15a
0001211235	M149 $\frac{12}{0,8}$
0001211236	M149 $\frac{12}{0,8}$
0001211237	$\frac{0}{/}$

BOSCH	RMA $V_{Kw} -!$	BOSCH	RMA $V_{Kw} -!$	BOSCH	RMA $V_{Kw} -!$
0001211239	0	0001211526	M034 $12/0,8$	0001212211	0
0001211241	M293 $12/0,8$	0001211527	M145 $12/0,8$	0001212212	0
0001211242	M018 $12/0,8$ 15a	0001211527	M149 $12/0,8$	0001212213	0
0001211246	M023 $12/0,8$	0001211528	M145 $12/0,8$	0001212214	0
0001211247	M024 $12/0,8$	0001211528	M149 $12/0,8$	0001212400	0
0001211247	M024 $12/0,8$	0001211529	M034 $12/0,8$	0001212401	0
0001211248	M024 $12/0,8$	0001211530	M034 $12/0,8$	0001212402	0
0001211248	M024 $12/0,8$	0001211533	M159 $12/0,7$ 15a	0001212403	0
0001211251	M251 0	0001211533	M159 $12/0,7$ 15a	0001214002	M346 0
0001211252	M251 0	0001211535	M076 $12/0,8$	0001218002	M121X $12/2,9$
0001211253	M251 $12/0,9$	0001211535	M076 $12/0,8$	0001218003	M157 $12/2,2$
0001211254	M251 $12/0,9$	0001211536	M056 $12/0,9$	0001218004	M066X $12/2,2$
0001211255	M106 $12/0,8$ 15a	0001211538	0	0001218005	M066X $12/2,2$
0001211255	M106 $12/0,8$ 15a	0001211706	0	0001218006	M088 $12/2,2$
0001211256	M106 $12/0,8$ 15a	0001211986	0	0001218007	M040 $12/2,2$
0001211256	M106 $12/0,8$ 15a	0001211987	M012 $12/0,7$	0001218008	M045 $12/2,2$
0001211257	M111 $12/0,8$ 15a	0001211988	M013 $12/0,7$	0001218009	M037 $12/2,2$ 30h
0001211257	M111 $12/0,8$ 15a	0001211989	M159 $12/0,7$ 15a	0001218009	M037 $12/2,2$ 30h
0001211258	M111 $12/0,8$ 15a	0001211989	M159 $12/0,7$ 15a	0001218010	M048 $12/2,2$
0001211258	M111 $12/0,8$ 15a	0001211990	$12/0,8$ 15a	0001218011	M162 $12/2,2$
0001211259	M024 $12/0,8$	0001211991	M152 0	0001218012	M258 $12/2,2$
0001211259	M024 $12/0,8$	0001211992	$12/0,7$	0001218012	M258 $12/2,2$
0001211260	M024 $12/0,8$	0001211993	$12/0,7$	0001218012	M258 $12/2,2$
0001211260	M024 $12/0,8$	0001211995	M152 $12/0,8$ 15a	0001218013	M258 $12/2,2$
0001211410		0001211996	M152 $12/0,8$ 15a	0001218013	M258 $12/2,2$
0001211500	M108 $12/0,8$ 15a	0001211997	0	0001218013	M258 0
0001211500	M108 $12/0,8$ 15a	0001211998	$12/0,7$	0001218014	M053 $12/2,2$
0001211501	M108 $12/0,8$ 15a	0001212002	M109 0	0001218015	
0001211501	M108 $12/0,8$ 15a	0001212003	$12/0,7$	0001218016	M247 $12/2,2$
0001211502	M149 $12/0,8$	0001212004		0001218017	M066X $12/2,2$
0001211502	M145 $12/0,8$	0001212005	M109 $12/0,7$	0001218018	M258 $12/2,2$
0001211503	M145 $12/0,8$	0001212006	M109 $12/0,7$	0001218018	M258 $12/2,2$
0001211503	M149 $12/0,8$	0001212007	M109 $12/0,7$	0001218018	M258 $12/2,2$
0001211504	M024 $12/0,8$	0001212008	M109 $12/0,7$	0001218019	M246 $12/2,2$
0001211504	M148 $12/0,8$	0001212009	M109 0	0001218020	M157 $12/2,2$
0001211505	M024 $12/0,8$	0001212012	M109 $12/0,7$	0001218021	M088 $12/2,2$
0001211505	M148 $12/0,8$	0001212013	$12/0,7$	0001218021	M088 $12/2,2$
0001211512	M076 $12/0,8$	0001212204	0	0001218022	M285 $12/2,2$
0001211512	M082 $12/0,8$	0001212205	0	0001218022	M285 $12/2,2$
0001211513	M159 $12/0,7$ 15a	0001212206	0	0001218023	M151 $12/2,2$
0001211513	M159 $12/0,7$ 15a	0001212207	0	0001218024	M054 $12/2,2$
0001211514	M152 0	0001212208	M109 $12/0,7$	0001218026	M037 $12/2,2$ 30h
0001211515	0	0001212209	M109 $12/0,7$	0001218026	M037 $12/2,2$ 30h
0001211525	M034 $12/0,8$	0001212210		0001218027	PM087 0

BOSCH RMA $V_{Kw -!}$

0001218029	PM088	0	
0001218100	M278	0	
0001218101	M246	12	2,2
0001218102	M053	12	2,2
0001218103	M054	12	2,2
0001218104	PM089	0	
0001218105	M307	12	2,2
0001218106	M285	12	2,2
0001218106	M285	12	2,2
0001218108	M088	12	2,2
0001218108	M088	12	2,2
0001218109	PM088	0	
0001218110	M247	12	2,2
0001218111	M066X	12	2,2
0001218112	M066X	12	2,2
0001218113	M258	12	2,2
0001218114	M258	12	2,2
0001218115	M258	12	2,2
0001218116	M394	0	
0001218117	M394	0	
0001218120	M048X	12	2,2
0001218121	M048	12	2,2
0001218122	M162	12	2,2
0001218125	M151	12	2,2
0001218126	M040	12	2,2
0001218127	PM089	0	
0001218128	M307	12	2,2
0001218129	M285	12	2,2
0001218129	M285	12	2,2
0001218130	M066X	12	2,2
0001218130	M066X	12	2,2
0001218131	M045	12	2,2
0001218133	M048X	12	2,2
0001218134	M037	12	2,2 30h
0001218134	M037	12	2,2 30h
0001218135	PM087	0	
0001218136	PM090	0	
0001218141	M228	12	2,2
0001218145	M048X	12	2,2
0001218146	M048X	12	2,2
0001218147	M048X	12	2,2
0001218148	M351	12	1,8
0001218149	PM091	0	
0001218150	M088	12	2,2

BOSCH RMA $V_{Kw -!}$

0001218150	M088	12	2,2
0001218151	PM092	0	
0001218152	M277X	12	3,1
0001218153	PM093	0	
0001218154	M053	12	2,2
0001218155	M048	12	2,2
0001218156	M088	12	2,2
0001218156	M088	12	2,2
0001218157	PM094	0	
0001218158	M151	12	2,2
0001218158	M151	12	2,2
0001218159	M284	12	2,2
0001218160	PM088	0	
0001218162	M088	12	2,2
0001218163	M246	12	2,2
0001218164	PM092	0	
0001218165	M088	12	2,2
0001218166	PM095	0	
0001218167	M246	12	2,2
0001218168	M277X	12	3,1
0001218171	M037	0	
0001218172	PM096	0	
0001218173	PM097	0	
0001218174	M352	12	2,2
0001218175	M151	12	2,2
0001218176	M353	0	
0001218177	M395	0	
0001218620	M157		
0001218703	M054		
0001218711	M066X		
0001218715			
0001218722	M162		
0001218728	M307		
0001218730	M066X		
0001218735	PM087		
0001218741	M228		
0001218757	PM094		
0001218758	M151		
0001218759	M284		
0001218764	PM092		
0001218765	M088		
0001218766	PM095		
0001218767	M246		
0001218768	M277		

BOSCH RMA $V_{Kw -!}$

0001218770	RM004		
0001218771	M037		
0001218772	PM096		
0001218774	M352		
0001218777	M395		
0001218812	RM005		
0001218818	M252		
0001219002	PM580		
0001219003	PM581		
0001219005	PM582		
0001219009	PM098	0	
0001219012	PM583		
0001223001	PM094	0	
0001223002	PM096	0	
0001223003	PM099	0	
0001223005	PM100	0	
0001223006	PM584		
0001223007	PM099	0	
0001223010	PM585		
0001223013	PM102	0	
0001223014	PM094	0	
0001223016	PM586		
0001223018	PM587		
0001223504	PM150		
0001223505	PM588		
0001230002	PM163		
0001230004	PM589		
0001230006	PM103	0	
0001230007	PM104	0	
0001230010	PM104	0	
0001230011	PM590		
0001230015	PM591		
0001230016	PM591		
0001230016	PM591	0	
0001230027	RM054		
0001230028	RM006		
0001231002	PM105	0	
0001231003	PM106	0	
0001231004	PM170		
0001231005	PM592		
0001231007	PM107	0	
0001231008	PM164		
0001231009	PM108	0	
0001231010	PM593		

BOSCH	RMA $\sqrt{Kw - !}$
0001231011	PM109 0
0001231012	RM060
0001231014	PM110 0
0001231016	PM594
0001231017	PM595
0001231019	PM107
0001231029	PM164
0001231030	PM107
0001231033	PM105
0001241001	RM056
0001241014	RM057
0001305016	M172 0
0001307024	RM098 0
0001310007	0
0001310008	0
0001310013	
0001311001	M172 12 1,1
0001311001	M172 12 1,1
0001311016	M038 12 1,0
0001311023	M049 0
0001311024	M049 0
0001311025	M038 12 1,0
0001311026	M041 12 1,1
0001311027	M172 12 1,1
0001311027	M172 12 1,1
0001311028	M093 12 1,0
0001311029	M093 12 1,0
0001311030	M093 12 1,0
0001311031	M093 12 1,0
0001311032	M172 12 1,1
0001311033	M049 12 1,1
0001311033	M049 12 1,1
0001311034	M049 12 1,1
0001311034	M049 12 1,1
0001311037	M049 12 1,1
0001311037	M049 12 1,1
0001311038	M043 12 1,0
0001311038	M043 12 1,0
0001311039	M041 12 1,1
0001311039	M041 12 1,1
0001311040	M011 12 0,9
0001311041	M109 12 1,1 15a
0001311042	M299 12 1,5
0001311043	M299 0

BOSCH	RMA $\sqrt{Kw - !}$
0001311044	M044 12 1,0
0001311045	M038 12 1,0
0001311046	M049 0
0001311047	0
0001311048	M043 12 1,0
0001311049	M049 0
0001311054	
0001311056	RM098 0
0001311100	M072 12 1,5
0001311101	M049 12 1,1
0001311101	M049 12 1,1
0001311103	M172 12 1,1
0001311103	M172 12 1,1
0001311104	M172 0
0001311105	0
0001311106	0
0001311108	M041 12 1,1
0001311108	M041 12 1,1
0001311109	M049 0
0001311110	M025 12 1,0
0001311111	M025 0
0001311112	M093 12 1,0
0001311113	M043 12 1,0
0001311114	M172 0
0001311115	M044 0
0001311116	M044 12 1,0
0001311117	12 1,1
0001311118	M109 12 1,1 15a
0001311118	M109 12 1,1 15a
0001311119	M047 12 1,3
0001311120	M049 0
0001311122	M109 12 1,1 15a
0001311122	M109 12 1,1 15a
0001311123	M044 12 1,0
0001311124	0
0001311125	M073 12 1,1
0001311126	12 1,1
0001311128	0
0001311129	M011 12 0,9
0001311130	M011 12 0,9
0001311131	M025 12 1,0
0001311132	M026 0
0001311133	M044 12 1,0
0001311134	PM020 0

BOSCH	RMA $\sqrt{Kw - !}$
0001311135	PM020 0
0001311136	M109 12 1,1 15a
0001311137	M109 12 1,1 15a
0001311137	M109 12 1,1 15a
0001311139	M182 0
0001311140	M109 12 1,1 15a
0001311140	M109 12 1,1 15a
0001311141	M109 12 1,1 15a
0001311141	M109 12 1,1 15a
0001311142	M109 12 1,1 15a
0001311142	M109 12 1,1 15a
0001311143	M109 12 1,1 15a
0001311143	M109 12 1,1 15a
0001311145	M093 12 1,0
0001311146	M172 12 1,1
0001311146	M172 12 1,1
0001311147	M172 12 1,1
0001311147	M172 12 1,1
0001311149	M043 12 1,0
0001311149	M043 12 1,0
0001311150	M070 12 1,5
0001311151	M073 12 1,1
0001312001	RM097 0
0001312100	0
0001312101	0
0001312102	0
0001312103	0
0001312104	M250 12 1,7
0001312104	M250 12 1,7
0001312105	M250 12 1,7
0001312105	M250 12 1,7
0001312108	M250 12 1,7
0001312108	M250 12 1,7
0001312109	M250 12 1,7
0001312109	M250 12 1,7
0001312110	0
0001312111	0
0001313001	M197 12 1,5
0001313003	M197 12 1,5
0001313003	M197 12 1,5
0001313005	M197 12 1,5
0001313005	M197 12 1,5
0001313007	M197 12 1,5
0001313007	M197 12 1,5

BOSCH	RMA $V_{Kw} -!$
0001314001	M049 12/ 1,1
0001314002	M197 12/ 1,5
0001314002	M197 12/ 1,5
0001314005	M165 12/ 1,5
0001314010	
0001314012	M051 12/ 1,5
0001314012	M051 12/ 1,5
0001314013	M051 12/ 1,5
0001314013	M051 12/ 1,5
0001314014	M063 12/ 1,5
0001314014	M063 12/ 1,5
0001314015	M063 12/ 1,5
0001314015	M063 12/ 1,5
0001314016	PM552
0001314017	M155 12/ 1,5
0001314018	M197 12/ 1,5
0001314018	M197 12/ 1,5
0001314022	M101 12/ 1,5
0001314025	M299 12/ 1,5
0001314026	M026 12/ 1,6
0001314027	M087 12/ 1,5
0001314029	M165 12/ 1,5
0001314030	M164 12/ 1,5
0001314031	
0001314032	M299
0001314033	M197 0
0001314034	M103 12/ 1,7
0001314035	M140 12/ 1,5 15a
0001314036	M140 12/ 1,5
0001314036	M140 12/ 1,5
0001314037	PM555 0
0001314038	PM555 0
0001314041	M164 12/ 1,5
0001314043	M299 12/ 1,5
0001314045	M299 12/ 1,7 30h
0001314047	RM041 0
0001315002	RM097 0
0001315004	
0001315183	
0001316001	
0001317006	M218 0
0001317007	M063 12/ 1,5
0001317007	M063 12/ 1,5
0001317008	M063 12/ 1,5

BOSCH	RMA $V_{Kw} -!$
0001317008	M063 12/ 1,5
0001317009	M051 12/ 1,7
0001317009	M051 12/ 1,7
0001317010	M051 12/ 1,7
0001317010	M051 12/ 1,7
0001317011	M218 12/ 1,7
0001317012	M218 12/ 1,7
0001317013	M052 12/ 1,7
0001317014	M051 12/ 1,7
0001317014	M051 12/ 1,7
0001317015	M051 12/ 1,7
0001317015	M051 12/ 1,7
0001317016	M218 12/ 1,7
0001317016	M218 12/ 1,7
0001317017	M218 12/ 1,7
0001317018	M051 12/ 1,7
0001317018	M051 12/ 1,7
0001317019	M051 12/ 1,7
0001317020	M051 12/ 1,7
0001317021	M051 12/ 1,7
0001317021	M051 12/ 1,7
0001317022	M052 12/ 1,7
0001317023	M264 12/ 1,7
0001317023	M264 12/ 1,7
0001317024	PM553
0001317025	M052 12/ 1,7
0001354008	PM111 0
0001354012	
0001354013	
0001354014	
0001354031	PM112 0
0001354038	PM113 0
0001354067	PM114 0
0001354073	PM115 0
0001354080	PM115 0
0001354089	PM116 0
0001354090	PM117 0
0001354091	M355 12/ 2,5
0001354095	PM112 0
0001354097	PM114 0
0001354099	PM114 0
0001354100	PM118 0
0001358003	
0001358006	

BOSCH	RMA $V_{Kw} -!$
0001358017	
0001358020	PM119 0
0001358021	PM124
0001358027	PM122
0001358034	PM120 0
0001358038	
0001358041	PM121 0
0001358044	PM122
0001358046	PM122 12/ 2,4
0001358047	PM123 0
0001358048	
0001358049	PM122 12/ 2,4
0001358050	PM124 0
0001358051	PM119 0
0001358073	PM122
0001358200	M059 12/ 2,5
0001358201	M059 12/ 2,5
0001358202	M059 12/ 2,5
0001358305	PM122
0001359001	
0001359004	
0001359008	PM120 0
0001359012	PM122 0
0001359014	PM115 0
0001359015	PM160
0001359016	PM121 0
0001359019	PM125 0
0001359021	M091 12/ 3,5
0001359024	M091 0
0001359025	PM126 0
0001359027	PM122 12/ 2,4
0001359038	PM159
0001359041	0
0001359043	PM128 0
0001359044	
0001359045	PM129 0
0001359046	PM122 0
0001359047	PM162
0001359048	
0001359049	PM122 0
0001359068	0
0001359069	PM129 0
0001359071	M091 0
0001359072	PM126 0

BOSCH RMA $\sqrt{\text{Kw}} - !$

0001359073	PM122	$\frac{12}{2,4}$
0001359074	PM115	0
0001359075	PM125	0
0001359078	PM122	0
0001359081		
0001359082	PM130	0
0001359083	PM159	
0001359084	PM128	0
0001359087		
0001359089	PM131	0
0001359090	PM121	0
0001359091	M091	0
0001359094	PM127	0
0001359095	PM120	0
0001359099		
0001359102	M091	$\frac{12}{3,5}$
0001359102	M091	$\frac{12}{3,5}$
0001359106	M295	$\frac{12}{2,8}$
0001359107	PM124	0
0001359108	PM119	0
0001359109		
0001359110	PM130	0
0001359111		
0001359111	PM132	0
0001359113	PM159	
0001359116		
0001359118	PM133	0
0001359119	PM134	0
0001359122	PM135	0
0001359124	PM162	0
0001359126	RM096	
0001359127	M027	0
0001359128	M295	$\frac{12}{2,8}$
0001359217	M295	0
0001360007	PM142	
0001360010	PM136	0
0001360012	PM137	0
0001360013	PM108	
0001360013	PM108	0
0001360014	PM137	0
0001360015	PM138	0
0001360016	PM139	0
0001360017		
0001360022	PM106	0

BOSCH RMA $\sqrt{\text{Kw}} - !$

0001360023	PM140	0
0001360026	PM141	0
0001360027	PM142	0
0001360034	PM106	
0001360035	PM137	0
0001360036	PM140	0
0001360037	PM106	0
0001360038	PM136	0
0001360039		
0001360041	PM139	0
0001360043	PM138	0
0001360049	PM143	0
0001360050	PM108	0
0001360052	PM106	0
0001360056	PM144	0
0001360057		
0001360058	PM141	0
0001360060	PM145	0
0001360061	PM110	0
0001360063	PM146	0
0001360063	PM146	0
0001360065	PM106	0
0001362001	M089	$\frac{12}{2,0}$
0001362002	M089	$\frac{12}{2,0}$
0001362003	M253	$\frac{12}{2,0}$
0001362004	M253	$\frac{12}{2,0}$
0001362005	M079	$\frac{12}{2,0}$
0001362006	M079	$\frac{12}{2,0}$
0001362008	PM147	$\frac{12}{2,0}$
0001362009	PM117	0
0001362011	M288	
0001362012	PM118	0
0001362013	PM118	0
0001362014	M064	$\frac{12}{2,0}$
0001362015	M064	$\frac{12}{2,0}$
0001362016	PM148	$\frac{12}{2,4}$
0001362017	M355	$\frac{12}{2,5}$
0001362018	M355	$\frac{12}{2,5}$
0001362021	PM114	0
0001362022	PM117	0
0001362023	PM111	0
0001362024	PM118	0
0001362025	PM149	0
0001362027	M253	$\frac{12}{2,0}$

BOSCH RMA $\sqrt{\text{Kw}} - !$

0001362028	M253	$\frac{12}{2,0}$
0001362029	M089	$\frac{12}{2,0}$
0001362030	M089	$\frac{12}{2,0}$
0001362031		
0001362032	PM150	0
0001362034	PM148	$\frac{12}{2,4}$
0001362035	PM117	0
0001362036	PM111	0
0001362037	M064	$\frac{12}{2,0}$
0001362038	M253	$\frac{12}{2,0}$
0001362039	PM150	0
0001362040	M355	$\frac{12}{2,5}$
0001362041	PM118	0
0001362043	PM149	0
0001362044	M079	$\frac{12}{2,0}$
0001362045	M079	$\frac{12}{2,0}$
0001362046	PM123	0
0001362047	M089	$\frac{12}{2,0}$
0001362049		$\frac{12}{2,0}$
0001362050	PM114	0
0001362051	PM151	0
0001362052	PM124	0
0001362058		0
0001362059	M288	$\frac{12}{2,4}$
0001362060	PM688	0
0001362061	M153	$\frac{12}{2,0}$
0001362062	M027	$\frac{12}{2,5}$
0001362062	M027	$\frac{12}{2,5}$
0001362063	PM115	0
0001362064	PM125	0
0001362067	M294	$\frac{12}{2,8}$
0001362069	M065	$\frac{12}{2,0}$
0001362070	M065	$\frac{12}{2,0}$
0001362071	M064	$\frac{12}{2,0}$
0001362073	M028	$\frac{12}{2,0}$
0001362075	M356	$\frac{12}{2,4}$
0001362076	M355	$\frac{12}{2,5}$
0001362077	M065	$\frac{12}{2,0}$
0001362078	M065	$\frac{12}{2,0}$
0001362079	M153	$\frac{12}{2,0}$
0001362081	M254	$\frac{12}{2,0}$
0001362083	M066	$\frac{12}{2,0}$
0001362084	PM688	
0001362091	PM152	0

BOSCH RMA $V_{Kw} -!$

0001362092	M288	12 2,4
0001362093	M309	12 2,4
0001362100	M187	12 2,4
0001362102	M027X	12 2,5
0001362105	PM150	0
0001362300	PM115	0
0001362301	PM125	0
0001362303	M288	0
0001362304	M288	0
0001362305	PM148	12 2,4
0001362306	PM149	0
0001362307	M059	12 2,5
0001362308	M356	12 2,4
0001362310	PM129	0
0001362312	PM121	0
0001362313	PM148	12 2,4
0001362314	PM149	0
0001362316	PM121	0
0001362319	PM751	
0001362321	PM751	
0001362341		
0001362600	M089	12 2,0
0001362601	M089	0
0001362602	M296	12 0,8
0001362603	M296	12 0,8
0001362606	M296	12 0,8
0001362607	M285	12 2,2
0001362700	PM154	0
0001363101	PM155	0
0001363101	PM155	0
0001363106		0
0001363111	PM155	0
0001363111	PM155	0
0001363123		
0001363126	RM029	
0001364100	PM156	0
0001364101		
0001364102	PM139	0
0001364104	PM139	0
0001364106	PM122	
0001364200	PM139	0
0001364203	PM139	0
0001364206	PM139	0
0001364300		

BOSCH RMA $V_{Kw} -!$

0001364301	PM156	0
0001364400	PM157	0
0001364402	PM139	0
0001365004	PM158	0
0001366001	PM118	0
0001366003		0
0001366004	M355	12 2,5
0001366005	PM113	0
0001366009	PM114	0
0001366025	PM112	0
0001366029	PM116	0
0001367001	PM115	0
0001367004	PM122	12 2,4
0001367005	PM159	0
0001367006	PM160	0
0001367007	PM137	
0001367007	PM126	0
0001367008	M288	
0001367009		
0001367013	PM119	0
0001367014	M091	0
0001367017	PM161	0
0001367026	PM133	0
0001367028	M091	12 3,5
0001367029	PM135	0
0001367030		
0001367032	PM162	0
0001367034	PM128	0
0001367037	PM121	0
0001367038	PM128	0
0001367039		
0001367039	PM132	0
0001367042	PM129	0
0001367043	M295	12 2,8
0001367045	PM131	0
0001367046	PM131	0
0001367049	PM134	0
0001367051		
0001367054		
0001367055	PM130	0
0001367056	M059	0
0001367059	PM128	0
0001367067	PM162	0
0001367069		

BOSCH RMA $V_{Kw} -!$

0001367070	PM120	0
0001367071	PM127	0
0001367072		
0001367073	PM133	0
0001367075	PM121	0
0001367076	PM121	0
0001367077	PM163	0
0001367078	PM121	0
0001367079	PM751	
0001367081		
0001367082	M091	0
0001367300	PM128	0
0001367301	PM128	0
0001367302	PM120	
0001367303	PM128	0
0001368001	PM137	0
0001368002		0
0001368007	PM137	0
0001368010	PM136	0
0001368011		0
0001368016	PM164	0
0001368017	PM110	0
0001368018	PM143	0
0001368019	PM138	0
0001368020	PM146	0
0001368020	PM146	0
0001368021	PM142	0
0001368022	PM106	
0001368024	PM106	0
0001368026	PM165	0
0001368028	PM144	0
0001368030	PM140	0
0001368034	PM141	0
0001368035	PM106	0
0001368037	PM166	0
0001368038	PM167	0
0001368039	PM166	0
0001368040	PM165	0
0001368041	PM168	0
0001368042	PM645	0
0001368051	PM165	0
0001368055	PM106	0
0001368056	PM169	0
0001368057	PM170	0

BOSCH	RMA $\sqrt{\text{Kw -!}}$	BOSCH	RMA $\sqrt{\text{Kw -!}}$	BOSCH	RMA $\sqrt{\text{Kw -!}}$
0001368060	RM030	0001371008	RM087 0	0001402056	
0001368062	PM106 0	0001371019		0001402057	
0001368063	PM110 0	0001371019		0001402058	
0001368066	PM171 0	0001372001	PM180 0	0001402059	PM184 0
0001368068	RM031	0001372002	RM091 0	0001402064	
0001368069		0001372005		0001402069	PM185 0
0001368070	PM108 0	0001372005		0001402075	PM186 0
0001368072	PM171 0	0001372006	PM892 0	0001402079	PM187 0
0001368074	PM110 0	0001372007	RM091 0	0001402081	PM184 0
0001368076	PM145 0	0001372008		0001402083	PM184 0
0001368077	PM172 0	0001401005		0001410001	
0001368081	PM164 0	0001401007	RM035	0001410002	
0001368082	PM173 0	0001401011	PM181 0	0001410005	
0001368083	PM174 0	0001401012		0001410007	
0001368085		0001401013		0001410010	PM188 0
0001368300	PM106 0	0001401017		0001410012	
0001368301	PM136 0	0001401023	PM182 0	0001410015	PM188 0
0001368302		0001401025		0001410016	PM188 0
0001368304	PM108 0	0001401028	PM183 0	0001410017	PM188 0
0001368305	PM169 0	0001401034		0001410018	
0001368306	PM108 0	0001401035		0001410021	RM036
0001368307	PM106 0	0001401036		0001410024	PM189 0
0001368309	PM106 0	0001401037		0001410029	RM037
0001368310	PM169 0	0001401037	PM190	0001410030	
0001368311		0001401044		0001410034	PM188 0
0001368312	RM032	0001401045		0001410037	PM190 0
0001368313	PM157 0	0001401049	PM181 0	0001410041	PM188 0
0001368321	RM033	0001401050	PM181 0	0001410044	PM191 0
0001369001	PM121 0	0001401052		0001410045	PM188 0
0001369005	PM121 0	0001401056		0001410046	PM192 0
0001369007	PM175 0	0001401060	PM182 0	0001410050	
0001369014	PM176 0	0001401066		0001410052	
0001369015	PM160 0	0001401068		0001410053	PM193 0
0001369016	PM177 0	0001401070	PM181 0	0001410057	
0001369017	PM126 0	0001402008		0001410058	PM120
0001369018	PM178 0	0001402011		0001410060	
0001369019	PM175 0	0001402037		0001410062	
0001369020	RM034	0001402038		0001410063	PM193 0
0001369022	PM121 0	0001402040		0001410065	PM194 0
0001369023	PM160 0	0001402041		0001410067	PM195 0
0001369024	PM176	0001402043		0001410068	PM192 0
0001371004	RM040 0	0001402053		0001410081	PM193 0
0001371006	PM179 0	0001402054	PM184 0	0001410087	PM196 0
0001371007		0001402055	PM184 0	0001410088	PM189 0

BOSCH	RMA $\sqrt{\text{Kw}} -!$	BOSCH	RMA $\sqrt{\text{Kw}} -!$	BOSCH	RMA $\sqrt{\text{Kw}} -!$
0001410091		0001414022		0001416044	PM192 0
0001410094	PM197 0	0001415001	PM204 0	0001416045	PM185 0
0001410098	PM198 0	0001415002	PM184 0	0001416046	
0001410099		0001415004		0001416046	
0001410106		0001415006	PM205 0	0001416047	PM184 0
0001410108		0001415007	PM197 0	0001416048	PM209 0
0001410109		0001415008	PM190 0	0001416052	PM207 0
0001410111	PM199 0	0001415010		0001416053	
0001410115	PM198 0	0001415011	PM206 0	0001416054	PM184 0
0001410116	PM192 0	0001415013		0001416055	
0001410416		0001415014		0001416061	PM170 0
0001411005	PM198 0	0001415015		0001416062	PM210 0
0001411008	PM192 0	0001415016	PM201 0	0001416067	PM210 0
0001411009	PM189 0	0001415017	PM207 0	0001416068	PM210 0
0001411010	PM200 0	0001415021		0001416074	PM211 0
0001411012	PM192 0	0001415027	PM204 0	0001416078	PM204 0
0001411013	0	0001416002	PM204 0	0001416079	PM204 0
0001411014		0001416003	PM206 0	0001417001	PM189 0
0001411016	PM201 0	0001416004	PM197 0	0001417002	
0001411017	PM202 0	0001416005	PM192 0	0001417005	PM194 0
0001411021	PM198 0	0001416008		0001417006	PM202 0
0001411022	0	0001416009	PM201 0	0001417007	PM198 0
0001411023	0	0001416011	PM207 0	0001417009	
0001411025	PM194 0	0001416012		0001417017	PM188 0
0001411026	PM202 0	0001416013	PM317 0	0001417023	PM200 0
0001411027	0	0001416017		0001417025	
0001411030		0001416020		0001417036	PM188 0
0001411036	RM038	0001416021		0001417037	0
0001413001	PM221 0	0001416022	PM184 0	0001417038	0
0001413002		0001416023	PM204 0	0001417041	PM192 0
0001413003		0001416024	PM184 0	0001417042	PM213 0
0001413006	PM181 0	0001416025	0	0001417043	PM190 0
0001413007		0001416026		0001417045	PM198 0
0001413010		0001416027		0001417046	
0001413017	PM203 0	0001416028	PM187 0	0001417047	
0001414001	PM185 0	0001416029		0001417047	
0001414003	PM184 0	0001416030	PM193 0	0001417049	0
0001414007		0001416032	PM196 0	0001417051	PM189 0
0001414008		0001416035		0001417053	PM215 0
0001414010	PM184 0	0001416036	PM199 0	0001417060	
0001414011	PM187 0	0001416038		0001417061	PM215
0001414017	PM317 0	0001416040	PM205 0	0001417063	PM216 0
0001414018		0001416041	PM195 0	0001417064	PM217 0
0001414019		0001416043	PM195 0	0001417065	PM218 0

BOSCH	RMA $\sqrt{\text{Kw}} -!$	BOSCH	RMA $\sqrt{\text{Kw}} -!$	BOSCH	RMA $\sqrt{\text{Kw}} -!$
0001417067	PM216 0/	0986010010	12/ 0,8	0986010241	M082 0/
0001417068	PM215 /	0986010011	0/ 0,8	0986010242	M137 /
0001417069	PM216 0/	0986010020	M081 12/ 0,6	0986010243	M137 /
0001417073	PM202 0/	0986010021	M081 0/	0986010248	M082 0/
0001417074	PM202 0/	0986010028	M081 /	0986010248	M137 0/
0001417075	PM219 0/	0986010028	M081 0/	0986010250	M180 12/ 0,8
0001417075	/	0986010030	M095 12/ 0,7	0986010251	M180 12/ 0,8
0001417076	PM216 0/	0986010031	M095 0/	0986010258	M180 0/
0001418001	PM221 0/	0986010040	M094 12/ 0,6	0986010260	M075X 12/ 0,8
0001418002	/	0986010041	M094 12/ 0,6	0986010261	M075X 12/ 0,8
0001418003	/	0986010050	M094 12/ 0,6	0986010268	M075X 0/
0001418004	/	0986010051	M094 12/ 0,6	0986010268	M075X 0/
0001418009	PM182 /	0986010060	12/ 0,8	0986010270	0/
0001418012	PM181 0/	0986010071	0/	0986010271	0/
0001418014	PM203 0/	0986010080	M158 12/ 0,8	0986010280	M118 12/ 0,8
0001418016	PM222 0/	0986010081	12/ 0,8	0986010280	M070 12/ 0,8
0001420001	PM753 0/	0986010100	7/	0986010280	M118 12/ 0,8
0001420002	PM223 0/	0986010110	12/ 0,8	0986010281	M118 /
0001420003	PM753 0/	0986010120	M096 12/ 0,8	0986010281	M118 12/ 0,8
0001420004	PM753 0/	0986010121	M096 12/ 0,8	0986010281	M070 12/ 0,8
0001420005	PM753 /	0986010128	M096 /	0986010281	M203 12/ 0,8
0001420006	PM223 0/	0986010128	M096 0/	0986010283	/
0001420008	PM223 0/	0986010128	M093 /	0986010290	M011 12/ 0,9
0001420009	PM753 0/	0986010128	M096 0/	0986010291	M011 12/ 0,9
0001420010	PM223 0/	0986010130	M174 0/	0986010300	M136 12/ 0,9 15a
0001420011	PM223 0/	0986010131	M174 12/ 1,0 15a	0986010308	M136 0/
0001420012	PM216 0/	0986010140	M158 12/ 0,8	0986010310	M017 12/ 0,8
0001420013	PM753 0/	0986010143	/	0986010311	M017 12/ 0,8
0001420015	PM216 0/	0986010150	M118 0/	0986010320	12/ 0,9
0001421001	0/	0986010151	12/ 0,8	0986010321	0/
0001501020	/	0986010160	M196 12/ 0,8	0986010330	M012 12/ 0,7
0001501029	/	0986010161	M196 12/ 0,8	0986010331	M012 12/ 0,7
0001501033	/	0986010170	M152 0/	0986010340	M013 12/ 0,7
0001501035	/	0986010180	12/ 1,0	0986010341	M013 12/ 0,7
0001510017	0/	0986010190	M021 0/	0986010350	M016 12/ 0,8 15a
0003111038	M043 0/	0986010191	M021 12/ 1,0	0986010351	M016 12/ 0,8 15a
0010300003	0/	0986010200	M010 0/	0986010358	M016 0/
0010300006	0/	0986010200	M010 12/ 0,8	0986010360	M031 12/ 0,7
0010300100	0/	0986010201	M010 0/	0986010361	M031 12/ 0,8 15a
0136355030	0/	0986010201	M010 12/ 0,8	0986010370	M106 12/ 0,8 15a
0136355060	0/	0986010220	M100 12/ 0,8	0986010371	M106 0/
0136355072	0/	0986010221	M100 12/ 0,8	0986010378	M106 0/
0136355081	/	0986010223	M100 /	0986010380	0/
0136355081	0/	0986010240	M082 12/ 0,8	0986010390	M076 12/ 0,8

BOSCH	RMA $V_{Kw} -!$	BOSCH	RMA $V_{Kw} -!$	BOSCH	RMA $V_{Kw} -!$
0986010391	M076 $12/0,8$	0986010601	M157 $12/2,2$	0986010800	$0/$
0986010398	M082 $0/$	0986010610	M038 $12/1,0$	0986010810	$0/$
0986010400	M159 $12/0,7$ 15a	0986010611	M038 $0/$	0986010811	$0/$
0986010401	M159 $0/$	0986010620	$0/$	0986010820	M051 $0/$
0986010408	M159 $0/$	0986010621	$0/$	0986010821	M051 $0/$
0986010410	M107 $12/0,8$ 15a	0986010630	M072 $12/1,5$	0986010830	M063 $0/$
0986010411	M107 $12/0,8$ 15a	0986010631	M072 $0/$	0986010831	M063 $0/$
0986010418	M107 $0/$	0986010640	M049 $12/1,1$	0986010840	M155 $12/1,5$
0986010420	M149 $12/0,8$	0986010648	M049 $0/$	0986010850	M197 $12/1,5$
0986010430	M293 $12/0,8$	0986010650	M172 $12/1,1$	0986010858	M197 $0/$
0986010431	M293 $12/0,8$	0986010651	M172 $12/1,1$	0986010860	M101 $12/1,5$
0986010440	M018 $12/0,8$ 15a	0986010658	M172 $0/$	0986010861	M101 $12/1,5$
0986010441	M018 $12/0,8$ 15a	0986010658	M172 $0/$	0986010870	M299 $12/1,5$
0986010450	M023 $12/0,8$	0986010658	M172 $0/$	0986010871	M299 $0/$
0986010450	M131 $12/0,8$	0986010660	$0/$	0986010880	M026 $12/1,6$
0986010451	M131 $12/0,8$	0986010661	$0/$	0986010881	M026 $12/1,6$
0986010451	M023 $12/0,8$	0986010670	M041 $12/1,1$	0986010890	M087 $12/1,5$
0986010460	M024 $12/0,8$	0986010671	M041 $0/$	0986010900	M165 $12/1,5$
0986010468	M024 $0/$	0986010678	M041 $0/$	0986010910	M063 $12/1,5$
0986010470	M251 $0/$	0986010680	M025 $12/1,0$	0986010918	M063 $0/$
0986010471	M251 $12/0,8$ 15a	0986010690	M093 $0/$	0986010920	M051 $12/1,7$
0986010480	M108 $12/0,8$ 15a	0986010690	M093 $12/1,0$	0986010928	M051 $0/$
0986010488	M108 $0/$	0986010691	M093 $12/1,0$	0986010930	M052 $12/1,7$
0986010490	M149 $0/$	0986010700	$6/$	0986010940	M218 $12/1,7$
0986010491	$12/0,7$	0986010710	M043 $12/1,0$	0986010941	M218 $0/$
0986010498	M149 $12/0,8$	0986010711	M043 $0/$	0986010950	M059 $12/2,5$
0986010510	M152 $12/0,8$ 15a	0986010718	M043 $0/$	0986010951	M059 $0/$
0986010520	$0/$	0986010720	M073 $12/1,1$	0986010960	PM120 $0/$
0986010530	$12/0,7$	0986010721	M073 $12/1,1$	0986010961	PM120 $0/$
0986010531	$12/0,7$	0986010723	M073 $0/$	0986010970	PM108 $0/$
0986010550	$12/0,7$	0986010730	PM025 $12/1,5$	0986010971	PM108 $0/$
0986010551	$0/$	0986010730	$12/1,5$	0986010980	PM110 $0/$
0986010560	$0/$	0986010731	$0/$	0986010990	PM148 $12/2,4$
0986010561	$0/$	0986010740	M047 $12/1,3$	0986011000	M253 $12/2,0$
0986010570	$0/$	0986010741	M047 $12/1,3$	0986011010	PM118 $0/$
0986010580	M109 $12/0,7$	0986010751	M047 $12/1,3$	0986011020	PM149 $0/$
0986010581	$0/$	0986010760	M047 $12/1,3$	0986011020	PM149 $0/$
0986010590	M121X $0/$	0986010761	M047 $12/1,3$	0986011021	PM149 $0/$
0986010590	M121X $12/2,9$	0986010770	M044 $12/1,0$	0986011030	M079 $12/2,0$
0986010590	M121X $0/$	0986010771	M044 $12/1,0$	0986011031	M079 $12/2,0$
0986010591	M121X $12/2,9$ 15a	0986010780	M109 $12/1,1$ 15a	0986011033	M079 $0/$
0986010591	M121X $12/2,9$ 15a	0986010781	M109 $12/1,1$ 15a	0986011040	PM123 $0/$
0986010591	M121X $12/2,9$	0986010788	M109 $0/$	0986011060	M027 $12/2,5$
0986010600	M157 $12/2,2$	0986010790	$12/1,1$	0986011061	M027 $12/2,5$

BOSCH RMA $\sqrt{\text{Kw}} - !$

0986011070	M064 $\frac{12}{2,0}$
0986011071	M064 $\frac{12}{2,0}$
0986011080	M028 $\frac{0}{}$
0986011081	M028 $\frac{12}{2,0}$
0986011090	M065 $\frac{12}{2,0}$
0986011100	M153 $\frac{12}{2,0}$
0986011110	M254 $\frac{12}{2,0}$
0986011111	M254 $\frac{12}{2,0}$
0986011130	PM115 $\frac{0}{}$
0986011140	$\frac{12}{2,4}$
0986011150	M089 $\frac{12}{2,0}$
0986011160	PM155 $\frac{0}{}$
0986011161	PM155 $\frac{0}{}$
0986011170	PM139 $\frac{0}{}$
0986011180	PM158 $\frac{0}{}$
0986011190	PM112 $\frac{0}{}$
0986011200	PM122 $\frac{12}{2,4}$
0986011210	PM126 $\frac{0}{}$
0986011220	M091 $\frac{12}{3,5}$
0986011221	M091 $\frac{0}{}$
0986011240	PM128 $\frac{0}{}$
0986011250	PM132 $\frac{0}{}$
0986011251	$\frac{0}{}$
0986011260	M295 $\frac{12}{2,8}$
0986011261	M295 $\frac{0}{}$
0986011270	PM137 $\frac{0}{}$
0986011280	PM136 $\frac{0}{}$
0986011290	PM164 $\frac{0}{}$
0986011310	PM138 $\frac{0}{}$
0986011311	PM138 $\frac{0}{}$
0986011330	PM146 $\frac{0}{}$
0986011331	PM146 $\frac{0}{}$
0986011340	PM142 $\frac{0}{}$
0986011341	PM142 $\frac{0}{}$
0986011360	PM106 $\frac{0}{}$
0986011370	PM140 $\frac{0}{}$
0986011380	PM141 $\frac{0}{}$
0986011430	PM190 $\frac{0}{}$
0986011440	PM188 $\frac{0}{}$
0986011460	PM193 $\frac{0}{}$
0986011480	PM196 $\frac{0}{}$
0986011490	PM189 $\frac{0}{}$
0986011510	PM189 $\frac{0}{}$
0986011520	PM192 $\frac{0}{}$

BOSCH RMA $\sqrt{\text{Kw}} - !$

0986011530	PM221 $\frac{0}{}$
0986011540	PM181 $\frac{0}{}$
0986011550	PM184 $\frac{0}{}$
0986011570	PM204 $\frac{0}{}$
0986011580	PM206 $\frac{0}{}$
0986011590	$\frac{0}{}$
0986011600	M067 $\frac{12}{0,6}$
0986011601	M067 $\frac{12}{0,6}$
0986011601	M067 $\frac{0}{}$
0986011610	$\frac{12}{0,8}$
0986011611	$\frac{12}{0,8}$
0986011640	$\frac{12}{1,5}$
0986011641	$\frac{0}{}$
0986011650	M077 $\frac{0}{}$
0986011651	M077 $\frac{12}{0,6}$
0986011658	M119 $\frac{0}{}$
0986011670	PM908 $\frac{12}{0,6}$
0986011671	PM908 $\frac{12}{0,6}$
0986011690	M179 $\frac{0}{}$
0986011691	M179 $\frac{12}{0,7}$
0986011700	$\frac{12}{1,0}$
0986011701	$\frac{12}{0,7}$
0986011710	$\frac{12}{0,7}$
0986011711	$\frac{0}{}$
0986011721	$\frac{12}{0,8}$
0986011730	M078 $\frac{0}{}$
0986011731	M078 $\frac{12}{0,7}$
0986011740	M119 $\frac{12}{0,8}$
0986011741	M119X $\frac{12}{1,0}$
0986011741	M119 $\frac{12}{0,8}$
0986011748	M119 $\frac{0}{}$
0986011760	$\frac{12}{1,1}$
0986011761	$\frac{0}{}$
0986011770	M124X $\frac{12}{0,9}$
0986011771	M124X $\frac{12}{0,9}$
0986011780	M280 $\frac{12}{1,1}$
0986011781	M280 $\frac{12}{1,1}$
0986011790	M156 $\frac{12}{2,0}$
0986011791	M156 $\frac{12}{2,0}$
0986011793	M156 $\frac{0}{}$
0986011800	M161 $\frac{12}{2,2}$
0986011801	M161 $\frac{12}{2,2}$
0986011803	M161 $\frac{0}{}$
0986011810	M084X $\frac{12}{0,9}$

BOSCH RMA $\sqrt{\text{Kw}} - !$

0986011810	M084 $\frac{12}{0,9}$
0986011811	M084X $\frac{12}{0,9}$
0986011811	M084 $\frac{12}{0,9}$
0986011820	M117 $\frac{0}{}$
0986011821	M117 $\frac{12}{1,1}$
0986011830	M192 $\frac{12}{0,9}$
0986011831	M192 $\frac{12}{0,9}$
0986011838	M192 $\frac{0}{}$
0986011841	$\frac{12}{0,6}$
0986011870	M032 $\frac{0}{}$
0986011871	M032 $\frac{12}{0,8}$
0986011890	M033X $\frac{12}{0,8}$
0986011891	M033 $\frac{12}{0,8}$
0986011898	M033 $\frac{0}{}$
0986011910	M114 $\frac{12}{0,8}$
0986011911	M114 $\frac{12}{0,8}$
0986011911	M114 $\frac{0}{}$
0986011921	M035 $\frac{12}{0,8}$
0986011931	M097 $\frac{12}{0,8}$
0986011941	M039 $\frac{12}{0,5}$
0986012000	PM780 $\frac{0}{}$
0986012001	$\frac{0}{}$
0986012010	PM780 $\frac{0}{}$
0986012011	$\frac{0}{}$
0986012021	$\frac{0}{}$
0986012031	$\frac{0}{}$
0986012061	PM603 $\frac{0}{}$
0986012080	M424 $\frac{0}{}$
0986012081	M424 $\frac{0}{}$
0986012090	PM405 $\frac{0}{}$
0986012091	$\frac{0}{}$
0986012101	PM405 $\frac{0}{}$
0986012110	PM369 $\frac{0}{}$
0986012111	PM369 $\frac{0}{}$
0986012120	PM370 $\frac{0}{}$
0986012121	PM370 $\frac{0}{}$
0986012130	$\frac{0}{}$
0986012131	$\frac{0}{}$
0986012140	$\frac{0}{}$
0986012141	$\frac{0}{}$
0986012150	M130 $\frac{0}{}$
0986012151	M128 $\frac{12}{1,0}$
0986012160	M128 $\frac{0}{}$
0986012161	M128 $\frac{0}{}$

BOSCH	RMA $V_{Kw} -!$
0986012170	0
0986012171	PM407 0
0986012171	PM403 0
0986012210	PM600 0
0986012211	PM600 0
0986012221	PM600 0
0986012230	M424 0
0986012231	M424 0
0986012240	M424 0
0986012241	M424 0
0986012250	PM602 0
0986012251	PM602 0
0986012261	PM744 0
0986012270	M433 0
0986012271	M433 0
0986012280	PM408 0
0986012281	PM408 0
0986012290	PM341 12/0,8
0986012290	M320 12/0,8
0986012290	M320
0986012291	M320 12/0,8
0986012291	M320
0986012300	M425 12/0,8
0986012301	M425X
0986012301	M425 0
0986012310	PM425 0
0986012311	PM425 0
0986012320	M116 12/1,4 15a
0986012321	M116 12/0,9
0986012328	M116 0
0986012330	M022 12/0,9
0986012331	M022 0
0986012340	M102 12/0,8
0986012341	M102 12/0,8
0986012350	M030 12/0,7
0986012351	M030 12/0,7
0986012358	M030 0
0986012360	M068 12/0,9
0986012380	M088 0
0986012381	M088 0
0986012400	M103 0
0986012401	M103 0
0986012410	M140 12/1,5
0986012418	M140 0

BOSCH	RMA $V_{Kw} -!$
0986012420	PM121 0
0986012430	PM127 0
0986012431	PM127 0
0986012440	M296 12/0,8
0986012470	PM130 0
0986012480	PM198 0
0986012570	0
0986012590	M150 12/0,9 15a
0986012590	M150 12/0,9 15a
0986012591	M150 0
0986012598	M150 0
0986012598	M150 0
0986012600	M111 12/0,8 15a
0986012601	M111 0
0986012610	M040 12/2,2
0986012620	M037 12/2,2 30h
0986012621	M037 0
0986012630	12/1,7
0986012631	0
0986012640	0
0986012650	M250 12/1,7
0986012658	M250 0
0986012660	0
0986012661	0
0986012670	PM150 0
0986012671	PM150 0
0986012680	PM125 0
0986012690	M089 0
0986012700	PM156 0
0986012710	PM119 0
0986012730	PM199 0
0986012740	PM191 0
0986012750	PM133 0
0986012780	PM134 0
0986012821	PM423 0
0986012831	PM404 0
0986012840	0
0986012841	M127 12/0,8
0986012851	PM293 0
0986012851	M130 12/1,0
0986012861	PM408 0
0986012870	M425 0
0986012871	M425X 0
0986012880	M330 0

BOSCH	RMA $V_{Kw} -!$
0986012881	M330 12/0,8
0986012900	PM351 0
0986012901	PM351 0
0986012911	PM372 0
0986012920	PM526 0
0986012921	PM526 0
0986012931	PM643 0
0986012931	PM643
0986012931	PM643
0986012940	PM144 0
0986012950	PM106 0
0986012970	PM205 0
0986012980	M164 12/1,5
0986012990	M197 0
0986012991	0
0986013000	M140 12/1,5 15a
0986013010	M083 12/1,4
0986013013	M083
0986013020	12/1,4
0986013050	M014 12/1,7
0986013070	M243 0
0986013080	M015 12/1,7
0986013080	M015 12/1,7
0986013081	M015 0
0986013088	M015 0
0986013088	M015 0
0986013090	M214 12/1,7
0986013090	M214 12/1,7
0986013091	M214 0
0986013098	M214 0
0986013100	M162 12/2,2
0986013101	M162 0
0986013110	M285 12/2,2
0986013118	M285 0
0986013120	M102 12/0,8
0986013121	M102 12/0,8
0986013130	12/2,2
0986013140	M066X 12/2,2
0986013140	M066X 12/2,0
0986013141	M066X 0
0986013150	M216 12/1,7
0986013160	M237 12/1,4
0986013161	M237 0
0986013170	PM145 0

BOSCH	RMA $V_{Kw} -!$	BOSCH	RMA $V_{Kw} -!$	BOSCH	RMA $V_{Kw} -!$
0986013171	PM145 0	0986013440	PM202 0	0986013730	PM204 0
0986013180	PM167 0	0986013450	PM213 0	0986013730	PM204 0
0986013190	M059 12/2,8	0986013470	M148 12/0,9 15a	0986013740	M055 12/1,0
0986013200	M120X 12/1,9	0986013470	M068 12/0,9	0986013741	M055 12/1,0
0986013200	M120 12/1,9	0986013478	M148 0	0986013741	M055
0986013201	M120X 12/1,9	0986013480	PM128 0	0986013770	PM165 0
0986013210	M104 12/0,9	0986013490	PM106 0	0986013780	M125 0
0986013211	M104 12/0,9	0986013500	M433 0	0986013781	M125 12/2,2
0986013213	M104	0986013501	M433 0	0986013790	0
0986013220	M260 12/1,4	0986013510	M433 0	0986013791	12/2,8
0986013228	M260 0	0986013511	M433 0	0986013800	M010 12/2,8
0986013230	M029 12/1,0	0986013521	PM434 0	0986013801	M010 0
0986013231	M029 12/1,0	0986013531	PM785 0	0986013803	M010
0986013240	M105 12/1,7	0986013541	PM424 0	0986013810	PM894 12/2,5
0986013240	M103 12/1,7	0986013541	PM424 0	0986013811	PM894 12/2,5
0986013241	M105 12/1,7	0986013550	PM377 0	0986013820	M297 12/3,1
0986013241	M105 12/1,7	0986013551	PM377 0	0986013821	M297 12/2,5
0986013260	PM201 0	0986013561	0	0986013830	M276 0
0986013270	M137 12/0,8	0986013571	PM431 0	0986013831	M276 12/3,1
0986013271	M134 12/0,8	0986013581	PM294 0	0986013840	0
0986013280	M138 12/0,9	0986013581	M432 0	0986013841	12/1,2
0986013280	M217 0	0986013590	M034 12/0,8	0986013850	M222
0986013290	M134 12/0,8	0986013591	M034 0	0986013850	M222 12/1,1
0986013290	M134 0	0986013600	M240 12/1,4	0986013850	M074 12/0,9
0986013298	M134 0	0986013601	M240 0	0986013851	M222 0
0986013310	0	0986013610	M099 12/1,4	0986013851	M176 12/1,1
0986013311	12/2,2	0986013610	M226 12/1,0	0986013851	M074 12/0,9
0986013340	PM020 0	0986013611	M313 12/1,4	0986013853	M222
0986013341	PM020 0	0986013611	M226 12/1,0	0986013860	M124X 12/1,0
0986013350	M257 12/1,7	0986013618	M099 0	0986013861	M124X 12/1,0
0986013351	M257 0	0986013620	M046 12/0,9	0986013863	M124X
0986013360	M263 12/1,4	0986013621	M046 12/0,9	0986013871	PM247 0
0986013360	M263 0	0986013630	M048 12/2,2	0986013880	0
0986013361	M263 12/1,4	0986013640	M053 12/2,2	0986013881	0
0986013368	M263 0	0986013641	M053 12/2,2	0986013910	M247 12/2,2
0986013380	0	0986013650	M246 12/2,2	0986013940	M056 12/0,9
0986013381	0	0986013651	M246 12/2,2	0986013941	M056 12/0,9
0986013390	PM098 0	0986013660	M054 12/2,2	0986013960	0
0986013400	M045 12/2,2	0986013670	PM555 0	0986013971	M129 12/0,8
0986013410	M258 12/2,2	0986013680	PM152 0	0986013981	PM446 0
0986013410	M258 0	0986013690	PM162 0	0986013991	PM429 0
0986013418	M258 0	0986013700	PM166 0	0986014001	M329 12/0,8
0986013420	PM207 0	0986013710	PM168 0	0986014041	PM294 0
0986013430	PM194 0	0986013720	PM169 0	0986014051	M194 12/1,0

BOSCH	RMA $V_{Kw} -!$	BOSCH	RMA $V_{Kw} -!$	BOSCH	RMA $V_{Kw} -!$
0986014051	PM286 $12/1,0$	0986014541	M325X	0986014860	M143 $12/0,9$
0986014061	PM295 $0/$	0986014550	PM185 $0/$	0986014860	M143 $0/$
0986014071	M333 $12/2,0$	0986014560	PM210 $0/$	0986014861	M143 $12/0,9$
0986014081	PM459 $0/$	0986014570	M057 $12/1,4$	0986014870	PM195 $0/$
0986014091	PM623 $0/$	0986014580	M238 $12/1,4$	0986014880	$0/$
0986014101	PM400 $0/$	0986014581	M238 $0/$	0986014890	M299X $12/1,7$ 30h
0986014111	PM745 $0/$	0986014590	M195 $0/$	0986014900	M185 $0/$
0986014141	M193 $12/2,2$	0986014591	M195 $0/$	0986014900	M185 $0/$
0986014141	M193 $12/2,0$	0986014600	M260 $12/1,4$	0986014900	M185 $0/$
0986014151	PM409 $0/$	0986014601	M260 $0/$	0986014901	M185 $0/$
0986014161	PM380 $0/$	0986014610	M243 $12/1,4$	0986014910	PM192 $0/$
0986014171	M324 $12/1,2$	0986014620	M069X $12/1,4$	0986014920	PM192 $0/$
0986014181	PM275 $0/$	0986014628	M069X $0/$	0986014930	M061 $12/1,1$
0986014191	PM379 $0/$	0986014630	M112 $12/0,9$ 15a	0986014940	PM051 $0/$
0986014201	PM327 $0/$	0986014640	M115 $12/1,0$ 15a	0986014950	RM039 $0/$
0986014211	M441 $0/$	0986014660	M088 $12/2,2$	0986014951	RM039 $0/$
0986014221	PM383 $0/$	0986014660	M088X $0/$	0986014960	M062X $12/1,4$
0986014231	M374 $0/$	0986014661	M088X $0/$	0986014971	PM400 $0/$
0986014231	M374 $12/1,2$	0986014661	M088 $0/$	0986014981	M433 $0/$
0986014261	PM523 $0/$	0986014680	PM088 $0/$	0986014991	M431 $0/$
0986014271	PM388 $0/$	0986014681	PM088 $0/$	0986014991	M431 $0/$
0986014281	PM272 $0/$	0986014690	M278 $0/$	0986015001	PM456 $0/$
0986014311	$0/$	0986014691	M278 $12/3,1$	0986015010	M202 $0/$
0986014321	$0/$	0986014700	M058 $12/1,7$	0986015011	M202 $12/0,9$
0986014331	M211 $12/0,8$	0986014701	M058 $12/0,8$	0986015011	M017 $0/$
0986014341	PM364 $0/$	0986014710	M033X $12/0,8$	0986015021	M332 $12/2,0$
0986014350	M327 $12/0,7$	0986014711	M033X $12/0,8$	0986015031	PM796 $0/$
0986014351	M327 $12/0,7$	0986014718	M033X $0/$	0986015040	PM129 $0/$
0986014351	M327 $0/$	0986014721	M308 $0/$	0986015050	M375 $12/1,4$ 30h
0986014360	M334 $0/$	0986014730	PM121 $0/$	0986015060	$0/$
0986014361	M334 $12/0,6$	0986014740	PM121 $0/$	0986015063	$0/$
0986014371	M446 $0/$	0986014750	$12/1,1$	0986015090	M307 $12/2,2$
0986014381	M328 $12/0,6$	0986014761	PM512 $0/$	0986015110	PM462 $0/$
0986014391	PM435 $0/$	0986014770	M113 $12/1,1$	0986015150	M261 $12/1,4$
0986014411	M326 $12/0,9$	0986014770	M113X $12/1,4$	0986015158	M261 $0/$
0986014451	PM416 $0/$	0986014771	M113X $12/1,4$	0986015160	$0/$
0986014471	PM419 $0/$	0986014771	M113 $12/1,1$	0986015170	$0/$
0986014481	PM601 $0/$	0986014800	M166 $12/0,8$	0986015178	$0/$
0986014491	PM443 $0/$	0986014801	M166 $0/$	0986015190	PM558 $0/$
0986014501	PM437 $0/$	0986014810	M191 $12/1,0$	0986015200	M190 $12/1,0$
0986014511	PM444 $0/$	0986014820	M191 $12/1,0$	0986015230	PM021 $0/$
0986014531	PM796 $0/$	0986014830	M251 $12/0,9$	0986015260	M244 $12/1,8$
0986014541	M325X $12/0,8$	0986014840	M175 $12/1,4$ 30h	0986015270	PM089 $0/$
0986014541	M325X $12/0,8$	0986014850	PM131 $0/$	0986015320	PM048 $0/$

BOSCH RMA $\frac{V}{Kw -!}$

0986015328	PM048	0
0986015331	M335	12/2,0
0986015341	PM272	0
0986015351	PM455	0
0986015391	PM381	0
0986015391	PM381	0
0986015400		
0986015401	M275	12/3,1
0986015410	M297	12/2,5
0986015411	M297X	0
0986015411	M297X	0
0986015420	PM154	0
0986015430	PM170	0
0986015470	PM050	0
0986015481	M442	0
0986015490	M190	12/1,0
0986015521		0
0986015540	M089	0
0986015551	M213	12/0,6
0986015560	M013X	12/1,1
0986015600	M200	12/1,4
0986015610	M151	12/2,2
0986015620	M299	0
0986015630	M062	12/1,4
0986015650		
0986015651		
0986015661		0
0986015670	PM215	0
0986015670	PM215	0
0986015680	PM223	0
0986015701	PM684	0
0986015721	PM296	0
0986015740	M304	12/1,4
0986015751		0
0986015751	PM385	0
0986015761	PM466	12/2,2
0986015771		12/2,2
0986015781	M337	12/0,8
0986015791	PM516	0
0986015910	M048X	12/2,2
0986015920	M252	0
0986015930	M228	12/2,2
0986015970	PM091	
0986015970	M310	12/1,8

BOSCH RMA $\frac{V}{Kw -!}$

0986015971	M310	12/1,8
0986015981	PM609	0
0986015991	PM347	0
0986016001	M426	0
0986016011	PM274	0
0986016021	PM265	0
0986016031	M336X	0
0986016031	M336X	0
0986016031	M336X	12/2,0
0986016100	PM216	0
0986016100	PM216	0
0986016110	M306	12/1,1
0986016120	M440	0
0986016130	PM024	0
0986016130	PM024	0
0986016133	PM024	
0986016140	M105	
0986016141	M105X	0
0986016141	M105X	12/2,0
0986016141	M105X	0
0986016143	M105	
0986016151	M423	0
0986016160	M340	12/1,4
0986016161	M340	0
0986016171	M423X	0
0986016190	M256	12/1,8
0986016200	M288	12/2,4
0986016210	M277	0
0986016210	M277X	12/3,1
0986016211	M277	12/3,1
0986016220	PM171	0
0986016230	M386	0
0986016240	M069	12/1,4
0986016250	PM052	0
0986016261	PM459	0
0986016271	PM273	0
0986016280	M099X	0
0986016290	M248	12/1,1
0986016300	M236	12/1,1
0986016310	M383	0
0986016320	M034	0
0986016330	M227	12/1,1
0986016340	M394	0
0986016350	M261	12/1,4

BOSCH RMA $\frac{V}{Kw -!}$

0986016353	M261	
0986016370		0
0986016371		0
0986016380	M083X	0
0986016380	M083X	
0986016390	M088X	
0986016390	M088	0
0986016390	M088	12/2,2
0986016400	M017X	12/1,2
0986016401	M017X	12/1,2
0986016401	M017X	
0986016420	PM469	12/1,2
0986016421	PM469	0
0986016431	M437	0
0986016441	PM430	0
0986016451	PM350	0
0986016470	M235X	12/1,4
0986016480	PM027	
0986016480	PM027	
0986016500	PM015	0
0986016500	PM015	0
0986016501	PM015	0
0986016511	PM462	0
0986016520	PM189	0
0986016530	M102X	12/1,1
0986016531	M102X	12/1,1
0986016533	M102X	
0986016550	PM176	0
0986016560	M381	0
0986016570	M415	12/0,9
0986016580	M338	12/1,0
0986016581	M338	0
0986016590	M201	12/1,4
0986016591	M201	0
0986016600	M017E	0
0986016610	M121	12/2,2
0986016611	M121	0
0986016611	M121	12/2,2
0986016651	M427X	0
0986016651	M427	
0986016660	M262	12/1,4
0986016661	M262	0
0986016681	PM268	
0986016700	M282	12/1,7

BOSCH RMA $V_{Kw} -!$

0986016710	M417	
0986016711	M417	0
0986016721	M017X	
0986016730	PM013	0
0986016740	M380	12 2,5
0986016750	M392	0
0986016780	PM026	0
0986016790	M255	0
0986016800	M255	12 1,1
0986016800	M255	12 1,1
0986016840	PM053	0
0986016860	PM031	0
0986016870	M058X	12 1,7
0986016880	M314	12 1,0
0986016890	M099	12 1,4
0986016900	M058	12 1,7
0986016900	M058	12 1,7
0986016910	M200	12 1,4
0986016920	PM055	0
0986016930	PM028	0
0986016933	PM028	
0986016950	PM094	0
0986016953	PM094	
0986016961	M271	12 1,0
0986016980	M289X	0
0986016980	M289X	12 1,8
0986016990	M396	0
0986017000	M313	
0986017010	PM092	0
0986017020	M284	12 2,2
0986017030	M268	12 0,8
0986017031	M268	12 0,8
0986017040	M270	12 0,8
0986017041	M270	12 0,8
0986017050	PM218	0
0986017060	M317	12 1,4
0986017070	M389	0
0986017080	PM597	0
0986017090	PM139	0
0986017100	PM209	0
0986017110	M185X	0
0986017111	M185X	0
0986017120	M143	12 0,9
0986017120	M143	0

BOSCH RMA $V_{Kw} -!$

0986017130	M419	
0986017131	M419	0
0986017150	PM090	0
0986017160	PM087	0
0986017170	PM054	
0986017180	PM058	0
0986017190	PM062	0
0986017220	M048X	
0986017220	M048X	12 2,2
0986017220	M048X	
0986017230	M048X	12 2,2
0986017240	PM105	0
0986017250	PM190	0
0986017260	M399	0
0986017270	PM172	0
0986017280	PM177	0
0986017290	PM178	0
0986017300	M037	12 2,2 30h
0986017310	M355	12 2,5
0986017320	PM180	0
0986017330	PM032	0
0986017361	PM251	0
0986017380	M120X	12 1,9
0986017381	M120X	0
0986017390	M120X	12 1,9
0986017391	M120X	0
0986017420	M385	0
0986017430	PM096	0
0986017440	PM044	0
0986017450	M315	12 1,8
0986017460	M289	0
0986017470	PM093	0
0986017480	PM097	0
0986017490	M352	12 2,2
0986017500	PM095	0
0986017500	M397	0
0986017500	M397	0
0986017510	PM160	0
0986017520	PM174	0
0986017530	M387	0
0986017533	M403	
0986017541	PM341	0
0986017551	M443	0
0986017561	M325	0

BOSCH RMA $V_{Kw} -!$

0986017571	PM350	0
0986017591	M428X	0
0986017601	M336	0
0986017611	PM394	
0986017640	M440	0
0986017641	M440	0
0986017651	PM257	0
0986017661	M443	0
0986017681	PM366	0
0986017691	M425X	
0986017721	PM376	0
0986017750	PM161	0
0986017760	PM179	0
0986017770	M382	0
0986017781	M405	0
0986017790	M384	0
0986017790	M384	0
0986017800	M316	12 2,2
0986017801	M316	0
0986017810	RM040	0
0986017830	PM070	0
0986017840	M319	12 0,7
0986017850	PM217	0
0986017860	PM164	0
0986017870	PM169	0
0986017880	PM173	0
0986017890	PM063	0
0986017910	PM065	0
0986017920	M314	0
0986017930	M391	0
0986017940	PM566	0
0986017950	M151	0
0986017960	M395	0
0986017970	M288	0
0986017980	PM157	0
0986017990	PM106	0
0986017990	PM106	
0986018000	PM211	0
0986018010	M143	0
0986018020	PM042	0
0986018030	PM045	0
0986018040	PM071	0
0986018050	PM036	0
0986018060	PM057	0

BOSCH	RMA $\sqrt{\text{Kw}} -!$	BOSCH	RMA $\sqrt{\text{Kw}} -!$	BOSCH	RMA $\sqrt{\text{Kw}} -!$
0986018070	M346 $\frac{12}{1,8}$	0986018520	M195 $\frac{0}{0}$	0986018870	PM016 $\frac{0}{0}$
0986018080	RM041 $\frac{0}{0}$	0986018521	M195 $\frac{0}{0}$	0986018880	M393 $\frac{0}{0}$
0986018090	PM219 $\frac{0}{0}$	0986018530	PM233 $\frac{0}{0}$	0986018890	PM039 $\frac{0}{0}$
0986018100	PM216 $\frac{0}{0}$	0986018531	$\frac{0}{0}$	0986018900	M384 $\frac{0}{0}$
0986018110	M379 $\frac{0}{0}$	0986018540	PM288 $\frac{0}{0}$	0986018910	PM046 $\frac{0}{0}$
0986018151	PM689 $\frac{0}{0}$	0986018541	PM288 $\frac{0}{0}$	0986018920	PM074 $\frac{0}{0}$
0986018161	PM224 $\frac{0}{0}$	0986018550	PM289 $\frac{0}{0}$	0986018930	PM077 $\frac{0}{0}$
0986018170	PM064 $\frac{0}{0}$	0986018551	PM289 $\frac{0}{0}$	0986018940	PM084 $\frac{0}{0}$
0986018180	PM066 $\frac{0}{0}$	0986018560	PM252 $\frac{0}{0}$	0986018950	PM099 $\frac{0}{0}$
0986018190	M116 $\frac{0}{0}$	0986018561	PM252 $\frac{0}{0}$	0986018960	PM102 $\frac{0}{0}$
0986018200	M150 $\frac{0}{0}$	0986018570	M414 $\frac{0}{0}$	0986018970	PM094 $\frac{0}{0}$
0986018210	M015 $\frac{0}{0}$	0986018570	$\frac{0}{0}$	0986018980	PM104 $\frac{0}{0}$
0986018220	M214 $\frac{0}{0}$	0986018571	M414 $\frac{0}{0}$	0986018990	PM107 $\frac{0}{0}$
0986018230	M134 $\frac{0}{0}$	0986018580	M416 $\frac{0}{0}$	0986018990	PM107 $\frac{0}{0}$
0986018240	M263 $\frac{0}{0}$	0986018581	M416 $\frac{0}{0}$	0986019000	PM204 $\frac{0}{0}$
0986018250	M258 $\frac{0}{0}$	0986018590	M017X $\frac{0}{0}$	0986019010	PM109 $\frac{0}{0}$
0986018260	M099 $\frac{0}{0}$	0986018591	M017X $\frac{0}{0}$	0986019020	PM103 $\frac{0}{0}$
0986018270	PM100 $\frac{0}{0}$	0986018601	M427 $\frac{0}{0}$	0986019030	M406 $\frac{0}{0}$
0986018290	PM096 $\frac{0}{0}$	0986018611	PM093 $\frac{0}{0}$	0986019040	M388 $\frac{0}{0}$
0986018310	M390 $\frac{0}{0}$	0986018621	PM301 $\frac{0}{0}$	0986019051	PM694 $\frac{0}{0}$
0986018321	M344 $\frac{0}{0}$	0986018630	PM069 $\frac{0}{0}$	0986019061	PM286 $\frac{0}{0}$
0986018331	M421 $\frac{0}{0}$	0986018641	RM090 $\frac{0}{0}$	0986019071	PM693 $\frac{0}{0}$
0986018340	PM037 $\frac{0}{0}$	0986018651	$\frac{0}{0}$	0986019081	M429 $\frac{0}{0}$
0986018350	RM086 $\frac{0}{0}$	0986018661	RM088 $\frac{0}{0}$	0986019091	PM411 $\frac{0}{0}$
0986018360	PM010 $\frac{0}{0}$	0986018671	M215 $\frac{0}{0}$	0986019101	PM256 $\frac{0}{0}$
0986018370	PM892 $\frac{0}{0}$	0986018680	M397 $\frac{0}{0}$	0986019111	PM497 $\frac{0}{0}$
0986018380	PM082 $\frac{0}{0}$	0986018690	PM017 $\frac{0}{0}$	0986019121	PM496 $\frac{0}{0}$
0986018390	PM080 $\frac{0}{0}$	0986018701	PM498 $\frac{0}{0}$	0986019131	PM498 $\frac{0}{0}$
0986018400	M416 $\frac{0}{0}$	0986018711	PM342 $\frac{0}{0}$	0986019141	PM488 $\frac{0}{0}$
0986018410	PM076 $\frac{0}{0}$	0986018721	M431 $\frac{0}{0}$	0986019151	PM489 $\frac{0}{0}$
0986018420	PM207 $\frac{0}{0}$	0986018731	PM397 $\frac{0}{0}$	0986019161	PM488 $\frac{0}{0}$
0986018430	PM073 $\frac{0}{0}$	0986018741	PM496 $\frac{0}{0}$	0986019171	PM479 $\frac{0}{0}$
0986018440	PM035 $\frac{0}{0}$	0986018751	PM419 $\frac{0}{0}$	0986019181	PM476 $\frac{0}{0}$
0986018450	PM241 $\frac{0}{0}$	0986018761	M428 $\frac{0}{0}$	0986019200	PM049 $\frac{0}{0}$
0986018450	PM241 $\frac{0}{0}$	0986018770	PM010 $\frac{0}{0}$	0986019220	PM023 $\frac{0}{0}$
0986018460	PM038 $\frac{0}{0}$	0986018780	RM091 $\frac{0}{0}$	0986019271	M120X $\frac{0}{0}$
0986018470	PM072 $\frac{0}{0}$	0986018790	PM198 $\frac{0}{0}$	0986019291	M265 $\frac{0}{0}$
0986018480	PM018 $\frac{0}{0}$	0986018800	RM087 $\frac{0}{0}$	0986019301	M408 $\frac{0}{0}$
0986018490	PM099 $\frac{0}{0}$	0986018800	RM087 $\frac{0}{0}$	0986019311	M255 $\frac{0}{0}$
0986018500	PM081 $\frac{0}{0}$	0986018810	PM202 $\frac{0}{0}$	0986019320	M027X $\frac{0}{0}$
0986018501	$\frac{0}{0}$	0986018830	PM538 $\frac{0}{0}$	0986019361	PM641 $\frac{0}{0}$
0986018501	$\frac{0}{0}$	0986018840	PM011 $\frac{0}{0}$	0986019370	M398 $\frac{0}{0}$
0986018510	PM254 $\frac{0}{0}$	0986018850	M083X $\frac{0}{0}$	0986019500	PM577 $\frac{0}{0}$
0986018511	PM254 $\frac{0}{0}$	0986018860	PM012 $\frac{0}{0}$	0986019550	PM577 $\frac{0}{0}$

BOSCH	RMA $\sqrt{\text{Kw}} -!$	BOSCH	RMA $\sqrt{\text{Kw}} -!$	BOSCH	RMA $\sqrt{\text{Kw}} -!$
0986019620		0986020381	M429X	0986021020	
0986019830	PM170	0986020391	PM411	0986021030	PM010
0986019860	PM043	0986020401	PM344	0986021060	PM551
0986019870	M143X	0986020411	PM727	0986021070	PM544
0986019880	M412	0986020421	PM412	0986021190	PM595
0986019890	PM562	0986020431	PM695	0986021200	
0986019900	M037	0986020441	PM290	0986021210	PM550
0986019910	PM034	0986020461	RM042	0986021220	PM578
0986019920	PM543	0986020471	PM696	0986021240	M143X
0986019930	M382	0986020491	PM297	0986021260	RM043
0986019940		0986020501	PM345	0986021270	RM044
0986019960	PM067	0986020511	PM375	0986021280	RM045
0986019970	PM068	0986020521	PM401	0986021290	RM046
0986019980	M037X	0986020561	PM827	0986021300	RM050
0986019991	M223	0986020581	PM501	0986021310	RM051
0986020001	M318	0986020591	PM503	0986021320	RM052
0986020011	PM598	0986020601	PM502	0986021330	RM053
0986020021	PM686	0986020621	PM495	0986021340	RM054
0986020031	PM454	0986020631	PM871	0986021360	RM055
0986020041	PM299	0986020681	PM337	0986021480	RM056
0986020051	PM599	0986020691	PM518	0986021490	RM057
0986020061	PM464	0986020701	PM361	0986021500	RM058
0986020070	PM164	0986020711	M343	0986021510	RM059
0986020121	PM926	0986020721	PM757	0986021520	RM060
0986020131	PM239	0986020731	M433	0986021530	RM061
0986020141	PM240	0986020741	PM374	0986021550	RM062
0986020151	M308	0986020751	M447	0986021580	PM606
0986020170	PM594	0986020761	PM472	0986028060	PM608
0986020181	M420	0986020771	PM470	0986X00019	
0986020220	PM564	0986020780	PM561	0986X00020	
0986020230	PM568	0986020791	PM501	1 987 X00 001	M390
0986020240	PM569	0986020791	PM500	6004AA0003	PM546
0986020250	PM572	0986020801	PM521	6004AA0008	PM546
0986020260	PM573	0986020811	PM349	6004AA0018	PM596
0986020270	PM579	0986020821	PM517	6004AA0021	
0986020280	PM574	0986020831	PM491	6004AA0022	
0986020290	PM563	0986020841	PM482	6004AA0027	PM546
0986020300	PM575	0986020850	PM541	6033AB1J00	
0986020320	PM576	0986020870	M143X	9000042021	$12 \frac{0}{0,7}$
0986020330	PM565	0986020880		9000042027	$12 \frac{0}{0,7}$
0986020340		0986020890	PM549	9000042031	M106 $\frac{0}{0}$
0986020350	PM547	0986020900	PM548	9000042031	M106 $\frac{0}{0}$
0986020360	PM584	0986021000	PM592	9000042034	$12 \frac{0}{0,7}$
0986020370	PM078	0986021010	PM567	9000042035	M031 $\frac{0}{0}$

BOSCH RMA $\frac{V}{Kw -!}$

9000042037	M320	0	
9000042037	M320	0	
9000042057	M150	0	
9000061020	M113		
9000082009		0	
9000082021	M166	12	0,8
9000082039	M166	12	0,8
9000082040	M166	12	0,8
9000082043		0	
9000082050	M148	12	0,9 15a
9000082050	M148	12	0,9 15a
9000082051		0	
9000082059	M148	0	
9000082060		0	
9000082061	M023	0	
9000082067	M017E	0	
9000082081	M357	12	0,8
9000082082	M166	12	0,8
9000083028	PM128	0	
9000083043	PM146	0	
9000083053	PM132	0	
9000083054	PM128	0	
9000083063	PM144	0	
9000083064	PM144	0	
9000083065	PM106	0	
9000083078			
9000084008	PM195	0	
9000084011	PM198	0	
9000084012	PM213	0	
9000084013	PM190	0	
9000084018	PM191	0	
9000084019	PM192	0	
9000084024	PM192	0	
9000141002	M078	12	0,7
9000141004	M078	12	0,7
9000141009	M078	12	0,7
9000141010	M078	12	0,7
9000141013	M203	12	0,8
9000141014	M078	12	0,7
9000141015	M078	12	0,7
9000141016	M077	12	0,6
9000141017	M203	12	0,8
9000141100	M119X	12	1,0
9000141100	M192	12	1,0

BOSCH RMA $\frac{V}{Kw -!}$

9000141101	M033X	12	0,8
9000141101	M033X	12	0,8
9000141103	M192	12	0,6
9000141103	M077	12	0,6
9000141104	M078	12	0,7
9000141107	M033X	12	0,8
9000141107	M033	12	0,8
9000141108		0	
9000141111	M119	12	1,0
9000141111	M119X	12	1,0
9000141112	M192	12	0,9
9000141112	M192	12	0,9
9000141113	M118	0	
9000141114	M018	12	0,8 15a
9000141116		0	
9000142001	M021	12	1,0
9000142002	M075X	12	0,8
9000142002	M075X	12	0,8
9000142003	M104	12	0,9
9000142100	M047	12	1,3
9000142101	M021	12	1,0
9000143002	PM126	0	
9000143200	PM112	0	
9000143400	PM147	0	
9000143406	M089	0	
9000143408	M089	0	
9000143413	M358	12	2,4
9000143501	PM139	0	
9000143601	PM106	0	
9000143601	PM106	0	
9000143604	PM597	0	
9000300937	M119X	0	
9000330107	PM908	12	0,6
9000330107	PM908	12	0,6
9000330113		12	0,6
9000330113		0	
9000330119	M077	12	0,6
9000330119	M077	12	0,6
9000330130	M078	12	0,7
9000330140	M067	12	0,6
9000330414	M114	12	0,8
9000330419	M047	12	1,3
9000330903	M021	0	
9000330910	M119X	12	1,0

BOSCH RMA $\frac{V}{Kw -!}$

9000330910	M192	12	1,0
9000330922	M032	12	0,8
9000330929	M033	12	0,8
9000330929	M033X	12	0,8
9000330937	M119X	12	1,0
9000330937	M119	12	1,0
9000330939	M033X	12	0,8
9000330939	M033	12	0,8
9000330948	M033	12	0,8
9000330948	M033X	12	0,8
9000330950	M119X	12	1,0
9000330950	M119	12	1,0
9000331001		12	0,8
9000331106		0	
9000331118	M134	0	
9000331201	M380	12	2,5
9000331203	M380	12	2,5
9000331405	M358	12	2,4
9000331406	M252	12	2,2
9000331411	M120X	12	1,9
9000331412	PM335	0	
9000331414	M156	12	2,0
9000331417		0	
9000331419	M089	0	
9000331420	M121X	12	2,9
9000331421	M252	12	2,2
9000331424	M252	12	2,2
9000331428	M252X	0	
9000331430	M252	12	2,2
9000331508	M179	12	0,7
9000331510	M081	12	0,6
9000331510	M081	12	0,6
9000331601		12	0,7
9000331602		12	0,7
9000331702	M010	12	0,8
9000331703	M075X	12	0,8
9000331703	M075X	12	0,8
9000331704	M118	12	0,8
9000331705	M117	12	1,1
9000331713	M084X	12	0,9
9000332501	M081	12	0,6
9000332501	M081	12	0,6
9000333104	M104	12	0,9
9000333105	M011	0	

BOSCH	RMA \sqrt{Kw} -!	BOSCH	RMA \sqrt{Kw} -!	BOSCH	RMA \sqrt{Kw} -!
9000333106	M104 $12/0,9$	9000692050	M150 $0/$	9007042015	$0/$
9000333109	M084X $12/0,9$	9000692051	$0/$	9007042016	$0/$
9000333112	M011 $12/0,9$	9000692062	M031 $0/$	9007042024	$12/0,7$
9000333114	M124X $12/0,9$	9000692069	M433 $0/$	9007042034	$12/0,7$
9000333115	M136 $12/0,9$ 15a	9000692069	M433 $0/$	9007044002	PM128 $0/$
9000333115	M136 $12/0,9$ 15a	9000692073	M194 $0/$	9007045003	M320 $0/$
9000333116	M136 $12/0,9$ 15a	9000692073	M194 $0/$	9007045006	M398 $0/$
9000333116	M136 $12/0,9$ 15a	9000692083	$0/$	9007045009	M398 $0/$
9000333117	M202 $12/0,9$	9000693013	M109 $0/$	9007045016	PM341 $0/$
9000333117	M202 $12/0,9$	9000694001	$0/$	9007045018	PM596 $0/$
9000333117	M202 $12/0,9$	9000694022	M433 $0/$	9007045020	M398 $0/$
9000333118	M137 $12/0,9$ 15a	9000694029	M248 $0/$	9009453044	$0/$
9000333118	M136 $12/0,9$ 15a	9004375442	M328 $0/$	9015728745	PM401 $0/$
9000333119	M134 $12/0,8$	9004475009	PM598 $0/$	AL68/31V1	PM118 $0/$
9000333119	M136 $12/0,8$	9004475012	$0/$	B001110040	M190 $0/$
9000333119	M137 $12/0,8$	9004475022	PM686 $0/$	B001110042	M099X $0/$
9000333121	M327 $0/$	9004475044	M106 $12/0,8$ 15a	B001110097	M314 $0/$
9000333122	M055 $0/$	9004475048	$0/$	B001110116	M150 $0/$
9000334101	M067 $12/0,6$	9004475057	$12/2,0$	B001110240	PM015 $0/$
9000334102	M055 $12/1,0$	9004475075	PM464 $0/$	B001111024	$0/$
9000334103	M330 $12/0,8$	9004475082	M223 $0/$	B001111025	M159 $0/$
9000334104	M118 $12/0,8$	9004475083	PM454 $0/$	B001111100	M083 $0/$
9000336310	PM139 $0/$	9004475085	M406 $0/$	B001111106	M099 $0/$
9000450010	$0/$	9004475111	PM599 $0/$	B001111143	M083 $0/$
9000450011	$0/$	9004475300	$0/$	B001111164	PM024 $0/$
9000451024	$0/$	9004475306	M114 $12/0,8$	B001111195	M388 $0/$
9000453003	$0/$	9004475310	M084X $12/0,9$	B001111214	M099 $0/$
9000453044	$0/$	9004475314	M308 $0/$	B001111217	$0/$
9000453083	$0/$	9004475316	M223 $0/$	B001111273	RM039 $0/$
9000475044	M106 $0/$	9004475318	M308 $0/$	B001111361	M415 $0/$
9000475044	M106 $0/$	9004475320	M318 $0/$	B001111390	PM028 $0/$
9000475310	M084X $0/$	9004475321	M059 $0/$	B001111399	M440 $0/$
9000475321	M059 $0/$	9004475325	M318 $0/$	B001111475	M260 $0/$
9000500039	PM459 $0/$	9004475404	$0/$	B001111498	M185X $0/$
9000500321	M433 $0/$	9004475442	M328 $0/$	B001115020	PM063 $0/$
9000500324	M433 $0/$	9004475448	M427 $0/$	B001116118	PM044 $0/$
9000692001	$0/$	9004475450	M406 $0/$	B001117012	M015 $0/$
9000692003	$12/0,7$	9004475454	PM027 $0/$	B001117013	M299X $0/$
9000692014	M107 $0/$	9004475455	PM299 $0/$	B001117050	PM051 $0/$
9000692015	M106 $0/$	9004475456	PM684 $0/$	B001117070	M214 $0/$
9000692019	M010 $0/$	9004475458	PM268 $0/$	B001117071	M014 $0/$
9000692026	M433 $0/$	9004475459	PM476 $0/$	B001117148	PM051 $0/$
9000692027	M119X $12/1,0$	9004475466	PM296 $0/$	B001117149	PM051 $0/$
9000692042	M433 $0/$	9004475467	M420 $0/$	B001117311	M120X $0/$

BOSCH RMA $\sqrt{\text{Kw}} -!$

B001126016	PM082	0/
B001127016	M313	0/
B001127041	PM076	0/
B001180009	M148	0/
B001181007	M150	0/
B001181013	M190	0/
B001181014	M191	0/
B001233092	M354	0/
B001233104	M066X	0/
B001233112	M066X	0/
B001233121	M088	0/
B001233158	M258	0/
B001233172	M088	0/
B001233216	M277X	0/
B001233261	M088	0/
B001315183	M165	0/
B001329010		/
B001329045	M052	0/
B001411324	PM189	0/
B001816006	PM164	0/
B001816326	PM106	0/
B001816592	PM169	0/
B001960018	PM180	0/
BNG4/24	PM184	0/
BPD6/24AR9Z11		0/
EGD1/12AR37	M172	0/
EJD3/12BR4	PM124	0/
F000AL0 401		/
F000AL0100		/
F000AL0101		/
F000AL0101		/
F000AL0102		/
F000AL0102		/
F000AL0103	RM083	/
F000AL0104	RM084	/
F000AL0108		/
F000AL0110	PM890	/
F000AL0110	PM890	/
F000AL0111	PM891	/
F000AL0300		/
F000AL0301		/
F000AL0302		/
F000AL0304		/
F000AL0305		/

BOSCH RMA $\sqrt{\text{Kw}} -!$

F000AL0306		/
F000AL0306		/
F000AL0307		/
F000AL0307		/
F000AL0309	RM081	/
F000AL0310	RM082	/
F000AL0320		/
F000AL0400		/
F000AL0502		/
F000AL0503		/
F000AL0801		/
F000AL0900	RM079	/
F005M00001	M314	0/
F005M00005		/
F005M00006		/
F005M00010	PM699	/
F005M00011	PM698	/
F005M00013	PM299	/
F005M00016	RM080	/
F005X10640		/
F009AL0101		/
F009AL0102		/
F009AL0103	RM083	/
F009AL0103	RM083	/
F009AL0104	RM084	/
F009AL0104	RM084	/
F009AL0301		/
F009AL0302		/
F009AL0304		/
F009AL0307		/
F009AL0309	RM081	/
F009AL0310	RM082	/
F009AL0801		/
L0 103		/
R007042024		0/

BOSCH RMA $\sqrt{\text{Kw}} -!$

MOTORINI

CARGO

CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$
110114	PM405	110252	PM778	110352	
110142	M424	110253	PM796	110354	
110143		110256	PM643	110355	PM644
110144	PM405	110260	PM423	110356	M422
110145	M128	110261		110363	
110146	M130	110262	PM787	110364	
110148	PM741	110263	PM379	110365	
110149	M433	110276		110367	
110150	M439	110277	PM371	110368	
110151	PM780	110278	PM372	110371	
110152	PM602	110279	M320	110383	PM730
110153	PM600	110280	PM377	110386	PM272
110154	PM603	110283	PM402	110389	PM400
110155	PM643	110286	PM408	110391	PM789
110156	PM615	110289	PM785	110393	M441
110157	PM403	110290	PM431	110394	M327
110158	M425X	110291	M324	110395	PM601
110159	M127	110292	PM409	110396	PM415
110160		110293	PM424	110397	PM444
110178		110294	M334X	110399	
110182	PM404	110295	PM351	110400	
110205		110296	M326	110403	PM512
110206		110297		110404	
110207		110298	M129	110409	
110208		110308	PM405	110410	M106
110209		110309	M374	110411	PM416
110210		110310	PM327	110412	PM270
110211		110311	PM384	110415	PM392
110212		110312	M194	110417	PM621
110213		110315	M425	110420	
110214		110316	M333	110421	PM747
110224		110317	PM459	110436	PM812
110225		110321	PM403	110437	
110226		110322		110438	
110227		110323		110439	
110228		110332	PM616	110440	
110229		110336		110441	
110230		110337		110442	
110231		110338		110443	
110232		110339		110444	PM779
110245	PM442	110340		110446	PM839
110246	PM426	110341		110447	M438X
110247	PM283	110347	PM223	110449	
110249	PM287	110351	RM039	110450	PM685

MOTORINI

CARGO

CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$
110452		110545		110640	
110453		110550		110656	PM770
110454		110551		110708	PM419
110459	RM095	110552	PM542	110709	
110460	RM096	110553	PM669	110710	PM676
110462	M294	110554	PM765	110711	PM465
110464	PM690	110555	PM773	110712	PM469
110465		110556	PM772	110713	PM015
110467	PM281	110557	PM768	110714	
110473	PM429	110558	PM762	110715	M332
110474	M370	110560	PM766	110716	PM527
110477	PM459	110565	PM645	110717	PM388
110478	PM273	110566		110718	PM623
110479	M425X	110568	PM413	110719	
110480	PM383	110571	PM385	110720	PM428
110481		110572	PM368	110723	PM278
110486	PM421	110573	PM432	110759	
110490	PM422	110574	M336X	110771	
110494	PM276	110575	PM265	110772	
110509		110576	PM396	110774	
110511		110578	PM387	110775	
110512		110579		110776	
110517		110580	PM279	110777	
110518	PM146	110581	PM433	110779	
110519		110582		110783	
110520	PM142	110583	PM792	110784	
110521		110584		110785	
110522	PM135	110585		110786	
110523	PM137	110587		110789	
110524	PM106	110589	PM464	110790	
110525		110592		110792	
110527		110600		110793	
110528		110601		110794	
110529	M091	110605		110795	
110530		110605		110796	
110531		110609		110797	
110532		110615	PM689	110807	PM609
110533		110616	PM280	110808	M431
110534		110617	PM617	110809	M193
110535		110624		110810	PM274
110536	PM122	110625	PM763	110811	M426
110537		110626	PM795	110812	
110538	PM182	110627	PM262	110813	PM150
110539		110637		110814	

CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$
110817		110932		111030	
110818	PM688	110933	PM378	111031	
110819	PM224	110934		111046	
110820	PM271	110938	PM436	111047	
110821		110940	PM427	111050	PM769
110822		110941		111051	
110823		110942	PM441	111052	
110824		110944	PM816	111053	
110825		110947	PM391	111054	
110826		110953		111055	M095
110827		110958	PM376	111056	
110828		110961	PM463	111057	
110829	M067	110962	PM448	111058	
110830		110963	PM447	111059	M150
110831		110980	PM170	111060	M014
110833		110981		111061	
110835		110983	PM744	111062	
110836	M026	110994		111063	
110837	M104	110996		111064	
110838		110997		111065	
110839		110998		111066	
110840		110999	PM753	111067	
110842		111000	PM752	111068	
110844		111001	PM159	111069	
110845		111003		111070	M105
110847		111004		111076	
110849		111005	PM746	111080	M201
110850		111006		111087	PM453
110851	M244	111008		111088	
110854		111010	M116	111098	PM627
110855		111011		111099	
110856	PM908	111013		111100	M078
110858		111014		111101	
110859		111015		111102	
110860		111019	PM775	111103	
110861		111020	PM776	111104	
110862		111021	M438	111105	
110864		111022	PM431	111106	
110865		111023	PM521	111107	PM555
110866		111024		111108	
110867	M214	111025	M056	111109	
110868		111027		111110	
110869		111028		111111	
110870		111029	M195	111112	

MOTORINI

CARGO

CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$
111113		111253	PM673	111400	
111114		111254	PM680	111401	
111115	M157	111262	PM786	111404	PM255
111116		111269	M263	111420	
111117		111270		111421	M228
111118		111271		111422	
111119		111272		111423	
111120	M066X	111273	PM261	111424	
111122		111274	M340	111425	PM022
111123	M143	111275	PM259	111440	
111124		111276	M445	111441	PM526
111125		111284		111442	
111126	M308	111287		111443	PM347
111127		111289		111444	PM523
111129	PM024	111299	PM834	111445	M336
111130	M102X	111300	PM386	111446	
111131	M134	111303	M338	111447	
111133		111303	M338	111448	PM275
111134		111304		111449	
111135		111305	M429	111450	PM516
111136	M423	111306	PM536	111451	PM364
111165		111307	PM535	111452	PM632
111182	M442	111310	M446	111453	PM375
111183		111311		111454	PM364
111189	PM824	111312	PM341	111455	PM488
111196	PM783	111332		111456	PM023
111197	PM485	111333	PM251	111457	PM361
111208	RM098	111334		111458	PM294
111209		111335	PM909	111459	M443
111210	RM097	111346	PM691	111460	PM360
111211		111347	M083	111461	M341
111212	PM767	111348		111463	PM495
111214	PM684	111349	M345	111464	
111218		111374	PM253	111465	PM355
111219		111379		111472	PM353
111224	PM782	111380		111473	PM349
111231		111382	PM518	111474	
111232		111385	M328	111475	M330
111241	PM299	111386	PM466	111476	
111242	PM363	111387	M335	111485	M343
111246	PM365	111393	PM678	111488	PM362
111247	PM651	111396	M398	111489	
111249		111398		111490	
111251	M017X	111399		111492	M412

MOTORINI

CARGO

CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$
111499	RM099	111634	PM622	111771	
111506	PM256	111636	PM139	111783	
111508		111637		111784	PM490
111520		111638	PM110	111785	
111523		111640	PM164	111790	
111525		111641		111791	
111534	M344	111642	PM370	111792	
111542	PM445	111643	M325X	111793	
111543	PM296	111679	PM479	111805	M336X
111544		111680	M387	111817	
111545	PM401	111681		111818	M320X
111546		111682	PM477	111821	PM013
111547		111683	PM432	111822	
111548	PM430	111685	M402	111823	PM566
111549	M447	111690	M421	111827	
111550	M428	111693		111836	PM613
111551	PM467	111694	M069	111838	PM793
111552	M437	111696	PM350	111839	PM847
111553		111698	M099X	111840	PM612
111554		111703	PM735	111844	
111555		111706	PM624	111845	PM825
111556	PM476	111724		111848	M314
111557		111728	PM373	111851	M399
111558		111730		111855	PM096
111559	PM268	111731	PM510	111856	
111560	M211	111737		111865	PM044
111561	M334	111741		111866	PM013
111562	PM357	111748		111868	
111563	PM354	111749		111874	PM095
111564		111750	M261	111885	
111565	PM394	111751		111900	M289
111566	PM509	111752	PM115	111904	M315
111567		111755		111905	
111573		111757		111906	M389
111574	PM599	111759		111907	
111581		111760	PM771	111908	
111585		111762	PM513	111909	PM070
111586		111763	PM522	111910	
111608	M201	111764	PM811	111911	M185X
111618	PM650	111765	PM808	111912	PM398
111619	M058X	111766	PM626	111913	PM395
111620		111768		111915	PM864
111622	PM835	111769		111918	PM865
111630	M269	111770	M288	111920	PM802

MOTORINI

CARGO

CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$
111921	PM658	112083	PM277	112236	
111922	PM655	112089		112246	PM654
111923	PM657	112103		112249	
111924	PM656	112115		112251	M420
111925		112116		112256	
111926		112117		112267	PM751
111927		112118		112275	PM755
111930		112119		112276	PM754
111931	M414	112120		112286	
111966		112122		112289	
111968	PM497	112123		112290	M307
111969	PM501	112124		112291	PM635
111970		112125	M048X	112293	PM542
111971	PM344	112131		112295	M120X
111981		112132		112296	PM618
111982	PM105	112133		112300	PM345
111983		112134		112301	PM238
111994	M391	112135		112304	RM085
111995	PM042	112136		112305	
111996	M352	112141	M235	112306	
112003	PM517	112163		112307	
112004		112166	M282	112309	
112005	PM071	112167	M256	112315	
112006	M397	112171		112319	M235X
112008	PM611	112172	M299X	112320	PM641
112014		112173	M288	112321	
112016		112174		112322	PM659
112026		112175		112323	PM749
112027	M411	112177	PM713	112336	
112029	PM301	112178	PM714	112340	PM027
112033	PM489	112185	PM734	112342	PM666
112034		112213	M427X	112347	PM243
112036	PM800	112214	M427	112364	PM500
112037		112215		112365	PM269
112039		112216	PM630	112366	
112040	RM041	112217	PM288	112367	PM505
112041		112218	PM237	112368	PM337
112047	PM863	112220		112369	
112052		112221	PM082	112370	
112053	PM094	112223		112371	PM271
112055		112224	RM040	112373	PM631
112071		112225		112374	PM272
112074	PM160	112226	M088X	112379	PM241
112080		112227	PM761	112380	PM314

MOTORINI

CARGO

CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$	CARGO	RMA $\sqrt{\text{Kw}} -!$
112381		112542		112985	PM633
112382		112544	PM830	112986	PM636
112383	M410	112545	PM822	113007	
112388	PM934	112546	PM821	113020	PM663
112390	PM692	112547	PM878	113022	PM296
112391		112552	PM049	113023	PM694
112429	PM080	112555		113024	PM693
112430		112580	PM717	113025	
112431	RM086	112581	RM091	113026	PM694
112432		112582	PM823	113036	PM745
112433		112591		113037	PM750
112434		112609	PM607	113038	PM411
112435		112610		113039	PM742
112436		112649	PM668	113040	PM411
112437	RM087	112651		113041	PM728
112438	PM081	112659	PM619	113042	PM738
112439		112660		113043	PM716
112440		112670		113044	PM719
112441	PM099	112672	PM647	113045	PM700
112442	PM163	112674	PM620	113046	PM701
112443		112675	PM640	113047	PM706
112444	PM079	112676	PM648	113095	PM791
112445	M393	112677	PM614	113096	PM818
112446	PM107	112710		113097	PM437
112454	M151	112719		113098	M326X
112455		112816	PM540	113099	PM797
112459		112817		113100	PM813
112474	PM239	112818		113101	PM809
112474	PM239	112819		113102	PM804
112475	PM240	112820		113103	PM810
112476	M418	112821	PM244	113104	PM832
112478	PM628	112822	PM869	113105	PM833
112489	PM873	112823	PM883	113106	PM838
112494	PM592	112844	PM637	113107	PM840
112496	PM553	112845	PM721	113108	PM494
112497	M375	112846	PM725	113109	PM845
112498	PM594	112911	PM675	113110	PM848
112499		112963		113111	PM842
112505	PM777	112964		113112	PM849
112507		112965		113113	PM843
112533	M037X	112966		113114	PM844
112536		112982	PM625	113115	PM851
112537	M258	112983	PM629	113116	PM854
112541		112984	PM410	113117	PM852

MOTORINI

CARGO

CARGO	RMA $\sqrt{Kw - !}$	CARGO	RMA $\sqrt{Kw - !}$	CARGO	RMA $\sqrt{Kw - !}$
113118	PM858	113210	PM649	113319	PM757
113119	PM857	113211	PM874	113323	PM758
113120	PM881	113214	PM799	113325	PM748
113121	PM828	113215		113327	PM683
113122	PM902	113219		113329	PM662
113128	PM743	113224	PM868	113339	PM893
113129	PM667	113229	PM724	113344	
113130	PM798	113230	PM807	113346	M406
113131	PM670	113231	PM803	113353	
113132	PM681	113234	PM723	113361	PM499
113134	M246	113237	PM815	113379	
113135	PM715	113238	PM856	113380	
113136	PM712	113239	PM836	113381	
113137	PM720	113240	PM855	113385	PM677
113138	PM722	113241	PM850	113387	M396
113139	PM341	113242	PM875	113388	PM671
113140	PM390	113243	PM880	113389	
113141	PM729	113244	PM871	113390	
113167	PM731	113254	PM899	113392	PM653
113168	PM820	113255	PM912	113393	
113169	PM837	113256	PM926	113394	
113170	PM861	113261	RM088	113396	
113171	PM862	113262	RM090	113398	PM674
113172	PM817	113266		113399	
113173	PM860	113267	PM069	113400	
113174	PM853	113268	PM552	113402	PM679
113175	PM866	113271	PM018	113408	PM639
113178	PM867	113276	M143X	113409	
113179	PM556	113277		113428	PM672
113181	PM586	113281	PM543	113429	PM794
113182		113282		113430	
113183	PM593	113286		113434	PM859
113184		113287	PM726	113436	
113191	PM652	113288	PM545	113443	
113193		113292		113444	
113194	PM736	113293		113445	PM399
113195	PM759	113297		113446	
113199	PM790	113299	PM016	113451	M284
113203	PM801	113303		113454	
113204	PM814	113307	M379	113459	PM872
113205	PM819	113312		113461	PM709
113206	PM831	113313	PM827	113464	
113207	PM841	113314	PM532	113465	PM120
113209	PM682	113318	PM739	113466	

MOTORINI

CARGO

CARGO **RMA** $\frac{V}{Kw -!}$

113467	
113468	
113475	PM806
113478	
113479	
113480	
113481	
113482	
113483	
113490	PM781
113491	PM784
113492	PM877
113494	PM610
113499	PM774
113504	PM703
113505	PM634
113508	
113509	PM574
113513	PM547
113515	PM561
113521	PM665
113527	
113532	
113534	
113551	PM756
113560	PM737
113570	
113585	PM708
113586	PM870
113587	
113594	
113596	PM805
113597	PM829
113601	PM876
113605	
113608	
113609	PM892
113613	PM546
113614	PM638
113615	PM718
113616	PM705
113617	
113618	PM711
113619	PM882

CARGO **RMA** $\frac{V}{Kw -!}$

113620	PM884
113629	PM879
113630	PM886
113635	PM826
113638	PM664

CARGO **RMA** $\frac{V}{Kw -!}$

DAIHATSU RMA $\frac{V}{Kw - !}$

2810013010	PM424	0/
2810013031		0/
2810013060	PM600	0/
2810013080	PM424	0/
2810015060	PM601	0/
2810015070	PM431	0/
2810024070	PM600	0/
2810026020		0/
2810026080		0/
2810027030	PM434	0/
2810036040	PM602	0/
2810036060	PM602	0/
2810036070	PM602	0/
2810040015	PM603	0/
2810056151	PM457	0/
2810064020	PM466	0/
2810064170	PM482	0/
2810064180	PM466	0/
2810064280	PM466	0/
2810072010	PM444	0/
2810072080	PM444	0/
2810087106	PM480	0/
2810087213	PM460	0/
2810087222		0/
2810087316	PM258	0/
2810087401	PM507	0/
2810087510	M444	0/
2810087511	M444	0/
2810087517	M444	0/
2810087526	M444	0/
2810087548	M444	0/
2810087601	PM429	0/
2810087602	PM473	0/
2810087603	PM474	0/
2810087606	PM473	0/
2810087708	M129	0/
2810087709	M337	0/
2810087710	PM446	0/
2810087713	PM446	0/
2810087715	PM430	0/
2810087719	PM461	0/
2810087721	PM446	0/
2810087722	M129	0/
2810087727	M129	/

DAIHATSU RMA $\frac{V}{Kw - !}$

2810087729	PM430	0/
2810087730	PM430	0/
2810087731	PM430	0/
2810087734	M129	0/
2810097204	PM604	/

DAIHATSU RMA $\frac{V}{Kw - !}$

DELCO RMA $\frac{V}{Kw -!}$

00E091	M420	
10455506	M143	0
10461470	PM105	
10479627	PM106	0
110397	M088	0
110566	PM269	
1109775	PM223	
1113905	PM223	0
1114848	PM223	0
111534	M336X	
112161	M420	
143	M094	
150	M095	
152	M081	
153	M096	
154	M093	
155	M180	
162	M096	
163	M094	
164	M096	
165	M093	
168	M095	
169	M143	
170		
171	M094	
172	M095	
173	M143	
174		
176	M093	
17610-Q1010	M336X	
177	M095	
19011501	PM892	
19024000	PM221	
19024010	PM204	0
19024011	PM206	
19024013	PM192	
19024013	PM192	
19024013		
19024015		
19024016	PM201	
19024016	PM201	
19024017		
19024018	PM207	
19024024	PM184	

DELCO RMA $\frac{V}{Kw -!}$

19024025	PM204	
19024028		
19024030	PM193	
19024032	PM196	
19024035	PM199	
19024035	PM188	
19024038	PM205	
19024038	PM188	
19024040	PM121	
19024040	PM195	
19024041		
19024042	PM209	
19024046		
19024047		
19024049	PM210	
19024051	PM189	
19024053	PM194	
19024055		
19024063		
19024064	PM199	
19024071	PM184	
19024075	PM192	
19024076	PM213	0
19024077	PM213	
19024077	PM190	
19024078	PM198	
19024079	PM179	
19024079		
19024079		
19024080	PM215	
19024084	PM216	
19024085	PM219	
19024085	PM218	
19024104	PM170	
19024109	PM211	
19024122	PM217	
19024124	PM217	
19024124	PM202	
19024133	RM040	
19024148	PM181	
19024152	PM185	
19024161	PM190	
19024178	PM216	
19024179	PM180	

DELCO RMA $\frac{V}{Kw -!}$

19024201	PM142	
19024204	PM106	
19024205	PM128	
19024214	PM144	
19024218		
19024223	PM128	
19024224	PM152	
19024225	PM106	
19024226	PM137	
19024230	M091	
19024231	PM138	
19024232	PM136	
19024238	PM119	
19024241	M028	
19024242	PM155	
19024245	PM120	
19024246	PM108	
19024247	PM123	
19024249	M089	
19024254	M027	
19024255	PM096	
19024256	PM146	
19024257	PM115	
19024258	PM106	
19024259	M059	
19024262	PM174	
19024263	PM172	
19024264	PM164	
19024265	PM173	
19024266	PM160	
19024267	M355	
19024268	PM110	
19024801		
19024813	PM156	
19024824	PM148	
3431 143	M094	$\frac{12}{0,6}$
3471 141	M174	$\frac{12}{1,0}$ 15a
3471 143	M094	$\frac{12}{0,6}$
3471 144	M174	$\frac{12}{1,0}$ 15a
3471 150	M095	$\frac{12}{0,7}$
3471 152	M096	$\frac{12}{0,8}$
3471 152	M096	$\frac{12}{0,8}$
3471 153	M096	$\frac{12}{0,8}$
3471 153	M096	$\frac{12}{0,8}$

DELCO	RMA \sqrt{Kw} -!
3471 154	M093 $\frac{12}{1,0}$
3471 155	M180 $\frac{12}{0,8}$
3471 155	M180 $\frac{12}{0,8}$
3471 157	$\frac{0}{}$
3471 159	$\frac{0}{}$
3471 162	M096 $\frac{12}{0,8}$
3471 162	M093 $\frac{12}{0,8}$
3471 163	M094 $\frac{12}{0,6}$
3471 164	M096 $\frac{12}{0,8}$
3471 164	M096 $\frac{12}{0,8}$
3471 164	M096 $\frac{12}{0,8}$
3471 165	M093 $\frac{12}{1,0}$
3471 168	M095 $\frac{12}{0,7}$
3471 169	M095 $\frac{12}{0,7}$
3471 170	M226 $\frac{12}{1,0}$
3471 170	M226 $\frac{12}{1,0}$
3471 171	M094 $\frac{12}{0,6}$
3471 172	M095 $\frac{12}{0,7}$
3471 173	M095 $\frac{12}{0,9}$
3471 174	M226 $\frac{12}{1,0}$
3471 176	M093 $\frac{12}{1,0}$
3471 177	M095 $\frac{12}{0,7}$
3471 190	M095 $\frac{0}{}$
3471 364	M174 $\frac{12}{1,0}$ 15a
3471 365	M174 $\frac{12}{1,0}$ 15a
3471 366	M095 $\frac{12}{0,7}$
3471 369	M096 $\frac{12}{0,8}$
3471 369	M096 $\frac{12}{0,8}$
3471 369	M096 $\frac{12}{0,8}$
3471 371	M095 $\frac{12}{0,7}$
3471 372	M093 $\frac{12}{1,0}$
3471 375	M093 $\frac{12}{1,0}$
3471 376	M093 $\frac{12}{1,0}$
3471 377	M180 $\frac{12}{0,8}$
3471 377	M180 $\frac{12}{0,8}$
3471 390	M094 $\frac{12}{0,6}$
3471 391	M093 $\frac{12}{1,0}$
3471 392	M093 $\frac{12}{1,0}$
3471 393	M095 $\frac{12}{0,7}$
3471 394	M180 $\frac{12}{0,8}$
3471 394	M180 $\frac{12}{0,8}$
3471 395	M064 $\frac{12}{2,0}$
3471 396	M052 $\frac{12}{1,7}$
3471 396	M052 $\frac{12}{1,7}$

DELCO	RMA \sqrt{Kw} -!
3471 397	M096 $\frac{12}{0,8}$
3471 397	M096 $\frac{12}{0,8}$
3471 397	M096 $\frac{12}{0,8}$
3471 850	M226 $\frac{12}{1,0}$
3471143	M094 $\frac{12}{0,8}$
3471169	M143 $\frac{12}{0,8}$
3471170	$\frac{12}{0,8}$
3471173	M143 $\frac{12}{0,8}$
3471174	$\frac{12}{0,8}$
3471850	$\frac{12}{0,8}$
3491 190	$\frac{12}{0,9}$
3491190	M143 $\frac{12}{0,9}$
366	M095 $\frac{12}{0,9}$
369	M096 $\frac{12}{0,9}$
377	M180 $\frac{12}{0,9}$
390	M094 $\frac{12}{0,9}$
391	M093 $\frac{12}{0,9}$
394	M180 $\frac{12}{0,9}$
395	M064 $\frac{12}{0,9}$
397	M096 $\frac{12}{0,9}$
850	$\frac{12}{0,9}$
9000700	M143 $\frac{12}{1,0}$
9000701	M226 $\frac{12}{1,0}$
9000751	M143 $\frac{12}{0,9}$
9000756	M143 $\frac{12}{0,9}$
9000758	M143 $\frac{12}{0,9}$
9000772	M143 $\frac{12}{0,9}$
9000781	M143 $\frac{12}{0,9}$
9000785	M143 $\frac{12}{0,9}$
9000791	M143 $\frac{12}{0,9}$
9000794	M314 $\frac{12}{0,9}$
9000794	M143 $\frac{12}{0,9}$
9000794	M099X $\frac{12}{0,9}$
9000802	M143 $\frac{12}{0,9}$
9000817	M099X $\frac{12}{0,9}$
9000820	RM089 $\frac{12}{0,9}$
96208781	M143 $\frac{12}{0,9}$
96208782	M143 $\frac{12}{0,9}$
96208783	M099X $\frac{12}{0,9}$
96208783	M143 $\frac{12}{0,9}$
96208783	M314 $\frac{12}{0,9}$
96208785	M314 $\frac{12}{0,9}$
96275481	PM732 $\frac{12}{0,9}$
96569440	PM732 $\frac{12}{0,9}$

DELCO	RMA \sqrt{Kw} -!
CER3087	M420 $\frac{12}{0,8}$
DRS0110	$\frac{12}{0,8}$
DRS0120	M096 $\frac{12}{0,8}$
DRS0190	M021 $\frac{12}{0,8}$
DRS0200	M010 $\frac{12}{0,8}$
DRS0250	M180 $\frac{12}{0,8}$
DRS0340	M013 $\frac{12}{0,8}$
DRS0350	M016 $\frac{12}{0,8}$
DRS0360	M031 $\frac{12}{0,8}$
DRS0370	M106 $\frac{12}{0,8}$
DRS0380	$\frac{12}{0,8}$
DRS0390	M082 $\frac{12}{0,8}$
DRS0400	M159 $\frac{12}{0,8}$
DRS0410	M107 $\frac{12}{0,8}$
DRS0430	M137 $\frac{12}{0,8}$
DRS0460	M024 $\frac{12}{0,8}$
DRS0470	M251 $\frac{12}{0,8}$
DRS0480	M034 $\frac{12}{0,8}$
DRS0530	$\frac{12}{0,8}$
DRS0570	$\frac{12}{0,8}$
DRS0590	M121X $\frac{12}{0,8}$
DRS0640	M049 $\frac{12}{0,8}$
DRS0710	M043 $\frac{12}{0,8}$
DRS0780	M109 $\frac{12}{0,8}$
DRS0810	$\frac{12}{0,8}$
DRS0830	M063 $\frac{12}{0,8}$
DRS0850	M197 $\frac{12}{0,8}$
DRS0890	M087 $\frac{12}{0,8}$
DRS0910	M063 $\frac{12}{0,8}$
DRS0920	M051 $\frac{12}{0,8}$
DRS0940	M218 $\frac{12}{0,8}$
DRS0950	M059 $\frac{12}{0,8}$
DRS0960	PM120 $\frac{12}{0,8}$
DRS0970	PM108 $\frac{12}{0,8}$
DRS0980	PM110 $\frac{12}{0,8}$
DRS0990	PM148 $\frac{12}{0,8}$
DRS1000	M253 $\frac{12}{0,8}$
DRS1010	PM118 $\frac{12}{0,8}$
DRS1020	PM149 $\frac{12}{0,8}$
DRS1040	PM123 $\frac{12}{0,8}$
DRS1060	M027 $\frac{12}{0,8}$
DRS1070	M064 $\frac{12}{0,8}$
DRS1080	M028 $\frac{12}{0,8}$
DRS1090	M065 $\frac{12}{0,8}$

DELCO	RMA $\sqrt{\text{Kw}} -!$	DELCO	RMA $\sqrt{\text{Kw}} -!$	DELCO	RMA $\sqrt{\text{Kw}} -!$
DRS1130	PM115	DRS2730	PM199	DRS3206	M223
DRS1140		DRS2750	PM133	DRS3207	M201
DRS1150	M089	DRS2780	PM134	DRS3216	M340
DRS1160	PM155	DRS2831	PM404	DRS3223	PM268
DRS1170	PM139	DRS2931	PM643	DRS3240	M105
DRS1180	PM158	DRS2940	PM144	DRS3248	PM521
DRS1190	PM112	DRS2970	PM205	DRS3260	PM201
DRS1200	PM122	DRS2980	M164	DRS3265	M271
DRS1210	PM126	DRS3018	M335X	DRS3267	M214
DRS1220	M091	DRS3027	RM039	DRS3268	M017X
DRS1240	PM128	DRS3050	M014	DRS3269	PM251
DRS1250		DRS3052	M440	DRS3274	M268
DRS1270	PM137	DRS3076	M124X	DRS3277	
DRS1280	PM136	DRS3080		DRS3289	PM689
DRS1290	PM164	DRS3090	M214	DRS3293	PM157
DRS1310	PM138	DRS3100		DRS3304	PM479
DRS1330	PM146	DRS3107	M017X	DRS3318	M105X
DRS1360	PM106	DRS3108	M222	DRS3338	PM375
DRS1370		DRS3114	PM024	DRS3343	
DRS1380	PM141	DRS3117	M105	DRS3344	PM394
DRS1440	PM188	DRS3118	PM028	DRS3350	M257
DRS1460	PM193	DRS3119	M017X	DRS3353	M443
DRS1480	PM196	DRS3126	M308	DRS3354	M447
DRS1530	PM221	DRS3129	M426	DRS3356	PM361
DRS1540	PM181	DRS3140		DRS3357	M320
DRS1550	PM184	DRS3143	PM299	DRS3359	M374
DRS1570	PM204	DRS3153	PM401	DRS3367	PM454
DRS1580	PM206	DRS3154	PM274	DRS3368	M308
DRS1601	M067	DRS3155	PM366	DRS3369	PM684
DRS2172		DRS3156	PM274	DRS3374	M442
DRS2311	PM425	DRS3159	M429	DRS3375	M328
DRS2320	M116	DRS3163	PM299	DRS3379	PM497
DRS2420	PM121	DRS3164	M338	DRS3380	
DRS2430	PM127	DRS3165	M336X	DRS3383	M443
DRS2480	PM198	DRS3168	M336	DRS3384	PM488
DRS2590		DRS3170	PM145	DRS3385	PM466
DRS2600		DRS3173	M252	DRS3386	PM470
DRS2650	M250	DRS3179		DRS3387	PM476
DRS2660		DRS3187	M417	DRS3388	PM476
DRS2670	PM150	DRS3189	M423	DRS3389	PM416
DRS2680	PM125	DRS3197	M059	DRS3393	PM087
DRS2690	M089	DRS3198	PM044	DRS3394	M344
DRS2700	PM156	DRS3202	M120X	DRS3406	PM286
DRS2710	PM119	DRS3205	M406	DRS3409	PM130

DELCO	RMA $\sqrt{\text{Kw}} -!$	DELCO	RMA $\sqrt{\text{Kw}} -!$	DELCO	RMA $\sqrt{\text{Kw}} -!$
DRS3420	PM207	DRS3645	PM419	DRS4341	
DRS3424	PM464	DRS3646	PM491	DRS4361	M334
DRS3426	PM599	DRS3649	PM482	DRS4411	M326
DRS3427	PM224	DRS3650	M246	DRS4481	PM601
DRS3430	PM194	DRS3679	PM641	DRS4550	PM185
DRS3440	PM202	DRS3680	PM152	DRS4560	PM210
DRS3443	PM686	DRS3685	PM054	DRS4570	M057
DRS3449	PM171	DRS3690	PM162	DRS4580	M238
DRS3455	PM598	DRS3700	PM166	DRS4590	M195
DRS3466		DRS3710	PM168	DRS4600	M260
DRS3470	M148	DRS3720	PM169	DRS4610	M243
DRS3473	M318	DRS3728	PM344	DRS4620	M069X
DRS3474	M406	DRS3730	PM204	DRS4630	M112
DRS3475	PM256	DRS3733	PM256	DRS4640	M115
DRS3478	PM013	DRS3743	M120X	DRS4680	PM088
DRS3479	M195	DRS3748	PM498	DRS4700	M058
DRS3484	M421	DRS3758	PM337	DRS4740	PM121
DRS3490	PM106	DRS3765		DRS4800	M113
DRS3535	M420	DRS3770	PM165	DRS4810	M191
DRS3545	M391	DRS3797	PM244	DRS4820	M191
DRS3558	M343	DRS3807	PM541	DRS4830	M251
DRS3561	PM435	DRS3819	PM078	DRS4840	M175
DRS3564	M137	DRS3828	PM109	DRS4850	PM131
DRS3565	M134	DRS3850	M222	DRS4860	M143
DRS3567	M235X	DRS3861	M124X	DRS4870	PM195
DRS3575	PM297	DRS3871	PM247	DRS4890	M299X
DRS3576	PM693	DRS3880		DRS4900	M185
DRS3576		DRS3910	M247	DRS4910	PM192
DRS3579	M431	DRS3940	M056	DRS4920	PM192
DRS3593	M277	DRS3971	M129	DRS4940	PM051
DRS3594	M037	DRS3991	PM429	DRS4960	M062X
DRS3595	PM411	DRS4051	M194	DRS4971	PM400
DRS3603	PM518	DRS4061	PM295	DRS4991	M431
DRS3610		DRS4071	M333	DRS5010	M017X
DRS3614		DRS4081	PM459	DRS5021	M332
DRS3618	M105	DRS4091	PM623	DRS5031	PM796
DRS3619		DRS4151	PM409	DRS5050	M375
DRS3624	PM237	DRS4171	M324	DRS5090	M307
DRS3625	PM036	DRS4191	PM275	DRS5150	M261
DRS3629	M223	DRS4211	M441	DRS5190	PM558
DRS3636		DRS4221	PM383	DRS5200	M190
DRS3638	M428	DRS4231	M374	DRS5230	PM021
DRS3643	PM488	DRS4261	PM523	DRS5260	
DRS3644	PM489	DRS4331	M211	DRS5320	

DELCO	RMA $\sqrt{\text{Kw}} -!$	DELCO	RMA $\sqrt{\text{Kw}} -!$	DELCO	RMA $\sqrt{\text{Kw}} -!$
DRS5341	PM272	DRS6600	M017E	DRS7391	M120X
DRS5351		DRS6660	M262	DRS7420	M385
DRS5401	M275	DRS6700	M282	DRS7430	PM096
DRS5420	PM154	DRS6730	PM013	DRS7450	M315
DRS5470	PM050	DRS6740	M380	DRS7460	M289
DRS5540	M089	DRS6750	M415	DRS7470	PM093
DRS5551	M213	DRS6780	PM026	DRS7480	PM097
DRS5560	M013X	DRS6800	M255	DRS7490	M352
DRS5600	M200	DRS6840	PM053	DRS7500	PM095
DRS5630	M062	DRS6860	PM031	DRS7520	PM174
DRS5670	PM215	DRS6870	M058X	DRS7530	M403
DRS5701	PM684	DRS6880	M314	DRS7760	PM179
DRS5721	PM296	DRS6890	M099	DRS7810	RM040
DRS5740	M304	DRS6900	M058	DRS7830	PM070
DRS5751	PM385	DRS6910	M200	DRS7840	M319
DRS5781	M337	DRS6920	PM055	DRS7850	PM217
DRS5910	M048X	DRS6950	PM094	DRS7860	PM164
DRS5930	M228	DRS6980	M289X	DRS7870	PM169
DRS5970	M310	DRS6990	M396	DRS7880	PM173
DRS5981	PM609	DRS7000	M313	DRS7890	PM063
DRS6021	PM265	DRS7020	M284	DRS7910	PM065
DRS6100	PM216	DRS7041	M270	DRS7920	M314
DRS6110	M306	DRS7050	PM218	DRS7940	PM566
DRS6190	M256	DRS7060	M317	DRS7950	M151
DRS6200	M288	DRS7070	M389	DRS7970	M288
DRS6220	PM171	DRS7090	PM139	DRS7990	PM106
DRS6230		DRS7100	PM209	DRS8000	PM211
DRS6240	M069	DRS7110	M185X	DRS8010	M143
DRS6250	PM052	DRS7120	M143	DRS8020	PM042
DRS6280		DRS7180	PM058	DRS8030	PM045
DRS6290	M248	DRS7190	PM062	DRS8040	PM071
DRS6300	M236	DRS7230	M048X	DRS8060	PM057
DRS6310	M383	DRS7240	PM105	DRS8070	M346
DRS6320	M034	DRS7250	PM213	DRS8080	RM041
DRS6330	M227	DRS7250	PM190	DRS8090	PM219
DRS6340	M394	DRS7260	M399	DRS8110	M379
DRS6370		DRS7270	PM172	DRS8180	PM066
DRS6380	M083X	DRS7280	PM177	DRS8230	M134
DRS6390		DRS7290	PM178	DRS8240	M263
DRS6431	M437	DRS7300	M037X	DRS8250	
DRS6470	M235X	DRS7310	M355	DRS8270	
DRS6520	PM189	DRS7320	PM180	DRS8290	PM096
DRS6550	PM176	DRS7330	PM032	DRS8310	M390
DRS6560	M381	DRS7381	M120X	DRS8340	

DELCO	RMA $\sqrt{Kw - !}$	DELCO	RMA $\sqrt{Kw - !}$	DELCO	RMA $\sqrt{Kw - !}$
DRS8350	RM086				
DRS8370	PM892				
DRS8380	PM082				
DRS8390	PM080				
DRS8420					
DRS8430					
DRS8440					
DRS8460					
DRS8490	PM099				
DRS8500	PM081				
DRS8571	M414				
DRS8630	PM069				
DRS8680	M397				
DRS8770	PM010				
DRS8780	RM091				
DRS8790					
DRS8800	RM087				
DRS8810	PM202				
DRS8840					
DRS8860	PM012				
DRS8870	PM016				
DRS8880	M393				
DRS8890					
DRS8930					
DRS8950	PM099				
DRS8960					
DRS8970	PM094				
DRS8990	PM107				
DRS9000	PM204				
DRS9030	M406				
DRX67095	PM105	0			
DRX67095	PM105				
DRX67095	PM105				
DRX67131	PM106	0			
DRX67149	PM105	0			
DRX67149	PM105				
DRZ5163	PM023				
DRZ5177	M412				
DRZ5178	M398				
X16478	M143	0			
ZGS00395M13	PM106				

DENSO	RMA $\sqrt{Kw - !}$	DENSO	RMA $\sqrt{Kw - !}$	DENSO	RMA $\sqrt{Kw - !}$
0280000197	PM603 $\frac{0}{\sqrt{}}$	0280002061	$\frac{0}{\sqrt{}}$	0280002932	PM780 $\frac{0}{\sqrt{}}$
0280000280	$\frac{0}{\sqrt{}}$	0280002100	$\frac{0}{\sqrt{}}$	0280002933	PM780 $\frac{0}{\sqrt{}}$
0280000322	M326 $\frac{0}{\sqrt{}}$	0280002150	M439 $\frac{0}{\sqrt{}}$	0280002970	M334X $\frac{0}{\sqrt{}}$
0280000370	PM602 $\frac{0}{\sqrt{}}$	0280002151	M439 $\frac{0}{\sqrt{}}$	0280003000	PM602 $\frac{0}{\sqrt{}}$
0280000430	PM778 $\frac{0}{\sqrt{}}$	0280002160	M334X $\frac{0}{\sqrt{}}$	0280003001	$\frac{0}{\sqrt{}}$
0280000470	M412 $\frac{0}{\sqrt{}}$	0280002161	M334X $\frac{0}{\sqrt{}}$	0280003004	$\frac{0}{\sqrt{}}$
0280000510	PM423 $\frac{0}{\sqrt{}}$	0280002164	M334X $\frac{0}{\sqrt{}}$	0280003005	PM602 $\frac{0}{\sqrt{}}$
0280000960	PM414 $\frac{0}{\sqrt{}}$	0280002220	M334X $\frac{0}{\sqrt{}}$	0280003006	$\frac{0}{\sqrt{}}$
0280001010	PM603 $\frac{0}{\sqrt{}}$	0280002240	M439 $\frac{0}{\sqrt{}}$	0280003030	$\frac{0}{\sqrt{}}$
0280001011	PM603 $\frac{0}{\sqrt{}}$	0280002241	M439 $\frac{0}{\sqrt{}}$	0280003032	$\frac{0}{\sqrt{}}$
0280001012	PM603 $\frac{0}{\sqrt{}}$	0280002250	PM415 $\frac{0}{\sqrt{}}$	0280003050	PM780 $\frac{0}{\sqrt{}}$
0280001013	PM603 $\frac{0}{\sqrt{}}$	0280002251	$\frac{0}{\sqrt{}}$	0280003051	PM780 $\frac{0}{\sqrt{}}$
0280001080	PM603 $\frac{0}{\sqrt{}}$	0280002260	PM779 $\frac{0}{\sqrt{}}$	0280003052	PM780 $\frac{0}{\sqrt{}}$
0280001082	PM603 $\frac{0}{\sqrt{}}$	0280002261	PM415 $\frac{0}{\sqrt{}}$	0280003090	PM415 $\frac{0}{\sqrt{}}$
0280001083	PM603 $\frac{0}{\sqrt{}}$	0280002262	PM415 $\frac{0}{\sqrt{}}$	0280003091	$\frac{0}{\sqrt{}}$
0280001240	PM423 $\frac{0}{\sqrt{}}$	0280002263	PM415 $\frac{0}{\sqrt{}}$	0280003100	PM415 $\frac{0}{\sqrt{}}$
0280001250	$\frac{0}{\sqrt{}}$	0280002330	PM415 $\frac{0}{\sqrt{}}$	0280003101	$\frac{0}{\sqrt{}}$
0280001370	PM778 $\frac{0}{\sqrt{}}$	0280002331	$\frac{0}{\sqrt{}}$	0280003240	$\frac{0}{\sqrt{}}$
0280001371	PM778 $\frac{0}{\sqrt{}}$	0280002360	PM778 $\frac{0}{\sqrt{}}$	0280003241	$\frac{0}{\sqrt{}}$
0280001372	PM778 $\frac{0}{\sqrt{}}$	0280002361	PM778 $\frac{0}{\sqrt{}}$	0280003290	PM782 $\frac{0}{\sqrt{}}$
0280001620	$\frac{0}{\sqrt{}}$	0280002362	PM778 $\frac{0}{\sqrt{}}$	0280003291	PM782 $\frac{0}{\sqrt{}}$
0280001621	$\frac{0}{\sqrt{}}$	0280002363	PM778 $\frac{0}{\sqrt{}}$	0280003292	PM782 $\frac{0}{\sqrt{}}$
0280001623	PM415 $\frac{0}{\sqrt{}}$	0280002364	PM778 $\frac{0}{\sqrt{}}$	0280003350	PM445 $\frac{0}{\sqrt{}}$
0280001730	PM602 $\frac{0}{\sqrt{}}$	0280002380	PM778 $\frac{0}{\sqrt{}}$	0280003360	PM783 $\frac{0}{\sqrt{}}$
0280001731	$\frac{0}{\sqrt{}}$	0280002560	PM423 $\frac{0}{\sqrt{}}$	0280003440	PM784 $\frac{0}{\sqrt{}}$
0280001740	PM602 $\frac{0}{\sqrt{}}$	0280002570	PM602 $\frac{0}{\sqrt{}}$	0280003441	PM784 $\frac{0}{\sqrt{}}$
0280001741	$\frac{0}{\sqrt{}}$	0280002571	PM602 $\frac{0}{\sqrt{}}$	0280003500	PM747 $\frac{0}{\sqrt{}}$
0280001850	M439 $\frac{0}{\sqrt{}}$	0280002572	PM602 $\frac{0}{\sqrt{}}$	0280003501	PM747 $\frac{0}{\sqrt{}}$
0280001851	$\frac{0}{\sqrt{}}$	0280002660	PM602 $\frac{0}{\sqrt{}}$	0280003600	PM415 $\frac{0}{\sqrt{}}$
0280001861	M328 $\frac{0}{\sqrt{}}$	0280002661	PM602 $\frac{0}{\sqrt{}}$	0280003601	PM415 $\frac{0}{\sqrt{}}$
0280001863	M328 $\frac{0}{\sqrt{}}$	0280002662	PM602 $\frac{0}{\sqrt{}}$	0280003602	PM415 $\frac{0}{\sqrt{}}$
0280001890	$\frac{0}{\sqrt{}}$	0280002664	$\frac{0}{\sqrt{}}$	0280003603	PM415 $\frac{0}{\sqrt{}}$
0280001891	$\frac{0}{\sqrt{}}$	0280002665	PM602 $\frac{0}{\sqrt{}}$	0280003604	PM415 $\frac{0}{\sqrt{}}$
0280001940	PM415 $\frac{0}{\sqrt{}}$	0280002670	PM602 $\frac{0}{\sqrt{}}$	0280003660	M368 $\frac{0}{\sqrt{}}$
0280001941	PM415 $\frac{0}{\sqrt{}}$	0280002680	PM602 $\frac{0}{\sqrt{}}$	0280003700	PM602 $\frac{0}{\sqrt{}}$
0280001970	PM603 $\frac{0}{\sqrt{}}$	0280002681	PM602 $\frac{0}{\sqrt{}}$	0280003701	$\frac{0}{\sqrt{}}$
0280001971	PM603 $\frac{0}{\sqrt{}}$	0280002682	PM602 $\frac{0}{\sqrt{}}$	0280003710	PM602 $\frac{0}{\sqrt{}}$
0280001972	PM603 $\frac{0}{\sqrt{}}$	0280002800	PM778 $\frac{0}{\sqrt{}}$	0280003711	$\frac{0}{\sqrt{}}$
0280001973	PM603 $\frac{0}{\sqrt{}}$	0280002801	PM778 $\frac{0}{\sqrt{}}$	0280003730	$\frac{0}{\sqrt{}}$
0280001974	PM603 $\frac{0}{\sqrt{}}$	0280002830	PM780 $\frac{0}{\sqrt{}}$	0280003730	M328 $\frac{12}{0,6}$
0280001975	PM603 $\frac{0}{\sqrt{}}$	0280002870	PM781 $\frac{0}{\sqrt{}}$	0280003740	$\frac{0}{\sqrt{}}$
0280001976	PM603 $\frac{0}{\sqrt{}}$	0280002871	PM781 $\frac{0}{\sqrt{}}$	0280003741	M137 $\frac{12}{0,8}$
0280002000	PM602 $\frac{0}{\sqrt{}}$	0280002930	PM780 $\frac{0}{\sqrt{}}$	0280003770	PM603 $\frac{0}{\sqrt{}}$
0280002001	PM602 $\frac{0}{\sqrt{}}$	0280002931	PM780 $\frac{0}{\sqrt{}}$	0280003800	M439 $\frac{0}{\sqrt{}}$

DENSO	RMA $\sqrt{Kw - !}$	DENSO	RMA $\sqrt{Kw - !}$	DENSO	RMA $\sqrt{Kw - !}$
0280003801	0	0280004250	M326X 0	0280004650	PM600 0
0280003820	PM778 0	0280004251	M326X $12/0,9$	0280004651	PM600 0
0280003821	PM778	0280004252	M326X 0	0280004680	PM600 0
0280003822	PM778 0	0280004253	M326X $12/0,9$	0280004681	PM600 0
0280003823	PM778	0280004270	PM602 0	0280004690	PM600 0
0280003824	PM778	0280004271	0	0280004691	PM600 0
0280003825	PM778 0	0280004320	M326 $12/0,9$	0280004700	PM600 0
0280003827	0	0280004321	M326 $12/0,9$	0280004701	0
0280003830	M439 0	0280004322	M326 $12/0,9$	0280004710	PM600 0
0280003840	PM780 0	0280004323	M326 $12/0,9$	0280004730	PM427 0
0280003841	PM780 0	0280004330	PM602 0	0280004750	PM602 0
0280003842	PM780 0	0280004331	PM602 0	0280004790	M329 $12/0,8$
0280003900	PM780 0	0280004332	PM602 0	0280004810	PM603 0
0280003901	PM780 0	0280004340	PM415 0	0280004811	PM603 0
0280003910	0	0280004341	PM415 0	0280004812	PM603 0
0280003910	0	0280004342	PM415 0	0280004851	M326 0
0280003920	PM780 0	0280004343	PM415 0	0280004900	M326 $12/0,9$
0280003921	PM780 0	0280004350	M326X	0280004940	M326 $12/0,9$
0280003950	PM602 0	0280004351	M326X	0280004950	M326 0
0280003960	PM602 0	0280004440	PM602 0	0280004951	M326X $12/0,9$
0280004000	PM416 0	0280004480	0	0280004980	M128 0
0280004001	PM416 $12/1,0$	0280004490	PM602 0	0280004990	PM428
0280004010	M130 $12/1,0$	0280004491	PM602 0	0280005040	PM782
0280004011	M130 $12/1,0$	0280004500	PM780 0	0280005050	PM276
0280004020	PM416 0	0280004501	0	0280005060	PM276 0
0280004021	PM416 0	0280004510	PM416 0	0280005061	0
0280004022	PM416 0	0280004512	PM416 0	0280005100	M326 $12/0,9$
0280004023	PM416 0	0280004520	M438	0280005110	M326 $12/0,9$
0280004024	PM416 0	0280004530	M369 0	0280005120	M128X $12/1,0$
0280004030	PM600 0	0280004532	PM415 0	0280005120	M128X $12/1,0$
0280004031	PM600 0	0280004540	M326 $12/0,9$	0280005140	M326X
0280004032	PM600 0	0280004541	M326 $12/0,9$	0280005170	M127 $12/0,8$
0280004040	PM600 0	0280004543	M326 0	0280005200	0
0280004041	PM600 0	0280004550	M130 $12/1,0$	0280005201	0
0280004042	PM600 0	0280004550	M130 $12/1,0$	0280005210	
0280004050	PM600 0	0280004580	M128 0	0280005210	0
0280004090	PM741 0	0280004600	PM600 0	0280005210	M043
0280004160	0	0280004601	PM600 0	0280005240	M130 $12/1,0$
0280004200	PM428	0280004610	M130	0280005290	M439 $12/0,8$
0280004210	0	0280004611	0	0280005300	PM417 0
0280004240	M326 $12/0,9$	0280004620	0	0280005330	PM785 0
0280004241	M326 $12/0,9$	0280004630	PM780 0	0280005331	PM785 0
0280004242	M326 $12/0,9$	0280004631	PM780 0	0280005332	PM785 0
0280004243	M326 $12/0,9$	0280004640	PM780 0	0280005333	PM785 0

DENSO	RMA $V_{Kw} -!$	DENSO	RMA $V_{Kw} -!$	DENSO	RMA $V_{Kw} -!$
0280005334	PM785 0	0280005910	PM424 0	0280006396	PM780 0
0280005335	PM785 0	0280005911	PM424 0	0280006420	PM602 0
0280005360	M329 12 0,8	0280005912	PM424 0	0280006421	PM602 0
0280005361	12 0,8	0280005990	0	0280006422	PM602 0
0280005400	M159 12 0,7 15a	0280005991	0	0280006430	PM780 0
0280005401	M159 12 0,7 15a	0280005992	PM416 0	0280006440	PM432 0
0280005410	M043 12 1,0	0280006000	PM425 0	0280006441	0
0280005410	M043 12 1,0	0280006001	PM425 0	0280006490	PM600 0
0280005430	M128 0	0280006001	PM425 0	0280006491	PM600 0
0280005470	M128 0	0280006010	PM422	0280006492	PM600 0
0280005500	0	0280006011	PM422	0280006493	PM600 0
0280005510	0	0280006012	PM422	0280006494	PM600 0
0280005530	M370 0	0280006013	PM422	0280006495	PM600 0
0280005550	M370 24 3,1	0280006030	M128X 12 1,0	0280006500	PM364 0
0280005551	M370 24 3,1	0280006030	M128X 12 1,0	0280006510	M328 12 0,6
0280005560	PM786 0	0280006031	M128X 12 1,0	0280006511	M328 12 0,6
0280005580	PM419	0280006031	M128X 12 1,0	0280006520	PM787 0
0280005581	PM419 0	0280006040	M128X 12 1,0	0280006530	PM788 0
0280005600	0	0280006040	M128X 12 1,0	0280006540	PM364 0
0280005620	M370 0	0280006041	M128X 0	0280006550	PM364 0
0280005690	M370 0	0280006041	M128X 0	0280006551	0
0280005710	0	0280006050	PM283 0	0280006560	PM672
0280005720	M127 12 0,8	0280006100	PM435 0	0280006561	PM672
0280005730	PM420 0	0280006103	PM435 0	0280006600	M128 12 1,0
0280005740	M439 12 0,8	0280006140	PM426 0	0280006601	M128 0
0280005750	M127 12 0,8	0280006200	PM279 0	0280006610	PM294
0280005751	M127 12 0,8	0280006220	0	0280006620	M130 12 1,0
0280005800	PM421 0	0280006250	PM427 0	0280006621	M130 12 1,0
0280005820	PM416	0280006260	PM428 0	0280006700	M128X 12 1,0
0280005821	PM416 0	0280006261	PM428	0280006700	M128X 12 1,0
0280005822	PM416 0	0280006280	PM839 0	0280006701	M128X 12 1,0
0280005860	PM422 0	0280006290	PM429 0	0280006701	M128X 12 1,0
0280005861	PM422 0	0280006291	PM429 0	0280006710	M128X 12 1,0
0280005862	PM422 0	0280006300	PM430 0	0280006710	M128X 12 1,0
0280005863	PM422 0	0280006330	M334X 12 0,6	0280006711	M128X 12 1,0
0280005870	PM429 0	0280006360	PM425 0	0280006711	M128X 12 1,0
0280005880	PM262 0	0280006361	PM425 0	0280006720	PM283 0
0280005881	PM262	0280006362	PM425 0	0280006721	PM283 0
0280005882	PM262	0280006390	0	0280006790	PM785 0
0280005883	PM262	0280006391	PM780 0	0280006800	0
0280005884	PM262	0280006392	0	0280006801	PM602 0
0280005890	PM433	0280006393	PM780 0	0280006810	PM602 0
0280005891	PM433	0280006394	0	0280006811	PM602 0
0280005900	PM423 0	0280006395	0	0280006812	PM602 0

DENSO	RMA $V_{Kw -!}$	DENSO	RMA $V_{Kw -!}$	DENSO	RMA $V_{Kw -!}$
0280006813	PM602 0/	0280007121	M076 12/ 0,8	0280007470	PM747 0/
0280006820	PM603 0/	0280007121	M082 12/ 0,8	0280007471	PM747 0/
0280006821	PM603 0/	0280007131	PM790 /	0280007520	PM603 0/
0280006822	PM603 0/	0280007132	PM790 /	0280007521	PM603 0/
0280006823	PM603 0/	0280007133	PM790 /	0280007530	PM602 0/
0280006860	PM419 0/	0280007170	PM791 0/	0280007550	PM416 0/
0280006870	PM419 0/	0280007171	PM791 /	0280007551	0/
0280006871	PM419 0/	0280007172	PM791 /	0280007560	PM423 0/
0280006880	PM419 0/	0280007190	M130 12/ 1,0	0280007561	PM423 /
0280006881	PM419 0/	0280007191	M130 12/ 1,0	0280007570	PM416 /
0280006890	PM419 0/	0280007210	M128 12/ 1,0	0280007580	PM459 0/
0280006891	PM419 0/	0280007220	PM792 /	0280007581	PM459 0/
0280006892	PM419 0/	0280007221	PM792 0/	0280007590	0/
0280006892	PM419 /	0280007222	PM792 /	0280007600	PM351 0/
0280006893	PM419 /	0280007230	PM792 0/	0280007620	PM435 0/
0280006910	PM419 0/	0280007231	PM792 0/	0280007621	PM435 0/
0280006920	PM782 /	0280007240	PM433 0/	0280007640	PM420 /
0280006921	PM782 /	0280007241	PM433 0/	0280007650	M128 /
0280006930	M326 12/ 0,9	0280007242	PM433 0/	0280007650	M128 0/
0280006960	PM431 0/	0280007260	M329 12/ 0,8	0280007650	PM351 /
0280006961	PM431 0/	0280007270	M329 12/ 0,8	0280007651	PM293 0/
0280006962	PM431 0/	0280007272	0/	0280007660	PM419 0/
0280006970	PM431 /	0280007290	M127 12/ 0,8	0280007680	0/
0280006980	PM431 /	0280007300	PM793 /	0280007681	0/
0280007000	PM432 0/	0280007301	PM793 /	0280007700	M128X 0/
0280007001	PM432 0/	0280007307	M335 /	0280007711	M159 12/ 0,7 15a
0280007002	PM432 /	0280007320	PM434 0/	0280007711	M159 12/ 0,7 15a
0280007003	PM432 /	0280007321	PM434 0/	0280007720	PM788 0/
0280007004	PM432 /	0280007331	PM789 0/	0280007760	PM787 0/
0280007073	0/	0280007332	PM789 0/	0280007780	0/
0280007090	0/	0280007350	0/	0280007790	PM432 0/
0280007091	PM600 0/	0280007370	M335 12/ 2,0	0280007791	PM432 0/
0280007092	PM600 0/	0280007372	M335 12/ 2,0	0280007792	PM110 /
0280007093	PM600 0/	0280007373	M335 12/ 2,0	0280007810	PM433 0/
0280007100	PM789 0/	0280007380	PM434 0/	0280007820	0/
0280007101	PM789 0/	0280007390	PM434 0/	0280007830	PM436 0/
0280007102	PM789 0/	0280007391	PM434 0/	0280007911	0/
0280007110	M082 12/ 0,8	0280007392	PM434 0/	0280007980	PM601 0/
0280007110	M076 12/ 0,8	0280007430	PM794 /	0280007981	PM601 0/
0280007110	M082 12/ 0,8	0280007431	PM794 /	0280007990	PM293 12/ 1,0
0280007111	M082 12/ 0,8	0280007440	M329 12/ 0,8	0280007990	PM293 12/ 1,0
0280007111	M082 12/ 0,8	0280007460	PM747 0/	0280007991	0/
0280007120	M076 12/ 0,8	0280007461	PM747 0/	0280007992	PM434 0/
0280007120	M082 12/ 0,8	0280007462	PM747 0/	0280008000	M130 12/ 1,0

DENSO RMA $V_{Kw} -!$

0280008001	0
0280008010	PM293 $12_{1,0}$
0280008010L	0
0280008011	0
0280008040	0
0280008050	PM431 0
0280008051	PM431 0
0280008060	PM437 0
0280008061	PM437 0
0280008070	PM419 0
0280008071	PM419 0
0280008072	PM419
0280008160	M128 $12_{1,0}$
0280008180	M128X $12_{1,0}$
0280008181	0
0280008200	PM476 0
0280008220	PM437 0
0280008230	PM795
0280008320	M438X 0
0280008321	M438X
0280008322	M438X
0280008370	PM466 0
0280008371	PM466 0
0280008380	PM440 0
0280008400	PM441 0
0280008401	PM441
0280008403	PM441
0280008404	PM441
0280008410	PM654
0280008411	PM654
0280008430	PM442 0
0280008431	PM442
0280008432	PM442
0280008440	PM424 0
0280008451	PM443 0
0280008460	M128 0
0280008570	PM364 0
0280008571	0
0280008580	PM351 0
0280008581	PM351 0
0280008590	PM788 0
0280008620	PM533 0
0280008621	0
0280008670	M130 $12_{1,0}$

DENSO RMA $V_{Kw} -!$

0280008671	0
0280008690	PM293 0
0280008700	PM293 0
0280008730	M328 $12_{0,6}$
0280008760	M335 $12_{2,0}$
0280008761	M335 $12_{2,0}$
0280008762	M335 $12_{2,0}$
0280008770	PM293 0
0280008780	PM788 0
0280008890	M439
0280008920	PM600 0
0280008921	PM600 0
02800089220	M328
02800089221	M328
0280008941	0
0280008951	0
0280008980	PM443 0
0280008990	0
0280009000	PM437 0
0280009010	PM603 0
0280009020	PM602 0
0280009030	PM485 0
0280009031	PM485
0280009032	PM485
0280009070	PM437 0
0280009071	PM437 0
0280009080	PM787
0280009090	M328 $12_{0,6}$
0280009091	M328 $12_{0,6}$
0280009112	PM785 0
0280009120	M432 0
0280009121	M432 0
0280009181	M329 $12_{0,8}$
0280009220	M328 $12_{0,6}$
0280009221	M328 $12_{0,6}$
0280009260	PM444 0
0280009261	PM444 0
0280009270	PM416 0
0280009271	0
0280009320	PM294 0
0280009321	PM294 0
0280009330	M370
0280009331	M370
0280009380	PM445 0

DENSO RMA $V_{Kw} -!$

0280009381	PM444 0
0280009430	0
0280009470	M444 0
0280009490	M129 $12_{0,8}$
0280009500	M337 $12_{0,8}$
0280009501	M337 $12_{0,8}$
0280009510	PM446 0
0280009570	PM747
0280009580	M432 0
0280009592	M335
0280009670	PM466
0280009680	PM796 0
0280009690	PM601 0
0280009710	PM434 0
0280009711	PM434 0
0280009720	PM796 0
0280009730	PM797
0280009760	PM798
0280009770	PM799
0280009800	PM364 0
0280009801	0
0280009810	PM788 0
0280009811	0
0280009820	PM447 0
0280009830	PM448 0
0280009831	PM448
0280009860	PM415 0
0280009861	0
0280009900	M446 0
0280009901	M446 0
0280009902	M446 0
0280009940	M334 0
0280009960	PM789 0
1280000020	PM432 0
1280000040	PM400 0
1280000050	M438 0
1280000070	PM427
1280000071	PM427
1280000101	PM425 0
1280000102	PM425 0
1280000110	PM420
1280000111	PM420 0
1280000120	M432 0
1280000130	PM294 0

DENSO RMA $\sqrt{\text{Kw}} -!$

1280000131	0
1280000140	PM436
1280000141	PM436 0
1280000170	PM428 0
1280000171	PM428 0
1280000180	PM428
1280000181	PM428
1280000220	PM444 0
1280000260	M438
1280000261	M438
1280000280	M194 $12/1,0$
1280000280	M194 $12/1,0$
1280000281	0
1280000290	PM287 $12/1,0$
1280000291	0
1280000300	PM295 0
1280000301	0
1280000350	M211 $12/0,8$
1280000351	M211 $12/0,8$
1280000360	M335 0
1280000370	M128 0
1280000450	PM466 0
1280000461	M425X 0
1280000462	M425X 0
1280000471	M412
1280000472	M412
1280000490	PM670
1280000491	PM670
1280000492	PM670
1280000520	PM419
1280000530	M370
1280000560	PM443 0
1280000561	PM443 0
1280000570	PM449 0
1280000590	PM450 0
1280000591	PM450 0
1280000600	M446 0
1280000620	PM416 0
1280000621	PM416 0
1280000622	PM416 0
1280000670	PM287 $12/1,0$
1280000671	0
1280000690	M442 0
1280000700	M130 $12/1,0$

DENSO RMA $\sqrt{\text{Kw}} -!$

1280000710	PM420 0
1280000720	PM421 0
1280000721	PM421
1280000740	PM420
1280000770	PM782
1280000771	PM782
1280000772	PM782
1280000830	PM268 0
1280000930	PM443 0
1280000960	PM428 0
1280000971	PM800
1280000972	PM800
1280000973	PM800
1280001000	PM801
1280001001	PM801
1280001002	PM801
1280001040	PM452 0
1280001041	PM452 0
1280001060	PM414 0
1280001070	PM459 0
1280001150	PM453
1280001151	PM453 0
1280001152	PM453
1280001160	PM428
1280001161	PM428
1280001180	PM454 0
1280001181	PM454 0
1280001200	PM788 0
1280001210	PM788 0
1280001220	PM351 0
1280001221	0
1280001230	PM364 0
1280001231	0
1280001240	PM423
1280001241	PM423 0
1280001250	PM416 0
1280001251	PM416 0
1280001290	0
1280001291	0
1280001300	PM676 0
1280001301	0
1280001310	0
1280001350	PM796 0
1280001351	0

DENSO RMA $\sqrt{\text{Kw}} -!$

1280001360	M260 $12/1,4$
1280001360	M260 $12/1,4$
1280001370	PM455 0
1280001371	PM455 0
1280001440	PM456 0
1280001441	PM456 0
1280001490	PM802
1280001491	PM802
1280001520	PM444 0
1280001540	M328 $12/0,6$
1280001541	M328 0
1280001560	PM023 0
1280001561	PM023 0
1280001570	PM457 0
1280001571	PM457 0
1280001574	PM457 0
1280001610	PM796 0
1280001620	M325 $12/0,8$
1280001621	M325 $12/0,8$
1280001630	PM445 0
1280001660	0
1280001700	0
1280001790	PM458 0
1280001860	M328 0
1280001861	M328 $12/0,6$
1280001862	M328 $12/0,6$
1280001863	M328 0
1280001890	M211 $12/0,8$
1280001900	PM459 0
1280001901	PM459 0
1280001930	M334 $12/0,6$
1280001950	M334 0
1280002040	PM459 0
1280002041	PM459 0
1280002050	PM796 0
1280002060	PM796 0
1280002130	M422 0
1280002131	M422 0
1280002190	PM295 0
1280002210	PM446 0
1280002250	0
1280002280	PM449 0
1280002380	PM791 0
1280002420	PM459

DENSO	RMA $V_{Kw} -!$	DENSO	RMA $V_{Kw} -!$	DENSO	RMA $V_{Kw} -!$
1280002421	PM459	1280003381	PM461	1280004520	PM807
1280002430	PM459	1280003470	PM462	1280004530	M129
1280002431	PM459	1280003471	PM462	1280004531	M129
1280002540	PM788	1280003472	PM462	1280004532	M129
1280002550	M211	1280003480	M440	1280004540	M076
1280002551	M211	1280003481	M440	1280004540	M082
1280002570	PM791	1280003482	M440	1280004560	PM785
1280002580	PM022	1280003500	PM023	1280004570	PM465
1280002581	PM022	1280003590	M438X	1280004571	PM465
1280002590		1280003621	M444	1280004660	PM432
1280002591		1280003641	M328	1280004661	PM432
1280002600	PM296	1280003662	M444	1280004662	PM432
1280002610	PM600	1280003730	PM558	1280004670	PM676
1280002611	PM600	1280003740	M137	1280004720	PM463
1280002621		1280003741	M137	1280004861	PM808
1280002640		1280003810	PM446	1280004862	PM808
1280002660	M190	1280003840	M440	1280004880	M442
1280002670	M137	1280004010	M334	1280004890	M076
1280002680	PM460	1280004020	PM805	1280004890	M082
1280002682	PM460	1280004030	M328	1280004891	M076
1280002750	PM803	1280004031	M328	1280004900	PM426
1280002790	M137	1280004060	M334	1280004910	PM809
1280002800	M211	1280004080	PM463	1280004930	PM416
1280002820	M128	1280004081	PM463	1280004950	PM810
1280002830	PM336	1280004082	PM463	1280004951	PM810
1280002831		1280004083	PM463	1280004960	PM811
1280002860	M446	1280004110	PM800	1280004970	PM812
1280002861	M446	1280004111	PM800	1280005080	M194
1280002862	M446	1280004112	PM800	1280005080	M194
1280002880	PM432	1280004200	M328	1280005081	
1280002881	PM432	1280004201	M328	1280005090	PM799
1280002950	PM654	1280004230	M134	1280005091	PM799
1280003080	PM458	1280004270	PM676	1280005110	PM295
1280003081	PM458	1280004271		1280005161	M337
1280003082	PM458	1280004340	PM794	1280005230	PM287
1280003090	M325X	1280004390	PM464	1280005261	M438X
1280003091	M325X	1280004391	PM464	1280005270	PM813
1280003180	PM804	1280004420	PM015	1280005280	PM813
1280003181	PM804	1280004420	PM015	1280005300	PM799
1280003182	PM804	1280004420	PM015	1280005301	PM799
1280003190	PM295	1280004430	M442	1280005330	PM794
1280003340	PM444	1280004450	M442	1280005331	PM794
1280003350	PM445	1280004461	PM806	1280005340	PM469
1280003380	PM461	1280004480	PM460	1280005350	PM466

DENSO	RMA $\sqrt{\text{Kw}} -!$	DENSO	RMA $\sqrt{\text{Kw}} -!$	DENSO	RMA $\sqrt{\text{Kw}} -!$
1280005350	PM466 $\frac{0}{\text{ }}$	1280005951	M440 $\frac{0}{\text{ }}$	1280007090	PM444 $\frac{0}{\text{ }}$
1280005410	PM814 $\frac{\text{ }}$	1280005952	M440 $\frac{0}{\text{ }}$	1280007100	PM445 $\frac{0}{\text{ }}$
1280005411	PM814 $\frac{\text{ }}$	1280005980	M442 $\frac{0}{\text{ }}$	1280007110	PM819 $\frac{0}{\text{ }}$
1280005560	PM467 $\frac{0}{\text{ }}$	1280006060	PM431 $\frac{\text{ }}$	1280007121	PM465 $\frac{\text{ }}$
1280005561	PM467 $\frac{0}{\text{ }}$	1280006170	PM457 $\frac{0}{\text{ }}$	1280007122	PM465 $\frac{\text{ }}$
1280005570	PM467 $\frac{\text{ }}$	1280006210	M446 $\frac{0}{\text{ }}$	1280007140	M412 $\frac{0}{\text{ }}$
1280005571	PM467 $\frac{\text{ }}$	1280006211	M446 $\frac{0}{\text{ }}$	1280007141	M412 $\frac{\text{ }}$
1280005580	PM467 $\frac{\text{ }}$	1280006212	M446 $\frac{0}{\text{ }}$	1280007190	M437 $\frac{0}{\text{ }}$
1280005581	PM468 $\frac{0}{\text{ }}$	1280006230	PM430 $\frac{0}{\text{ }}$	1280007190	M437 $\frac{0}{\text{ }}$
1280005620	PM794 $\frac{\text{ }}$	1280006240	PM430 $\frac{0}{\text{ }}$	1280007191	M437 $\frac{0}{\text{ }}$
1280005621	PM794 $\frac{\text{ }}$	1280006280	PM427 $\frac{0}{\text{ }}$	1280007200	PM364 $\frac{0}{\text{ }}$
1280005630	PM459 $\frac{0}{\text{ }}$	1280006300	PM430 $\frac{0}{\text{ }}$	1280007201	PM364 $\frac{\text{ }}$
1280005631	$\frac{0}{\text{ }}$	1280006330	PM419 $\frac{0}{\text{ }}$	1280007280	PM457 $\frac{0}{\text{ }}$
1280005640	$\frac{0}{\text{ }}$	1280006340	PM472 $\frac{0}{\text{ }}$	1280007281	PM457 $\frac{0}{\text{ }}$
1280005650	M129 $\frac{12}{0,8}$	1280006341	PM472 $\frac{0}{\text{ }}$	1280007282	PM457 $\frac{0}{\text{ }}$
1280005680	PM460 $\frac{0}{\text{ }}$	1280006391	PM794 $\frac{\text{ }}$	1280007283	PM457 $\frac{0}{\text{ }}$
1280005681	PM460 $\frac{0}{\text{ }}$	1280006420	PM460 $\frac{0}{\text{ }}$	1280007350	M335 $\frac{12}{2,0}$
1280005682	PM460 $\frac{0}{\text{ }}$	1280006421	PM460 $\frac{0}{\text{ }}$	1280007353	M335 $\frac{12}{2,0}$
1280005690	PM465 $\frac{0}{\text{ }}$	1280006422	PM460 $\frac{0}{\text{ }}$	1280007360	PM419 $\frac{0}{\text{ }}$
1280005691	PM465 $\frac{0}{\text{ }}$	1280006560	PM465 $\frac{\text{ }}$	1280007361	PM419 $\frac{0}{\text{ }}$
1280005700	PM469 $\frac{0}{\text{ }}$	1280006690	$\frac{12}{0,8}$	1280007362	PM419 $\frac{0}{\text{ }}$
1280005701	PM469 $\frac{0}{\text{ }}$	1280006720	PM424 $\frac{0}{\text{ }}$	1280007380	PM820 $\frac{\text{ }}$
1280005710	PM469 $\frac{\text{ }}$	1280006721	PM424 $\frac{0}{\text{ }}$	1280007381	PM820 $\frac{\text{ }}$
1280005720	PM815 $\frac{\text{ }}$	1280006750	PM473 $\frac{0}{\text{ }}$	1280007382	PM820 $\frac{\text{ }}$
1280005721	PM815 $\frac{\text{ }}$	1280006780	PM474 $\frac{0}{\text{ }}$	1280007383	PM820 $\frac{\text{ }}$
1280005722	PM815 $\frac{\text{ }}$	1280006810	PM419 $\frac{0}{\text{ }}$	1280007390	M440 $\frac{0}{\text{ }}$
1280005723	PM815 $\frac{\text{ }}$	1280006811	PM419 $\frac{0}{\text{ }}$	1280007400	PM465 $\frac{\text{ }}$
1280005730	PM816 $\frac{0}{\text{ }}$	1280006830	PM419 $\frac{0}{\text{ }}$	1280007460	PM298 $\frac{0}{\text{ }}$
1280005731	PM816 $\frac{0}{\text{ }}$	1280006831	PM419 $\frac{0}{\text{ }}$	1280007470	PM693 $\frac{\text{ }}$
1280005732	PM816 $\frac{0}{\text{ }}$	1280006832	PM419 $\frac{0}{\text{ }}$	1280007471	PM693 $\frac{0}{\text{ }}$
1280005733	PM816 $\frac{\text{ }}$	1280006833	PM419 $\frac{0}{\text{ }}$	1280007480	PM821 $\frac{\text{ }}$
1280005760	PM258 $\frac{0}{\text{ }}$	1280006870	PM817 $\frac{\text{ }}$	1280007500	PM023 $\frac{0}{\text{ }}$
1280005780	PM015 $\frac{0}{\text{ }}$	1280006960	PM431 $\frac{\text{ }}$	1280007560	PM459 $\frac{0}{\text{ }}$
1280005780	PM015 $\frac{0}{\text{ }}$	1280006961	PM431 $\frac{\text{ }}$	1280007561	PM459 $\frac{\text{ }}$
1280005780	PM015 $\frac{0}{\text{ }}$	1280006962	PM431 $\frac{\text{ }}$	1280007562	PM459 $\frac{\text{ }}$
1280005781	PM015 $\frac{0}{\text{ }}$	1280006970	PM676 $\frac{0}{\text{ }}$	1280007600	PM110 $\frac{0}{\text{ }}$
1280005840	PM470 $\frac{0}{\text{ }}$	1280006971	$\frac{0}{\text{ }}$	1280007601	PM110 $\frac{0}{\text{ }}$
1280005850	PM471 $\frac{0}{\text{ }}$	1280006980	PM431 $\frac{\text{ }}$	1280007602	PM110 $\frac{0}{\text{ }}$
1280005930	PM023 $\frac{0}{\text{ }}$	1280006990	PM465 $\frac{0}{\text{ }}$	1280007603	PM110 $\frac{0}{\text{ }}$
1280005940	M440 $\frac{0}{\text{ }}$	1280007000	PM465 $\frac{\text{ }}$	1280007604	PM110 $\frac{\text{ }}$
1280005941	PM462 $\frac{0}{\text{ }}$	1280007002	PM465 $\frac{\text{ }}$	1280007680	PM470 $\frac{0}{\text{ }}$
1280005941	M440 $\frac{0}{\text{ }}$	1280007010	PM459 $\frac{0}{\text{ }}$	1280007701	PM447 $\frac{\text{ }}$
1280005942	M440 $\frac{0}{\text{ }}$	1280007030	PM448 $\frac{0}{\text{ }}$	1280007710	PM286 $\frac{12}{1,0}$
1280005950	M440 $\frac{0}{\text{ }}$	1280007080	PM818 $\frac{\text{ }}$	1280007710	PM286 $\frac{12}{1,0}$

DENSO	RMA $\frac{V}{Kw -!}$	DENSO	RMA $\frac{V}{Kw -!}$	DENSO	RMA $\frac{V}{Kw -!}$
1280007711	PM286 $\frac{0}{12, 1,0}$	1280008660	M190 $\frac{12}{1,0}$	1280009800	PM794 $\frac{0}{12, 1,0}$
1280007712	PM286 $\frac{0}{12, 1,0}$	1280008670	$\frac{0}{12, 1,0}$	1280009801	PM794 $\frac{0}{12, 1,0}$
1280007713	PM286 $\frac{12}{1,0}$	1280008690	M134 $\frac{12}{0,8}$	1280009820	PM830 $\frac{0}{12, 1,0}$
1280007714	PM286 $\frac{0}{12, 1,0}$	1280008690	M137 $\frac{12}{0,8}$	1280009860	PM481 $\frac{0}{12, 1,0}$
1280007750	PM672 $\frac{0}{12, 1,0}$	1280008780	PM465 $\frac{0}{12, 1,0}$	1280009870	PM482 $\frac{0}{12, 1,0}$
1280007810	PM811 $\frac{0}{12, 1,0}$	1280008784	PM465 $\frac{0}{12, 1,0}$	1280009880	PM481 $\frac{0}{12, 1,0}$
1280007912	$\frac{0}{12, 1,0}$	1280008870	$\frac{0}{12, 1,0}$	1280009890	PM481 $\frac{0}{12, 1,0}$
1280007920	PM419 $\frac{0}{12, 1,0}$	1280008871	$\frac{0}{12, 1,0}$	1280009950	M438X $\frac{0}{12, 1,0}$
1280007921	PM419 $\frac{0}{12, 1,0}$	1280008890	PM828 $\frac{0}{12, 1,0}$	1280009970	PM831 $\frac{0}{12, 1,0}$
1280007922	PM419 $\frac{0}{12, 1,0}$	1280008891	PM828 $\frac{0}{12, 1,0}$	1280009971	PM831 $\frac{0}{12, 1,0}$
1280007923	PM419 $\frac{0}{12, 1,0}$	1280008990	M134 $\frac{12}{0,8}$	1280009972	PM831 $\frac{0}{12, 1,0}$
1280007990	M440 $\frac{0}{12, 1,0}$	1280009050	M438 $\frac{0}{12, 1,0}$	2280000110	PM420 $\frac{0}{12, 1,0}$
1280008030	PM023 $\frac{0}{12, 1,0}$	1280009051	M438 $\frac{0}{12, 1,0}$	2280000111	PM420 $\frac{0}{12, 1,0}$
1280008070	PM475 $\frac{0}{12, 1,0}$	1280009190	PM477 $\frac{0}{12, 1,0}$	2280000140	PM420 $\frac{0}{12, 1,0}$
1280008101	PM822 $\frac{0}{12, 1,0}$	1280009191	PM477 $\frac{0}{12, 1,0}$	2280000141	PM420 $\frac{0}{12, 1,0}$
1280008110	PM823 $\frac{0}{12, 1,0}$	1280009220	PM480 $\frac{0}{12, 1,0}$	2280000200	PM466 $\frac{0}{12, 1,0}$
1280008111	PM823 $\frac{0}{12, 1,0}$	1280009260	$\frac{0}{12, 1,0}$	2280000210	M194 $\frac{12}{1,0}$
1280008130	PM824 $\frac{0}{12, 1,0}$	1280009300	PM471 $\frac{0}{12, 1,0}$	2280000210	M194 $\frac{12}{1,0}$
1280008140	$\frac{0}{12, 1,0}$	1280009330	M130 $\frac{0}{12, 1,0}$	2280000211	M194 $\frac{12}{1,0}$
1280008141	$\frac{0}{12, 1,0}$	1280009360	PM829 $\frac{0}{12, 1,0}$	2280000211	M194 $\frac{12}{1,0}$
1280008170	PM822 $\frac{0}{12, 1,0}$	1280009380	M412 $\frac{0}{12, 1,0}$	2280000220	PM832 $\frac{0}{12, 1,0}$
1280008171	PM822 $\frac{0}{12, 1,0}$	1280009470	PM473 $\frac{0}{12, 1,0}$	2280000250	PM420 $\frac{0}{12, 1,0}$
1280008200	PM476 $\frac{0}{12, 1,0}$	1280009500	PM471 $\frac{0}{12, 1,0}$	2280000270	PM457 $\frac{0}{12, 1,0}$
1280008210	PM477 $\frac{0}{12, 1,0}$	1280009520	PM471 $\frac{0}{12, 1,0}$	2280000311	PM015 $\frac{0}{12, 1,0}$
1280008220	PM825 $\frac{0}{12, 1,0}$	1280009540	PM287 $\frac{0}{12, 1,0}$	2280000340	PM471 $\frac{0}{12, 1,0}$
1280008240	PM423 $\frac{0}{12, 1,0}$	1280009550	PM443 $\frac{0}{12, 1,0}$	2280000351	PM419 $\frac{0}{12, 1,0}$
1280008270	PM462 $\frac{0}{12, 1,0}$	1280009580	PM419 $\frac{0}{12, 1,0}$	2280000360	PM833 $\frac{0}{12, 1,0}$
1280008310	M437 $\frac{0}{12, 1,0}$	1280009581	PM419 $\frac{0}{12, 1,0}$	2280000361	PM833 $\frac{0}{12, 1,0}$
1280008311	M437 $\frac{0}{12, 1,0}$	1280009582	PM419 $\frac{0}{12, 1,0}$	2280000400	M335 $\frac{0}{12, 1,0}$
1280008311	M437 $\frac{0}{12, 1,0}$	1280009590	M335 $\frac{12}{2,0}$	2280000410	PM465 $\frac{0}{12, 1,0}$
1280008312	M437 $\frac{0}{12, 1,0}$	1280009591	M335 $\frac{12}{2,0}$	2280000420	PM462 $\frac{0}{12, 1,0}$
1280008320	PM364 $\frac{0}{12, 1,0}$	1280009592	M335 $\frac{12}{2,0}$	2280000440	PM445 $\frac{0}{12, 1,0}$
1280008321	PM364 $\frac{0}{12, 1,0}$	1280009610	PM463 $\frac{0}{12, 1,0}$	2280000450	PM466 $\frac{0}{12, 1,0}$
1280008350	PM015 $\frac{0}{12, 1,0}$	1280009680	PM782 $\frac{0}{12, 1,0}$	2280000460	PM466 $\frac{0}{12, 1,0}$
1280008360	PM015 $\frac{0}{12, 1,0}$	1280009700	PM679 $\frac{0}{12, 1,0}$	2280000470	M412 $\frac{0}{12, 1,0}$
1280008400	M440 $\frac{0}{12, 1,0}$	1280009701	PM679 $\frac{0}{12, 1,0}$	2280000471	M412 $\frac{0}{12, 1,0}$
1280008480	PM826 $\frac{0}{12, 1,0}$	1280009702	PM679 $\frac{0}{12, 1,0}$	2280000472	M412 $\frac{0}{12, 1,0}$
1280008500	PM015 $\frac{0}{12, 1,0}$	1280009710	M440 $\frac{0}{12, 1,0}$	2280000473	M412 $\frac{0}{12, 1,0}$
1280008530	M325 $\frac{12}{0,8}$	1280009720	M440 $\frac{0}{12, 1,0}$	2280000570	PM419 $\frac{0}{12, 1,0}$
1280008531	M325 $\frac{12}{0,8}$	1280009730	PM416 $\frac{0}{12, 1,0}$	2280000571	PM419 $\frac{0}{12, 1,0}$
1280008560	PM827 $\frac{0}{12, 1,0}$	1280009740	PM416 $\frac{0}{12, 1,0}$	2280000572	PM419 $\frac{0}{12, 1,0}$
1280008620	PM479 $\frac{0}{12, 1,0}$	1280009750	PM694 $\frac{0}{12, 1,0}$	2280000573	PM419 $\frac{0}{12, 1,0}$
1280008621	PM479 $\frac{0}{12, 1,0}$	1280009751	PM694 $\frac{0}{12, 1,0}$	2280000574	PM419 $\frac{0}{12, 1,0}$
1280008650	M134 $\frac{12}{0,8}$	1280009752	PM694 $\frac{0}{12, 1,0}$	2280000575	PM419 $\frac{0}{12, 1,0}$

DENSO	RMA $V_{Kw -!}$	DENSO	RMA $V_{Kw -!}$	DENSO	RMA $V_{Kw -!}$
2280000640	M335X $0/$	2280001540	M134 $12_{0,8}$	2280002630	PM229 $0/$
2280000661	PM834 $/$	2280001590	PM419 $/$	2280002640	PM821 $/$
2280000662	PM834 $0/$	2280001600	PM479 $0/$	2280002690	M335X $0/$
2280000663	PM834 $/$	2280001601	PM479 $0/$	2280002730	PM848 $/$
2280000664	PM834 $/$	2280001610	PM836 $/$	2280002740	PM492 $0/$
2280000691	PM485 $0/$	2280001611	PM836 $/$	2280002750	PM849 $/$
2280000710	PM465 $/$	2280001661	PM419 $0/$	2280002831	PM476 $0/$
2280000790	M438X $0/$	2280001690	PM837 $/$	2280002840	PM476 $/$
2280000791	M438X $/$	2280001700	PM838 $/$	2280002841	PM476 $/$
2280000800	M438X $0/$	2280001710	PM015 $0/$	2280002850	PM476 $0/$
2280000810	PM679 $/$	2280001840	PM839 $/$	2280002851	PM476 $0/$
2280000820	M428X $0/$	2280001880	PM822 $/$	2280002860	PM493 $0/$
2280000821	M428X $0/$	2280001881	PM822 $/$	2280002880	PM444 $/$
2280000822	M428X $0/$	2280001890	PM681 $/$	2280002890	PM494 $0/$
2280000830	M428 $0/$	2280001891	PM681 $/$	2280002900	PM488 $0/$
2280000831	M428 $/$	2280001892	PM681 $/$	2280002940	PM487 $0/$
2280000832	M428 $0/$	2280001900	PM481 $0/$	2280002960	PM487 $0/$
2280000880	PM466 $0/$	2280001960	PM840 $/$	2280002980	PM466 $0/$
2280000890	PM838 $/$	2280002030	PM841 $/$	2280003000	PM466 $0/$
2280000900	PM487 $0/$	2280002031	PM841 $/$	2280003010	PM850 $/$
2280000940	PM488 $0/$	2280002032	PM841 $/$	2280003012	PM850 $/$
2280000941	PM488 $0/$	2280002050	PM842 $/$	2280003020	PM851 $/$
2280000950	PM835 $/$	2280002060	PM843 $/$	2280003021	PM851 $/$
2280000951	PM835 $/$	2280002061	PM843 $/$	2280003030	PM852 $/$
2280000970	M438X $0/$	2280002062	PM843 $/$	2280003032	PM852 $/$
2280000980	M438X $0/$	2280002120	M335X $0/$	2280003040	PM853 $/$
2280000990	M438 $0/$	2280002121	M335X $/$	2280003060	PM494 $0/$
2280000991	M438 $/$	2280002122	M335X $/$	2280003080	PM457 $0/$
2280001000	PM427 $0/$	2280002123	M335X $/$	2280003260	PM837 $/$
2280001020	PM428 $0/$	2280002190	M335 $12_{2,0}$	2280003280	PM490 $/$
2280001021	PM428 $/$	2280002220	PM430 $0/$	2280003282	PM490 $/$
2280001022	PM428 $/$	2280002260	M427X $0/$	2280003330	PM495 $0/$
2280001040	PM427 $/$	2280002261	M427X $/$	2280003331	PM495 $0/$
2280001041	PM427 $/$	2280002290	PM844 $/$	2280003380	M433 $0/$
2280001050	M422 $/$	2280002291	PM844 $/$	2280003381	M433 $0/$
2280001060	PM426 $/$	2280002292	PM844 $/$	2280003390	PM854 $/$
2280001061	PM426 $/$	2280002310	PM845 $/$	2280003391	PM854 $/$
2280001070	PM427 $0/$	2280002360	PM846 $0/$	2280003392	PM854 $/$
2280001100	PM489 $0/$	2280002500	M428 $0/$	2280003393	PM854 $/$
2280001110	PM015 $0/$	2280002550	PM847 $/$	2280003400	PM855 $/$
2280001160	PM475 $0/$	2280002570	PM490 $0/$	2280003401	PM855 $/$
2280001530	M438 $0/$	2280002571	PM490 $0/$	2280003402	PM855 $/$
2280001531	M438 $0/$	2280002572	PM490 $0/$	2280003403	PM855 $/$
2280001540	M137 $12_{0,8}$	2280002610	PM491 $0/$	2280003640	PM501 $/$

DENSO	RMA $\sqrt{\text{Kw}} -!$	DENSO	RMA $\sqrt{\text{Kw}} -!$	DENSO	RMA $\sqrt{\text{Kw}} -!$
2280003641	PM095 $\frac{0}{\text{ }}$	2280004961	PM499 $\frac{0}{\text{ }}$	2280006270	PM871 $\frac{\text{ }}$
2280003642	PM095 $\frac{0}{\text{ }}$	2280004970	PM500 $\frac{0}{\text{ }}$	2280006271	PM871 $\frac{\text{ }}$
2280003660	M438 $\frac{\text{ }}$	2280004971	PM500 $\frac{\text{ }}$	2280006272	PM871 $\frac{\text{ }}$
2280003710	PM856 $\frac{\text{ }}$	2280004972	PM500 $\frac{\text{ }}$	2280006273	PM871 $\frac{\text{ }}$
2280003740	PM490 $\frac{\text{ }}$	2280004980	PM501 $\frac{0}{\text{ }}$	2280006280	PM505 $\frac{\text{ }}$
2280003750	PM857 $\frac{\text{ }}$	2280005020	PM502 $\frac{\text{ }}$	2280006281	PM505 $\frac{\text{ }}$
2280003800	PM420 $\frac{0}{\text{ }}$	2280005021	PM502 $\frac{0}{\text{ }}$	2280006282	PM505 $\frac{\text{ }}$
2280003801	PM420 $\frac{0}{\text{ }}$	2280005022	PM502 $\frac{\text{ }}$	2280006283	PM505 $\frac{\text{ }}$
2280003802	PM420 $\frac{0}{\text{ }}$	2280005023	PM502 $\frac{\text{ }}$	2280006300	PM877 $\frac{\text{ }}$
2280003840	PM400 $\frac{0}{\text{ }}$	2280005040	PM866 $\frac{\text{ }}$	2280006320	PM878 $\frac{\text{ }}$
2280003841	PM400 $\frac{0}{\text{ }}$	2280005140	PM682 $\frac{\text{ }}$	2280006321	PM878 $\frac{\text{ }}$
2280003842	PM400 $\frac{\text{ }}$	2280005270	PM428 $\frac{\text{ }}$	2280006391	PM794 $\frac{\text{ }}$
2280003980	PM454 $\frac{0}{\text{ }}$	2280005300	PM857 $\frac{\text{ }}$	2280006430	M444 $\frac{0}{\text{ }}$
2280003981	PM454 $\frac{0}{\text{ }}$	2280005301	PM857 $\frac{\text{ }}$	2280006450	PM879 $\frac{\text{ }}$
2280003990	PM858 $\frac{\text{ }}$	2280005302	PM857 $\frac{\text{ }}$	2280006470	PM441 $\frac{\text{ }}$
2280003991	PM858 $\frac{\text{ }}$	2280005340	PM503 $\frac{0}{\text{ }}$	2280006471	PM441 $\frac{\text{ }}$
2280003992	PM858 $\frac{\text{ }}$	2280005341	PM503 $\frac{\text{ }}$	2280006530	PM506 $\frac{0}{\text{ }}$
2280004020	PM496 $\frac{0}{\text{ }}$	2280005382	PM432 $\frac{0}{\text{ }}$	2280006612	M335X $\frac{\text{ }}$
2280004030	PM859 $\frac{\text{ }}$	2280005480	M446 $\frac{0}{\text{ }}$	2280006620	PM507 $\frac{0}{\text{ }}$
2280004080	PM860 $\frac{\text{ }}$	2280005490	PM868 $\frac{\text{ }}$	2280006660	PM880 $\frac{\text{ }}$
2280004082	PM860 $\frac{\text{ }}$	2280005620	PM794 $\frac{\text{ }}$	2280006662	PM880 $\frac{\text{ }}$
2280004083	PM860 $\frac{\text{ }}$	2280005621	PM794 $\frac{\text{ }}$	2280006663	PM880 $\frac{\text{ }}$
2280004090	PM861 $\frac{\text{ }}$	2280005630	PM830 $\frac{\text{ }}$	2280006730	PM496 $\frac{0}{\text{ }}$
2280004092	PM861 $\frac{\text{ }}$	2280005641	PM869 $\frac{\text{ }}$	2280006750	PM498 $\frac{0}{\text{ }}$
2280004093	PM861 $\frac{\text{ }}$	2280005670	PM870 $\frac{\text{ }}$	2280006840	PM489 $\frac{0}{\text{ }}$
228000410	PM465 $\frac{\text{ }}$	2280005680	PM871 $\frac{\text{ }}$	2280007130	M437 $\frac{\text{ }}$
2280004210	PM229 $\frac{0}{\text{ }}$	2280005790	PM872 $\frac{\text{ }}$	2280007150	M438X $\frac{0}{\text{ }}$
2280004300	PM862 $\frac{\text{ }}$	2280005811	PM873 $\frac{\text{ }}$	2280007160	M446 $\frac{0}{\text{ }}$
2280004304	PM862 $\frac{\text{ }}$	2280005860	PM817 $\frac{\text{ }}$	2280007190	PM821 $\frac{\text{ }}$
2280004310	PM497 $\frac{0}{\text{ }}$	2280005861	PM817 $\frac{\text{ }}$	2280007200	PM858 $\frac{\text{ }}$
2280004320	PM498 $\frac{0}{\text{ }}$	2280005862	PM817 $\frac{\text{ }}$	2280007210	PM604 $\frac{\text{ }}$
2280004320	PM498 $\frac{0}{\text{ }}$	2280005910	PM874 $\frac{\text{ }}$	2280007220	PM242 $\frac{0}{\text{ }}$
2280004390	PM416 $\frac{0}{\text{ }}$	2280005911	PM874 $\frac{\text{ }}$	2280007390	PM862 $\frac{\text{ }}$
2280004391	PM863 $\frac{\text{ }}$	2280005920	PM495 $\frac{\text{ }}$	2280007391	PM862 $\frac{\text{ }}$
2280004550	PM864 $\frac{\text{ }}$	2280005980	PM504 $\frac{0}{\text{ }}$	2280007392	PM862 $\frac{\text{ }}$
2280004560	PM865 $\frac{\text{ }}$	2280006112	PM875 $\frac{\text{ }}$	2280007420	PM881 $\frac{\text{ }}$
2280004572	M422 $\frac{\text{ }}$	2280006113	PM875 $\frac{\text{ }}$	2280007421	PM881 $\frac{\text{ }}$
2280004640	M446 $\frac{\text{ }}$	2280006120	PM876 $\frac{\text{ }}$	2280007430	PM882 $\frac{\text{ }}$
2280004641	M446 $\frac{0}{\text{ }}$	2280006121	PM876 $\frac{\text{ }}$	2280007432	PM882 $\frac{\text{ }}$
2280004780	PM814 $\frac{\text{ }}$	2280006122	PM876 $\frac{\text{ }}$	2280007550	PM883 $\frac{\text{ }}$
2280004840	PM494 $\frac{\text{ }}$	2280006170	PM505 $\frac{0}{\text{ }}$	2280007581	PM893 $\frac{\text{ }}$
2280004861	PM290 $\frac{\text{ }}$	2280006172	PM505 $\frac{\text{ }}$	2280007591	PM018 $\frac{\text{ }}$
2280004890	PM290 $\frac{0}{\text{ }}$	2280006173	PM505 $\frac{\text{ }}$	2280007671	M438 $\frac{\text{ }}$
2280004960	PM499 $\frac{0}{\text{ }}$	2280006260	PM428 $\frac{\text{ }}$	2280007740	PM884 $\frac{\text{ }}$

MOTORINI

DENSO

DENSO	RMA $\sqrt{\text{Kw}} -!$	DENSO	RMA $\sqrt{\text{Kw}} -!$	DENSO	RMA $\sqrt{\text{Kw}} -!$
2280007791	PM885 0				
2280008040	PM681				
2280008041	PM681				
2280008150	M335X 0				
2280008330	PM886				
2280008350	PM827				
2280008360	PM508 0				
2280008420	PM754				
2280008490	PM290				
2280008540	PM532				
2280008550	PM532				
2280008930	PM887				
2280009050	PM419				
2280009220	PM095				
2280009221	PM095				
2280009540	PM888				
4280000670	M185X				
9622809283	PM476				
9622809290	PM488				
9622809431	PM497				
9622809673	PM496				
9622809675	PM498				
9622809684	PM489				
9712809862	PM479				
9722809094	PM488				
MS4280000670	M185X				

DUCELLIER=V RMA V / Kw -!
ALFO

DUCELLIER= RMA V / Kw -!
VALEO

DUCELLIER= RMA V / Kw -!
VALEO

EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$
910010		910530		911040	
910020	M081	910550		911050	M089
910030	M095	910570		911060	M027
910040	M094	910580		911063	M027X
910060		910590	M121X	911070	M064
910070		910600		911080	M028
910080		910610	M038	911090	M065
910110		910630	M072	911110	M254
910120	M096	910640	M049	911130	
910121	M096	910650	M172	911140	
910131	M174	910660		911143	
910140		910670	M041	911150	M089
910150	M118	910680	M025	911160	
910151	M118	910690	M093	911170	
910171		910693	M093	911180	
910190	M021	910710		911200	
910200	M010	910720	M073	911210	
910220	M100	910730		911220	M091
910250	M180	910740	M011	911240	
910260	M075X	910770	M044	911260	M295
910261	M075X	910780	M109	911270	
910262	M075X	910790		911280	
910270		910800	M109	911290	
910290	M011	910810		911300	
910300	M136	910820	M051	911310	
910310	M017	910830	M063	911330	
910330	M012	910850	M197	911360	
910340	M013	910860	M101	911380	
910350	M016	910870	M299	911410	
910360	M031	910880	M026	911430	
910370	M106	910890	M140	911440	
910380		910900		911450	
910390	M076	910910	M063	911460	
910400		910920	M051	911470	
910410		910930	M052	911490	
910420		910940	M218	911510	
910430	M293	910950	M059	911520	
910440		910960		911540	
910450	M023	910970		911550	
910460		910980		911570	
910470	M251	910990		911580	
910480	M108	911000	M253	911590	
910490		911010		911601	M067
910510	M152	911030	M079	911611	

EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$
911631		912211		912851	
911641		912221		912861	
911651		912231	M424	912871	M425
911671		912251		912872	
911681		912261		912881	M330
911691	M179	912271	M433	912901	
911701		912281		912911	
911711		912291	M320	912921	
911721		912301	M425	912931	
911731	M078	912311		912932	
911741		912320	M116	912933	
911751		912330		912980	M164
911761	M021	912340	M102	912990	
911771		912343	M102X	913010	M083
911780	M280	912360	M148	913014	
911783	M280	912380	M088	913015	
911791	M156	912420		913017	
911801	M161	912430		913018	M335
911811	M084X	912440	M296	913019	
911812	M084X	912440	M296	913023	
911821	M117	912460		913024	M325
911831		912480		913025	
911841		912520		913026	
911871	M032	912590	M111	913027	
911891	M033X	912600	M111	913028	
911910	M114	912610	M040	913029	
911921	M035	912620	M037	913032	
911941	M039	912623	M037	913035	
911981		912630		913036	M193
912001		912640	M109	913037	
912011		912650	M250	913038	
912021		912660		913039	
912031		912670		913043	
912061		912680		913044	
912071		912690	M089	913045	M327
912091		912700		913046	
912101		912710		913047	
912111		912720		913048	
912121		912730		913049	
912131		912740		913050	M014
912161	M128	912750		913052	M440
912171		912780		913053	
912172		912831		913055	
912201		912841	M127	913057	

EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$
913058		913129		913187	
913065		913130	M264	913188	M032
913066		913133		913189	M423
913068		913134		913193	
913073		913135		913194	
913074		913136		913195	
913075	M121X	913137		913196	M134
913076	M124X	913138	M128	913197	
913077		913139	M426	913198	M305
913078	M157	913140	M066X	913199	M305
913080	M015	913143		913200	M120
913083		913144		913202	M120X
913084	M277	913145		913203	
913085		913146		913204	
913086		913148		913205	M406
913087		913149		913206	M223
913088		913150	M216	913207	M201
913089		913153		913208	
913090	M214	913154		913209	
913093		913155		913210	M104
913094		913156		913213	
913095		913157		913214	M427
913096	M424	913158		913215	
913098	M328	913159	M429	913216	M340
913099	M329	913160	M237	913217	
913100	M162	913163		913218	
913103	M113	913164	M338	913219	
913104	M283	913165		913220	M260
913105	M301	913166	M434	913223	
913106	M120X	913167		913224	
913107	M017X	913168		913225	
913108	M222	913169		913226	
913109	M448	913170		913227	
913110	M285	913173	M252	913228	
913113	M102X	913174		913229	
913114		913175		913230	M029
913115	M105	913176		913233	M422
913116	M202	913177		913234	
913117		913178		913235	
913118		913179		913236	
913119	M017X	913183		913237	
913123		913184		913238	
913124	M044	913185		913239	
913126	M308	913186		913240	M103

EDR	RMA $\frac{V}{Kw -!}$	EDR	RMA $\frac{V}{Kw -!}$	EDR	RMA $\frac{V}{Kw -!}$
913243		913303		913363	
913244		913304		913364	
913245		913305		913365	
913246		913306		913366	
913247		913307	M444	913367	
913248		913308	M405	913368	M308
913249		913309	M316	913369	
913253		913313	M409	913373	
913254		913314	M384	913374	
913255		913315	M411	913375	
913256		913316		913376	
913257		913317	M269	913377	
913258		913318	M105X	913378	
913259		913319	M355	913379	
913260		913320		913380	
913263		913323		913383	
913264		913324		913384	
913265	M271	913325		913385	
913266	M110	913326		913386	
913267		913327		913387	
913268	M017X	913328		913388	
913269		913329		913389	
913270	M138	913333		913390	
913273		913336	M309	913393	
913274	M268	913337		913394	M344
913275		913338		913395	
913277		913339	M341	913396	
913278	M445	913340		913397	
913279		913343		913398	
913280	M136	913344		913399	
913283		913345	M342	913400	M045
913284		913346		913403	
913285		913347		913404	
913286		913348		913405	
913287		913349		913406	
913288	M382	913350	M257	913407	
913289		913353		913408	
913293		913354	M447	913409	
913294		913355	M424	913410	M258
913295		913356		913413	
913296		913357		913414	
913297		913358		913415	M436
913298		913359		913416	
913299		913360	M263	913417	

EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$
913418		913475		913583	
913419		913476		913584	M407
913420		913477		913585	
913423		913478		913586	M404
913424		913479	M195	913587	
913425		913483		913588	
913426		913484	M421	913589	M408
913427		913490		913590	
913428		913501	M433	913593	M277
913429		913511		913594	
913430		913521		913595	
913433		913531		913596	
913434		913536		913597	
913435		913537		913598	
913436		913538		913599	
913437		913539		913600	M240
913438		913541		913603	
913439		913543		913604	
913440		913544		913605	
913443		913545	M222	913606	
913444		913546		913607	
913445		913547		913608	
913446		913551		913609	
913447		913555		913610	M099
913448		913556		913611	M226
913449		913557	M400	913613	
913450		913558		913614	
913453	M210	913559		913615	
913454	M391	913561		913616	
913455		913563	M136	913617	
913456		913564	M137	913618	M105
913457		913565	M137	913619	
913458		913566		913620	M046
913459		913567	M235	913623	M017X
913463		913568		913624	
913464		913569		913625	M416
913465		913571		913626	
913466		913573		913627	
913467		913574		913628	
913468 *****		913575		913629	M223
913469		913576		913630	M048
913470	M148	913577		913633	
913473	M318	913579	M431	913634	
913474		913581	M432	913635	

EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$	EDR	RMA $\sqrt{\text{Kw}} -!$
913636		914151		914991	M431
913637		914171	M324	915010	M202
913638	M428	914191		915021	M332
913639		914211	M441	915031	
913640	M053	914221		915040	
913643		914231		915050	M375
913644		914261		915090	M307
913645		914331	M442	915150	M261
913646		914332	M211	915200	M190
913647		914341		915230	
913648		914361	M334	915260	M244
913649		914411	M326	915270	
913650	M246	914461		915320	
913653		914481		915341	
913654	M120X	914560		915351	
913660	M054	914570	M057	915401	M275
913664	M137	914580	M238	915420	
913670		914590	M195	915430	
913690		914600	M260	915470	
913720		914610	M243	915490	M190
913740	M055	914620	M069X	915540	M089
913770		914630	M112	915550	
913781	M125	914640	M115	915551	M213
913791		914680		915560	M013X
913801	M010	914690		915600	M200
913811		914700		915610	M151
913821	M297	914730		915630	M062
913821	M297X	914740		915670	
913831	M276	914800	M061	915672	
913841		914803	M166	915701	
913850	M074	914810	M191	915721	
913861	M124X	914820	M191	915723	
913871		914830	M251	915740	M304
913880		914840	M175	915751	
913910		914860	M095	915781	M337
913940	M056	914861		915910	M048X
913950		914870		915930	M228
913971	M129	914880		915970	M310
913991		914890	M299X	915981	
914051		914900		916021	
914061		914910		916100	
914071	M333	914940		916110	M306
914081		914960	M062X	916190	M256
914091		914971		916196	

EDR	RMA \sqrt{Kw} -!	EDR	RMA \sqrt{Kw} -!	EDR	RMA \sqrt{Kw} -!
916200	M288	917041	M270	917970	
916230	M386	917050		918010	M143
916240	M069	917060	M317	918020	
916250		917070	M389	918030	
916280	M099X	917080		918040	
916290	M248	917090		918060	
916300	M236	917100		918070	M346
916310	M383	917110	M185X	918080	
916320		917120	M143	918090	
916330	M227	917180		918110	M379
916340	M394	917190		918230	M134
916350	M217	917220	M048X	918240	M263
916370		917230	M048X	918250	M258
916380	M083X	917240		995104	
916390	M088X	917250		995104	
916431	M437	917260		995115	
916470	M235	917270		995115	
916520		917290	M314	995149	
916530		917300	M037X	995149	
916550		917310	M355	995150	
916560	M381	917320		995161	
916570		917330		995162	M239
916600	M017E	917381	M120X	995163	
916660	M262	917391	M120X	995172	
916700	M282	917407		995173	M345
916730		917420	M385	995177	M412
916740		917450	M315	995178	M398
916750	M392	917460			
916780		917470			
916790	M255	917480			
916800	M255	917490	M352		
916840		917500	M397		
916860		917520			
916870		917530	M387		
916880	M314	917760			
916890	M099	917810			
916900		917830			
916910	M200	917840	M319		
916920		917850			
916950		917870			
916980	M289	917880			
916990	M396	917890			
917000	M313	917940			
917020	M284	917950	M151		

EFEL	RMA $\sqrt{\text{Kw}} -!$	EFEL	RMA $\sqrt{\text{Kw}} -!$	EFEL	RMA $\sqrt{\text{Kw}} -!$
02201	PM106 0/	12080	PM155 0/	22709	
03106		12590	PM192 0/	22710	
03285	PM184 0/	12760	PM120 /	22711	
04667	PM184 0/	12800		22713	
06000	0/	12900		22715	PM215 0/
06030	0/	12950	PM201 0/	22718	PM213 0/
06690	0/	12960	PM123 0/	22801	
06710		12990		22802	
06730		13000	M089 0/	22806	
06770	0/	13090	PM106 0/	36368	0/
06860	PM202 0/	13100		36383	0/
06940		13130	PM164 0/	36384	0/
07640	0/	13140	PM164 0/	36392	0/
08280	PM192 0/	13470		36503	0/
08780	PM192 0/	13850		36504	0/
08790		14100	PM148 0/	36506	0/
09620		14650	PM135 0/	36507	0/
10420	PM128 0/	14660	M027 /	36549	0/
10430	PM122 0/	14860	M027X 0/	36576	0/
10440	PM106 0/	22201	PM184 0/	36676	0/
10450	PM142 /	22602	PM204 0/	6000	0/
10460	PM106 /	22603		6030	0/
10570		22604	PM192 0/		
10600		22605			
10610	PM188 0/	22606	PM201 0/		
10650		22607			
10655	PM189 0/	22608	PM207 0/		
10800		22609			
10810		22612			
10825		22616			
11206	PM192 0/	22617			
11360		22621			
11370	M091 0/	22622	PM201 0/		
11380		22623			
11420	PM135 0/	22624			
11430	PM146 0/	22625			
11520	PM136 0/	22626	PM184 0/		
11580	PM106 0/	22701	PM189 0/		
11640	PM122 0/	22702			
11750	PM119 0/	22703	PM194 0/		
11830	M089 0/	22704			
11930	PM138 0/	22705			
11930	M091 /	22706			
12070	M028 0/	22708			

ELMOT RMA $\frac{V}{Kw -!}$

8020010001	M271
8020020000	M270
8020030000	M106
809001	M213 $\frac{12}{0,6}$
809001	M213
8100000	M270
8170000	M106
B7605/12	M039 $\frac{12}{0,5}$
E10015/12	
E100L15/12	M114 $\frac{12}{0,8}$
E100N15/12	0
E80	M271 0
E801/12	M271 $\frac{12}{1,0}$
E808120001	M271
E808120001	M271
E80C	
KTM301005	M213 $\frac{12}{0,6}$
R10002	0
R10003	M114 0
R108	PM137 0
R10B	
R10G	
R10TA	PM142
R10U	
R1101	PM162
R1102	
R1103	PM135
R1104	PM225 0
R1105	
R1106	PM162
R1107	M091
R1110	PM162
R1112	PM122
R11A	PM162
R11B	0
R11C	PM135
R11F	PM162
R11G	PM225 0
R11H	
R11K	PM122
R11N	PM162
R11W	M091
R2017	
R2024	PM202 0

ELMOT RMA $\frac{V}{Kw -!}$

R2028	
R2042	PM189 0
R20D1	
R20W	
R20Z	
R2205	
R2206	
R2207	PM194 0
R2209	
R2210	
R2212	
R2213	PM190 0
R2214	
R2215	
R2216	
R2222	
R2238	
R2305	
R2306	PM135
R2308	0
R2309	
R2310	PM192
R2311	
R2313	
R2314	
R2316	
R2317	
R2318	
R2321	
R2322	
R2323	
R2324	
R2325	
R2326	
R2333	
R2334	PM170
R7602	M213 0
R76A	M213 $\frac{12}{0,6}$
R8001	M271 $\frac{12}{1,0}$
R8002	M270 0
R8003	M106 0
R8004	M056 0
R8006	0
R8007	M032 0

ELMOT RMA $\frac{V}{Kw -!}$

R80C	M270 0
R80C	M270
R80C1	M270 $\frac{12}{0,8}$
R80G	M106 0
R80G	M106
R80K	M056 $\frac{12}{0,9}$
R80Z	

FEMSA	RMA $\sqrt{Kw - !}$
36431C	
36432C	
36433C	
MEA163	M210 0
MOA1208	M179 12 0,7
MOA1210	M081 12 0,6
MOA1210	M081 12 0,6
MOA1213	M179 12 0,7
MOA128	M179 0
MOA128	M075X
MOB121	
MOB121	12 0,7
MOB122	
MOB122	12 0,7
MOC1210	M293 0
MOC1213	M084X 12 0,9
MOC1213	M084 12 0,9
MOC1214	M021 12 1,0
MOC122	M010 12 0,8
MOC123	M075 12 0,8
MOC124	M196 0
MOC127	0
MOC129	M174 12 1,0 15a
MOC12X5	M117 12 1,1
MOK121	M081 12 0,6
MOK121	M081 12 0,6
MOK1210	M081 0
MOK1212T	M081 0
MOK1213T	M076 0
MOS1210	M077 12 0,6
MRC123	RM075 0
MRF1208	M355 0
MRF1217	M355 0
MRF128	M355 0
MTA121	M032 0
MTA1213	12 0,6
MTA1214	M077 12 0,6
MTA1214	M119 12 0,6
MTA1219	M077 12 0,6
MTA1219	M119 12 0,6
MTA1219M	M119
MTA1220	0
MTA123	0
MTA1230	M078 12 0,7

FEMSA	RMA $\sqrt{Kw - !}$
MTA1237	M077 12 0,6
MTA1238	12 0,6
MTA1239	M033 12 0,8
MTA1240	M067 12 0,6
MTA1241	12 0,6
MTA1243	M077 12 0,6
MTA1243	M119 12 0,6
MTA126	0
MTA127	12 0,6
MTA128	M118 0
MTA12P15	M119
MTA12P7	PM908 12 0,6
MTB1219	0
MTB12V19	0
MTC2527	0
MTC2527	0
MTD121	M039 0
MTD1214	M114 12 0,8
MTD1218	0
MTD1219	M047 12 1,3
MTD129	M047 12 1,3
MTJ121	12 0,8
MTL1221	M355 0
MTL126	M355 0
MTS121	0
MTS1210	M192
MTS1210	M192 12 0,8
MTS1210	M119 12 0,8
MTS1210	M192 12 0,8
MTS1221	0
MTS1222	M032 12 0,8
MTS1223	12 0,8
MTS1229	M033 12 0,8
MTS123	M021 0
MTS1234	0
MTS1237	M119 12 0,8
MTS1237	M119 12 0,8
MTS1238	0
MTS1239	M033 12 0,8
MTS1239	M033X 12 0,8
MTS1242	M033 12 0,8
MTS1247	M035
MTS1247	M035 12 0,8
MTS1247	M035 12 0,8

FEMSA	RMA $\sqrt{Kw - !}$
MTS1248	M033 12 0,8
MTS1250	M119 12 0,8
MTS1250	M119 12 0,8
MTS1251	M119 12 0,8
MTS1251	M119 12 0,8
MTS12P13	M021 0
MTS12P3	M021 0
MTU121	12 0,8
MTV121	0
MTV123	0
MTV124	M070 12 0,8
MTV125	0
MTV126	M070 12 0,8
MTV128	M118 12 0,8
MZS123	M021 0

FIAT	RMA $\frac{V}{Kw -!}$	FIAT	RMA $\frac{V}{Kw -!}$	FIAT	RMA $\frac{V}{Kw -!}$
106023		4142222	$\frac{12}{0,8}$	4369349	$\frac{12}{0,8}$
106023		4145430	M032 $\frac{0}{0}$	4392459	M018 $\frac{12}{0,8}$ 15a
1110025	M058	4156064	M047 $\frac{12}{1,3}$	4392461	M026
1110025	M058	4162784	$\frac{0}{0}$	4392461	M026 $\frac{12}{1,6}$
11130219	M033 $\frac{12}{0,8}$	4162785	$\frac{12}{0,6}$	43924610	M026 $\frac{0}{0}$
112123		4169093	M091 $\frac{0}{0}$	4401806	M033 $\frac{12}{0,8}$
130019808	M284 $\frac{0}{0}$	4169095	PM138	4401806	M033 $\frac{12}{0,8}$
130019808	M284	4169095	PM138 $\frac{0}{0}$	4410342	$\frac{0}{0}$
1300198080	M284	4169096	M091	4412878	M018 $\frac{12}{0,8}$ 15a
1329201080	PM102	4169096	M091	4412894	M028 $\frac{12}{2,0}$
1329201080		4169096	PM150	4421708	M047
1342792080	M390	4169096	M091	4421708	M047 $\frac{12}{1,3}$
1342792080		4169096	PM150 $\frac{0}{0}$	4435660	M018 $\frac{12}{0,8}$ 15a
1347058080	RM017	4172004	PM138 $\frac{0}{0}$	4436732	M032 $\frac{0}{0}$
1349920080		4172113	PM150 $\frac{12}{3,5}$	4443493	M166 $\frac{0}{0}$
1349920080		4179626	PM202 $\frac{0}{0}$	4443494	M166 $\frac{12}{0,8}$
139201080	$\frac{0}{0}$	4181961	$\frac{12}{0,6}$	4448694	M028 $\frac{12}{2,0}$
1473638080	PM094 $\frac{0}{0}$	4187587	PM138 $\frac{0}{0}$	4451826	M110 $\frac{0}{0}$
1473638080	PM094	4198226	$\frac{12}{0,8}$	4457725	
1475489080	PM094 $\frac{0}{0}$	4198227	$\frac{0}{0}$	4468806	M033X $\frac{0}{0}$
1475489080	PM094	4198600	M032 $\frac{12}{0,8}$	4468806	M033X $\frac{0}{0}$
2961928		4198601	M032 $\frac{12}{0,8}$	4469985	M011 $\frac{12}{0,9}$
30180355	M011 $\frac{0}{0}$	4199576	$\frac{0}{0}$	4469986	M011 $\frac{12}{0,9}$
33353237	M143X	4220995	$\frac{12}{0,6}$	4469987	M011 $\frac{12}{0,9}$
3914191	M033X	4229113	M033 $\frac{12}{0,8}$	4470118	M011 $\frac{12}{0,9}$
3914191	M033X $\frac{0}{0}$	4229113	M033 $\frac{12}{0,8}$	4470377	M023 $\frac{12}{0,8}$
3915113	M033	4229114	M033 $\frac{12}{0,8}$	4470378	M023 $\frac{12}{0,8}$
3915113	M033 $\frac{0}{0}$	4229114	M033 $\frac{12}{0,8}$	4474714	M035 $\frac{12}{0,8}$
3917420	M089 $\frac{0}{0}$	4231018	PM138	4474715	M035 $\frac{12}{0,8}$
4060919	$\frac{12}{1,4}$	4231018	PM138 $\frac{0}{0}$	4474746	M114 $\frac{12}{0,8}$
4060920	$\frac{12}{1,4}$	4232191	PM138 $\frac{0}{0}$	4474747	M114 $\frac{12}{0,8}$
4061012	$\frac{12}{1,4}$	42498112	PM146 $\frac{0}{0}$	4474750	M114 $\frac{12}{0,8}$
4064058	$\frac{0}{0}$	42498212	PM146 $\frac{0}{0}$	4474762	M047 $\frac{12}{1,3}$
4085959	$\frac{12}{0,7}$	4262641	$\frac{0}{0}$	4474763	M047 $\frac{12}{1,3}$
4085977	$\frac{0}{0}$	4269114	PM138 $\frac{0}{0}$	4474804	$\frac{12}{0,8}$
4109803	$\frac{0}{0}$	4287971	M039 $\frac{12}{0,5}$	4474805	$\frac{12}{0,8}$
411049	$\frac{0}{0}$	4287972	M039 $\frac{12}{0,5}$	4474851	M039 $\frac{12}{0,5}$
4111200	$\frac{0}{0}$	4287978	M039 $\frac{0}{0}$	4474852	M039 $\frac{12}{0,5}$
4111220	$\frac{12}{0,6}$	4288328	M039 $\frac{12}{0,5}$	4474917	M097 $\frac{12}{0,8}$
4112049	$\frac{12}{0,6}$	4294494	M047 $\frac{12}{1,3}$	4474918	M097 $\frac{12}{0,8}$
411220	$\frac{0}{0}$	4294495	M047 $\frac{12}{1,3}$	4475025	M047 $\frac{12}{1,3}$
4117351	$\frac{12}{0,5}$	4350064	M166 $\frac{12}{1,1}$	4475130	M047 $\frac{12}{1,3}$
4117353	$\frac{0}{0}$	4367018		4475131	M047 $\frac{12}{1,3}$
4117354	$\frac{0}{0}$	4367018	M047 $\frac{0}{0}$	4475132	$\frac{0}{0}$

FIAT	RMA \sqrt{Kw} -!	FIAT	RMA \sqrt{Kw} -!	FIAT	RMA \sqrt{Kw} -!
46231500	M270 0	46231640	M028 0	46468696	M382 0
46231503	M039 12 0,5	46231642	M054 12 2,2	46473784	M384 0
46231504	M033 12 0,8	46231643	M284	46473785	M268 0
46231505	M033X 12 0,8	46231644	M228 12 2,2	46478945	M384 0
46231505	M033 12 0,8	46231645	M228 0	46518059	M268 0
46231508	M039 12 0,5	46261576	M044 0	46518059	M268
46231510	M056 12 0,9	46401068	PM227 0	46521786	
46231511	M265 0	46406469	0	46521787	RM067
46231525	M032 12 0,8	46406471	0	46522234	PM241 0
46231526	M035 12 0,8	46406472	M219 0	46531437	M410 0
46231527	M018 12 0,8 15a	46406473	M046 0	46548654	M401 0
46231528	M018 12 0,8 15a	46406938	M404 0	46555708	
46231529	M018 12 0,8 15a	46406970	0	46740241	0
46231530	M166 12 0,8	46406973	M402 0	46740242	M265
462315300	M166 12 0,8	46406973	M402 0	46740242	M401 0
46231531	M268 0	46406974	M402X 0	46748349	M393 0
46231535	M283 0	46414610	M316 0	46748350	M393 0
46231537	M269 0	46414831	M200 0	46748351	M384 0
46231540	M023 12 0,8	46416897	M283 0	46748355	M410 0
46231540	M283 12 0,8	46417006	M283 0	46758240	PM102
46231541	M405 0	46419332	M405 0	46763529	M268 0
46231545	M382 0	46419392	M405	46763530	RM081
46231550	M046 12 0,9	46419913	0	46765839	0
46231555	M046 0	46419914	0	46774415	0
46231555	M046 0	46429594	M268 0	46774416	0
46231570	0	46430721	M058X 0	46774417	0
46231575	M011 12 0,9	46430784	M384	46777550	
46231576	M044 12 1,0	46430784	M384 0	46791692	M382
46231578	M113 0	46430785	M268	46796553	RM082
46231580	M102X 0	46430785	M268 0	46800155	0
46231590	0	46431502	M409 0	46800159	
46231592	M057 12 1,4	46432262	M408 0	46803965	
46231598	M010 0	46432301	M270 0	46821681	M393 0
46231600	M113 12 1,1	46434037	M269 0	46823543	M384
46231600	M113 12 1,1	46437520	PM241	46823543	0
46231601	M058 12 1,7	46439669	M058X 0	46823548	PM895
46231602	M058 0	46439700	M058X 0	46823548	M143X
46231603	M026 12 1,6	46440079	0	4682996	0
46231604	M048 12 2,2	46446291	M058 0	4682998	PM150
46231605	M026 12 1,6	46451529	M410 0	4682998	PM150 0
46231606	0	46451895	M411 0	4682999	PM138
46231607	M048X 0	46454211	M402 0	4682999	PM138 0
46231607	M048X 0	46463250	M411 0	46830212	PM241
46231610	M053 12 2,2	46465475	M408 0	46830212	

FIAT	RMA $\sqrt{Kw - !}$	FIAT	RMA $\sqrt{Kw - !}$	FIAT	RMA $\sqrt{Kw - !}$
4691200	PM155	4737759	PM135	4807378	PM138
4691200	PM155	4737761		4807379	PM146
4692477	PM138	4738575		4807379	PM146
4699704	PM138	4739353		4816170	PM753
4699705	M091	4741669	M028	4818562	
4701920	PM138	4741699	M028	4856056	M027
4701920	PM138	4744841	PM155	4856056	M027
4702248	M091	4745929		4880691	PM140
4703751	M091	4745930	M027	4919664	
4706008	PM146	4745930	M027	50001602	
4706008	PM146	4745930	M027	50004908	RM066
4706720	PM142	4752403	PM155	50004908	RM062
4706931	PM155	4752403	PM155	50004909	RM063
4709418		4755108	PM138	50008582	RM067
4710224	PM150	4755109	M091	5023299	
4710406	PM198	4755109	M091	50232991	PM247
4711699	M027	4755110	PM135	5111319	M091
4712894	M028	4755111	PM146	51772325	
4712894	M028	4755111	PM146	51776205	
4713805	M028	4755113	PM142	51776205	
4713807	M028	4755113	PM142	55192482	M384
4713807	M028	4759929	PM150	55193406	M382
4716026	PM146	4761852		55193407	M393
4716026	PM146	4763995		55193410	M200
4716062	PM146	4763996	M091	55193460	M382
4719664	M027	4763996	M091	55195029	
4719664	M027	4774976		55353257	M143X
4719666	PM135	47749764		553532570	M143X
4722682	PM150	4780974	PM223	5884563	M045
4722682	PM150	4782801		5894371	M182
4728682	PM150	4782802	PM202	5894371	
4728682	PM150	4782803	PM194	5933930	M026
4732240		4784745	PM207	5959701	M113
4732241	PM202	4784746		5959702	M011
4732242	PM194	4784747	PM207	5962684	M033X
4735444		4785541	PM140	5968605	M301
4737754	PM138	4786023		5968605	M283
4737754	PM138	4807373		5969050	M061
4737755	M091	4807374	M027	5969105	M061
4737755	M091	4807374	M027	5972684	M033X
4737756	PM146	4807375	M091	5972684	M033
4737756	PM146	4807376	PM135	5972684	M033X
4737757	PM142	4807377	PM155	5984563	M045
4737758		4807377	PM155	5984563	M045

FIAT	RMA $\sqrt{Kw - !}$	FIAT	RMA $\sqrt{Kw - !}$	FIAT	RMA $\sqrt{Kw - !}$
5984563	M045 $12/2,2$	60777242	M062X $0/$	7540278	M347 $0/$
5985182	M048X $0/$	60777242	M062X $0/$	7541569	M057 $12/1,4$
5985182	M048X $0/$	60800295	M057 $0/$	7541569	M057 $12/1,4$
5985182	M048 $12/2,2$	60800295	M057 $0/$	7541569	M057 $0/$
5985265	M053 $12/2,2$	60813403	M200 $0/$	7564668	M028 $12/2,0$
5985265	M053 $0/$	608134060	M200 $0/$	7565057	M048 $0/$
5985556	M113 $0/$	60813460	M200 $0/$	7576186	M045 $0/$
5985556	M113 $0/$	60813461	M382 $0/$	7580192	M058 $12/1,7$
5990470	M035 $12/0,8$	60814706	M200 $0/$	7580192	M058 $0/$
5991741	M046 $0/$	60814706	M200 $0/$	7580575	M054 $12/2,2$
5991832	M046 $12/0,9$	60814911	M384 $0/$	7587118	M026 $12/1,6$
5996771	M026 $12/1,6$	60817002	M384 $0/$	7588942	M057 $12/1,4$
5997309	$0/$	61227993	PM191 $0/$	7588942	M057 $12/1,4$
5997309	M058 $0/$	61583669	$0/$	7589005	M228 $12/2,2$
5997309	M058 $12/1,7$	63984678	$0/$	7589151	M228 $0/$
5999906	M056 $12/0,9$	6412969	M151 $12/2,2$	75891510	M228 $0/$
60412969	M151 $0/$	6706931	PM155 $0/$	75891510	M228 $12/2,2$
60412969	M151 $0/$	6706931	PM155 $0/$	7589411	M046 $12/0,9$
60504218	M013 $0/$	7130430	$12/0,5$	7589435	M053 $12/2,2$
60512847	M200 $12/1,4$	71716562	M105 $0/$	7589547	M283 $12/0,8$
60512969	M151 $0/$	71716563	M105 $0/$	7589547	M023 $12/0,8$
60512969	M151 $0/$	71716564	M105 $0/$	7589655	M283 $12/0,8$
60512969	M151 $0/$	71716565	M105 $0/$	7589655	M023 $12/0,8$
60521584	$0/$	71719595	M105 $0/$	7597118	M026 $0/$
60521584	M012 $0/$	71719596	M105 $0/$	7597118	M026 $12/1,6$
60521994	$0/$	71719598	M105 $0/$	7608589	M045 $12/2,2$
60521994	$0/$	71719599	M105 $0/$	7609068	M026 $0/$
60522387	M062 $0/$	71719600	M105 $0/$	7612952	M056 $12/0,9$
60522387	M062 $0/$	71719601	M105 $0/$	7613744	M045 $0/$
60523034	M062X $0/$	71719602	M105 $0/$	7621040	M056 $12/0,9$
60537529	$0/$	71719603	M105 $0/$	7622104	M056 $12/0,9$
60537529	$0/$	71719604	M105 $0/$	76221040	M056 $12/0,9$
60555389	M182 $0/$	71719605	M105 $0/$	7626281	M219 $0/$
60555389	$0/$	71719606	M105 $0/$	7626281	M219 $0/$
60562973	M013 $0/$	71719607	PM243 $0/$	7642260	M048X $0/$
60562973	M013 $0/$	71719608	M390 $0/$	7642261	M048X $12/2,2$
60562974	M013X $0/$	71719608	$0/$	7658554	M048 $0/$
60562974	$0/$	71738330	M390 $0/$	7658555	M053 $12/2,2$
60562974	M013X $0/$	7501995	M166 $0/$	7658556	M048 $0/$
60562974	M013X $0/$	75019950	M166 $0/$	76624204	$0/$
60585343	M200 $0/$	75204899	$0/$	7666135	M054 $12/2,2$
60620761	M402 $0/$	75207601	$0/$	7666528	M023 $12/0,8$
606558756	M200 $0/$	75207601	PM144 $0/$	7667227	M056 $0/$
60655876	M200 $0/$	7533231	M213 $12/0,6$	7668314	M386 $0/$

FIAT	RMA $\sqrt{\text{Kw}} -!$	FIAT	RMA $\sqrt{\text{Kw}} -!$	FIAT	RMA $\sqrt{\text{Kw}} -!$
76683140	M386 0/	77167660	M058 /	77515430	M028 12/ 2,0
7668988	M270 0/	7716767	M048X 0/	77535430	M057 12/ 1,4
7674733	M053 0/	7716769	M048X 0/	77535430	M057 12/ 1,4
7679933	M407 0/	7716771	M048X 0/	7755043	M166 0/
7680615	M046 0/	77168430	M035 12/ 0,8	77550430	M166 12/ 0,8
7680615	M046 0/	77175430	M033 12/ 0,8	77563430	M061 0/
7680616	0/	77194430	0/	77603430	M023 12/ 0,8
7680619	M048X 12/ 2,2	7719541	M271 12/ 1,0	77604430	0/
7692102	M058X 0/	77201430	M033 12/ 0,8	77612430	M010 12/ 0,8
7696591	M113 0/	77201430	M033X 12/ 0,8	77671430	M053 12/ 2,2
7696595	M271 0/	77206430	12/ 0,8	77679430	M228 12/ 2,2
77028560	M027 12/ 2,5	77211430	M047 12/ 1,3	77682430	M027 0/
77028560	M027 12/ 2,5	77218430	12/ 0,8	7770210	M058X 12/ 1,7
77040560	PM138 0/	77235430	M113 12/ 1,1	77716430	M044 12/ 1,0
77040561	PM138 0/	77235430	M113 12/ 1,1	77722459	M265 12/ 0,8
77050262	PM146 0/	7726946	M228 0/	7772456	M268 0/
77050262	PM146 0/	7727483	M046 0/	7772459	M268 0/
77050561	0/	7727484	M057 12/ 1,4	7772462	M362 0/
77050561	0/	77274850	M200 0/	7772859	0/
77050562	PM146 0/	7727487	M053 0/	7773812	M283 0/
77050562	PM146 0/	7727534	M386 0/	77784430	M044 0/
77065560	PM142 0/	77276430	M039 12/ 0,5	7783714	M409 0/
7706908	M045 0/	77276431	M039 12/ 0,5	7785449	M268 0/
77080560	PM155 0/	77305430	M056 12/ 0,9	7785949	M269 0/
77080560	PM138 0/	7731823	M048 0/	7796598	M268 0/
77080561	PM155 0/	77323430	M058 12/ 1,7	7796599	PM324 0/
77080561	PM155 0/	77337430	M026 12/ 1,6	8122161	PM193 0/
77097430	PM142 0/	7733966	M283 0/	8122191	PM188 0/
77097430	PM142 0/	7735162	M265 0/	8122191	PM188 0/
77129430	12/ 0,6	7737262	M270 0/	8222161	PM193 /
77130560	PM142 0/	77387430	M018 12/ 0,8	82224044	RM037 0/
77138430	M047 12/ 1,3	77398430	M023 12/ 0,8	82301308	M044 12/ 1,0
77145430	M032 12/ 0,8	7740560	PM138 0/	82327995	M044 0/
77161410	0/	77412430	M048 12/ 2,2	82329731	M044 0/
77161430	M044 0/	77414430	PM138 0/	82357752	M044 0/
7716192	M026 0/	77414431	PM138 0/	82374412	M044 /
7716194	0/	77416435	M046 12/ 0,9	82374412	M044 12/ 1,0
7716195	M048X 0/	77418430	M097 12/ 0,8	88205001	PM150 0/
7716195	M048 0/	77425430	M045 12/ 2,2	88205005	PM150 0/
7716196	M048X 0/	77444430	PM138 0/	88205006	M091 12/ 3,5
7716197	M386 0/	77445430	PM138 0/	88205018	0/
7716198	M113 0/	77452430	M053 12/ 2,2	88205019	0/
77162784	0/	77510430	M011 12/ 0,9	88205020	0/
7716766	M058 0/	77512430	0/	8823932	M237 12/ 1,4

FIAT RMA $\frac{V}{Kw - !}$

8862534	PM142	/
8961386	PM142	0/
8961949	PM184	0/
8962534	PM142	/
8962534	PM142	0/
8962687		0/
9151139080		/
9151139080	M010	12/0,8
91535770	M157	0/
9153695080	M010	12/0,8
929162	PM155	/
929162	PM155	0/
95684147	RM014	/
9603503580	M105	/
9603503580	M105	/
9603503580	M105	/
9603503680	M105	0/
961170588		0/
9611705880	PM094	/
9611705880	PM094	/
961301578	M102X	0/
961301578	M102X	/
9613022580	M102X	0/
9613022580	M102X	/
96130578	M102X	0/
961323028	M102X	0/
9613230280	M102X	/
9615519880	M102X	/
9615519880	M102X	/
9619310280	M102X	/
9624291380	M102X	/
9624291380	M102X	/
9625168680	M102X	/
9625382480	PM094	/
9625382480	PM094	/
9625382580	M390	/
9625382680	M105	/
9625382780	M105	/
96294732	M102X	0/
9629473280	M102X	/
9629473280	M102X	/
9635659580	PM094	/
9635659580		/
9635659780		/

FIAT RMA $\frac{V}{Kw - !}$

9639846780	PM094	/
9639846780		/
9947830	M105	0/
9947830	M105	/
A2E3514	M033	12/0,8
V450DT		/

FIAT RMA $\frac{V}{Kw - !}$

FORD	RMA $\sqrt{\text{Kw}} -!$	FORD	RMA $\sqrt{\text{Kw}} -!$	FORD	RMA $\sqrt{\text{Kw}} -!$
0018882	M389	1088649	M317 $\frac{0}{0}$	1574643	M152 $\frac{12}{0,8}$ 15a
015741	M043	1092115	M317 $\frac{0}{0}$	1591213	M082 $\frac{12}{0,8}$
1003308	M289	1092116	M389 $\frac{0}{0}$	1591213	
1007765	M289 $\frac{0}{0}$	1093471	M420 $\frac{0}{0}$	1613334	M082
1008802	M243	1105310	M420	1626195	M059
1008804		1111210	PM080 $\frac{0}{0}$	1626195	M059
1008813	M307	1116389	M317 $\frac{0}{0}$	1626269	
1008822	M137	1118336	M307 $\frac{0}{0}$	1638241	
1008827	M134	1120214	PM245 $\frac{0}{0}$	1638241	
1008828	M137	1120215	PM244 $\frac{0}{0}$	1638243	M243 $\frac{0}{0}$
1008829	M190	1120215	PM244	1638243	M243
1008833	M243	1133994	M307	1644028	M214
1008835	M214	1140110	PM244 $\frac{0}{0}$	1653206	M059 $\frac{12}{2,5}$
1008836	M138	1140110	PM244	1654766	PM089
1008838	M260 $\frac{0}{0}$	1140111	PM245 $\frac{0}{0}$	1F1U11000AA	
1008842	PM021	1140757	PM605	1F1Z11002A	
1011330	M389 $\frac{0}{0}$	1140760	M317	1M2111000AA	M313
1011331	M317 $\frac{0}{0}$	1147432	PM080	1S4U11000AA	M307
1012221	M289	1149703	PM548	1S7U11000AB	PM245 $\frac{0}{0}$
1012395	M289	1151641	PM244	1S7U11000AC	PM245 $\frac{0}{0}$
1018882	M389 $\frac{0}{0}$	1214371	PM244	1S7U11000BA	PM244 $\frac{0}{0}$
1018883	M317 $\frac{0}{0}$	1214371	PM244	1S7U11000BB	PM244 $\frac{0}{0}$
1019852	M403	1307578	M317	1S7U11000BC	PM244 $\frac{0}{0}$
1027300	M214	1307578	M317	1W4U11000CA	PM607
1027772	M403 $\frac{0}{0}$	1309581	PM548	2C1611000AA	PM244
1027928	M420 $\frac{0}{0}$	1309581	PM548	2S6U11000CA	M317
1029405	M289X	1344589	PM606	2S6U11000CB	M317
1030151	M387 $\frac{0}{0}$	1344589	PM606	2S6U11000DA	PM548
1032666	M313	1438288	M049 $\frac{12}{1,1}$	2S6U11000DB	PM548
1033781	M403	1438288	M049	2S6U11000EB	PM605
1057652	M235X $\frac{0}{0}$	1438288		2S7T11000AB	PM244
1057654	PM027	1438561	M043 $\frac{12}{1,0}$	2S7T11000DA	PM244 $\frac{0}{0}$
1058429	M307 $\frac{0}{0}$	1438561		3238665	$\frac{0}{0}$
1059179	M420 $\frac{0}{0}$	1476964	M152 $\frac{12}{0,8}$ 15a	3242283	$\frac{0}{0}$
1059564	M289 $\frac{0}{0}$	1478942	M049 $\frac{12}{1,1}$	3259110231	RM072
1061267	M307 $\frac{0}{0}$	1507703		377911023D	RM064
1061458	M235X $\frac{0}{0}$	1516027	M152 $\frac{12}{0,8}$ 15a	3852582	$\frac{0}{0}$
1063999	M317	1517025	PM598	3904005	
1064000	M317 $\frac{0}{0}$	1539703	M159 $\frac{12}{0,7}$ 15a	3918688	PM160
1072559	M289	1539703		3960404	
1073093	M307	1568698	M043	3961474	M425
1073108	M420 $\frac{0}{0}$	1568699	M049 $\frac{12}{1,1}$	3M5T11000EA	PM608
1085273	PM253 $\frac{0}{0}$	1571105	M159 $\frac{12}{0,7}$ 15a	4078768	PM244 $\frac{0}{0}$
1087280	PM027	1571105		436765	

FORD	RMA \sqrt{Kw} -!	FORD	RMA \sqrt{Kw} -!	FORD	RMA \sqrt{Kw} -!
4M5T11000CA	PM606	5023560	M285 $\frac{12}{2,2}$	6127592	M043
4M5T11000KB	RM013	5023577		6127593	
5003623	M049 $\frac{12}{1,1}$	5023587	M307	6130474	
5003624	M152 $\frac{12}{0,8}$ 15a	5023593	M307	6147936	M214
5003627	M153 $\frac{12}{2,0}$	5023595	M263	6157856	
5003633		5023597	M190 $\frac{12}{1,0}$	6157876	M263 $\frac{12}{1,4}$
5003634		5023598	M260	6157877	M260 $\frac{12}{1,4}$
5003636	M152 $\frac{12}{0,8}$ 15a	5023599	M285 $\frac{12}{2,2}$	6158978	M214
5003638		5023601	PM089	6160440	M420
5003638	M159 $\frac{12}{0,7}$ 15a	5023607	M043 $\frac{12}{1,0}$	6160440	M059
5003639		5023717	M261	6164752	M190
5003639	M043 $\frac{12}{1,0}$	5023738	M138 $\frac{12}{0,9}$	6175119	
5003641	M159 $\frac{12}{0,7}$ 15a	5023943	PM558	6177073	M307
5003643	M059	5026489	PM250 $\frac{0}{0}$	6194727	M285 $\frac{12}{2,2}$
5003643	M059 $\frac{12}{2,5}$	5026490	M311 $\frac{0}{0}$	6203379	M214 $\frac{12}{1,7}$
5004494	M081 $\frac{12}{0,6}$	5026491	M311 $\frac{0}{0}$	6203381	M307
5007080	M076 $\frac{12}{0,8}$	5026712	M312 $\frac{0}{0}$	6203384	M138 $\frac{12}{0,9}$
5007080		5026713	M312 $\frac{0}{0}$	6504726	M260
5007082	M082 $\frac{12}{0,8}$	5026806	M235X	6504728	
5007083	M136	5027116	M260	6504730	PM089
5007084		5027117	M263	6504742	M190 $\frac{12}{1,0}$
5007087	M136 $\frac{12}{0,9}$ 15a	5027123	M190	6565322	M311 $\frac{0}{0}$
5007089	M076 $\frac{12}{0,8}$	5027131	M137	6565323	M312 $\frac{0}{0}$
5008966	M153 $\frac{12}{2,0}$	5027807	M261	6683311	M214 $\frac{12}{1,7}$
5008970	M081 $\frac{12}{0,6}$	5030456	M137	6775699	M235X
5008971		5030457	M043	6775703	M235X $\frac{0}{0}$
5008975		544228		6775704	PM027
5010212		547911023D	RM062	67GB11000CA	M263 $\frac{0}{0}$
5010217		5752791	$\frac{0}{0}$	6816674	M134
5012450	M260	5R2911001AA	RM079	6816674	
5014236	M243	6023384	M138 $\frac{12}{0,9}$	6816676	M261 $\frac{0}{0}$
5016235	M214	6029039	M076 $\frac{12}{0,8}$	6816676	M261
5020468	PM021	6039198	M059	6816678	M138
5021193	M261	6042529	M043 $\frac{12}{1,0}$	6816678	M138
5021195	M263	6091923		6994100	M190 $\frac{0}{0}$
5021197	PM558	6091924		69BB11000OB	PM089 $\frac{0}{0}$
5021205	M190 $\frac{12}{1,0}$	6092294	PM130	69EB11000DA	M152 $\frac{12}{0,8}$ 15a
5021206	M260	6092295	M059	6C1T11000AB	RM014
5022412	M243	6092296	PM167	6C1T11000AC	RM014
5022454	M137	6094378	M159	6G9N11000CC	RM010
5022454	M137 $\frac{12}{0,8}$	6114855		6G9N11000KB	RM015
5023431	M214 $\frac{12}{1,7}$	6114855	RM038	6G9N11000LA	RM022
5023549	M214 $\frac{12}{1,7}$	6127591		6TF11001DA	
5023558	PM089	6127591	M243	7003145	M214 $\frac{0}{0}$

FORD	RMA $V_{Kw} -!$
7003146	M214 0/
7012883	PM033 0/
702000150	M294 /
7085852	M260 /
7085852	M260 0/
70858852	M260 /
70AB11001AA	PM598 /
70GB11000BA	M049 12/ 1,1
70GB11000BA	M049 12/ 1,1
715F11000JA	M059 12/ 2,5
715F11000MA	M059 /
715F11000MA	M059 12/ 2,5
7177333	M235X 0/
71AB11000BA	0/
71AB11001AA	PM598 /
71AB11001BA	0/
71BB11000AA	M049 12/ 1,1
71BB11000AA	M049 12/ 1,1
71BB11000BA	M043 /
71BB11000BA	M043 12/ 1,0
71BB11000BA	M043 12/ 1,0
71BB11000DA	M159 0/
71BB11000E2A	0/
71BB11000E2B	0/
71BB11000EA	/
71BB11000LB	M152 12/ 0,8 15a
71EB11000BA	M049 12/ 1,1
71EB11000BA	M049 12/ 1,1
71EB11000CA	M152 /
71EB11000CA	M152 12/ 0,8 15a
71YB11000AA	M294 12/ 2,8
71ZB11001AB	0/
7239483	PM229 0/
733F11000BA	0/
733F11000BA	0/
73AB11000AA	M159 /
73AB11000AA	M159 12/ 0,7 15a
73AB11000BA	/
73AB11000BA	M159 /
73AB11000BA	M159 /
73AB11000BA	M159 12/ 0,7 15a
73BB11000B2A	0/
73BB11000BA	/
73GB11000AA	0/

FORD	RMA $V_{Kw} -!$
73GB11000BA	M159 12/ 0,7 15a
7412672	M307 /
74EB11000BA	0/
755F11000AA	M059 12/ 2,5
755F11000AB	M059 12/ 2,5
755F11000BB	M059 /
755F11000BB	M059 12/ 2,5
755F11000CA	M059 0/
75AB11000A2A	M043 0/
75AB11000A2B	M043 /
75AB11000B2A	M043 0/
75EB11000BA	0/
76AB11000AA	M159 /
76AB11000AA	M159 /
76AB11000AA	M159 12/ 0,7 15a
76AB11300AA	M159 0/
76BB11000AA	M043 12/ 1,0
76BB11000AA	M043 12/ 1,0
76BB11000AD	M043 12/ 1,0
76EB11000AA	/
76EB11000AA	M049 12/ 1,1
76EB11000AA	M049 12/ 1,1
76EB11000BA	0/
775F11000BB	M059 12/ 2,5
77BB11000AA	M152 12/ 0,8 15a
77BB11000AA	M152 12/ 0,8 15a
77BB11000BA	M260 /
77BB11000BA	M260 0/
77FB11000AA	M137 0/
77FB11000AA	M082 12/ 0,8
77FB11000BA	M137 /
77FB11000BA	M082 12/ 0,8
77FB11000BA	M076 12/ 0,8
77FB11000BA	M137 12/ 0,8
77FB11000CA	M082 12/ 0,6
77FB11000CA	M081 12/ 0,6
77FB11000CA	M081 12/ 0,6
77FB11000EA	M081 12/ 0,6
77FB11000EA	M081 12/ 0,6
78AB11000AA	M251 0/
78AB11000BA	/
78AB11000CA	M159 12/ 0,7 15a
78BB11000AA	0/

FORD	RMA $V_{Kw} -!$
78GB11000CA	M153 12/ 2,0
78GB11000CB	M153 12/ 2,0
78GB11000DA	M153 12/ 2,0
78VB11000D	PM025 /
78VB11000DA	0/
78VB11000EA	/
795F11000CA	M059 12/ 2,5
79AB11000AB	0/
79AB11000BB	M159 12/ 0,7 15a
79AB11000BC	M159 /
79AB11000BC	M043 12/ 0,7 15a
79AB11000BO	M159 /
79BB11000B2A	/
79FB11000AA	M082 /
79FB11000AB	M081 /
79FB11000AB	M081 12/ 0,6
79FB11000AB	M082 12/ 0,6
79FB11000AB	M082 12/ 0,6
79FB11000AB	M081 12/ 0,6
79FB11000AC	M082 /
79FB11000AC	M082 12/ 0,8
79FB11000AC	M082 12/ 0,8
79FB11000AC	M137 12/ 0,8
79FB11000AL	M076 12/ 0,8
79FB11000EA	M081 0/
81866002	PM160 /
81866002	PM160 0/
81866002	PM160 /
81AB11000AA	M082 /
81AB11000AA	M076 12/ 0,8
81AB11000AA	M137 12/ 0,8
81AB11000AA	M082 12/ 0,8
81AB11000AB	M076 12/ 0,8
81AB11000AB	M082 12/ 0,8
81AB11000BA	/
81AB11000BA	M082 12/ 0,8
81AB11000BA	M136 /
81AB11000BA	M136 12/ 0,8
81AB11000BC	0/
81AB11000BO	M159 12/ 0,7 15a
81AB11000CA	M137 12/ 0,9 15a
81AB11000CA	M136 12/ 0,9 15a
81AB11000DA	M082 0/
81AB11000DB	M082 12/ 0,8

FORD	RMA \sqrt{Kw} -!	FORD	RMA \sqrt{Kw} -!	FORD	RMA \sqrt{Kw} -!
81AB11000DB	M082 $\frac{12}{0,8}$	82GB11000EA	M152 $\frac{12}{0,8}$ 15a	85GB11000BA	M260 $\frac{12}{1,4}$
81AB11000EA	M076 $\frac{12}{0,8}$	82GB11000FA	M152 $\frac{12}{0,8}$	85GB11000BA	M260 $\frac{12}{1,4}$
81AB11000EA	M076 $\frac{12}{0,8}$	82GB11000FA	M152 $\frac{12}{0,8}$ 15a	85GB11000CA	M260 $\frac{12}{1,4}$
81AB11000EA	M137 $\frac{12}{0,8}$	82GB11000FA	M152 $\frac{12}{0,8}$	85GB11000CA	M260 $\frac{12}{1,4}$
81AB11000EA	M082 $\frac{12}{0,8}$	835F11000AA	M059 $\frac{12}{2,5}$	85GB11000DA	M243 $\frac{12}{1,4}$
81AB11000EB	M082 $\frac{12}{0,8}$	835F11000AA	M059 $\frac{12}{2,5}$	85GB11000DA	M243 $\frac{12}{1,4}$
81AB11000EB	M137 $\frac{12}{0,8}$	835F11000AC	M059 $\frac{12}{2,5}$	85GB11000EA	M043 $\frac{12}{1,0}$
81AB11000FA	M082 $\frac{12}{0,8}$	835F11000AC	M059 $\frac{12}{2,5}$	85GB11000FA	M043 $\frac{12}{1,0}$
81AB11000FA	M082 $\frac{12}{0,8}$	835F11000BB	M059 $\frac{12}{2,5}$	85GB11000GA	M260 $\frac{12}{1,4}$
81AB11000FB	M076 $\frac{12}{0,8}$	835F11000CA	M059 $\frac{12}{2,5}$	85GB11000GA	M260 $\frac{12}{1,4}$
81AB11000FB	M082 $\frac{12}{0,8}$	835FX11000BB	M059 $\frac{12}{2,5}$	85GX11000BA	M260 $\frac{12}{1,4}$
81AB11000GB	M137 $\frac{12}{0,8}$	83BB11000AA	M285 $\frac{12}{2,2}$	85GX11000BA	M260 $\frac{12}{1,4}$
81AB11000GB	M076 $\frac{12}{0,8}$	83BB11000AA	M285 $\frac{12}{2,2}$	85GX11000DA	M243 $\frac{12}{1,4}$
81AB11000GB	M082 $\frac{12}{0,8}$	83BB11000AB	M159 $\frac{12}{2,2}$	85GX11000DA	M243 $\frac{12}{1,4}$
81AB11000GB	M076 $\frac{12}{0,8}$	83BB11000AB	M159 $\frac{12}{2,2}$	85GX11000EA	M043 $\frac{12}{1,0}$
81AX11000BA	M082 $\frac{12}{0,8}$	83BB11000BA	M159 $\frac{12}{2,2}$	85GX11000EA	M043 $\frac{12}{1,0}$
81AX11000BA	M082 $\frac{12}{0,8}$	83BB11000BA	M159 $\frac{12}{2,2}$	85GX11000FA	M043 $\frac{12}{1,0}$
81AX11000BA	M082 $\frac{12}{0,8}$	83BB11000BB	M159 $\frac{12}{2,2}$	85HU11001A	M043 $\frac{12}{1,0}$
81BB11000AA	M261 $\frac{12}{1,4}$	83BB11000BB	M159 $\frac{12}{2,2}$	86513093	RM034 $\frac{12}{1,4}$
81DB11000BB	RM038 $\frac{12}{1,4}$	83BB11000CA	M159 $\frac{12}{2,2}$	866B11000AA	M285 $\frac{12}{2,2}$
82005342	PM160 $\frac{12}{1,4}$	83BB11000CA	M159 $\frac{12}{2,2}$	86AB11000A1A	M214 $\frac{12}{2,2}$
82005342	PM160 $\frac{12}{1,4}$	83BB11000DA	M159 $\frac{12}{2,2}$	86AB11000AA	M214 $\frac{12}{2,2}$
82007917	PM160 $\frac{12}{1,4}$	83BB11000DA	M159 $\frac{12}{2,2}$	86AB11000AC	M214 $\frac{12}{1,7}$
82013922	PM160 $\frac{12}{1,4}$	83BB11000EA	M159 $\frac{12}{2,2}$	86AB11000AC	M214 $\frac{12}{1,7}$
82AB11000AB	M076 $\frac{12}{1,4}$	83BB11000EB	M159 $\frac{12}{2,2}$	86AB11000BA	M134 $\frac{12}{0,8}$
82AB11000AB	M082 $\frac{12}{1,4}$	83BB11000FA	M159 $\frac{12}{2,2}$	86AB11000BA	M076 $\frac{12}{0,8}$
82AB11000BA	M261 $\frac{12}{1,4}$	83BB11000FB	M159 $\frac{12}{2,2}$	86AB11000BA	M137 $\frac{12}{0,8}$
82AB11000BA	M261 $\frac{12}{1,4}$	83BB11000KB	M296 $\frac{12}{0,8}$	86AB11000CA	M137 $\frac{12}{0,8}$
82DB10300BB	RM038 $\frac{12}{1,4}$	83DB11000BB	PM263 $\frac{12}{0,8}$	86AB11000CA	M082 $\frac{12}{0,8}$
82DB10300BB	RM038 $\frac{12}{1,4}$	83FB11000AA	M082 $\frac{12}{0,8}$	86AB11000CA	M138 $\frac{12}{0,8}$
82DB11000BA	RM038 $\frac{12}{1,4}$	83FB11000AA	M076 $\frac{12}{0,8}$	86AB11000CA	M138 $\frac{12}{0,8}$
82DB11000BA	RM038 $\frac{12}{1,4}$	83FB11000AA	M076 $\frac{12}{0,8}$	86AB11000DA	M136 $\frac{12}{0,8}$
82DB11000BB	RM038 $\frac{12}{1,4}$	83FB11000AA	M082 $\frac{12}{0,8}$	86AB11000DA	M136 $\frac{12}{0,9}$ 15a
82DB11000DA	PM130 $\frac{12}{0,8}$	84AB11000AA	M214 $\frac{12}{1,7}$	86AB11000DA	M136 $\frac{12}{0,9}$ 15a
82DB11000DA	PM130 $\frac{12}{0,8}$	84AB11000AA	M264 $\frac{12}{1,7}$	86AB11000EA	M261 $\frac{12}{1,4}$
82DB11000EA	M059 $\frac{12}{0,8}$	84AB11000AA	M214 $\frac{12}{1,7}$	86AB11000EA	M261 $\frac{12}{1,4}$
82DB11000EA	PM263 $\frac{12}{0,8}$	84AB11000AB	M214 $\frac{12}{1,7}$	86AB11000EA	M261 $\frac{12}{1,4}$
82DB11000FA	PM167 $\frac{12}{0,8}$	84AB11000AC	M214 $\frac{12}{1,7}$	86AB11000FA	M134 $\frac{12}{0,8}$
82GB11000BA	M152 $\frac{12}{0,8}$	84AB11000AC	M214 $\frac{12}{1,7}$	86AB11000GA	M138 $\frac{12}{0,8}$
82GB11000CA	M152 $\frac{12}{0,8}$	84AU11001A	M214 $\frac{12}{1,7}$	86AB11000HA	M137 $\frac{12}{0,8}$
82GB11000DA	M030 $\frac{12}{0,7}$	84AU11001B	M214 $\frac{12}{1,7}$	86AB11000HA	M137 $\frac{12}{0,8}$
82GB11000DA	M030 $\frac{12}{0,7}$	84AU11001D	M214 $\frac{12}{1,7}$	86AB11000HA	M138 $\frac{12}{0,8}$
82GB11000EA	M152 $\frac{12}{0,8}$	85AB11000BA	M134 $\frac{12}{0,8}$	86AB11000JA	M137 $\frac{12}{0,8}$
82GB11000EA	M152 $\frac{12}{0,8}$	85BB11000AA	PM021 $\frac{12}{0,8}$	86AB11000JA	M137 $\frac{12}{0,8}$
82GB11000EA	M152 $\frac{12}{0,8}$	85BB11000AB	PM021 $\frac{12}{0,8}$	86AB11000KA	M082 $\frac{12}{0,8}$
82GB11000EA	M152 $\frac{12}{0,8}$	85GB11000BA	M260 $\frac{12}{0,8}$	86AB11000KA	M136 $\frac{12}{0,8}$

FORD	RMA $\sqrt{Kw - !}$	FORD	RMA $\sqrt{Kw - !}$	FORD	RMA $\sqrt{Kw - !}$
86AB11000NA	0	87BB11000GA	M190	89BB11000CA	PM250
86AB11000RA	M134 12/0,8	87BB11000GA	M190 12/1,0	89BB11000DA	PM089
86AB11000SA	M134 12/0,8	87BB11000JA	M260 12/1,4	89BB11000DB	PM089
86AB11000TA	M137 12/0,8	87BB11000JB	M260	89BB11000DC	PM089
86AB11000TA	M137 12/0,8	87BB11000JB	M260 12/1,4	89FB11000AA	M134 12/0,8
86AB11000TA	M138 12/0,8	87BB11000KA	M285 12/2,2	89FB11000AA	M134 12/0,8
86AB11000VA	M134 12/0,8	87BB11000KB	M285 12/2,2	89FB11000AA	M134 12/0,8
86BB11000AA	0	87BB11000KB	M296 12/2,2	89FB11000AA	M138 12/0,8
86BB11000AA	0	87BX11000DA	0	89FB11000BA	M137 12/0,8
86BB11000BA	0	87GB11000AA	0	89FB11000BA	M137 12/0,8
86BB11000BA	0	87GB11000AA	0	89FB11000BA	M138 12/0,8
86BB11000NA	0	87GB11000BA	M030 12/0,7	89FB11000CA	M138
86BB11000NA	0	87GB11000BA	M030 12/0,7	89FB11000CA	M138 12/0,9
86BB11000SA	M190 12/1,0	87GB11000BB	M030 12/0,7	89FB11000CA	M137 12/0,9
86FB11000CA	M136	87GB11000BB	M030 12/0,7	89FX11000BA	M137
86GB11000AA	M159 12/0,7	87GB11000CA	M263 12/1,4	89VB11000AA	PM025
86GB11000AA	M159 12/0,7 15a	87GB11000CA	M263 12/1,4	89VX11000AA	0
86GB11000AA	M159 12/0,7 15a	87GB11000CA	M263 12/1,4	900X11000AA	M137
86GB11000CA	M030 12/0,7	87GB11000CB	M263 12/1,4	900X11000BA	PM558
86GB11000CA	M030 12/0,7	87GB11000CB	M263 12/1,4	900X11000BA	PM558
86GB11000EA	M030 12/0,7	87GB11000CB	M263 12/1,4	90BB11000BB	0
86GB11000EA	M030 12/0,7	87GX11000AA	0	91AB11000AA	
86GB11000GA	M263 12/1,4	87GX11000AA	0	91AB11000AA	M261 12/1,4
86GB11000GA	M263 12/1,4	87VB11000AA	0	91AB11000AA	M261 12/1,4
86GB11000GA	M263 12/1,4	87VB11000AA	0	91AB11000AB	M261 12/1,4
86GB11000HA	M260 12/1,4	87VB11000BA	0	91AB11000AB	M261 12/1,4
86GB11000JA	M243	886B11000AA	M285	91AB11000AB	M261 12/1,4
86GB11000JA	M243 12/1,4	88BB11000BA	M243 12/1,4	91AB11000BA	M134 12/0,8
86GB11000JB	M243	88GB11000AA	M285 12/2,2	91AB11000BA	M134 12/0,8
86GB11000JB	M243 12/1,4	88VB11000AA	PM025	91AB11000BA	M134 12/0,8
874F11000AA	0	89821291	PM160	91AB11000BJ	M136 12/0,8
87BB11000AA	0	898821291	PM160	91AB11000BJ	M134 12/0,8
87BB11000AA	0	89AB11000AA	M214 12/1,7	91AB11000CA	M134
87BB11000CA	M190	89AB11000AA	M214 12/1,7	91AB11000CB	M134 12/0,8
87BB11000DA	PM558	89AB11000AA	M214 12/1,7	91AB11000DA	M134 12/0,8
87BB11000DA	PM558	89AB11000BA	M214 12/1,7	91AB11000EA	M134 12/0,8
87BB11000EA	M190	89AB11000BA	M214 12/1,7	91AB11000EA	M134
87BB11000EA	M034	89AB11000BA	M214 12/1,7	91AB11000EB	M214 12/1,7
87BB11000EB	M034	89AB11000CA	M307 12/2,2	91AB11000FA	M214
87BB11000EB	M190 12/1,0	89AB11000VA	M137	91AB11000FB	M214 12/1,7
87BB11000EC		89BB11000AA		91AB11000FB	M214 12/1,7
87BB11000EC	M190 12/1,0	89BB11000AA	M244	91AB11000GA	M214 12/1,7
87BB11000FA	PM558	89BB11000AB		91AB11000GA	M214 12/1,7
87BB11000FA	PM558	89BB11000AB	M244 12/1,8	91AB11000HA	M307 12/2,2

FORD	RMA $\sqrt{\text{Kw}} - !$	FORD	RMA $\sqrt{\text{Kw}} - !$	FORD	RMA $\sqrt{\text{Kw}} - !$
91AB11000HB	M307 $\frac{12}{2,2}$	91BB11000KA	M243 $\frac{12}{1,4}$	92AB11000GB	M217 $\frac{12}{1,4}$
91AB11000IA	M134 $\frac{12}{0,8}$	91BB11000LA		92AB11000HA	M214
91AB11000JA	M134 $\frac{12}{0,8}$	91BB11000LA	M244 $\frac{12}{1,8}$	92AB11000HA	M214 $\frac{12}{1,7}$
91AB11000JA	M134 $\frac{12}{0,8}$	91BB11000MA	PM250 $\frac{12}{1,8}$	92AB11000HA	M214 $\frac{12}{1,7}$
91AB11000JA	M134 $\frac{12}{0,8}$	91BB11000MA	PM250 $\frac{12}{1,8}$	92AB11000HB	
91AB11000JA	M138 $\frac{12}{0,8}$	91BB11000NA	PM089 $\frac{0}{}$	92AB11000HB	M214 $\frac{12}{1,7}$
91AB11000JB	M134 $\frac{12}{0,8}$	91BB11000NB	PM089 $\frac{0}{}$	92AB11000HB	M214 $\frac{12}{1,7}$
91AB11000JB	M134 $\frac{12}{0,8}$	91BX11000FA		92AB11000JA	M138
91AB11000JB	M134 $\frac{12}{0,8}$	91BX11000FA	M190 $\frac{0}{}$	92AB11000JA	M217 $\frac{12}{0,9}$
91AB11000KA	M137 $\frac{12}{0,8}$	91BX11000FX	M190 $\frac{0}{}$	92AB11000KA	M134 $\frac{12}{0,8}$
91AB11000KA	M137 $\frac{12}{0,8}$	91BX11000FX		92AX11000FA	M217 $\frac{12}{1,4}$
91AB11000KB	M137	91BX11000HB	M260 $\frac{0}{}$	92AX11000HA	M214 $\frac{0}{}$
91AB11000KB	M137 $\frac{12}{0,8}$	91BX11000HB	M260	92AX11000HB	M214
91AB11000KB	M137 $\frac{12}{0,8}$	91BX11000JA	M263 $\frac{0}{}$	92AX11000JA	M134 $\frac{0}{}$
91AB11000LA	M138	91BX11000JA		92BB11000AA	M190 $\frac{12}{1,0}$
91AB11000LA	M138 $\frac{12}{0,9}$	91BX11000KA	M243 $\frac{0}{}$	92VB11000AA	PM025 $\frac{0}{}$
91AB11000LA	M137 $\frac{12}{0,9}$	91BX11000LA		92VB11000AB	
91AB11000LB	M138	91BX11000LA	M244 $\frac{0}{}$	92VB11000AB	PM025 $\frac{0}{}$
91AB11000LB	M138 $\frac{12}{0,9}$	91BX11000MA	PM250 $\frac{0}{}$	92VB11000BA	$\frac{0}{}$
91AB11000LB	M137 $\frac{12}{0,9}$	91BX11000NB	PM089	92VX11000AA	PM025 $\frac{0}{}$
91AB11000LB	M138 $\frac{0}{}$	91DA11001AAB	RM079	92VX11000AB	$\frac{0}{}$
91AB11000PA	M214 $\frac{12}{1,7}$	91DA11001AB	RM080	92VX11000BA	$\frac{0}{}$
91AX11000AB	M261	91GB11000AA	M243	93BB11000AA	M235X
91AX11000AB		91GB11000AA	M243 $\frac{12}{1,4}$	93BB11000AA	M235X $\frac{12}{1,4}$
91AX11000HA	M307 $\frac{0}{}$	91GB11000AA	M243 $\frac{12}{1,4}$	93BB11000AB	M235X
91AX11000JA	M134 $\frac{0}{}$	91GB11000AB	M243	93BB11000AB	M235X $\frac{12}{1,4}$
91AX11000KA	M137 $\frac{0}{}$	91GB11000AB	M243 $\frac{12}{1,4}$	93BB11000BA	PM027 $\frac{0}{}$
91AX11000KB	M137 $\frac{0}{}$	91GB11000AB	M243 $\frac{12}{1,4}$	93BB11000BB	PM027 $\frac{0}{}$
91AX11000KB	M137	91GB11000BA	M285 $\frac{12}{2,2}$	93BB11000CA	M235X
91AX11000LA	M138 $\frac{0}{}$	91GB11000BA	M285 $\frac{12}{2,2}$	93BB11000CA	M235 $\frac{12}{1,4}$
91AX11000LA	M138	91GX11000AB	M243	93BB11000CB	M235X
91BB11000AA	M190 $\frac{12}{1,0}$	91GX11000AB	M243 $\frac{12}{1,4}$	93BB11000CB	M235 $\frac{12}{1,4}$
91BB11000BA	$\frac{0}{}$	92AB11000AA	M134 $\frac{12}{0,8}$	93BB11000DB	M235 $\frac{12}{1,4}$
91BB11000CA	M261	92AB11000AB	$\frac{0}{}$	93BB11000HA	M235
91BB11000DA	M190 $\frac{12}{1,0}$	92AB11000CA	M134 $\frac{12}{0,8}$	93BB11000HB	M235X $\frac{12}{1,4}$
91BB11000EA	$\frac{0}{}$	92AB11000DA	M261	93BB11000HC	M235X $\frac{0}{}$
91BB11000FA		92AB11000EA	M261	93BB11000JB	PM027 $\frac{0}{}$
91BB11000FA	M190 $\frac{12}{1,0}$	92AB11000EA	M217 $\frac{0}{}$	93BB11000JC	PM027 $\frac{0}{}$
91BB11000HA	M260	92AB11000FA	M261 $\frac{12}{1,4}$	93BB11000KA	PM253 $\frac{0}{}$
91BB11000HA	M260 $\frac{12}{1,4}$	92AB11000FB	M261	93BB11000KB	PM253 $\frac{0}{}$
91BB11000HB	M260	92AB11000FB	M261 $\frac{12}{1,4}$	93BB11000KC	PM253 $\frac{0}{}$
91BB11000HB	M260 $\frac{12}{1,4}$	92AB11000GA	M261	93BB11000KD	PM253 $\frac{0}{}$
91BB11000JA		92AB11000GA	M217 $\frac{12}{1,4}$	94AX11000AA	M137
91BB11000JA	M263 $\frac{12}{1,4}$	92AB11000GB	M261	94AX11000AA	M082 $\frac{0}{}$

FORD	RMA $\sqrt{Kw - !}$	FORD	RMA $\sqrt{Kw - !}$	FORD	RMA $\sqrt{Kw - !}$
94GX11000AA	M043	96FB11000CC	M389	98VB11000BBB	M420
94GX11000AA	M043	96FB11000KB	M317 $12/1,4$	B50518400	M431
95AB11000CA	M134	96FB11000KC	M317 $12/1,4$	BF5T11001AA	M277
95FB11000BB	M403	96FB11000KD	M317	BF5T11001AA	M277
95FB11000BC	M403	96FB11000LB	M389	C20F11001A	0
95FB11000BD	M403	96FB11000LC	M389	C20F11001D	0
95FB11000BD	M403	96FB11000LD	M389	C20F11001E	0
95FB11000BG	M403	96FB11000MC	M403	C20Z11001A	0
95GB11000AB	PM033	96FB11000ME	M403	C20Z11002A	0
95GB11000AB	PM033	96FB11000ME	M403	C2VF11002A	0
95GB11000CA	M190	97BB11000B3D	M307	C2VY11002A	0
95GB11000DA	PM033	97BB11000B3D	M307	C30F11001A	0
95GB11000EA	M260	97BB11000BB	M307	C30F11001B	0
95GB11000EA	M260 $12/1,4$	97BB11000BB	M307 $12/2,2$	C30Z11002B	0
95GB11000FA		97BB11000BC	M307	C30Z11002C	0
95GB11000FA	M190 $12/1,0$	97BB11000BD	M307	C40F11001A	0
95GX11000EA	M260	97JB11000AB	M387	C40F11001B	0
95SB11000BC	M389	97KB11000AA	M403	C4TF11001B	0
95VW11000AA	M236	97KB11000AA	M387	C4TZ11002B	0
95VW11000AA	M236 $12/1,1$	97KB11000AB	M403	C4VF11001A	0
95VW11000AB	M236	97KB11000AB	M387	C4VY11002A	0
95VW11000AB	M236	97KB11000AC	M403	C4ZF11001A	0
95VW11000BA	M248	97KB11000AC	M387	C5AF11001A	0
95VW11000BA	M248	97VB11000AA	M420	C5TF11001A	
95VW11000BB	M248	97VB11000AB	M420	C5TZ11001A	0
95VW11000BB	M248	97VW11000AA	M289	C5TZ11002A	0
95VW11000BC	PM070	97VW11000BA	M313	C5TZ11002C	
95VW11000CA	M383	98AB11000AC	M307	C6AF11001A	0
95VW11000CB	M289X $12/1,8$	98AB11000AD	M307	C6FF11001	
95VW11000CB	M282 $12/1,7$	98AB11000BB	M317	C6NF11000A	M294
95VW11000CC	M289X	98AB11000BC	M317	C6TF11000A	
95VW11000DA	M282	98AB11000BD	M317	C6TF11000C	
95VW11000EA	M310	98AB11000CA	M317	C6TZ11002E	
95VW11000EB	M313 $12/1,8$	98AB11000CB	M317	C6VF11001A	0
95VW11000EC	M313 $12/1,8$	98AB11000CC	M317	C6VY11002A	0
95VW11000GA	M313	98AB11000CD	M317	C70F11001A	0
95VW11000GA	M313	98AB11000EC		C7AF11001A	0
95VW11000GA	M289X $12/1,8$	98BB11000AA	PM253	C7AF11001B	
96BB11000A3C	M235X	98BB11000CD	PM264	C7AF11001C	0
96BB11000A4B	M235X	98BB11000GA	M260	C7AF11001E	0
96BB11000AA	M235X $12/1,4$	98BB11000GA	M260	C7AF11001F	0
96BB11000AB	M235X $12/1,4$	98VB11000B1A	M420	C7NN11000A	M294
96BB11000AC	M235X	98VB11000B3A	M420	C7NN11000B	M294
96FB11000CB	M389	98VB11000B3B	M420	C7TF11001A	0

FORD	RMA $\sqrt{\text{Kw -!}}$	FORD	RMA $\sqrt{\text{Kw -!}}$	FORD	RMA $\sqrt{\text{Kw -!}}$
C7ZF11001A	/	D40Z11002A	0	E3AZ11002A	/
C8AF11001A	0	D42F11001AB	0	E3TF11000AA	PM751
C8VF11001A	0	D42F11001BA	0	E3TF11001AA	/
C8VF11002A	0	D4AF11001AA	0	E3TU11000AA	PM751
C8VY11002A	0	D4AZ11002A	0	E3TZ11002A	/
C8VY11002C	0	D4NN11000B	M294	E3TZ11002B	PM751
C9AF11001A	0	D4TZ11002D	0	E3TZ11002D	/
C9AF11001B	0	D50F11001AA	0	E3TZ11002E	/
D0AF11001A	0	D50F11001AA	0	E47F10001AA	/
D0AF11001B	0	D50F11001BA	0	E4DF11001AA	/
D0AF11001C	0	D53018400	PM744	E4DF11001BA	/
D0AF11001E	0	D5AF11001AB	0	E4DZ11002B	/
D0NN11000A	M294	D5AF11001EA	0	E4TF11000AA	PM751
D0NN11000B	M294	D5AZ11002C	0	E5TF11000AA	PM751
D0TF11001A	0	D5FF11001AA	0	E5TZ11002B	PM751
D0VF11000A	0	D5TF11001AA	0	E6DF11001AA	/
D0VF11001A	0	D5TF11001C	0	E6DZ11002C	/
D0ZF11001A	0	D5TF11001DA	0	E6HT11001CA	/
D12F11001AA	0	D60F11001AA	0	E6HZ11002C	/
D12F11001AB	0	D60F11002A	0	E6HZ11002D	/
D1AF11001A	0	D60F11002AA	0	E8TF11000AA	PM751 0
D1AF11001AA	0	D6BF11001BA	0	E98F11000AA	0
D1AZ11002A	0	D6DF11002B	0	E98F11000BA	0
D1FF11001AA	0	D6TF11001AA	0	E9SF11000AA	0
D1FZ11002A	0	D6TF11001BA	0	E9SF11000AB	0
D1NN11000A	M294	D6TF11001DA	0	E9SF11000BA	0
D20F11001AA	0	D6TZ11002A	0	E9SZ11002A	0
D20F11001BA	0	D6TZ11002B	0	E9SZ11002B	0
D22F11001AA	0	D78VB11000EA	/	ED11001	RM080
D22F11001AB	0	D8NN11000CA	M294	ERR5009	M277
D2AF11001AA	0	D8NN11000CE	M294	F02Z11002A	RM080
D2AF11001BA	0	D8OF11001AA	0	F07U11000BA	0
D2AF11001CA	0	D9NN11000AA	M294	F0NN11000CA	PM160 0
D2AF11001DA	0	E1AF11001BA	0	F0TZ11002B	0
D2AF11001EA	0	E1AF11002B	0	F32Z11002B	PM366 0
D2AF11001JA	0	E25F11001AA	/	F3RU11131DB	0
D2FF11001AB	0	E25Y11002A	/	F3RZ11002C	PM253 0
D2NN11000B	M294	E25Z11002A	/	F6RU11131BA	0
D2TF11001AA	0	E2BF11001AA	/	F7HT11000AC	PM590 0
D2VF11001AA	0	E2BZ11002A	/	F7HT11000CA	PM590 0
D2ZF11001AA	0	E2SF11001AA	0	F7RU11000AA	PM342 0
D30Z11002A	0	E2SF11002AA	0	F89211002A	RM080
D3TF11001DA	0	E37F11001A	/	F8RU11130DB	M317 0
D40F11001AA	/	E3AF11001AA	/	F91BB11000MA	PM250 0

FORD	RMA $\sqrt{\text{Kw -!}}$	FORD	RMA $\sqrt{\text{Kw -!}}$	FORD	RMA $\sqrt{\text{Kw -!}}$
FONN11000CA	PM160 $\frac{0}{\text{ }}$	R83BB11000CA		R96FB11000LC	M389 $\frac{0}{\text{ }}$
FONN11000CA	PM160 $\frac{\text{ }}$	R85GB11000DA	M243 $\frac{0}{\text{ }}$	R98AB11000AC	M307 $\frac{\text{ }}$
FS0518400A	PM274 $\frac{\text{ }}$	R85GB11000DA	M243 $\frac{\text{ }}$	R98VB11000B1A	M420 $\frac{0}{\text{ }}$
NAD500220	PM583 $\frac{\text{ }}$	R85GX11000FA		RF0118400	PM400 $\frac{\text{ }}$
NN500210	M277 $\frac{\text{ }}$	R86AB11000A1A	M214 $\frac{0}{\text{ }}$	RF0118400A	PM400 $\frac{\text{ }}$
R71AB11001AA	PM598 $\frac{\text{ }}$	R86AB11000CA	M137 $\frac{0}{\text{ }}$	RV90BB11000BA	M311 $\frac{0}{\text{ }}$
R71BB11000LB	M152 $\frac{\text{ }}$	R86AB11000DA	M136 $\frac{0}{\text{ }}$	RV90BX11000AA	M311 $\frac{12}{1,4}$
R71BB11000LB	M152 $\frac{0}{\text{ }}$	R86AB11000DA		RV90BX11000BA	M312 $\frac{12}{1,4}$
R71BB11000LB		R86GB11000JB	M243 $\frac{0}{\text{ }}$	TAR911023	RM078 $\frac{\text{ }}$
R73AB11000BA	M159 $\frac{\text{ }}$	R86GB11000JB	M243 $\frac{\text{ }}$	TJG911023B	RM074 $\frac{\text{ }}$
R73AB11000BA		R87BB11000DA	PM558 $\frac{0}{\text{ }}$	TJG911023B	RM074 $\frac{\text{ }}$
R755F11000BB	M059 $\frac{0}{\text{ }}$	R87BX11000DA	PM558 $\frac{\text{ }}$	V84FB11000AA	M136 $\frac{12}{0,8}$
R755F11000BB	M059 $\frac{\text{ }}$	R87GB11000AA	$\frac{0}{\text{ }}$	V84FB11000BA	M136 $\frac{\text{ }}$
R76AB11000AA	M159 $\frac{\text{ }}$	R87GB11000AA	$\frac{0}{\text{ }}$	V84FB11000BA	M136 $\frac{12}{0,8}$
R76AB11000AA		R88BX11000BA	M243 $\frac{0}{\text{ }}$	V84FX11000BA	M136 $\frac{0}{\text{ }}$
R76BB11000AA	M043 $\frac{\text{ }}$	R89BB11000AB	M244 $\frac{0}{\text{ }}$	V84FX11000BA	M136 $\frac{\text{ }}$
R76EB11000AA	M049 $\frac{0}{\text{ }}$	R89BB11000AB		V85BB11000AA	PM021 $\frac{0}{\text{ }}$
R76EB11000AA		R89FB11000AA	M134 $\frac{0}{\text{ }}$	V85BB11000AB	PM021 $\frac{0}{\text{ }}$
R76EB11000BA	$\frac{0}{\text{ }}$	R89FB11000BA	M137 $\frac{0}{\text{ }}$	V85FB11000AA	PM021 $\frac{0}{\text{ }}$
R77BB11000AA	M152 $\frac{\text{ }}$	R89FB11000CA	M138 $\frac{0}{\text{ }}$	V85FB11000AB	PM021 $\frac{0}{\text{ }}$
R77BB11000AA	M152 $\frac{0}{\text{ }}$	R89FB11000CA	M138 $\frac{\text{ }}$	V90BB11000AA	M311 $\frac{12}{1,4}$
R77BB11000AA		R900X11000BA	PM558 $\frac{0}{\text{ }}$	V90BB11000AB	M311 $\frac{12}{1,4}$
R77BB11000BA	M152 $\frac{0}{\text{ }}$	R90X11000BA	PM558 $\frac{0}{\text{ }}$	V90BB11000BA	M312 $\frac{12}{1,4}$
R77BB11000BA	M152 $\frac{\text{ }}$	R91AX11000HB	M307 $\frac{0}{\text{ }}$	V90BB11000BB	M312 $\frac{12}{1,4}$
R77BB11000BA		R91AX11000JB	M134 $\frac{\text{ }}$	V90BX11000AA	M311 $\frac{12}{1,4}$
R77FB11000BA	M076 $\frac{0}{\text{ }}$	R91AX11000KB	M137 $\frac{\text{ }}$	V90BX11000BA	M312 $\frac{0}{\text{ }}$
R77FB11000BA		R91BB11000KA	M243 $\frac{0}{\text{ }}$	V94GB11000AC	PM229 $\frac{0}{\text{ }}$
R78VB11000DA	M093 $\frac{0}{\text{ }}$	R91BX11000FA	M190 $\frac{\text{ }}$	V95GB11000AA	PM229 $\frac{0}{\text{ }}$
R78VB11000DA	PM025 $\frac{0}{\text{ }}$	R91BX11000NB	PM089 $\frac{\text{ }}$	XC3U11000BA	PM585 $\frac{0}{\text{ }}$
R81AB11000BA	M013X $\frac{0}{\text{ }}$	R91GX11000AB	M243 $\frac{0}{\text{ }}$	XC3U11000CA	PM588 $\frac{\text{ }}$
R81AB11000BA	M013X $\frac{\text{ }}$	R92AB11000FB	M261 $\frac{\text{ }}$	XC4511001CA	RM077 $\frac{\text{ }}$
R81AB11000BA		R92AX11000HB	M214 $\frac{\text{ }}$	XE11001C	RM080 $\frac{\text{ }}$
R81AB11000CA	M136 $\frac{0}{\text{ }}$	R92AX11000JB	M134 $\frac{\text{ }}$	XS7U11000C3A	M235X $\frac{\text{ }}$
R81AB11000CA		R93BB11000AB	M235 $\frac{0}{\text{ }}$	XS7U11000C4A	M235X $\frac{\text{ }}$
R82DB11000DA	PM130 $\frac{0}{\text{ }}$	R93BB11000AC	M235X $\frac{0}{\text{ }}$	XS7U11000C4A1	M235X $\frac{0}{\text{ }}$
R82DB11000EA	PM263 $\frac{0}{\text{ }}$	R93BB11000BB	PM027 $\frac{\text{ }}$	YC1U11000AB	PM244 $\frac{0}{\text{ }}$
R82DB11000EA	M059 $\frac{\text{ }}$	R93BB11000JB	PM027 $\frac{\text{ }}$	YC1U11000AB	PM244 $\frac{\text{ }}$
R82GB11000EA		R93BB11000JC	PM027 $\frac{\text{ }}$	YC1U11000AE	PM244 $\frac{\text{ }}$
R82GB11000EA	M152 $\frac{0}{\text{ }}$	R94AX11000AA	M137 $\frac{\text{ }}$	YC1U11000AE	PM244 $\frac{\text{ }}$
R82GB11000EA		R95FB11000BD	M403 $\frac{\text{ }}$	YM2111000AB	PM080 $\frac{\text{ }}$
R835X11000AC	M059 $\frac{0}{\text{ }}$	R95GX11000EA	M260 $\frac{0}{\text{ }}$	YM2111000BA	PM080 $\frac{0}{\text{ }}$
R83AB11000AB	M214 $\frac{0}{\text{ }}$	R95VW11000DA	M282 $\frac{\text{ }}$	YS4U11000AA	M317 $\frac{0}{\text{ }}$
R83AB11000AB	M214 $\frac{\text{ }}$	R96FB11000CC	M389 $\frac{0}{\text{ }}$	YS4U11000AB	M317 $\frac{0}{\text{ }}$
R83BB11000CA	M159 $\frac{0}{\text{ }}$	R96FB11000KC	M317 $\frac{0}{\text{ }}$	YS4U11000BA	M317 $\frac{\text{ }}$

FORD

RMA $\sqrt{\text{Kw}}$ -!

FORD

RMA $\sqrt{\text{Kw}}$ -!

FORD

RMA $\sqrt{\text{Kw}}$ -!

ZBA911023A	RM068 $\sqrt{\text{Kw}}$ -!
ZBA911023A	RM068 $\sqrt{\text{Kw}}$ -!
ZBC911023	M148 $\sqrt{\text{Kw}}$ -!
ZBU911023	RM070 $\sqrt{\text{Kw}}$ -!
ZBU911023	RM070 $\sqrt{\text{Kw}}$ -!

HALLA	RMA $\frac{V}{Kw -!}$	HALLA	RMA $\frac{V}{Kw -!}$	HALLA	RMA $\frac{V}{Kw -!}$
HSC107100	M425X $\frac{0}{/}$				
HSC108100	PM609 $\frac{0}{/}$				
HSC109120	PM376 $\frac{0}{/}$				
HSG120500	M193 $\frac{0}{/}$				
HSG120510	PM387 $\frac{0}{/}$				
HSG232500	PM396 $\frac{0}{/}$				
HSP112110	M426 $\frac{0}{/}$				
HSP112130	M429 $\frac{0}{/}$				
HSP112140	PM363 $\frac{0}{/}$				
HSP112150	PM536 $\frac{0}{/}$				
HSP112160	PM535 $\frac{0}{/}$				

HELLA RMA $\sqrt{\text{Kw}} -!$

CS101	PM143
CS103	PM122
CS1030	PM182
CS1031	PM203
CS1032	PM224
CS1033	PM225
CS1034	PM192
CS1035	PM226
CS1036	M239
CS1037	M058X
CS1038	M270
CS1039	
CS1040	PM190
CS1041	PM057
CS1042	M402
CS1043	M409
CS1044	M399
CS1045	M384
CS1046	PM087
CS1047	PM076
CS1048	PM058
CS1049	PM044
CS1050	M317 ¹² 1,4
CS1051	PM097
CS1052	PM227
CS1053	M382
CS1054	PM056
CS1055	PM093
CS1056	M318
CS1057	M319
CS1058	PM027
CS1059	M058
CS106	PM129
CS1060	M416
CS1061	PM179
CS1062	PM070
CS1063	PM566
CS1065	PM229
CS1066	PM033
CS1067	M185X
CS1068	PM231
CS1069	PM175
CS107	PM334
CS1070	PM027

HELLA RMA $\sqrt{\text{Kw}} -!$

CS1071	PM043
CS1072	PM063
CS1073	M288
CS1074	PM037
CS1075	M083X
CS1076	PM324
CS1076	PM324
CS1077	PM180
CS1078	PM030
CS109	PM147 ¹² 2,0
CS1106	M376
CS1107	M235X ¹² 1,4
CS1108	PM233
CS1109	M400
CS1110	M243
CS1111	M391
CS1112	PM105
CS1113	PM065
CS1114	PM042
CS1115	PM083
CS1116	PM216
CS1116	PM216
CS1117	M414
CS1118	M352
CS1119	PM071
CS1120	PM151
CS1121	PM124
CS1122	PM222
CS1123	PM161
CS1124	M411
CS1125	M408
CS1126	PM160
CS1127	
CS1128	
CS1129	PM157
CS113	M253
CS1130	PM103
CS1131	PM234
CS1132	PM036
CS114	PM148
CS115	M031 ¹² 0,7
CS116	M106
CS1160	PM235
CS1161	PM219

HELLA RMA $\sqrt{\text{Kw}} -!$

CS1162	M088
CS1162	M088X
CS1163	PM217
CS1164	PM761
CS1165	PM082
CS1166	M093
CS1167	PM216
CS1168	
CS1169	RM040
CS117	M109
CS1170	M404 ¹² 2,2
CS1171	PM236
CS1172	PM066
CS1173	PM149
CS1174	PM237
CS1175	PM238
CS1176	PM072
CS1177	M105
CS1177	M105
CS1178	PM211
CS1179	PM010
CS118	M041 ¹² 1,1
CS1180	M395
CS1181	PM080
CS1182	RM085
CS1183	M143
CS1184	PM154
CS1185	PM096
CS1186	M430
CS1187	PM084
CS1188	RM086
CS1189	PM596
CS119	M070
CS119	M299
CS119	M072
CS1190	PM034
CS1191	M410
CS1191	M410
CS1192	M401
CS1192	M268
CS1192	M408
CS1192	M401
CS1192	M401
CS1192	PM305

HELLA	RMA $\sqrt{\text{Kw}} -!$	HELLA	RMA $\sqrt{\text{Kw}} -!$	HELLA	RMA $\sqrt{\text{Kw}} -!$
CS1193	PM239	CS1254	PM011	CS1293	PM572
CS1194	PM077	CS1255	PM539	CS1294	PM569
CS1195	M402X	CS1255	PM012	CS130	M070
CS1195	M407	CS1256	PM039	CS130	M118
CS1196	PM045	CS1257	M143X	CS131	M013 ¹² / _{0,7}
CS1197	PM073	CS1258	RM089	CS132	M109
CS1198	PM102	CS1259	PM545	CS1322	PM565
CS1199	RM087	CS126	M078 ¹² / _{0,7}	CS1323	PM573
CS120	PM106	CS1260	PM899	CS1324	PM564
CS1200	PM081	CS1261	PM173	CS1325	PM760
CS1201	M277X	CS1262	RM090	CS1326	PM094
CS1202	PM100	CS1263	PM926	CS1327	PM571
CS1203	PM099	CS1264	M384	CS1328	PM920
CS1204	PM934	CS1265	PM687	CS1329	PM919
CS1205	PM163	CS1266	PM577	CS133	M018
CS1206	PM314	CS1267	PM164	CS1330	PM563
CS1207	PM240	CS1268	PM594	CS135	
CS1208	PM078	CS1269	PM892	CS136	M051
CS1209	PM079	CS127	¹² / _{0,7}	CS138	M021
CS121	PM198	CS1270	M223X	CS139	M114
CS1210	PM732	CS1271	PM046	CS140	M172 ¹² / _{1,1}
CS1211	PM918	CS1272	PM016	CS141	
CS1212	PM241	CS1273	PM710	CS142	M075
CS1213	M393	CS1274	RM091	CS142	M075X
CS122	M081	CS1275	PM605	CS143	M084
CS122	M082	CS1276	PM912	CS143	M084X
CS123	M137	CS1277	PM243	CS147	M035 ¹² / _{0,8}
CS123	M082	CS1278	RM092	CS148	M064
CS123	M076	CS1279	PM106	CS149	M064 ¹² / _{2,0}
CS124	M064	CS128	M079	CS150	M075X
CS124	M064	CS1280		CS150	M179
CS1241	PM011	CS1281	PM239	CS152	¹² / _{1,5}
CS1242	PM242	CS1282	PM561	CS153	
CS1243	PM107	CS1283	PM547	CS154	
CS1244	PM243	CS1284		CS155	M161
CS1245	PM244	CS1285	PM170	CS156	M077
CS1246	PM245	CS1286	PM574	CS156	M293
CS1247	PM068	CS1287	M313X	CS156	M293
CS1248	PM109	CS1288		CS162	M095
CS1249	PM040	CS1289	PM548	CS162	M143
CS1250	PM067	CS129	M010	CS163	M156 ¹² / _{2,0}
CS1251	RM088	CS1290	PM897	CS165	M117
CS1252	PM246	CS1291	RM093	CS166	M067 ¹² / _{0,6}
CS1253	PM543	CS1292	PM883	CS168	M100

HELLA	RMA \sqrt{Kw} -!
CS169	M124X
CS169	M124
CS170	M021 $12' 1,0$
CS18	
CS180	M012 $12' 0,7$
CS181	
CS182	M047 $12' 1,3$
CS183	M073
CS184	M044 $12' 1,0$
CS185	M063
CS186	PM128
CS188	M089 $12' 2,0$
CS188	M089
CS191	PM204
CS194	PM184
CS198	PM189
CS200	M294
CS201	PM645
CS21	
CS230	M027
CS231	PM155
CS232	PM138
CS240	M091
CS261	M174
CS261	M096
CS263	M180
CS266	M295
CS267	M022
CS268	M087
CS268	M140
CS269	PM164
CS270	$12' 0,8$ 15a
CS272	M051
CS273	M101
CS274	
CS275	M011
CS276	
CS278	M082 $12' 0,8$
CS278	M138
CS278	M137
CS278	M136
CS280	M280
CS282	M116
CS285	M131

HELLA	RMA \sqrt{Kw} -!
CS285	M283
CS285	M023
CS286	M026
CS289	M028
CS290	M052
CS292	M172
CS293	M145
CS293	M108
CS293	M034
CS293	M107
CS294	M150 $12' 0,9$ 15a
CS294	M111
CS295	M014
CS297	M148
CS297	M068
CS298	M251
CS299	M218
CS300	PM555
CS301	M153
CS306	M104
CS308	M039
CS310	M202
CS310	M017 $12' 0,8$
CS310	M017X
CS311	M164
CS311	M165 $12' 1,5$
CS314	M254
CS315	M119X
CS315	M119
CS315	M192
CS316	M029 $12' 1,0$
CS317	M124X
CS321	M084
CS321	M084X
CS322	M052
CS322	M015
CS322	M015X
CS323	
CS324	
CS325	M264
CS325	M214
CS326	M102
CS327	M083
CS327	M083X

HELLA	RMA \sqrt{Kw} -!
CS328	M243
CS329	M263
CS330	M260
CS331	M088
CS331	M088
CS332	RM039
CS333	PM247
CS334	M025
CS335	PM119
CS336	PM130
CS337	M059
CS338	M121
CS338	M121X
CS339	PM130
CS340	M296
CS341	M214
CS342	M103
CS343	M285
CS344	M033
CS344	M270
CS344	M055
CS345	M059
CS346	M237 $12' 1,4$
CS347	M065
CS348	M250
CS349	PM167
CS350	M258
CS351	M053
CS352	M010
CS353	M121X
CS353	M121
CS354	M120
CS355	M075X
CS356	M162
CS357	M261
CS358	M257
CS359	PM021
CS360	M216 $12' 1,7$
CS361	M157
CS362	M010
CS363	M097
CS364	M113X
CS364	M113
CS365	

HELLA RMA $\frac{V}{Kw - !}$

CS366	M297X	
CS366	M297	$\frac{12}{2,5}$
CS367		
CS368	M061	
CS369		
CS370	M246	
CS371	M056	$\frac{12}{0,9}$
CS372	M099	
CS373	M105	
CS373	M105X	
CS374	M058	
CS375	M062	
CS376	M045	
CS376	M048X	
CS377	M175	
CS378	M037	
CS379	M044	
CS380	M110	
CS381		$\frac{12}{2,5}$
CS382	M161	
CS383	PM193	
CS384	PM199	
CS385		
CS386	M066X	
CS386	M066X	
CS387	PM139	
CS388	PM141	
CS389	M240	$\frac{12}{1,4}$
CS390	M176	
CS390	M222	
CS391	PM110	
CS392		
CS393	M046	
CS394	PM146	
CS395	PM121	
CS396	M166	
CS397		
CS398	PM158	
CS399		
CS500	M238	
CS501	PM156	
CS502	PM207	
CS503	PM115	
CS504	M048	

HELLA RMA $\frac{V}{Kw - !}$

CS505	M032	
CS506	PM201	
CS508		
CS509	M115	$\frac{12}{1,0}$ 15a
CS510	M054	
CS511	PM125	
CS514	M057	
CS515	M299X	
CS516	M185	
CS518	M226	
CS519	M143	$\frac{12}{0,9}$
CS523	M215	
CS524	M278	$\frac{12}{3,1}$
CS526	PM194	
CS526	PM194	
CS528	M308	$\frac{12}{0,8}$
CS528	M308	
CS529	M301	
CS530	PM137	
CS531		
CS535	M095	
CS535	M143	
CS536	M131	
CS536	M283	
CS541	M244	
CS542	M195	
CS543	M277	
CS543	M277X	
CS544	PM192	
CS545	M215	
CS546	PM195	
CS547		
CS548	M069X	$\frac{12}{1,4}$
CS550	PM149	
CS551	PM024	
CS554	M228	
CS555	M089	
CS556		
CS559	M191	$\frac{12}{1,0}$
CS561	PM684	
CS562	M190	$\frac{12}{1,0}$
CS564	PM202	
CS565	PM206	
CS566	M102X	

HELLA RMA $\frac{V}{Kw - !}$

CS567	M275	
CS569	M227	
CS569	M112	
CS570	PM248	
CS571		
CS573	M276	
CS574	PM050	
CS575	M120X	
CS576	M247	
CS577	M375	$\frac{12}{1,4}$ 30h
CS578	PM020	
CS579	M223	
CS580	M297X	$\frac{12}{2,5}$
CS581	M222	
CS581	M222	
CS582		
CS583	PM051	
CS584	M219	
CS585	M200	$\frac{12}{1,4}$
CS587	M305	
CS588	M304	
CS589	M305	$\frac{12}{1,4}$
CS590	M277	
CS590	M277	
CS591	RM094	
CS592	M138	$\frac{12}{0,9}$
CS592	M134	$\frac{12}{0,8}$
CS592	M137	$\frac{12}{0,8}$
CS594	M390	
CS594	M105	
CS595	PM169	
CS597	M392	
CS598	M256	$\frac{12}{1,8}$
CS599	M394	
CS60		
CS600	PM053	
CS601	M306	
CS602		
CS603		
CS604	PM162	
CS605	PM132	
CS606	M063	
CS606	PM048	
CS607	PM120	

HELLA	RMA \sqrt{Kw} -!
CS608	PM108
CS609	PM558
CS61	
CS610	M406
CS611	M151
CS612	M227
CS613	M307
CS614	M306
CS615	M386
CS616	M383
CS617	PM210
CS618	M150
CS618	M248 $12/1,1$
CS618	M111
CS619	M236
CS62	$12/0,7$
CS620	M282
CS621	M176
CS622	M182
CS623	PM263
CS624	M069
CS625	M243 $12/1,4$
CS65	
CS66	M094 $12/0,6$
CS67	
CS680	M262 $12/1,4$
CS681	M017X
CS682	PM135
CS683	M251
CS684	M120X
CS685	M261
CS686	M062X $12/1,4$
CS687	M013X
CS688	PM215
CS689	M027X
CS69	M152 $12/0,8$ 15a
CS69	M049
CS690	
CS691	M308
CS692	M213 $12/0,6$
CS693	M309
CS694	
CS695	PM685
CS696	

HELLA	RMA \sqrt{Kw} -!
CS697	
CS698	
CS699	PM170
CS70	M096 $12/0,8$
CS700	
CS701	RM095 $12/2,1$
CS702	
CS703	PM689
CS704	M074
CS706	PM121
CS707	PM118
CS708	
CS709	M048X $12/2,2$
CS710	PM191
CS711	M271 $12/1,0$
CS712	M105X
CS713	PM091
CS713	M310
CS714	M260
CS715	M440
CS716	M089
CS717	M281
CS718	PM159
CS719	M235X $12/1,4$
CS72	M049 $12/1,1$
CS720	PM249
CS721	PM089
CS722	PM250
CS723	M034
CS723	M255
CS724	M217
CS725	PM026
CS726	PM140
CS727	M099X
CS74	M158
CS74	M072
CS76	M038
CS77	M024 $12/0,8$
CS77	M016 $12/0,8$ 15a
CS78	M159
CS78	M030
CS782	PM092
CS783	PM134
CS784	M415

HELLA	RMA \sqrt{Kw} -!
CS785	
CS786	M311
CS787	M312 $12/1,4$
CS788	M255
CS789	M313 $12/1,8$
CS79	M149 $12/0,8$
CS79	M145 $12/0,8$
CS79	M107 $12/0,8$ 15a
CS79	M107
CS79	M108
CS79	M034
CS790	M235
CS791	M417
CS792	PM055
CS793	PM054
CS794	PM088
CS795	M091
CS796	M268
CS796	M265
CS797	
CS798	PM684
CS80	M093
CS800	M269 $12/0,9$
CS801	M396
CS802	PM031
CS803	
CS804	PM123
CS805	PM197
CS806	
CS807	M388
CS808	
CS81	M197
CS83	M295
CS83	M197
CS86	M043
CS87	M174
CS878	M381
CS879	M314
CS880	M255 $12/1,1$
CS881	PM213
CS882	PM251
CS883	M362 $12/0,9$
CS884	PM028
CS885	PM094

HELLA RMA $\sqrt{\text{Kw}} -!$

CS886	PM252	
CS887	PM176	
CS888	PM052	
CS889	PM599	
CS89	M041	$12/1,1$
CS90	M033	$12/0,8$
CS90	M033X	$12/0,8$
CS91	M032	
CS92	M203	$12/0,8$
CS92	M203	
CS92	M070	$12/0,8$
CS93	M070	
CS93	M196	$12/0,8$
CS93	M118	
CS94	PM908	
CS941	M423	
CS944	PM162	
CS946	PM333	
CS946	M010	
CS947	PM779	
CS948	RM096	
CS949	PM690	
CS95	M077	$12/0,6$
CS95	M119	
CS95	M119X	
CS95	M192	
CS950		
CS951	PM181	
CS951	PM181	
CS951	PM181	
CS951	PM181	
CS951	PM181	
CS951	PM181	
CS951	PM181	
CS951	PM181	
CS952		
CS953		
CS954	PM200	
CS955	PM187	
CS956	PM183	
CS957	RM097	
CS958	M044	
CS959	RM098	
CS960	M389	

HELLA RMA $\sqrt{\text{Kw}} -!$

CS961	PM253	
CS962	PM218	
CS963	M265	
CS964	M419	
CS965	M057	
CS97	PM136	
CS971	M403	
CS972	PM025	
CS973	M284	$12/2,2$
CS974	M289	
CS975	M283	$12/0,9$
CS975	M283X	
CS976	M385	
CS977	M420	
CS978	PM254	
CS978	PM254	
CS979	PM022	
CS98	PM190	
CS980	M017E	
CS981	M405	
CS982	PM032	
CS983	PM215	
CS984	M037X	
CS985	PM049	
CS986	M387	
CS987	RM099	
CS988	M315	$12/1,8$
CS988	M315	
CS989	PM174	
CS99	PM192	
CS990	M398	
CS991	PM255	
CS992	M316	
CS993		
CS994	PM691	
CS995	PM113	
CS996	PM117	
CS997	PM335	
DC1004		
DC1004		
DC1005		
DC1005		
DC1006		
DC1006		

HELLA RMA $\sqrt{\text{Kw}} -!$

DC1007		
DC1007		
DC1009		
DC1011		
DC1011		
DC1011		
DC1011		
DC1012		
DC1012		
DC1012		
DC1013		
DC1014		
DC1014		
DC1015		
DC1016		
DC1017		
DC1017		
DC1018		
JS1000	M431	
JS1001	PM256	
JS1003	PM257	
JS1003	PM449	
JS1004	M429	
JS1005	PM258	
JS1006	M345	$12/1,2$
JS1007	PM259	
JS1008	M445	
JS1009	PM260	
JS1010	PM680	
JS1011	PM261	
JS1012	PM262	
JS1013	PM449	
JS1014	PM391	
JS1015	PM491	
JS1016	PM013	
JS1017	PM297	
JS1018	PM487	
JS1019	PM475	
JS1020	PM339	
JS1021	PM479	
JS1022	PM286	
JS1023	PM496	
JS1024	PM498	
JS1024	PM017	

HELLA	RMA $\sqrt{\text{Kw}} -!$	HELLA	RMA $\sqrt{\text{Kw}} -!$	HELLA	RMA $\sqrt{\text{Kw}} -!$
JS1079	PM013	JS1149	PM499	JS1301	PM341
JS1080	M428X	JS1150	PM298	JS1302	PM871
JS1081	M320X	JS1151	M427X	JS1303	PM659
JS1082	PM471	JS1152	PM289	JS1304	PM665
JS1083	PM291	JS1153	PM345	JS1305	PM544
JS1084	PM477	JS1154	PM502	JS1306	PM642
JS1085	PM482	JS1155	PM503	JS1307	PM889
JS1086	PM473	JS1156	M413	JS1308	PM888
JS1087	PM280	JS1157	PM500	JS1309	PM697
JS1088	PM095	JS1158	PM641	JS1310	PM887
JS1089	M335X	JS1210	PM704	JS1311	PM660
JS1090	PM419	JS1214	M380	JS1312	PM661
JS1091	M421	JS1214	M380	JS1313	PM702
JS1092	PM350	JS1215	PM290	JS1314	PM454
JS1093	PM510	JS1216	M418	JS1315	PM544
JS1094	PM374	JS1217	PM504	JS1316	PM707
JS1095	M429X	JS1218	PM505	JS156	
JS1096	PM342	JS1219	PM337	JS3	
JS1097	PM343	JS1220	PM507	JS300	M424
JS1098	M435	JS1221	PM412	JS301	PM369
JS1098	M431	JS1222	PM846	JS302	PM405
JS1099	PM492	JS1223	PM508	JS303	PM371
JS1100	M443	JS1224	PM532	JS304	PM372
JS1101	PM490	JS1225	PM519	JS305	M320
JS1102	PM386	JS1226	PM069	JS306	PM377
JS1103	PM470	JS1227	PM399	JS307	PM405
JS1104	PM522	JS1228	PM506	JS308	M374 ^{12/1,2}
JS1105	PM015	JS1229	PM885	JS309	PM327
JS1133	PM497	JS1230	PM893	JS310	M128
JS1134	PM493	JS1231	PM857	JS310	M128
JS1135	M397	JS1232	PM645	JS311	PM287
JS1136	PM340	JS1233	PM532	JS312	PM434
JS1137	PM517	JS1234	PM662	JS314	M128X
JS1138	PM501	JS1235	PM757	JS315	M130 ^{12/1,0}
JS1139	PM344	JS1236	PM018	JS316	PM423
JS1140	PM398	JS1237	PM490	JS317	PM796
JS1141	PM489	JS1238	PM739	JS318	PM384
JS1142	PM301	JS1239	PM420	JS319	M194 ^{12/1,0}
JS1143	PM468	JS1295	PM758	JS319	M194
JS1144	PM494	JS1296	PM740	JS320	PM402
JS1145	PM624	JS1297	PM604	JS320	PM402
JS1146	M431	JS1298	PM683	JS322	PM370
JS1147	PM288	JS1299	PM827	JS323	PM741
JS1148	PM630	JS1300	PM748	JS325	M433

HELLA RMA $\sqrt{\text{Kw}} -!$

JS325	M433
JS327	PM408
JS329	PM643
JS330	M439
JS331	PM780
JS333	PM600
JS335	PM602
JS336	PM603
JS337	PM778
JS338	PM785
JS339	PM431
JS339	PM431
JS342	PM403
JS343	PM643
JS344	M193
JS345	PM379
JS345	PM379
JS346	
JS347	PM283
JS348	PM787
JS349	M425
JS350	M425X
JS351	PM403
JS353	PM623
JS354	PM459
JS355	PM380
JS356	M432
JS357	M325
JS358	PM273
JS359	PM272
JS360	M127
JS362	PM409
JS363	PM388
JS364	PM527
JS365	PM400
JS368	PM600
JS370	M172
JS371	PM424
JS372	M334X $^{12}_{0,6}$
JS373	PM351
JS375	PM293
JS375	PM293
JS376	M129
JS377	PM443

HELLA RMA $\sqrt{\text{Kw}} -!$

JS378	M441
JS379	PM272
JS380	M327 $^{12}_{0,7}$
JS381	PM601
JS382	PM437
JS383	PM415
JS384	
JS385	PM444
JS386	PM446
JS387	M328
JS388	PM425
JS389	PM512
JS391	PM533
JS392	PM419
JS393	PM788
JS395	PM370
JS396	M425X
JS397	M332
JS399	PM281
JS512	M446
JS513	PM383
JS517	M336X $^{12}_{2,5}$
JS520	PM385
JS521	PM429
JS522	M434
JS525	PM456
JS527	PM445
JS532	PM676
JS533	PM465
JS534	PM459
JS537	PM407
JS538	PM381
JS539	PM265
JS540	PM282
JS549	PM459
JS552	PM432
JS553	PM396
JS554	
JS556	PM526
JS557	M442
JS558	M211 $^{12}_{0,8}$
JS560	PM015
JS560	PM015
JS563	PM469

HELLA RMA $\sqrt{\text{Kw}} -!$

JS568	M252 $^{12}_{2,2}$
JS568	M314
JS626	PM296
JS627	M201 $^{12}_{1,4}$
JS628	M426
JS629	M333 $^{12}_{2,0}$
JS630	M334
JS631	M325X
JS632	M440
JS633	PM609
JS634	PM401
JS635	PM365
JS636	PM274
JS637	PM274
JS638	M374
JS639	PM268
JS640	M431
JS641	PM464
JS642	M335
JS643	PM376
JS644	PM455
JS645	PM295
JS646	PM744
JS647	PM347
JS648	M427
JS649	PM523
JS650	M336 $^{12}_{2,0}$
JS651	M423
JS652	PM462
JS652	M440
JS653	PM336
JS654	PM359
JS655	PM458
JS656	M370
JS657	PM430
JS658	PM299
JS659	PM435
JS660	M336X
JS660	M336X
JS661	M337
JS662	PM275
JS663	PM466
JS664	PM454
JS665	PM461

HELLA RMA $\frac{V}{Kw -!}$

JS666	PM433
JS667	PM357
JS668	PM516
JS669	PM416
JS670	PM364
JS671	M437
JS672	M338
JS673	PM747
JS674	PM404
JS675	PM442
JS676	PM426
JS677	PM644
JS678	M422
JS679	PM270
JS728	PM392
JS729	PM621
JS730	M438X
JS731	PM420
JS732	PM421
JS733	PM422
JS734	PM428
JS735	PM414
JS736	PM417
JS737	PM542 ¹² 1,2
JS738	PM765
JS739	PM773
JS740	PM772
JS741	PM768
JS742	PM762
JS743	PM764
JS744	PM766
JS745	PM413
JS746	PM279
JS747	PM366
JS748	PM278
JS749	PM763
JS750	PM770
JS751	PM632
JS752	PM352
JS753	M340 ¹² 1,4
JS754	PM521
JS755	M424
JS756	PM375
JS757	PM364

HELLA RMA $\frac{V}{Kw -!}$

JS758	M328
JS759	PM341
JS760	PM460
JS761	PM457
JS762	PM023
JS763	PM361
JS764	PM416
JS765	PM294
JS766	M443
JS766	M443
JS767	PM276
JS768	PM360
JS769	M341
JS770	M193 ¹² 2,0
JS770	M193
JS770	PM397
JS771	PM514
JS772	PM373
JS773	PM354
JS774	PM466
JS775	PM410
JS776	PM271
JS777	PM395
JS778	PM627
JS779	M342
JS780	PM485
JS781	PM363
JS890	M447
JS891	PM520
JS892	PM394
JS893	PM509
JS893	PM509
JS894	PM476
JS895	PM378
JS896	PM436
JS897	PM427
JS898	PM447
JS899	PM450
JS900	PM452
JS901	M444
JS902	PM481
JS903	PM387
JS904	PM280
JS905	PM617

HELLA RMA $\frac{V}{Kw -!}$

JS906	PM463
JS907	PM746
JS908	M438
JS909	PM453
JS910	PM448
JS911	PM353
JS912	PM495
JS913	M428
JS914	PM349
JS914	PM349
JS915	PM368
JS916	PM474
JS917	PM472
JS918	PM488
JS919	PM367
JS920	PM355
JS922	PM536
JS923	PM535
JS924	PM518
JS925	PM411
JS926	PM440
JS927	PM393
JS928	PM389
JS929	PM441
JS930	PM816
JS931	PM782
JS932	PM783
JS933	PM824
JS934	PM769
JS935	M374
JS936	M252X
JS937	PM362
JS938	PM513
JS939	M343 ¹² 1,2
JS940	PM348
JS941	M344 ¹² 1,4
JS942	M412
JS943	PM467
JS998	PM480
JS999	PM277
JS999	PM277
US1027	
US1027	
US1027	

HELLA	RMA V/Kw -!	HELLA	RMA V/Kw -!	HELLA	RMA V/Kw -!
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1027	/				
US1028	/				
US628	/				
US811	PM752				
US813	/				
US814	/				
US814	/				
US814	/				
US814	/				
US814	/				
US816	/				
US816	/				
US816	/				
US816	/				
US816	/				
US816	/				
US816	/				
US816	/				
US817	/				
US819	/				
US823	PM753				
US827	PM223				
US837	/				
US845	PM751				
US866	/				
US870	/				

HITACHI	RMA $\sqrt{\text{Kw}} -!$	HITACHI	RMA $\sqrt{\text{Kw}} -!$	HITACHI	RMA $\sqrt{\text{Kw}} -!$
S108101	PM610	S114156	M424	S114180G	PM405
S108112	PM611	S114156A	M424	S114180M	PM405
S108116	PM612	S114160	M424	S114181	PM405
S10841	PM613	S114160A	M424	S114182	PM405
S10861F	PM612	S114160B	M424	S114182B	PM405
S10863	M128	S114160D	M424	S114182E	PM405
S10863	M128	S114160E	M424	S114182F	PM405
S10876	PM614	S114160F	M424	S114182G	PM405
S10876A	PM614	S114160G	M424	S114184	PM617
S10876B	PM614	S114160H	M424	S114192	PM459
S10889	M128	S114161	PM369	S114194	PM618
S10889	M128	S114161B	PM369	S114202	PM459
S10894	PM611	S114161E	PM369	S114202A	PM459
S11126	M424	S114161F	PM369	S114208	M424
S113105		S114162	M424	S114208B	M424
S114103	PM405	S114162A	PM616	S114210	M128
S114103K	PM405	S114162D	PM616	S114211	M128
S114103L	PM405	S114163	M424	S114213	PM619
S114103M	PM405	S114163A	M424	S114213A	PM619
S114103N	PM405	S114163B	M424	S114221	M128
S114103P	PM405	S114163C	M424	S114222	M128
S114105	PM265	S114163E	M424	S114227	M128
S114108	PM405	S114163F	M424	S114229	
S114108L	PM405	S114164	PM615	S114229E	PM371
S114108M	PM405	S114164A	PM615	S114229F	PM371
S114111		S114166		S114230	PM620
S114112		S114169		S114230A	PM620
S114116	PM420	S114170	PM405	S114232	M172
S114121	PM371	S114170B	PM405	S114232	M172 ¹² / _{1,1}
S114121N	PM371	S114170E	PM405	S114232A	M172
S114122	PM371	S114172	PM371	S114235	PM621
S114126	PM405	S114172A	PM371	S114235A	PM621
S114126M	PM405	S114172D	PM371	S114237	M172
S114139	PM405	S114172E	PM371	S114237	M172 ¹² / _{1,1}
S114140	M128	S114173	PM371	S11423K	PM617
S114141	M128	S114173B	PM371	S114240	
S114146	PM420	S114173E	PM371	S114244	PM420
S114149	M128	S114173F	PM371	S114245	M128
S114150	PM615	S114174	PM405	S114247	PM459
S114150L	PM615	S114180	PM405	S114247A	PM459
S114151	PM615	S114180A	PM405	S114247B	PM459
S114151L	PM615	S114180B	PM405	S114247C	PM459
S114152	PM369	S114180E	PM405	S114249	PM283
S114155	PM369	S114180F	PM405	S114252	PM622

HITACHI	RMA $\frac{V}{Kw -!}$	HITACHI	RMA $\frac{V}{Kw -!}$	HITACHI	RMA $\frac{V}{Kw -!}$
S114252A	PM622	S114305	M128 $\frac{12}{1,0}$	S114377	PM514 $\frac{0}{}$
S114252C	PM622	S114306	PM625	S114378	PM527 $\frac{0}{}$
S114252E	PM622 $\frac{0}{}$	S114309	PM625	S114378A	PM527
S114252F	PM622 $\frac{0}{}$	S114315	M320 $\frac{12}{0,8}$	S114381	PM542 $\frac{12}{1,2}$
S114253	PM377 $\frac{0}{}$	S114315	M320 $\frac{12}{0,8}$	S114385	PM627 $\frac{0}{}$
S114254	PM377 $\frac{0}{}$	S114316	M320 $\frac{12}{0,8}$	S114389	PM327 $\frac{0}{}$
S114254A	PM377	S114316	M320 $\frac{12}{0,8}$	S114389A	PM327
S114254B	PM377	S114317	PM526 $\frac{0}{}$	S114390	PM327 $\frac{0}{}$
S114254C	PM377	S114317A	PM526	S114390A	PM327
S114254D	PM377	S114317B	PM526	S114391	M441 $\frac{0}{}$
S114254F	PM377	S114318	PM526 $\frac{0}{}$	S114391A	M441
S114255	M374 $\frac{0}{}$	S114318A	PM526	S114393	PM383 $\frac{0}{}$
S114255A	M374	S114319	PM372 $\frac{0}{}$	S114393A	PM383
S114257	PM420 $\frac{0}{}$	S114320	PM372 $\frac{0}{}$	S114395	PM379 $\frac{12}{2,0}$
S114257A	PM420	S114320A	PM372	S114395A	PM379 $\frac{0}{}$
S114257C	PM420	S114322	PM523 $\frac{0}{}$	S114396	PM287 $\frac{12}{1,0}$
S114257D	PM420	S114322A	PM523	S114396D	PM287
S114257G	PM420 $\frac{0}{}$	S114323	PM626	S114402	M320 $\frac{0}{}$
S114258	PM377 $\frac{0}{}$	S114340	PM293 $\frac{12}{1,0}$	S114403	PM516 $\frac{0}{}$
S114258A	PM377	S114341	PM293 $\frac{0}{}$	S114403B	PM516
S114258C	PM377	S114344	PM377 $\frac{0}{}$	S114403B	PM516
S114268	PM377 $\frac{0}{}$	S114345	PM527 $\frac{0}{}$	S114411B	PM410
S114269	M128 $\frac{0}{}$	S114345A	PM527	S114414	PM628 $\frac{0}{}$
S114270	PM459	S114345B	PM527	S114414A	PM628
S114271	PM459 $\frac{0}{}$	S114348	PM371 $\frac{0}{}$	S114416	$\frac{0}{}$
S114272	PM283 $\frac{0}{}$	S114348A	PM371	S114418	M442 $\frac{0}{}$
S114290	PM623 $\frac{0}{}$	S114349	PM420 $\frac{0}{}$	S114419	M442 $\frac{0}{}$
S114290A	PM623	S114349A	PM420	S114419A	M442
S114290B	PM623	S114349B	PM420	S114419A	M442
S114293	PM273 $\frac{0}{}$	S114350	PM293 $\frac{12}{1,0}$	S114424	M442 $\frac{0}{}$
S114295	PM405 $\frac{0}{}$	S114351	PM293 $\frac{12}{1,0}$	S114424A	M442
S114295A	PM405	S114354D	$\frac{0}{}$	S114426	$\frac{0}{}$
S114295B	PM405	S114356	$\frac{0}{}$	S114427	PM405 $\frac{0}{}$
S114296	M374 $\frac{12}{1,2}$	S114357	PM512 $\frac{0}{}$	S114429	M445 $\frac{0}{}$
S114296A	M374	S114357A	PM512	S114429A	M445
S114296B	M374	S114357B	PM512	S114430	PM629
S114296C	M374	S114357C	PM512	S114430A	PM629
S114296D	M374	S114362	M211 $\frac{0}{}$	S114430B	PM629
S114297	M109 $\frac{12}{1,1}$ 15a	S114362A	M211	S114432	PM630 $\frac{0}{}$
S114297	M109 $\frac{12}{1,1}$ 15a	S114363	M128 $\frac{12}{1,0}$	S114432A	PM630
S114301	M128 $\frac{0}{}$	S114364	M320 $\frac{12}{0,8}$	S114439	PM629 $\frac{0}{}$
S114303	PM624 $\frac{0}{}$	S114367	PM273 $\frac{0}{}$	S114439A	PM629
S114303A	PM624	S114374	PM516 $\frac{0}{}$	S114440	PM385 $\frac{0}{}$
S114304	M374 $\frac{12}{1,2}$	S114374B	PM516	S114441	PM410 $\frac{0}{}$

HITACHI	RMA $V_{Kw -!}$	HITACHI	RMA $V_{Kw -!}$	HITACHI	RMA $V_{Kw -!}$
S114441A	PM410	S114503	PM513	S114568	M320 $^{12}_{0,8}$
S114441B	PM410	S114503A	PM513	S114568	M320
S114443	PM631	S114505	PM632 0	S114569	PM341
S114443A	PM631	S114505A	PM632	S114570	M338 $^{12}_{1,0}$
S114446	0	S114509	PM359 0	S114570A	M338
S114452	PM630 0	S114516	PM513 0	S114570B	M338
S114452A	PM630	S114517	PM361 $^{12}_{2,0}$	S114570C	M338
S114453	M374 $^{12}_{1,2}$	S114517C	PM361	S114576	PM634
S114454	M374 0	S114519	PM362 $^{12}_{2,0}$	S114603	0
S114456	PM630 0	S114519A	PM362	S114605	PM625
S114456A	PM630	S114520	M443 0	S114606	PM287
S114458	PM516 0	S114520A	M443	S114607	PM625
S114459	M374 $^{12}_{1,2}$	S114520B	M443	S114607A	PM625
S114460	PM630 0	S114523	M201 $^{12}_{1,4}$	S114607B	PM625
S114460A	PM630	S114525	PM362 0	S114607C	PM625
S114460B	PM630	S114525A	PM362	S114614	PM287 0
S114461	PM521 0	S114526	PM509 0	S114617	PM341
S114461A	PM521	S114526A	PM509	S114617A	PM341
S114461B	PM521	S114526B	PM509	S114625	PM621
S114464	PM630 0	S114527	PM633	S114630	PM341
S114464A	PM630	S114527A	PM633	S114630	PM341 $^{12}_{0,8}$
S114464B	PM630	S114527B	PM633	S114651	PM628 0
S114471	PM510 0	S114528	PM522 0	S114651A	PM628
S114471A	PM510	S114528A	PM522	S114653	PM631
S114472	PM510 0	S114530	M443 0	S114653A	PM631
S114472A	PM510	S114533	M443 0	S114653B	PM631
S114473	M423X 0	S114534	M443 0	S114655A	PM635
S114473	M423X 0	S114535	PM341 0	S114672	PM283
S114475	PM385 0	S11455	M424	S11470	PM616
S114475A	PM385	S114550	PM609 0	S114700	PM349 0
S114480	M423 0	S114550A	PM609	S114700A	PM349 0
S114480	M423 0	S114553	M111 $^{12}_{0,8}$ 15a	S114700B	PM349
S114480A	M423	S114553A	M111	S114701	PM349 0
S114480B	M423	S114554	M034 $^{12}_{0,8}$	S114701A	PM349 0
S114481	M340 $^{12}_{1,4}$	S114554	M034 $^{12}_{0,8}$	S114701B	PM349
S114481A	M340	S114554A	M034	S114701BR	PM349
S114482	PM510 0	S114554A	M034	S114705	M447 0
S114483	PM420 0	S114556	M442 0	S114705A	M447
S114483A	PM420	S114556A	M442	S114705B	M447
S114484	PM385 0	S114557	M442 0	S114705C	M447
S114486	PM385 0	S114557A	M442 0	S114705D	M447
S114495	PM385 0	S114557A	M442	S114705E	M447
S114501	M116 0	S114558	PM349 0	S11472	PM616
S114501A	M116	S114566	PM287 0	S114750	M443 0

HITACHI	RMA $\frac{V}{Kw -!}$	HITACHI	RMA $\frac{V}{Kw -!}$	HITACHI	RMA $\frac{V}{Kw -!}$
S114753	PM636	S114829	PM641 $\frac{0}{}$	S1277A	PM646
S114753A	PM636	S114829A	PM641	S1284	M309 $\frac{12}{2,4}$
S114753C	PM636	S114829B	PM641	S1285	PM147 $\frac{12}{2,0}$
S114754	PM637	S114839	PM632	S1287	PM147 $\frac{12}{2,0}$
S114754A	PM637	S114844	PM642	S1289	PM271
S114755	PM638	S114850	M344 $\frac{12}{1,4}$	S1292	
S114756	PM638	S114850A	M344	S1303	PM268
S114758	M338 $\frac{0}{}$	S114850B	M344	S1306	PM270 $\frac{0}{}$
S114762	M447 $\frac{0}{}$	S114850C	M344	S1306A	PM270
S114762A	M447 $\frac{0}{}$	S114869	PM641	S13101	M336 $\frac{0}{}$
S114762A	M447	S11487	M424 $\frac{0}{}$	S13102	M336 $\frac{12}{2,0}$
S114762B	M447	S114871	PM519 $\frac{0}{}$	S13104	M434 $\frac{0}{}$
S114766	M443 $\frac{0}{}$	S11487K	M424	S13105	PM265 $\frac{0}{}$
S114766A	M443	S11487M	M424	S13105A	PM265
S114767	M443 $\frac{0}{}$	S11491	PM643 $\frac{0}{}$	S13106	M336X $\frac{12}{2,0}$
S114769	PM341 $\frac{0}{}$	S11491K	PM643	S13106A	M336X
S114769A	PM341	S11492	PM616 $\frac{0}{}$	S13106B	M336X
S11477	$\frac{0}{}$	S11497	M424	S13106C	M336X
S114775	M338 $\frac{12}{1,0}$	S11705	M447 $\frac{0}{}$	S13106E	M336X
S114775A	M338	S1219	PM272 $\frac{0}{}$	S13107	M336X $\frac{12}{2,0}$
S114780	PM632	S1219C	PM272	S13107A	M336X $\frac{12}{2,0}$
S114800	M443 $\frac{0}{}$	S1219CK/KB	PM272	S13109	M333 $\frac{0}{}$
S114800A	M443	S1219K	PM272	S13109B	M336X
S114800B	M443	S1219KB	PM272	S13111	PM432
S114801	PM518 $\frac{0}{}$	S1238	PM272 $\frac{0}{}$	S13112	PM268 $\frac{0}{}$
S114801A	PM518	S1238A	PM272	S13112A	PM268
S114801B	PM518	S1238AB	PM272	S13114	PM268 $\frac{0}{}$
S114801C	PM518	S1238B	PM272	S13114A	PM268
S114801D	PM518	S1241	PM644 $\frac{0}{}$	S13120A	PM432
S114802A	M443	S1241A	PM644	S13120B	PM432
S114804	PM349	S1248	PM432	S13121	M333 $\frac{0}{}$
S114804A	PM517	S1258	PM432	S13122	PM269 $\frac{0}{}$
S114805	PM349	S1259	PM644 $\frac{0}{}$	S13126	PM269 $\frac{0}{}$
S114805A	PM349	S1263	PM272 $\frac{0}{}$	S13127	M336X $\frac{12}{2,0}$
S114806	PM517 $\frac{0}{}$	S1263A	PM272	S13127	M336X $\frac{12}{2,0}$
S114806A	PM517	S1263AB	PM272	S13127A	M336X
S114808	M421 $\frac{0}{}$	S1263B	PM272	S13127C	M336X
S114808A	M421	S1263C	PM272	S13131	PM256 $\frac{0}{}$
S114815	PM639	S1268	PM272 $\frac{0}{}$	S13138	PM647
S114817	PM640	S1268A	PM272	S13138A	PM647
S114817A	PM640	S1268B	PM272	S1318	M332
S114818	M320 $\frac{12}{0,8}$	S1268BD	PM272	S13204	PM648
S114818	M320 $\frac{12}{0,8}$	S1268D	PM272	S13207C	PM271
S114827	M447	S1273	PM645	S13210	PM268 $\frac{0}{}$

HITACHI	RMA $\frac{V}{Kw -!}$	HITACHI	RMA $\frac{V}{Kw -!}$	HITACHI	RMA $\frac{V}{Kw -!}$
S13210B	PM268	S13502A	M336	S2401C	PM649
S13210C	PM268	S1350A	PM388	S2401D	PM649
S13212	M336X ⁰	S13531	PM256 ⁰	S2403	PM278 ⁰
S1322	PM270 ⁰	S1361	M294	S2403A	PM278
S1327	PM270	S1361A	M294	S2403B	PM278
S1327A	PM270	S1362	M333 ^{12 2,0}	S2403C	PM278
S1328	PM270 ⁰	S1362A	M333	S2407	M340
S13289	PM271 ⁰	S1362B	M333	S25103	PM279 ⁰
S13302	M336 ⁰	S1362C	M333	S25106	PM650
S13302A	M336	S1363	⁰	S25106A	PM650
S13302B	M336	S1364	PM388 ⁰	S25110	PM280 ⁰
S13305	PM265 ⁰	S1365	PM273 ⁰	S25110A	PM280
S13305A	PM265	S1365B	PM273	S25110C	PM280
S13307	M336X ⁰	S1366	PM275 ⁰	S25110G	PM280
S13307A	M336X	S1366A	PM275	S25110M	PM280
S13321	M333 ⁰	S1369	PM388 ⁰	S25115	PM649
S13326	PM269	S1373	PM645 ⁰	S25120	PM278
S13327	M336X ⁰	S1373B	PM645	S25120A	PM278
S13331	PM256 ⁰	S1374	PM645 ⁰	S25121	PM651
S1333A	PM270	S1375	PM432	S25125A	PM649
S1333B	PM270	S1378	PM272	S25125B	PM649
S1334		S1381	M332 ^{12 2,0}	S25129	PM650
S1334A	⁰	S1382	M333 ⁰	S25129A	PM650
S1336	PM272 ⁰	S1382A	PM432	S25129C	PM650
S1338	PM272 ⁰	S1382B	PM432	S2512A	PM651
S1338A	PM272	S1383	M333 ^{12 2,0}	S25131	PM281 ⁰
S1338B	PM272	S1384	PM276 ⁰	S25131A	PM281
S1340	PM272 ⁰	S1384B	PM276	S25132	PM650
S1340A	PM272	S1389	PM271 ⁰	S25132A	PM650
S1341A	PM272	S1389A	PM271	S25132B	PM650
S1341B	PM272	S1389B	PM271	S25132C	PM650
S1341C	PM272	S1389C	PM271	S25132F	PM650
S1341D	PM272	S1389D	PM271	S25137A	PM279
S1343	PM272 ⁰	S1391	M066X ^{12 2,2}	S25137B	PM279
S1345	PM272 ⁰	S1391A	M066X	S25155	PM281 ⁰
S1345A	PM272	S1391A	M066X	S25155C	PM281
S1345B	PM272	S1392	M434 ⁰	S25155D	PM281
S1347	PM388 ⁰	S1392A	M434	S25156	PM282 ⁰
S1347A	PM388	S1403	PM277 ⁰	S25158A	PM652
S1347B	PM388	S14203	PM268 ⁰	S25158B	PM652
S1349	PM273 ⁰	S14210	PM277	S25164	PM280 ⁰
S1349A	PM273	S23551	M424 ⁰	S25164A	PM280
S1350	PM388 ⁰	S2401	M445 ⁰	S25212	PM278
S13502	M336 ⁰	S2401B	PM649	S25302	PM649

MOTORINI

HITACHI

HITACHI **RMA** $\frac{V}{Kw -!}$

HITACHI

RMA $\frac{V}{Kw -!}$

HITACHI

RMA $\frac{V}{Kw -!}$

S25303A	PM649 $\frac{V}{Kw -!}$
S25305	PM265 $\frac{V}{Kw -!}$
S2564	PM280 $\frac{V}{Kw -!}$
S2564B	PM280 $\frac{V}{Kw -!}$
S2564E	PM280 $\frac{V}{Kw -!}$
S2564F	PM280 $\frac{V}{Kw -!}$
S2575	PM280 $\frac{V}{Kw -!}$
S2575A	PM280 $\frac{V}{Kw -!}$

HONDA RMA $\sqrt{\text{Kw}} -!$

06312P8A5050	PM653	
06314P5M305RM	M427	
31100ZA10030	PM654	
31200568692		0
312006340	M128	0
31200634005	M128	0
31200634670	M128	0
31200634671	M128	0
312006348	M128	0
31200634810	M128	0
31200634811	M128	0
312006570	M128	0
31200657004	M130	12 1,0
31200657005	M128	0
31200657006	M128	0
31200657010	M130	12 1,0
31200657015	M128	0
31200657016	M128	0
31200657025	M128	0
31200657035	M128	0
31200657671	M130	12 1,0
31200671005	M128	0
31200671671	M130	12 1,0
312006730	M128	0
31200673005	M128	0
31200673015	M128	0
312006730152		0
31200676016		0
31200676600	PM283	0
31200676601	M128X	12 1,0
31200676601	M128X	12 1,0
31200676602	PM283	0
31200676603	PM283	0
31200676604	PM283	0
31200676605	PM283	0
31200679004	M128	0
312006790043		0
312006790052		0
312006790053	M128	0
31200679024		0
312006790340		0
312006790350		0
312006790441	M128	0
31200679814	M128	0

HONDA RMA $\sqrt{\text{Kw}} -!$

31200689006	M128X	12 1,0
31200689006	M128X	12 1,0
31200689016	M128X	12 1,0
31200689016	M128X	12 1,0
31200689661	M128X	12 1,0
31200689661	M128X	12 1,0
31200689662	M130	12 1,0
31200HA00682	PM655	
31200HA7315	PM656	
31200HA7773	PM657	
31200HC4023	PM658	
31200HE0003		
31200HM3671		
31200HM8003		
31200OLMA51		
31200P01003	M194	12 1,0
31200P01003	M194	12 1,0
31200P01003	M194	0
31200P01005	PM286	12 1,0
31200P01005	M194	0
31200P01015		0
31200P01902		
31200P03901	PM694	0
31200P03901	PM694	0
31200P03902		
31200P03902		0
31200P03904	PM694	
31200P03904	PM694	
31200P06L03	PM287	0
31200P0A003	M427X	
31200P0A0031	M427X	
31200P0A0032	M427X	
31200P0A004	PM674	
31200P0AA01		
31200P0AA04	PM674	
31200P0GA01		
31200P12005	M427	
31200P13005	M427	
31200P13903	PM695	
31200P13904	PM695	
31200P13905	PM693	
31200P13906	PM695	
31200P1JE01	PM288	0
31200P1JE010	PM288	0

HONDA RMA $\sqrt{\text{Kw}} -!$

31200P1JE03	PM288	0
31200P1KE01	PM289	0
31200P1KE01		
31200P2A003	PM290	0
31200P2A003	PM290	
31200P2C004		
31200P2C901	M194	
31200P2EA51		
31200P2JJ61	PM696	
31200P2MA61		
31200P2TJ01		
31200P30005	PM291	0
31200P30902	PM694	
31200P3FJ01	PM879	
31200P45G01	M427	0
31200P45G11	M427	
31200P45G5	PM295	0
31200P45S01	M427	0
31200P45SG110	M427	
31200P54003	PM858	
31200P5G003	PM866	
31200P5M004	M427	
31200P5M901		
31200P5M902		
31200P73A01	PM858	
31200P8AA01	PM653	
31200P9ME00	PM499	
31200PA0005	M128	12 1,0
31200PA00053		0
31200PA0006	M128	12 1,0
31200PA0016	M128	0
31200PA0671	M130	12 1,0
31200PA2663	M432	0
31200PA4912	M130	12 1,0
31200PA5004	PM293	0
31200PA5911	PM293	12 1,0
31200PA5912	PM293	0
31200PA5913	PM293	12 1,0
31200PA5921	M130	12 1,0
31200PA6005	PM293	0
31200PA6661	M130	12 1,0
31200PAO6	M128	0
31200PB1674		0
31200PB1932	M130	12 1,0

HONDA	RMA $\sqrt{\text{Kw}} -!$	HONDA	RMA $\sqrt{\text{Kw}} -!$	HONDA	RMA $\sqrt{\text{Kw}} -!$
31200PB1933	M130 $\frac{12}{1,0}$	31200PD1001	M432 $\frac{0}{}$	31200PE0902	$\frac{0}{}$
31200PB1934	M128 $\frac{12}{1,0}$	31200PD1003	$\frac{0}{}$	31200PE1661	$\frac{0}{}$
31200PB1935	M128 $\frac{12}{1,0}$	31200PD1042	M432 $\frac{0}{}$	31200PE1670	PM295 $\frac{0}{}$
31200PB20	M128 $\frac{0}{}$	31200PD2003	M432 $\frac{0}{}$	31200PE1671	PM295 $\frac{0}{}$
31200PB2003	M432 $\frac{0}{}$	31200PD20031	M432 $\frac{0}{}$	31200PE1672	PM295 $\frac{0}{}$
31200PB2006	M130 $\frac{12}{1,0}$	31200PD2006	M432 $\frac{0}{}$	31200PE1673	PM295 $\frac{0}{}$
31200PB2014	M130 $\frac{12}{1,0}$	31200PD20130	M432 $\frac{0}{}$	31200PE1674	PM295 $\frac{0}{}$
31200PB2016	M130 $\frac{12}{1,0}$	31200PD2016	M432 $\frac{0}{}$	31200PE672	$\frac{0}{}$
31200PC0004	PM293 $\frac{0}{}$	31200PD2026	M432 $\frac{0}{}$	31200PEJJ61	PM696 $\frac{0}{}$
31200PC0015	PM293 $\frac{0}{}$	31200PD2306	M432 $\frac{0}{}$	31200PG3673	$\frac{0}{}$
31200PC00150	M128 $\frac{12}{1,0}$	31200PD2660	$\frac{0}{}$	31200PG6004	M194 $\frac{12}{1,0}$
31200PC0884	M194 $\frac{0}{}$	31200PD2661	M128X $\frac{12}{1,0}$	31200PG6004	M194 $\frac{12}{1,0}$
31200PC0884	M194 $\frac{12}{1,0}$	31200PD2661	M128X $\frac{12}{1,0}$	31200PG6034	M194 $\frac{12}{1,0}$
31200PC0891	$\frac{0}{}$	31200PD26612	PM294 $\frac{0}{}$	31200PG6034	M194 $\frac{12}{1,0}$
31200PC1001	PM293 $\frac{0}{}$	31200PD2662	M432 $\frac{0}{}$	31200PG6663	M194 $\frac{12}{1,0}$
31200PC1004	PM293 $\frac{0}{}$	31200PD2663	M432 $\frac{0}{}$	31200PG6663	M194 $\frac{12}{1,0}$
31200PC1005	PM293 $\frac{12}{1,0}$	31200PD2664	M432 $\frac{0}{}$	31200PG6673	M194 $\frac{12}{1,0}$
31200PC20	M128 $\frac{0}{}$	31200PD6006	M432 $\frac{0}{}$	31200PG6673	M194 $\frac{12}{1,0}$
31200PC2004	M130 $\frac{12}{1,0}$	31200PDAE020	M418 $\frac{0}{}$	31200PG6911	PM295 $\frac{0}{}$
31200PC2014	M130 $\frac{12}{1,0}$	31200PE0003	PM287 $\frac{12}{1,0}$	31200PG69122M	PM295 $\frac{0}{}$
31200PC26	M128 $\frac{0}{}$	31200PE0013	PM287 $\frac{12}{1,0}$	31200PG6913	$\frac{0}{}$
31200PC2661	M128X $\frac{12}{1,0}$	31200PE0013	$\frac{0}{}$	31200PG6914	PM295 $\frac{12}{1,0}$
31200PC2661	M128X $\frac{12}{1,0}$	31200PE0015	PM287 $\frac{12}{1,0}$	31200PG6915	PM295 $\frac{0}{}$
31200PC2662	M128X $\frac{12}{1,0}$	31200PE005	$\frac{0}{}$	31200PG6916	PM295 $\frac{0}{}$
31200PC2662	M128X $\frac{12}{1,0}$	31200PE013	$\frac{0}{}$	31200PGAE30M5	M418 $\frac{0}{}$
31200PC2671	M130 $\frac{12}{1,0}$	31200PE0461	M194 $\frac{12}{1,0}$	31200PH1760	M432 $\frac{0}{}$
31200PC2672	$\frac{0}{}$	31200PE0461	M194 $\frac{12}{1,0}$	31200PH3003	PM296 $\frac{0}{}$
31200PC5004	PM293 $\frac{0}{}$	31200PE0661	M194 $\frac{12}{1,0}$	31200PH3006	PM296 $\frac{0}{}$
31200PC5015	PM293 $\frac{0}{}$	31200PE0661	$\frac{0}{}$	31200PH3951	PM296 $\frac{0}{}$
31200PC50150	M128 $\frac{12}{1,0}$	31200PE0662	M194 $\frac{12}{1,0}$	31200PH3953	PM296 $\frac{0}{}$
31200PC5024	M128X $\frac{12}{1,0}$	31200PE0662	M194 $\frac{12}{1,0}$	31200PH4S12	PM296 $\frac{0}{}$
31200PC5024	M128X $\frac{12}{1,0}$	31200PE0663	M194 $\frac{12}{1,0}$	31200PH7006	PM336 $\frac{0}{}$
31200PC5892	M130 $\frac{12}{1,0}$	31200PE0663	M194 $\frac{12}{1,0}$	31200PH7661	PM336 $\frac{0}{}$
31200PC6003	M432 $\frac{0}{}$	31200PE0663	$\frac{0}{}$	31200PH76610	$\frac{0}{}$
31200PC60033	M432 $\frac{0}{}$	31200PE0664	M194 $\frac{12}{1,0}$	31200PJ7903	$\frac{0}{}$
31200PC6014	M432 $\frac{0}{}$	31200PE0664	M194 $\frac{12}{1,0}$	31200PK2006	$\frac{0}{}$
31200PC6024	M432 $\frac{0}{}$	31200PE0664	$\frac{0}{}$	31200PK2306	PM296 $\frac{0}{}$
31200PC6661	M432 $\frac{0}{}$	31200PE0665	M194 $\frac{12}{1,0}$	31200PK2307	PM296 $\frac{0}{}$
31200PC66615	PM294 $\frac{0}{}$	31200PE0665	M194 $\frac{12}{1,0}$	31200PK2953	PM296 $\frac{0}{}$
31200PC6662	PM294 $\frac{0}{}$	31200PE0665	$\frac{0}{}$	31200PK2954	PM296 $\frac{0}{}$
31200PC6663	M128X $\frac{12}{1,0}$	31200PE0667	$\frac{0}{}$	31200PK2955	PM296 $\frac{0}{}$
31200PC6663	M128X $\frac{12}{1,0}$	31200PE0901	$\frac{0}{}$	31200PK2S02	PM296 $\frac{0}{}$
31200PC6664	PM294 $\frac{0}{}$	31200PE0901	PM287 $\frac{12}{1,0}$	31200PM1005	M194 $\frac{12}{1,0}$
31200PCXA01	PM886 $\frac{0}{}$	31200PE0902	PM287 $\frac{12}{1,0}$	31200PM1005	M194 $\frac{12}{1,0}$

HONDA RMA $\frac{V}{Kw - !}$

31200PM2J01	
31200PM3003	M194 $\frac{12}{1,0}$
31200PM3003	M194 $\frac{12}{1,0}$
31200PM30032	M194 $\frac{0}{}$
31200PM3004	M194 $\frac{12}{1,0}$
31200PM3004	M194 $\frac{12}{1,0}$
31200PM3005	PM295 $\frac{0}{}$
31200PM3101	M194 $\frac{12}{1,0}$
31200PM3101	M194 $\frac{12}{1,0}$
31200PM3J01	PM286 $\frac{0}{}$
31200PM3J02	M194 $\frac{12}{1,0}$
31200PM3J021	PM286 $\frac{0}{}$
31200PM3J03	M194 $\frac{12}{1,0}$
31200PM3J02	$\frac{0}{}$
31200PM5L01	$\frac{0}{}$
31200PM5L02	PM287 $\frac{0}{}$
31200PM5L02	$\frac{0}{}$
31200PM7005	PM295 $\frac{0}{}$
31200PM7306	PM295 $\frac{0}{}$
31200PM7306	PM295 $\frac{0}{}$
31200PP4EO5	$\frac{0}{}$
31200PR3004	PM297 $\frac{0}{}$
31200PR3J01	$\frac{0}{}$
31200PR40030	PM832 $\frac{0}{}$
31200PR4A01	PM818 $\frac{0}{}$
31200PT0003	M427X $\frac{0}{}$
31200PT00031	PM298 $\frac{0}{}$
31200PT0005	M427 $\frac{0}{}$
31200PT0005	M427 $\frac{0}{}$
31200PT0015	M427 $\frac{0}{}$
31200PT0900	PM693 $\frac{0}{}$
31200PT0903	PM693 $\frac{0}{}$
31200PT0904	PM693 $\frac{0}{}$
31200PT09040M	$\frac{0}{}$
31200PT0905	PM693 $\frac{0}{}$
31200PT0906	PM693 $\frac{0}{}$
31200PT1PO3	M427 $\frac{0}{}$
31200PT1T03	M427 $\frac{0}{}$
31200PT1T04	M427 $\frac{0}{}$
31200PTO003	M427X $\frac{0}{}$
31200PTO903	M427X $\frac{0}{}$
31200PY3004	PM738 $\frac{0}{}$
31200PY3024	PM738 $\frac{0}{}$
31200PY3A01	PM738 $\frac{0}{}$

HONDA RMA $\frac{V}{Kw - !}$

31200ZJ1004	
31200ZJ4003	
31201010974	M128 $\frac{0}{}$
31210ZE3013	PM803 $\frac{0}{}$
31400611014	M128 $\frac{0}{}$
31400611024	M128 $\frac{0}{}$
31400634670	M128 $\frac{0}{}$
31400PD6014	M128 $\frac{0}{}$
31400SAO671	M128 $\frac{0}{}$
31400SAO672	M128 $\frac{0}{}$
DDL9	PM290 $\frac{0}{}$
DDVD3	PM290 $\frac{0}{}$
DFLEA	PM287 $\frac{0}{}$
DR4FD	M130 $\frac{12}{1,0}$
DR4FM	M130 $\frac{12}{1,0}$
DR4R2	PM293 $\frac{0}{}$
DR4R6	M194 $\frac{12}{1,0}$
DR4R6	M194 $\frac{12}{1,0}$
DR4U2	PM298 $\frac{0}{}$
DR4U3	PM693 $\frac{0}{}$
DRD18	M128X $\frac{12}{1,0}$
DRD18	M128X $\frac{12}{1,0}$
DRDF3	M432 $\frac{0}{}$
DRDFE	M194 $\frac{0}{}$
DRDIV	M432 $\frac{0}{}$
DRK1E	
DRKF1	PM296 $\frac{0}{}$
DRLF0	M194 $\frac{0}{}$
DRLF1	M130 $\frac{0}{}$
DRLF0	$\frac{0}{}$
DRP1K	PM818 $\frac{0}{}$
DS4HX	PM886 $\frac{0}{}$
DSDEC	PM879 $\frac{0}{}$
DX4R4	PM286 $\frac{0}{}$
DX4RE	PM694 $\frac{0}{}$
DXDR6	PM858 $\frac{0}{}$
DXDRJ	PM858 $\frac{0}{}$
DXK	M427X $\frac{0}{}$
DXK14	M427X $\frac{0}{}$
MHG001	PM738 $\frac{0}{}$
MHG005	PM738 $\frac{0}{}$
P2T1S	

HONDA RMA $\frac{V}{Kw - !}$

HYUNDAI RMA \sqrt{Kw} -!

3160032540	M426	/
3610002500	PM659	/
3610002511	PM659	/
3610002550	PM659	/
3610011110	M425X	0/
3610011120	M425X	0/
3610011130	M425X	0/
3610011140	M425X	0/
3610011150	M425X	0/
3610011210		0/
3610021720	PM403	0/
3610021730	PM403	0/
3610021740	M425	0/
3610021750	M425	/
3610021770	PM376	0/
3610022000	M425	0/
3610022800	PM660	/
3610022850	PM661	/
3610023000	PM536	0/
3610023050	PM536	0/
3610023100	PM535	0/
3610023150	PM535	0/
3610023160		0/
3610027000	PM662	/
3610027510		/
3610029000	M105	0/
3610032500	M426	/
3610032510	M426	0/
3610032520	M426	0/
3610032530	M426	0/
3610032560	M429	0/
3610032610	M429	/
3610032630	M426	0/
3610032640	M429	0/
3610033000	PM536	0/
3610035010	PM273	0/
3610035020	PM299	0/
3610035030	PM299	/
3610035040	PM299	/
3610035050	PM299	0/
3610035510	PM363	0/
3610037110	PM663	/
3610037210	PM663	/
3610038050	PM664	/

HYUNDAI RMA \sqrt{Kw} -!

3610038090	PM665	/
3610041012	PM396	/
3610042010	M193	12/ 2,0
3610042010	M193	12/ 2,0
3610042011	M193	12/ 2,0
3610042011	M193	12/ 2,0
3610042050	M341	12/ 2,2
3610042250	PM399	/
3610047650	PM394	/
3610083010	PM666	/
3610093010	PM667	/

HYUNDAI RMA \sqrt{Kw} -!

ISKRA RMA $V_{Kw} -!$

10130105	M032 $12/0,8$
10130123	PM184 $0/$
10130141	$0/$
10130143	$0/$
10130172	M078 $12/0,7$
11130002	M039 $12/0,5$
11130003	$0/$
11130005	PM142 $0/$
11130007	M078 $12/0,7$
11130010	PM106 $0/$
11130026	PM122 $0/$
11130029	M179 $12/0,7$
11130034	PM908 $12/0,6$
11130041	PM204 $0/$
11130066	PM135 $0/$
11130074	PM122 $0/$
11130075	PM137 $0/$
11130076	PM645 $0/$
11130083	$0/$
11130084	M067 $12/0,6$
11130085	M067 $12/0,6$
11130102	M032 $12/0,8$
11130115	PM184 $0/$
11130117	PM148 $12/2,4$
11130121	PM142 $0/$
11130123	M027 $12/2,5$
11130124	PM146 $0/$
11130127	M091 $0/$
11130130	PM189 $0/$
11130134	PM908 $0/$
11130140	M091 $12/3,5$
11130141	PM137 $0/$
11130142	$0/$
11130143	$0/$
11130146	PM155 $0/$
11130151	PM137 $0/$
11130160	PM188 $0/$
11130162	M119 $0/$
11130164	PM192 $0/$
11130166	M032 $12/0,8$
11130170	$0/$
11130172	PM137 $0/$
11130178	$0/$
11130179	PM162 $0/$

ISKRA RMA $V_{Kw} -!$

11130193	M119X $12/1,0$
11130194	PM147 $12/2,0$
11130198	M074 $12/0,9$
11130199	M091 $12/3,5$
11130200	PM645 $0/$
11130201	PM119 $0/$
11130203	PM150 $0/$
11130207	PM128 $0/$
11130208	M017 $12/0,8$
11130210	M145 $12/0,8$
11130216	PM155 $0/$
11130217	M119 $0/$
11130218	M075X $12/0,8$
11130219	M033X $12/0,8$
11130225	PM138 $0/$
11130229	PM128 $0/$
11130230	PM106 $0/$
11130233	M102 $12/0,8$
11130234	M119 $0/$
11130244	M084X $12/0,9$
11130245	M010 $12/0,8$
11130246	M100 $12/0,8$
11130250	M288 $0/$
11130253	$0/$
11130254	PM159 $0/$
11130254	PM159 $0/$
11130266	M095 $12/0,7$
11130274	PM198 $0/$
1113028	M176 $0/$
11130281	$0/$
11130284	M084X $0/$
11130286	M100 $0/$
11130287	$0/$
11130288	PM139 $0/$
11130289	PM202 $0/$
11130291	M108 $12/0,8$ 15a
11130300	M089 $12/2,0$
11130321	M032 $12/0,8$
11130322	M091 $12/3,5$
11130328	M176 $0/$
11130334	M106 $12/0,8$ 15a
11130338	M102 $12/0,8$
11130339	PM106 $0/$
11130343	M079 $12/2,0$

ISKRA RMA $V_{Kw} -!$

11130345	M023 $12/0,8$
11130346	M017 $12/0,8$
11130347	M254 $12/2,0$
11130351	M096 $12/0,8$
11130352	M180 $12/0,8$
11130362	M119X $12/1,0$
11130364	PM142 $0/$
11130366	PM135 $0/$
11130373	PM645 $0/$
11130375	M010 $12/0,8$
11130376	PM162 $0/$
11130378	M119X $12/1,0$
11130385	M084X $0/$
11130389	PM192 $0/$
11130392	M283 $12/0,8$ 15a
11130392	M131 $0/$
11130395	M075X $12/0,8$
11130398	M176 $0/$
11130399	M089 $12/2,0$
11130403	M091 $0/$
11130404	M034 $0/$
11130407	PM106 $0/$
11130408	$0/$
11130409	M074 $0/$
11130410	M091 $0/$
11130411	PM645 $0/$
11130412	PM128 $0/$
11130414	PM162 $0/$
11130417	RM085 $0/$
11130418	M102 $12/0,8$
11130419	PM645 $0/$
11130421	$0/$
11130423	PM139 $0/$
11130428	PM193 $0/$
11130431	M100 $12/0,8$
11130483	M082 $0/$
11130484	PM122 $0/$
11130490	PM146 $0/$
11130491	PM137 $0/$
11130492	PM138 $0/$
11130500	M027 $0/$
11130505	RM039 $0/$
11130509	PM645 $0/$
11130510	$0/$

ISKRA	RMA $V_{Kw -!}$	ISKRA	RMA $V_{Kw -!}$	ISKRA	RMA $V_{Kw -!}$
11130519	M032 0	11130661	M056 0	11130885	M089
11130520	PM224 0	11130664		11130889	PM115
11130521		11130669		11130895	
11130526	PM689 0	11130672		11130896	
11130529	M176 0	11130673	PM137 0	11130897	PM599
11130531		11130679		11130910	M257 0
11130532	M027X 0	11130697	PM135	11130911	M069 0
11130534	PM121 0	11130705		11130912	M383 0
11130537	PM164 0	11130711		11130913	
11130551	PM122	11130716	M105	11130956	M017 0
11130556	M176 0	11130717	M235X	11130957	
11130558	M015 0	11130722	M014 0	11130963	M082 0
11130565		11130723	M310 0	11130964	M032
11130567	PM176 0	11130724	M386 0	11130965	M176 0
11130569	PM121 0	11130732		11130966	M095 0
11130579	M294 0	11130736	M288	11130967	M033 0
11130580	M095 0	11130743		11130969	M143
11130582	M017 0	11130748		11130972	PM688
11130586	M033 12 0,8	11130762		11130979	PM553
11130590	M084X 0	11130763		11130993	
11130593	RM039 0	11130766	PM140 0	11130996	PM241
11130595		11130769	M059 0	11130997	
11130596	PM120	11130772		11131002	
11130598	PM108 0	11130773	M069	11131010	M314
11130600	M096 0	11130775		11131016	
11130602	M140 0	11130776		11131038	PM129
11130603	0	11130777	M240 0	11131042	
11130604	PM186 0	11130787	M195 0	11131052	PM822
11130605	0	11130790	M017 0	11131054	PM070
11130608	0	11130795	PM690	11131055	M289
11130610	M116 12 0,9	11130809	PM609	11131056	M396
11130618		11130811		11131063	
11130619	PM158	11130819	PM121	11131085	
11130620		11130820		11131086	
11130624	M294 0	11130821		11131088	
11130626	PM169 0	11130836		11131100	PM692
11130626	PM169	11130841		11131109	PM096
11130627	PM160 0	11130842	PM592	11131117	PM794
11130629	PM645	11130844		11131121	
11130630	PM688	11130845	M306 0	11131136	PM872
11130642	M105 0	11130854		11131137	PM071
11130646	M120X 0	11130860	PM782	11131140	M288
11130647	M214 0	11130862		11131143	PM164
11130651	M099 0	11130881		11131144	

ISKRA	RMA \sqrt{Kw} -!	ISKRA	RMA \sqrt{Kw} -!	ISKRA	RMA \sqrt{Kw} -!
11131157		AZE0305	M078 $\frac{12}{0,7}$	AZE2538	
11131164	PM553	AZE0308	M067 $\frac{12}{0,6}$	AZE2540	
11131167		AZE1202	M268	AZE2541	M069
11131177	PM164	AZE1203	M202 $\frac{0}{0}$	AZE2543	
11131178		AZE1211	M032	AZE2544	
11131186	PM628	AZE1216	M143	AZE2545	
11131221		AZE1219		AZE2548	M195
11131223	PM586	AZE1225		AZE2557	
11131232	M105	AZE1227	PM692	AZE2558	
11131233		AZE1230	PM628	AZE2563	
11131236		AZE1501	M032 $\frac{12}{0,8}$	AZE2577	
11131267	PM554	AZE1502	M176 $\frac{0}{0}$	AZE2578	M069
11131274		AZE1507	M176 $\frac{0}{0}$	AZE2579	
11131285		AZE1508	M034 $\frac{0}{0}$	AZE2580	
11131300	PM794	AZE1511		AZE2617	
11131318		AZE1515	M137 $\frac{0}{0}$	AZE2623	PM070
11139008	PM181 $\frac{0}{0}$	AZE1516		AZE2624	M289
11139022	PM213 $\frac{0}{0}$	AZE1520	M032 $\frac{0}{0}$	AZE2625	M396
11139025	PM210 $\frac{0}{0}$	AZE1521	M176 $\frac{12}{1,1}$	AZE2634	PM071
11139029	PM170	AZE1523	M176 $\frac{12}{1,1}$	AZE2636	
11139030	PM215 $\frac{0}{0}$	AZE1526	M095 $\frac{12}{0,7}$	AZE2640	
11139034		AZE1528	M033 $\frac{12}{0,8}$	AZE2642	
11139038		AZE1540	PM609	AZE3502	M032 $\frac{12}{0,8}$
11139098		AZE2101		AZE3506	M077 $\frac{12}{0,6}$
11139107	PM218 $\frac{0}{0}$	AZE2105	PM553	AZE3506	M119 $\frac{12}{0,6}$
11139156		AZE2110	PM241	AZE3508	M032 $\frac{12}{0,8}$
11201068	$\frac{12}{0,6}$	AZE2111		AZE3512	M119 $\frac{0}{0}$
11203016		AZE2113	M314	AZE3513	M075 $\frac{12}{0,8}$
AAK4523		AZE2117	PM822	AZE3514	M033 $\frac{12}{0,8}$
AAK5313	PM640	AZE2138	PM872	AZE3517	M077 $\frac{12}{0,6}$
AZB0101	M032 $\frac{12}{0,8}$	AZE2141	PM553	AZE3517	M119 $\frac{12}{0,6}$
AZD0102	M067 $\frac{12}{0,6}$	AZE2151	M105	AZE3521	M119X $\frac{12}{1,0}$
AZD0301	M039 $\frac{12}{0,5}$	AZE2155	PM554	AZE3535	M027 $\frac{0}{0}$
AZD0305	M078 $\frac{12}{0,7}$	AZE2160		AZE3545	M119X $\frac{12}{1,0}$
AZD0308	M067 $\frac{12}{0,6}$	AZE2502	RM085	AZE3559	M084X $\frac{0}{0}$
AZD3502	M032 $\frac{12}{0,8}$	AZE2507	M015 $\frac{0}{0}$	AZE4535	PM096
AZD3508	M095 $\frac{12}{0,7}$	AZE2512	RM039 $\frac{0}{0}$	AZE4566	PM586
AZD3518	M010 $\frac{12}{0,8}$	AZE2513	M118 $\frac{0}{0}$	AZE4603	
AZD3521	M077 $\frac{12}{0,6}$	AZE2521	M105 $\frac{0}{0}$	AZE4620	
AZD3533	M174 $\frac{12}{1,0}$ 15a	AZE2522	M120X $\frac{0}{0}$	AZE5202	RM085
AZD3543	M010 $\frac{12}{0,8}$	AZE2523	M214 $\frac{0}{0}$	AZF3509	M119X $\frac{12}{1,0}$
AZE0201	M032 $\frac{12}{0,8}$	AZE2525	M099 $\frac{0}{0}$	AZF3512	M017 $\frac{12}{0,8}$
AZE0303	PM908 $\frac{12}{0,6}$	AZE2535	M235X	AZF3513	M145 $\frac{12}{0,8}$
AZE0304	M179 $\frac{12}{0,7}$	AZE2537	M310 $\frac{0}{0}$	AZF3515	M102 $\frac{12}{0,8}$

ISKRA	RMA $V_{Kw} -!$	ISKRA	RMA $V_{Kw} -!$	ISKRA	RMA $V_{Kw} -!$
AZF3517	M084X $12/0,9$	AZJ3117	PM645 $0/$	AZJ3247	PM162 $0/$
AZF3518	M010 $12/0,8$	AZJ3118	PM128 $0/$	AZJ3248	
AZF3519	M100 $12/0,8$	AZJ3119	PM162 $0/$	AZJ3255	
AZF3524	M108 $12/0,8$ 15a	AZJ3128	PM122 $0/$	AZJ3258	M288 $0/$
AZF3527	M106 $12/0,8$ 15a	AZJ3131	PM146 $0/$	AZJ3263	PM136 $0/$
AZF3528	M102 $12/0,8$	AZJ3132	PM137 $0/$	AZJ3263	
AZF3530	M023 $12/0,8$	AZJ3133	PM138 $0/$	AZJ3274	
AZF3531	M017 $12/0,8$	AZJ3137	M027 $12/2,5$	AZJ3277	PM140 $0/$
AZF3533	M096 $12/0,8$	AZJ3144	PM645 $0/$	AZJ3279	M059 $0/$
AZF3534	M180 $12/0,8$	AZJ3145		AZJ3283	PM121 $0/$
AZF3542	PM138 $0/$	AZJ3148	PM224 $0/$	AZJ3284	
AZF3543	M010 $12/0,8$	AZJ3149		AZJ3285	
AZF3545	M119X $12/1,0$	AZJ3151	PM689 $0/$	AZJ3297	PM782 $0/$
AZF3546	M084X $0/$	AZJ3155		AZJ3299	
AZF3547	M131 $0/$	AZJ3156	M027X $0/$	AZJ3310	
AZF3547	M283 $12/0,8$ 15a	AZJ3158	PM121 $0/$	AZJ3311	M089 $0/$
AZF3549	M075X $12/0,8$	AZJ3160	PM164 $0/$	AZJ3314	PM115 $0/$
AZF3551	M102 $12/0,8$	AZJ3169	PM122 $0/$	AZJ3317	
AZF3552	M100 $12/0,8$	AZJ3170	PM122 $0/$	AZJ3318	
AZF3555	RM039 $0/$	AZJ3177	PM154 $0/$	AZJ3319	PM599 $0/$
AZF3558	M017 $12/0,8$	AZJ3179	PM176 $0/$	AZJ3324	PM690 $0/$
AZF3558	M202 $12/0,8$	AZJ3181	PM121 $0/$	AZJ3333	
AZF3559	M084X $0/$	AZJ3182	M294 $0/$	AZJ3347	PM688 $0/$
AZF3560	M096 $0/$	AZJ3186		AZJ3351	
AZF4509	PM107 $0/$	AZJ3187	PM120 $0/$	AZJ3364	PM129 $0/$
AZF4510		AZJ3188	PM108 $0/$	AZJ3374	
AZF4514		AZJ3192		AZJ3375	
AZF4515	PM592 $0/$	AZJ3195		AZJ3386	M288 $0/$
AZF4559		AZJ3196	PM158 $0/$	AZJ3387	PM164 $0/$
AZF4573		AZJ3197		AZJ3388	
AZF4577	PM794 $0/$	AZJ3198	M294 $12/2,8$	AZJ3389	PM224 $0/$
AZF4582		AZJ3199	PM169 $0/$	AZJ3393	PM164 $0/$
AZF4611	PM794 $0/$	AZJ3201	PM160 $0/$	AZJ3404	
AZJ0402	PM122 $0/$	AZJ3203	PM645 $0/$	AZJ3503	$0/$
AZJ0404	PM122 $0/$	AZJ3204	PM688 $0/$	AZJ3508	PM148 $12/2,4$
AZJ0405	PM645 $0/$	AZJ3216		AZJ3514	M027 $12/2,5$
AZJ0501	PM106 $0/$	AZJ3218	PM149 $0/$	AZJ3515	PM146 $0/$
AZJ0602		AZJ3222	PM137 $0/$	AZJ3516	M091 $12/3,5$
AZJ3107	M089 $12/2,0$	AZJ3226		AZJ3517	M091 $12/3,5$
AZJ3110	M091 $12/3,5$	AZJ3231	PM110 $0/$	AZJ3518	PM137 $0/$
AZJ3113	PM106 $0/$	AZJ3234	PM162 $0/$	AZJ3520	PM155 $0/$
AZJ3114		AZJ3237	PM135 $0/$	AZJ3522	PM137 $0/$
AZJ3115	M074 $0/$	AZJ3242	PM115 $0/$	AZJ3525	PM162 $0/$
AZJ3116	M091 $0/$	AZJ3243		AZJ3531	PM147 $12/2,0$

ISKRA	RMA $V_{Kw} -!$	ISKRA	RMA $V_{Kw} -!$	ISKRA	RMA $V_{Kw} -!$
AZJ3534	M074 $12/0,9$	AZL3615	PM198 $0/$		
AZJ3535	M091 $12/3,5$	AZL3618	$0/$		
AZJ3536	PM645 $0/$	AZL3625	PM139 $0/$		
AZJ3537	PM119 $0/$	IS0201	$0/$		
AZJ3538	PM150 $0/$	IS0407	PM106 $0/$		
AZJ3542	PM155 $0/$	IS0417	RM085 $0/$		
AZJ3546	PM138 $0/$	IS0520	PM224 $0/$		
AZJ3548	PM128 $0/$	IS0565	$0/$		
AZJ3549	PM106 $0/$	IS0598	$0/$		
AZJ3554	M288 $0/$	IS0600	$0/$		
AZJ3557	PM159 $0/$	IS0600	$0/$		
AZJ3557	PM159 $0/$	IS0626	PM169 $0/$		
AZJ3567	M089 $12/2,0$	IS0632	PM224 $0/$		
AZJ3582	M091 $12/3,5$	IS0642	M105 $0/$		
AZJ3589	PM106 $0/$	IS0646	$0/$		
AZJ3590	M079 $12/2,0$	IS0647	$0/$		
AZJ3591	M254 $12/2,0$	IS0705	$0/$		
AZJ3593	PM110 $0/$	IS0723	$0/$		
AZJ3594	PM135 $0/$	IS0763	$0/$		
AZJ3598	PM645 $0/$	IS0766	$0/$		
AZJ3599	$0/$	IS0772	$0/$		
AZK3605	PM201 $0/$	IS0776	$0/$		
AZK5104	$0/$	IS0790	$0/$		
AZK5112	PM181 $0/$	IS0844	$0/$		
AZK5117	$0/$	IS0896	$0/$		
AZK5123	PM186 $0/$	ZB412/0609	M078 $0/$		
AZK5133	$0/$	ZB412/16/9	M078 $12/0,7$		
AZK5168	PM181 $0/$				
AZK5181	PM213 $0/$				
AZK5184	PM210 $0/$				
AZK5188	PM170 $0/$				
AZK5189	PM215 $0/$				
AZK5193	$0/$				
AZK5196	$0/$				
AZK5401	PM204 $0/$				
AZK5449	$0/$				
AZK5456	PM218 $0/$				
AZK5511	$0/$				
AZK5515	PM188 $0/$				
AZK5539	$0/$				
AZL3601	PM189 $0/$				
AZL3603	PM193 $0/$				
AZL3606	PM192 $0/$				
AZL3611	$0/$				

ISUZU	RMA $\sqrt{\text{Kw}} -!$	ISUZU	RMA $\sqrt{\text{Kw}} -!$	ISUZU	RMA $\sqrt{\text{Kw}} -!$
1811001410	PM279	5862026060	PM674	8942554392	PM677
1811001891	PM279 $\frac{0}{\text{ }}$	8104550190	PM675	8943205310	PM278
1811001910	PM668	8104550230	PM675	8943325860	M340 $\frac{12}{1,4}$
1811001911	PM668	8104550250	PM675	8943334380	PM278 $\frac{0}{\text{ }}$
1811002330	PM669	8104550530	PM675	8943377970	PM676 $\frac{0}{\text{ }}$
1811002340	PM670	8104654940	PM675	8943387970	PM676
1811002341	PM670	8411155670	M333 $\frac{12}{2,0}$	8943387980	PM465 $\frac{0}{\text{ }}$
1811002530	PM668	8912762340	PM636	8943444721	PM465
1811002531	PM668	8933002709	M345	8943446930	PM459
1812002650	PM671	8933004180	M239	8943601132	PM465
1812003140	PM671	8941150670	M333	8943601321	PM465
2911233280	PM636	8941155650	PM623 $\frac{0}{\text{ }}$	8943634280	PM677
2912559020	PM670	8941155650	PM623	8943647220	PM636
2912559140	PM432	8941155670	M333 $\frac{12}{2,0}$	8943647221	PM636
2912762340	PM636	8941155671	M333 $\frac{0}{\text{ }}$	8943665251	PM678
5811000112	PM270	8941155672	M333 $\frac{0}{\text{ }}$	8943718330	PM459 $\frac{0}{\text{ }}$
5811000180	PM279	894115650	PM623	8943719331	PM459
5811000252	PM279	8941160641	PM459	8943783300	PM459 $\frac{0}{\text{ }}$
5811000571	PM432	8941233870	PM466	8943843140	PM679
5811000800	PM270 $\frac{0}{\text{ }}$	8941313560	PM459 $\frac{0}{\text{ }}$	89438431401	PM636
5811000801	PM270 $\frac{0}{\text{ }}$	8941313562	PM459 $\frac{0}{\text{ }}$	8943843141	PM679
5811000860	PM276 $\frac{0}{\text{ }}$	8941313562	PM459	8943863280	M423 $\frac{0}{\text{ }}$
5811000991	PM432	8941333381	M445 $\frac{0}{\text{ }}$	8943876530	PM277 $\frac{0}{\text{ }}$
58110011	PM270	8941364000	PM432	8944104090	PM270
5811001111	PM270 $\frac{0}{\text{ }}$	8941364001	PM432	8944121420	PM459 $\frac{0}{\text{ }}$
5811001180	PM279	8941364480	M333 $\frac{12}{2,0}$	8944121421	PM459 $\frac{0}{\text{ }}$
5811001280	PM278	8941364481	M333	8944127301	PM432
5811001282	PM278	8941364482	M333 $\frac{12}{2,0}$	8944234520	PM651
5811001292	PM278	8941365070	PM270 $\frac{0}{\text{ }}$	8944299772	PM271 $\frac{0}{\text{ }}$
5811001331	PM270	8941416642	$\frac{0}{\text{ }}$	8944339120	PM268 $\frac{0}{\text{ }}$
5811001660	PM432	8941475492	PM271 $\frac{0}{\text{ }}$	8944339121	PM268 $\frac{0}{\text{ }}$
5811001661	PM432	8941492490	PM276 $\frac{0}{\text{ }}$	8944410870	PM465 $\frac{0}{\text{ }}$
5811001662	PM432	8941566710	PM459 $\frac{0}{\text{ }}$	8944410871	PM465
5811001663	PM432	8941566710	PM459	8944467700	PM677
5811001664	PM432	8941723260	PM459 $\frac{0}{\text{ }}$	8944479540	PM465 $\frac{0}{\text{ }}$
5811001690	PM672	8942044380	PM459 $\frac{0}{\text{ }}$	8944489590	PM432 $\frac{0}{\text{ }}$
5811001691	PM672	8942121420	$\frac{0}{\text{ }}$	8944489591	PM432 $\frac{0}{\text{ }}$
5811001830	PM432 $\frac{0}{\text{ }}$	8942121421	$\frac{0}{\text{ }}$	8944497820	PM676 $\frac{0}{\text{ }}$
5811001860	PM432	8942160641	PM459 $\frac{0}{\text{ }}$	8944532120	PM432
5811001920	PM627 $\frac{0}{\text{ }}$	8942160642	PM459 $\frac{0}{\text{ }}$	8944548911	M423X $\frac{0}{\text{ }}$
5811001921	PM627	8942340650	PM459 $\frac{0}{\text{ }}$	8944569000	PM651
5811210140	PM432	8942387580	M333 $\frac{0}{\text{ }}$	8944604170	PM268 $\frac{0}{\text{ }}$
5812002921	PM673	8942510881	PM676 $\frac{0}{\text{ }}$	8944604171	PM268 $\frac{0}{\text{ }}$
5822001660	$\frac{0}{\text{ }}$	8942549221	PM278 $\frac{0}{\text{ }}$	8944692460	PM459 $\frac{0}{\text{ }}$

ISUZU	RMA $\sqrt{Kw - !}$	ISUZU	RMA $\sqrt{Kw - !}$	ISUZU	RMA $\sqrt{Kw - !}$
8944694961	M333 0 /				
8944694962	0 /				
8944694963	M333 0 /				
8944729540	PM465 /				
8944729550	PM465 /				
8944807910	PM465 /				
8944839180	M423 /				
8944839180	M423 0 /				
8947183310	PM459 /				
8970298630	PM680 0 /				
8970429970	PM681 /				
8970429971	PM681 /				
8970429972	PM681 /				
8970645530	PM636 /				
8970653150	PM465 /				
8971125490	PM268 0 /				
8971177690	M340 0 /				
8971177700	M423 0 /				
8971185420	PM271 0 /				
8971197490	PM670 /				
8971203561	PM682 /				
8971239230	PM636 /				
8971333690	M344 0 /				
8971333691	M344 0 /				
8971333692	M344 0 /				
8971353432	PM432 0 /				
8971366880	PM268 /				
8971463383	PM268 0 /				
8971502030	M344 12' 1,4				
8971502040	M421 0 /				
8971502041	M421 0 /				
8971777690	M340 0 /				
8971891180	PM641 /				
8971891181	PM641 0 /				
8972105050	PM268 0 /				
8972236530	PM277 /				
8973860620	PM641 /				
94332586	M340 0 /				
94332586	M340 /				
94386328	M423 0 /				
94454891	M423 0 /				
94483918	M423 0 /				

KIA

RMA $\sqrt{\text{Kw}} -!$

KIA

RMA $\sqrt{\text{Kw}} -!$

KIA

RMA $\sqrt{\text{Kw}} -!$

OK71F18400B	PM400	/
3610021740	M425	/
3610032630	M426	/
3610032640	M429	/
3610032640	M429	/
KB30318400	M435	0/
KK0218400	PM609	/
KK37018400A	PM609	/
KK40118400	PM609	0/
KKY0218400	PM609	0/
KKY0218400	PM609	/
KY0218400	PM466	0/
MB30118400C	PM609	0/
MB30118400C	PM609	/
MB35918400A	M431	/
MB35918400A	M431	/
OB6S818400	M431	0/
OJE2618400A	PM365	/
OK24118400A	M431	0/
OK32618400	M431	/
OK55218400	PM683	/
OK71118400	PM400	0/
OK71F18400B	PM400	0/
OK90018400	M431	/
OK90018400B	M431	0/
OK95618400	PM274	/
OK95618400B	PM274	/

LADA

RMA $\frac{V}{Kw - !}$

LADA

RMA $\frac{V}{Kw - !}$

LADA

RMA $\frac{V}{Kw - !}$

21003708000	M114	$\frac{12}{0,8}$
21013708000	M114	$\frac{0}{}$
21013708000	M114	$\frac{0}{}$
210312VIP54	RM039	$\frac{0}{}$
21083708010	RM039	$\frac{0}{}$
210837080106	RM039	$\frac{0}{}$
21083708019	RM039	$\frac{0}{}$
21103708010	RM085	$\frac{0}{}$
2213708000	M114	$\frac{12}{0,8}$
293708	RM039	$\frac{0}{}$
3708000	M114	$\frac{0}{}$
4233708	M114	$\frac{12}{0,8}$
4243708	RM039	$\frac{0}{}$
4253708	M114	$\frac{12}{0,8}$
4263708	RM039	$\frac{0}{}$
57023708	RM085	$\frac{0}{}$
CT221128	M114	$\frac{12}{0,8}$
CT22112B	M114	$\frac{0}{}$
CT2213708000	M114	$\frac{12}{0,8}$
CT221K8	M114	$\frac{12}{0,8}$
KAT3K293708	RM039	$\frac{0}{}$
KAT3K353708	M114	$\frac{12}{0,8}$
KAT3KCT221126	M114	$\frac{12}{0,8}$

LUCAS	RMA $\sqrt{\text{Kw}} -!$
LRS100	0/
LRS100	PM598 /
LRS101	0/
LRS102	12/ 0,8
LRS103	0/
LRS106	0/
LRS107	PM130 0/
LRS108	12/ 0,8
LRS109	0/
LRS110	/
LRS110	0/
LRS112	0/
LRS113	M294 12/ 2,8
LRS115	M294 12/ 2,8
LRS120	0/
LRS121	M192 12/ 0,6
LRS121	M077 12/ 0,6
LRS121	M192 12/ 0,6
LRS124	M309 12/ 2,4
LRS125	M424 0/
LRS127	0/
LRS128	M070 12/ 0,8
LRS129	M294 12/ 2,8
LRS130	0/
LRS133	12/ 0,7
LRS134	0/
LRS135	M049 12/ 1,1
LRS135	M049 12/ 1,1
LRS136	0/
LRS137	RM096 0/
LRS139	PM335 0/
LRS141	M032 12/ 0,8
LRS144	M159 12/ 0,7 15a
LRS144	M159 12/ 0,7 15a
LRS147	PM162 0/
LRS148	12/ 0,7
LRS150	12/ 0,6
LRS150	12/ 0,6
LRS151	M294 12/ 2,8
LRS155	PM690 0/
LRS156	RM094 0/
LRS157	PM688 0/
LRS158	PM029 0/
LRS160	0/

LUCAS	RMA $\sqrt{\text{Kw}} -!$
LRS161	0/
LRS162	0/
LRS163	M307 0/
LRS164	0/
LRS166	0/
LRS168	M030 0/
LRS168	M043 0/
LRS170	M010 12/ 0,8
LRS172	0/
LRS173	PM645 0/
LRS176	M118 0/
LRS177	M021 0/
LRS178	M010 12/ 0,8
LRS178	M010 12/ 0,8
LRS180	12/ 0,8
LRS182	M091 0/
LRS183	M196 12/ 0,8
LRS183	M118 12/ 0,8
LRS184	0/
LRS184	PM686 /
LRS185	M083 0/
LRS185	M083X 0/
LRS187	0/
LRS188	PM405 0/
LRS189	0/
LRS190	PM147 12/ 2,0
LRS190	PM147 12/ 2,0
LRS192	M033 12/ 0,8
LRS192	M033 12/ 0,8
LRS195	PM689 0/
LRS196	M305 12/ 1,4
LRS198	0/
LRS199	0/
LRS202	M039 12/ 0,5
LRS203	PM908 12/ 0,6
LRS205	M011 12/ 0,9
LRS206	M016 12/ 0,8 15a
LRS206	M016 12/ 0,8 15a
LRS207	M021 0/
LRS208	12/ 0,8
LRS209	M096 12/ 0,8
LRS209	M096 12/ 0,8
LRS211	0/
LRS212	M294 12/ 2,8

LUCAS	RMA $\sqrt{\text{Kw}} -!$
LRS214	M128 0/
LRS215	PM334 0/
LRS217	M439 0/
LRS218	0/
LRS222	M114 12/ 0,8
LRS225	0/
LRS226	PM602 12/ 1,0
LRS227	PM371 0/
LRS229	M172 /
LRS229	M172 12/ 1,1
LRS230	0/
LRS231	M078 /
LRS231	M078 12/ 0,7
LRS232	PM645 0/
LRS233	M013X 0/
LRS234	M270 0/
LRS236	PM603 0/
LRS237	M094 12/ 0,6
LRS240	PM129 0/
LRS244	0/
LRS246	0/
LRS248	0/
LRS249	PM369 0/
LRS250	PM603 0/
LRS255	/
LRS255	M041 12/ 1,1
LRS256	M119 12/ 0,8
LRS256	M119 12/ 0,8
LRS259	M107 /
LRS259	M107 12/ 0,8 15a
LRS259	M107 12/ 0,8 15a
LRS260	M049 12/ 1,1
LRS260	M049 12/ 1,1
LRS261	PM779 0/
LRS262	M013 12/ 0,7
LRS266	PM600 0/
LRS268	M106 /
LRS268	M106 12/ 0,8 15a
LRS268	M106 12/ 0,8 15a
LRS269	M295 12/ 2,8
LRS272	M118 0/
LRS275	M044 12/ 1,0
LRS276	M391 0/
LRS278	12/ 1,1

LUCAS RMA $V/Kw -!$

LRS279	PM780	0/
LRS281		0/
LRS283		12/ 0,6
LRS283		0/
LRS286	M114	0/
LRS286	M114	0/
LRS287	M109	12/ 0,7
LRS291	M075X	12/ 0,8
LRS291	M075	12/ 0,8
LRS293	M210	0/
LRS295	M179	12/ 0,7
LRS298		0/
LRS301	PM224	0/
LRS301	PM224	/
LRS302	RM095	12/ 2,1
LRS302	RM095	12/ 2,1
LRS304	M059	12/ 2,5
LRS305		0/
LRS306		0/
LRS308	M117	12/ 1,1
LRS309	M021	12/ 1,0
LRS310	M124X	12/ 0,9
LRS311		0/
LRS312		0/
LRS318		0/
LRS319	PM405	0/
LRS320	PM643	0/
LRS322	PM371	0/
LRS323	M118	12/ 0,8
LRS324	M082	12/ 0,8
LRS324	M076	12/ 0,8
LRS327	M117	0/
LRS328	M161	12/ 2,2
LRS329	M100	12/ 0,8
LRS330	M156	12/ 2,0
LRS331	M079	12/ 2,0
LRS332		0/
LRS333	M084X	12/ 0,9
LRS334	PM403	0/
LRS335	M324	12/ 1,2
LRS336	PM407	0/
LRS336	PM403	0/
LRS338	PM370	0/
LRS340	M047	12/ 1,3

LUCAS RMA $V/Kw -!$

LRS341	M018	12/ 0,8	15a
LRS342	M035	12/ 0,8	
LRS343		12/ 0,8	
LRS344	M137	/	
LRS344	M082	12/ 0,8	
LRS344	M136	12/ 0,8	
LRS345		0/	
LRS347	M210	12/ 0,9	
LRS348		0/	
LRS350	M109	/	
LRS350	M109	12/ 1,1	15a
LRS351	M158	12/ 0,8	
LRS352	M072	12/ 1,5	
LRS353	M073	12/ 1,1	
LRS355		0/	
LRS356	M095	12/ 0,7	
LRS359	PM377	0/	
LRS360	M107	12/ 0,8	15a
LRS360	M107	12/ 0,8	15a
LRS360	M107	12/ 0,8	15a
LRS361	M034	12/ 0,8	
LRS363	M172	12/ 1,1	
LRS363	M172	12/ 1,1	
LRS364	M424	0/	
LRS365	M424	0/	
LRS366	M136	12/ 0,9	15a
LRS366	M136	12/ 0,9	15a
LRS367	PM281	0/	
LRS369		0/	
LRS370	M031	12/ 0,7	
LRS372	M065	12/ 2,0	
LRS374		12/ 1,5	
LRS375	PM130	0/	
LRS376	M064	12/ 2,0	
LRS379	PM384	0/	
LRS382	M101	12/ 1,5	
LRS382	M101	12/ 1,5	
LRS383	M121	12/ 2,2	
LRS385	PM602	0/	
LRS386		12/ 0,8	15a
LRS387	M051	12/ 1,5	
LRS387	M051	12/ 1,5	
LRS388		0/	
LRS389	M153	12/ 2,0	

LUCAS RMA $V/Kw -!$

LRS390	PM283	0/	
LRS391	PM523	0/	
LRS392	PM372	0/	
LRS392	PM372	0/	
LRS394	PM526	0/	
LRS395	PM377	0/	
LRS396	PM643	0/	
LRS397	PM293	0/	
LRS397	PM293	0/	
LRS400	M320	12/ 0,8	
LRS400	M320	12/ 0,8	
LRS401	M106	12/ 0,8	15a
LRS401	M106	12/ 0,8	15a
LRS402	M106	12/ 0,8	15a
LRS403	M425	0/	
LRS404	M436	0/	
LRS405	PM029	0/	
LRS408	M374	12/ 1,2	
LRS409	M180	12/ 0,8	
LRS409	M180	12/ 0,8	
LRS410	M075	12/ 0,8	
LRS410	M075X	12/ 0,8	
LRS413		0/	
LRS415	M433	0/	
LRS417	PM408	0/	
LRS418	M254	12/ 2,0	
LRS419	M063	12/ 1,5	
LRS422	PM325	0/	
LRS424		0/	
LRS426		0/	
LRS427	M041	12/ 1,1	
LRS427	M041	12/ 1,1	
LRS428	M326	12/ 0,9	
LRS429	M423	0/	
LRS430	M084X	12/ 0,9	
LRS435	PM128	0/	
LRS436	M017	12/ 0,8	
LRS437	M051	12/ 1,7	
LRS437	M051	12/ 1,7	
LRS438	PM514	0/	
LRS439	M193	12/ 2,0	
LRS439	M193	12/ 2,0	
LRS440	PM249	0/	
LRS442		0/	

LUCAS RMA $\frac{V}{Kw - !}$

LRS443	M061	12/1,1
LRS445	M097	12/0,8
LRS446	M011	12/0,9
LRS446	M011	12/0,9
LRS447	M011	/
LRS447	M011	12/0,9
LRS447	M011	12/0,9
LRS448	M026	12/1,6
LRS449	M011	12/0,9
LRS450	M166	12/0,8
LRS451	M033X	12/0,8
LRS451	M033X	12/0,8
LRS452	M301	12/1,1
LRS453	M026	12/1,6
LRS455	M264	12/1,7
LRS455	M214	12/1,7
LRS456	M293	12/0,8
LRS456	M293	12/0,8
LRS458	M075X	12/0,8
LRS458	M075X	12/0,8
LRS459	M102	12/0,8
LRS459	M102X	12/0,8
LRS460	M124X	12/1,0
LRS461	PM894	12/2,5
LRS462	M297	12/2,5
LRS463	M119X	12/1,0
LRS463	M119	12/1,0
LRS463	M192	12/1,0
LRS465	M120	0/
LRS465	M120X	0/
LRS466	M029	12/1,0
LRS467	M104	12/0,9
LRS468		0/
LRS469	PM383	0/
LRS470	M441	0/
LRS470	M441	0/
LRS471	PM327	0/
LRS471	PM327	0/
LRS473	M425	0/
LRS474	PM380	0/
LRS475	M103	12/1,7
LRS475	M103	12/1,7
LRS476	M105	12/1,7
LRS477	M171	12/2,1

LUCAS RMA $\frac{V}{Kw - !}$

LRS478	M052	12/1,7
LRS478	M052	12/1,7
LRS479	PM130	0/
LRS480	M128	0/
LRS482	M034	12/0,8
LRS484	M059	0/
LRS485	M127	12/0,8
LRS486	M334X	0/
LRS488		0/
LRS490	M439	12/0,8
LRS491	M334X	12/0,6
LRS492	PM684	0/
LRS493	PM785	0/
LRS495	M127	12/0,8
LRS496	PM424	0/
LRS497	M326	12/0,9
LRS499	PM021	0/
LRS500	PM404	0/
LRS501	PM745	0/
LRS502	PM272	0/
LRS503	M017	12/0,8
LRS504	PM600	0/
LRS505	M017	12/1,2
LRS505	M202	12/1,2
LRS506	PM435	0/
LRS507	PM419	0/
LRS508	M326	0/
LRS509	M329	12/0,8
LRS510		0/
LRS511	PM796	0/
LRS512	M130	0/
LRS514	M328	12/0,6
LRS515	M425X	0/
LRS516	M425	0/
LRS517	PM370	0/
LRS518	PM408	0/
LRS519		0/
LRS521	M148	12/0,9
LRS521	M068	12/0,9
LRS522	M116	12/1,4 15a
LRS523	M296	12/0,8
LRS525	M304	12/1,4
LRS526	M046	12/0,9
LRS527	M113	/

LUCAS RMA $\frac{V}{Kw - !}$

LRS527	M113	12/1,1
LRS528	M014	12/1,7
LRS529	M044	12/1,0
LRS530		0/
LRS531	M121X	12/2,9
LRS532	M280	/
LRS532	M280	12/1,1
LRS533	M124X	12/1,0
LRS534	M089	12/2,0
LRS535		0/
LRS536	M308	/
LRS536	M308	12/0,8
LRS538	M106	0/
LRS539	M223	/
LRS539	M223	12/1,0
LRS540	M106	0/
LRS541	M308	12/0,8
LRS541	M308	/
LRS542	M113	12/1,1
LRS543		0/
LRS543		0/
LRS544	M137	12/0,8
LRS544	M137	12/0,8
LRS545	PM287	12/1,0
LRS546	PM459	0/
LRS547	M333	12/2,0
LRS548	M374	12/1,2
LRS548	M374	/
LRS549	M061	12/1,1
LRS550		12/2,1
LRS552	RM099	0/
LRS553	PM263	0/
LRS556	M433	0/
LRS557	M433	0/
LRS558	M022	12/0,9
LRS558	M150	12/0,9
LRS559	M251	0/
LRS560	M111	12/0,8 15a
LRS560	M111	12/0,8 15a
LRS561		0/
LRS562		0/
LRS563	M140	/
LRS563	M140	12/1,5
LRS564	M218	12/1,7

LUCAS RMA $\frac{V}{Kw - !}$

LRS565	PM121	0
LRS566	PM126	0
LRS567	PM118	0
LRS568	PM149	0
LRS569	PM123	0
LRS570	PM115	0
LRS571		0
LRS572		0
LRS573		0
LRS574	M277	12/3,1
LRS575	M075X	
LRS575	M137	12/0,8
LRS575	M075X	12/0,8
LRS576	M082	12/0,8
LRS578	M214	12/1,7
LRS578	M214	12/1,7
LRS580	PM778	0
LRS581		0
LRS582	M077	12/0,6
LRS582	M119	12/0,6
LRS588	M032	12/0,8
LRS589	M055	12/1,0
LRS591	M045	12/2,2
LRS592	M176	12/1,1
LRS592	M176	12/1,1
LRS593	M011	12/0,9
LRS594		0
LRS594		0
LRS597	M104	12/0,9
LRS598	M104	0
LRS599	PM434	0
LRS600	PM601	0
LRS601	PM379	0
LRS601	PM379	0
LRS602	PM327	0
LRS604	PM351	0
LRS605	M327	12/0,7
LRS605	M327	12/0,7
LRS606	PM780	0
LRS607	PM423	0
LRS608	PM425	0
LRS609	PM444	0
LRS610	PM443	0
LRS611	M088	12/2,2

LUCAS RMA $\frac{V}{Kw - !}$

LRS611	M088	12/2,2
LRS612	M223	
LRS612	M223	12/0,9
LRS613	M318	
LRS613	M318	12/1,4 15a
LRS614	M056	12/0,9
LRS615	PM432	0
LRS617	M341	12/2,2
LRS620	PM130	0
LRS621	M243	0
LRS624	M433	0
LRS625	PM400	0
LRS626	PM400	0
LRS627	M431	0
LRS627	M431	0
LRS628	PM744	0
LRS631	PM120	0
LRS632	PM149	0
LRS633	PM108	0
LRS636	PM145	0
LRS638	PM127	0
LRS639	PM149	0
LRS640	PM215	0
LRS641	PM215	0
LRS642	PM215	0
LRS643		0
LRS644		0
LRS646	M040	12/2,2
LRS647	M182	12/1,1
LRS648	M148	12/0,9 15a
LRS648	M148	12/0,9 15a
LRS649	M037	12/2,2 30h
LRS649	M037	12/2,2 30h
LRS650	M157	12/2,2
LRS651	M137	12/0,9
LRS651	M138	12/0,9
LRS652	M134	0
LRS652	M137	0
LRS652	M138	0
LRS653	M260	12/1,4
LRS653	M260	12/1,4
LRS653	M260	12/1,4
LRS654	M263	12/1,4
LRS655	M083	12/1,4

LUCAS RMA $\frac{V}{Kw - !}$

LRS655	M083	12/1,4
LRS656	M216	12/1,7
LRS657	M015	12/1,7
LRS657	M015	12/1,7
LRS658	M162	12/2,2
LRS659		0
LRS660	M237	12/1,4
LRS661	M066X	12/2,2
LRS661	M066X	12/2,2
LRS662	M257	12/1,7
LRS663	M053	12/2,2
LRS664	M048	12/2,2
LRS665	M058	12/1,7
LRS666	M281	12/1,1
LRS671	M074	12/0,9
LRS671	M176	12/0,9
LRS672	PM158	0
LRS673	M059	12/2,5
LRS675	M134	12/0,8
LRS676	M285	12/2,2
LRS676	M285	12/2,2
LRS677	PM454	0
LRS677	PM454	
LRS678	PM464	0
LRS678	PM464	
LRS680	M115	12/1,0 15a
LRS681	M112	12/0,9 15a
LRS682		0
LRS683		
LRS683	M226	12/1,0
LRS684	M426	0
LRS688	M431	0
LRS689	PM469	0
LRS692	M432	0
LRS692	PM294	0
LRS693	PM459	0
LRS695	PM437	0
LRS696	PM466	0
LRS697	M131	12/0,8
LRS698	M250	12/1,7
LRS698	M250	12/1,7
LRS703	M419	0
LRS704	M338	12/1,0
LRS706	PM599	

LUCAS RMA $V \sqrt{Kw} -!$

LRS706	PM599	0
LRS707	PM558	0
LRS708	M406	
LRS708	M406	0
LRS709	M305	12 1,4
LRS710	M201	12 1,4
LRS711	M443	0
LRS711		
LRS712		
LRS712	PM250	12 1,8
LRS713	PM325	0
LRS714	RM039	0
LRS715	M143	12 0,9
LRS718	PM336	0
LRS719	M194	12 1,0
LRS719	PM295	12 1,0
LRS719	M194	12 1,0
LRS720	M129	12 0,8
LRS721	PM429	0
LRS722	M446	0
LRS723	PM015	0
LRS724	PM455	0
LRS725	PM512	0
LRS726	M440	0
LRS727	M336X	12 2,0
LRS727	M336X	
LRS728	M277X	12 3,1
LRS729	M240	12 1,4
LRS730	M195	12 1,4
LRS731	M191	12 1,0
LRS732	M217	12 1,4
LRS732	M217	12 1,4
LRS733	M214	12 1,7
LRS733	M214	12 1,7
LRS734		0
LRS735	M120X	12 1,9
LRS736		0
LRS737	M222	12 1,0
LRS738	M423X	0
LRS740	M213	0
LRS741	M335	0
LRS742	M200	12 1,4
LRS743	M228	12 2,2
LRS744	M247	12 2,2

LUCAS RMA $V \sqrt{Kw} -!$

LRS745	M243	12 1,4
LRS746	PM198	0
LRS747	PM164	0
LRS749	M102X	12 1,1
LRS750	M185	12 1,4 30h
LRS751	M105	12 1,7
LRS751	M105	12 1,7
LRS752	PM296	0
LRS754	M278	12 3,1
LRS755	M235	12 1,4
LRS756	M137	12 0,8
LRS756	M137	12 0,8
LRS757	M134	12 0,8
LRS757	M134	12 0,8
LRS758	M190	0
LRS759	PM558	0
LRS760	M260	12 1,4
LRS761	M034	12 0,8
LRS762	PM148	12 2,4
LRS763	PM133	0
LRS764	PM213	0
LRS765	PM169	0
LRS766	PM210	0
LRS767	PM170	0
LRS768	PM456	0
LRS769	M325	12 0,8
LRS778	PM202	0
LRS781	M310	
LRS781	M310	12 1,8
LRS782	M442	0
LRS783	M069X	12 1,4
LRS784	M383	0
LRS784	M383	0
LRS785	M248	12 1,1
LRS786	PM272	0
LRS787	M244	12 1,8
LRS788	M261	0
LRS788	M261	0
LRS789	PM609	0
LRS790	M251	12 0,9
LRS791	M236	12 1,1
LRS792	PM024	0
LRS793	PM341	0
LRS794	PM752	0

LUCAS RMA $V \sqrt{Kw} -!$

LRS795	M271	12 1,0
LRS795	M271	
LRS796	PM140	0
LRS797	PM171	0
LRS798		0
LRS799	PM215	0
LRS801	M012	12 0,7
LRS806	M158	12 0,8
LRS807	M038	12 1,0
LRS808	M299	12 1,5
LRS810	M067	12 0,6
LRS813	M152	12 0,8 15a
LRS814	M197	12 1,5
LRS814	M197	12 1,5
LRS816	M089	12 2,0
LRS817	PM184	0
LRS818	PM106	0
LRS819	PM189	0
LRS820	PM112	0
LRS821	PM221	0
LRS822	PM181	0
LRS823	PM188	0
LRS824	PM184	0
LRS825	PM189	0
LRS826	M039	12 0,5
LRS827	M023	12 0,8
LRS828	M028	12 2,0
LRS830		12 0,6
LRS830		0
LRS832	M097	0
LRS833		0
LRS834	M125	12 2,2
LRS835		12 2,8
LRS837	PM138	0
LRS838	M027	12 2,5
LRS838	M027	12 2,5
LRS839	PM155	0
LRS840	PM142	0
LRS841	PM146	0
LRS841	PM146	0
LRS845	PM194	0
LRS845	PM194	
LRS847	M091	12 3,5
LRS847	M091	12 3,5

LUCAS	RMA $\sqrt{Kw - !}$
LRS848	M091 0/
LRS849	M340 12/ 1,4
LRS850	PM150 0/
LRS854	M137 12/ 0,6
LRS854	M081 12/ 0,6
LRS857	M152 12/ 0,8 15a
LRS858	M152 0/
LRS859	M034 12/ 0,8
LRS860	PM201 0/
LRS860	PM191 0/
LRS861	PM193 0/
LRS862	PM188 0/
LRS865	PM206 0/
LRS867	M094 12/ 0,6
LRS869	M096 12/ 0,8
LRS869	M096 12/ 0,8
LRS870	M174 12/ 1,0 15a
LRS871	M093 12/ 1,0
LRS874	M010 0/
LRS875	0/
LRS876	M094 12/ 0,6
LRS877	M280 12/ 1,1
LRS878	PM190 0/
LRS883	PM192 0/
LRS884	M426 0/
LRS885	PM274 0/
LRS886	M431 0/
LRS886	M431 0/
LRS888	PM286 0/
LRS889	PM480 0/
LRS890	M238 0/
LRS891	M255 0/
LRS891	M255 0/
LRS892	M255 0/
LRS893	M394 0/
LRS894	M034 0/
LRS895	PM050 0/
LRS896	PM397 0/
LRS897	PM462 0/
LRS898	M143 0/
LRS899	M406 0/
LRS903	PM741 0/
LRS911	M025 12/ 1,0
LRS912	M108 12/ 0,8 15a

LUCAS	RMA $\sqrt{Kw - !}$
LRS912	M108 12/ 0,8 15a
LRS913	M034 12/ 0,8
LRS913	M149 12/ 0,8
LRS915	M109 12/ 1,1 15a
LRS916	M063 12/ 1,5
LRS916	M063 12/ 1,5
LRS917	M087 12/ 1,5
LRS917	M140 12/ 1,5
LRS918	M165 12/ 1,5
LRS919	M024 12/ 0,8
LRS919	M024 12/ 0,8
LRS920	M253 12/ 2,0
LRS921	PM122 12/ 2,4
LRS922	PM204 0/
LRS923	PM137 0/
LRS924	0/
LRS925	PM110 0/
LRS926	PM162 0/
LRS928	PM192 0/
LRS929	PM143 0/
LRS930	PM136 0/
LRS932	PM119 0/
LRS934	PM247 0/
LRS940	M246 12/ 2,2
LRS941	M028 12/ 2,0
LRS941	M028 12/ 2,0
LRS944	M091 0/
LRS945	PM195 0/
LRS946	PM138 0/
LRS947	PM318 0/
LRS950	PM116 0/
LRS954	PM116 0/
LRS959	0/
LRS960	PM156 0/
LRS961	PM139 0/
LRS962	PM141 0/
LRS963	M175 0/
LRS964	M256 0/
LRS965	M389 0/
LRS966	M313 0/
LRS967	M437 0/
LRS968	PM689 0/
LRS969	PM691 0/
LRS970	M048X 0/

LUCAS	RMA $\sqrt{Kw - !}$
LRS971	PM026 0/
LRS972	M151 0/
LRS972	M151 0/
LRS973	PM265 0/
LRS974	M344 0/
LRS975	M320 0/
LRS976	M059 0/
LRS976	M420 0/
LRS977	M289X 0/
LRS978	M403 0/
LRS978	M389 0/
LRS979	M429 0/
LRS979	M429 0/
LRS980	M078 12/ 0,7
LRS981	M157 0/
LRS981	M161 12/ 2,2
LRS982	0/
LRS983	12/ 0,8
LRS984	M110 12/ 0,7
LRS985	PM216 0/
LRS986	PM207 0/
LRS987	PM176 0/
LRS988	0/
LRS989	M268 12/ 0,8
LRS990	M227 12/ 1,1
LRS991	M258 12/ 2,2
LRS992	M235X 12/ 1,4
LRS993	PM027 0/
LRS994	M381 0/
LRS995	PM460 0/
LRS996	M280 0/
LRS997	M017X 0/
LRS999	M417 0/
LRT100	PM299 0/
LRT101	PM252 0/
LRT102	PM238 0/
LRT103	M345 0/
LRT104	M252 0/
LRT104	M314 0/
LRT105	PM454 0/
LRT106	M380 0/
LRT106	M336X 0/
LRT107	M314 0/
LRT108	PM094 0/

LUCAS	RMA $\frac{V}{Kw -!}$	LUCAS	RMA $\frac{V}{Kw -!}$	LUCAS	RMA $\frac{V}{Kw -!}$
LRT110	PM684 0/	LRT155	M413 0/	NSB131	M016 $\frac{12}{0,8}$ 15a
LRT111	PM367 0/	LRT156	PM357 0/	NSB132	M131 $\frac{12}{0,8}$
LRT113	0/	LRT157	PM282 0/	NSB133	M095 $\frac{12}{0,7}$
LRT114	PM268 0/	LRT158	M444 0/	NSB134	M102 $\frac{12}{0,8}$
LRT115	PM031 0/	LRT159	M099 0/	NSB136	M150 $\frac{12}{0,9}$ 15a
LRT116	M262 0/	LRT160	M304 0/	NSB137	M159 $\frac{12}{0,7}$ 15a
LRT117	PM253 0/	LRT161	M299X 0/	NSB307	M305 $\frac{12}{1,4}$
LRT118	PM476 0/	LRT163	M307 0/	NSB310	M113X $\frac{12}{1,4}$
LRT119	M185X 0/	LRT165	M387 0/	NSB311	M061 $\frac{12}{1,1}$
LRT120	M447 0/	LRT166	PM033 0/	NSB312	PM327 0/
LRT120	M447 /	LRT167	M317 0/	NSB317	M201 $\frac{12}{1,4}$
LRT121	M099X 0/	LRT169	PM044 0/	NSB400	M214 $\frac{12}{1,7}$
LRT122	0/	LRT170	M037 0/	NSB405	PM029 0/
LRT123	PM499 0/	LRT172	M315 0/	NSB501	PM333 0/
LRT124	M120X 0/	LRT173	PM566 0/	NSB501	PM333 0/
LRT125	PM013 0/	LRT174	M416 0/	NSB502	$\frac{12}{2,1}$
LRT125	PM013 0/	LRT175	M143 0/	NSB503	M309 0/
LRT126	M195 0/	LRT179	M289 /	NSB505	PM334 0/
LRT127	PM481 0/	LRT181	PM495 0/	NSB509	PM147 0/
LRT128	M176 0/	LRT181	PM495 /	NSB509	PM147 $\frac{12}{2,0}$
LRT129	PM015 0/	LRT182	M397 0/	NSB511	PM335 0/
LRT130	PM229 0/	LRT183	PM291 0/	NSB512	M277 0/
LRT131	M421 0/	LRT240	PM240 /	NSB512	PM335 0/
LRT132	M284 0/	LRT600	PM685 0/	NSB515	PM690 0/
LRT133	M396 0/	LRT601	0/	NSB520	M294 0/
LRT134	M399 0/	LRT602	0/	NSB521	M059 $\frac{12}{2,5}$
LRT135	PM174 0/	LRT603	0/	NSB527	0/
LRT136	M027X 0/	LRT604	0/	NSB528	0/
LRT137	PM106 0/	LRT605	0/	NSB529	PM645 0/
LRT138	M352 0/	LRT608	0/	NSB531	PM645 0/
LRT139	M385 0/	LRT609	0/	NSB532	RM095 0/
LRT140	PM032 0/	LRT610	0/	NSB535	PM130 0/
LRT141	M419 0/	LRT613	PM167 0/	NSB540	PM645 0/
LRT142	PM093 0/	LRT614	0/	NSB541	0/
LRT143	M319 0/	LRT616	0/	R27592	PM689 /
LRT144	M265 0/	LRT617	0/	SNB503	M309 $\frac{12}{2,4}$
LRT145	M269 0/	LRT618	PM685 0/		
LRT146	M405 0/	LRT641	PM685 0/		
LRT147	M283 0/	LRT642	0/		
LRT148	M402 0/	NSB100	M137 $\frac{12}{0,8}$		
LRT149	M316 0/	NSB104	0/		
LRT150	M058X 0/	NSB122	0/		
LRT151	PM435 0/	NSB127	M023 $\frac{12}{0,8}$		
LRT154	PM301 0/	NSB128	M056 $\frac{12}{0,9}$		

MANDO RMA $\frac{V}{Kw -!}$

HQ808670	M341	/
HSG120500		0/
M04686	PM609	0/
M35216	M435	0/
M39376	PM376	0/
M39646	M425	/
M43168	PM366	/
M43196	M431	0/
M52100	PM536	0/
M53486	PM535	0/
M56290	PM659	/
M60082	PM665	/
MC107012	M425X	0/
MC107023	M425X	0/
MC107023		/
MC108024	M431	0/
MC108027	PM609	0/
MC108030	PM609	0/
MC109011	PM609	0/
MC109015	M435	0/
MC109018	M425	0/
MC109021	M431	0/
MC109025	M425	0/
MC109028	M431	0/
MC109028	M431	0/
MC109028	M431	/
MC109032	PM376	0/
MC109036	M431	0/
MG112014	M426	0/
MG112022	PM299	0/
MG120413	M193	$\frac{12}{2,0}$
MG120413	M193	$\frac{12}{2,0}$
MG120416	PM387	0/
MG120445	PM397	0/
MG120558		0/
MG120906	M193	$\frac{12}{2,0}$
MG122202	M341	/
MG122404	PM400	0/
MG122433	M341	0/
MG232415	PM396	0/
MP112033	M429	0/
MP112038	PM356	0/
MP112040	M426	0/
MP112040	M426	/

MANDO RMA $\frac{V}{Kw -!}$

MP112041	PM299	0/
MP112042	M429	0/
MP112043	PM363	0/
MP117044	PM360	0/

MANDO RMA $\frac{V}{Kw -!}$

MARELLI RMA $\frac{V}{Kw - !}$

00027043010	
063102003010	M405
063114008010	M411
063223101010	M131
06322320010	M268
063223730010	M382
063226838	M243
063226942010	
106023	
1110025	M058
112123	
130019808	M284
1473638080	PM094
1475489080	PM094
22615	
22620	
23735	M049 0
24257	M105 0
25016	0
25022	0
25024	0
25041	0
25061	0
25062	0
25063	0
25065	0
25071	0
25075	12/0,8
25079	0
25083	12/0,8
25085	0
25087	0
25088	0
25089	12/0,8
25097	0
25105	12/0,8
25112	0
25118	0
25122	0
25138	0
25141	12/0,8
25142	PM598 0
25147	12/0,8
25148	PM598 0

MARELLI RMA $\frac{V}{Kw - !}$

25149	0
25150	0
25165	0
25182	M210 0
25196	0
25201	0
25204	M159
25204	M159 12/0,7 15a
25205	M159
25205	M159 12/0,7 15a
25206	0
25208	M159 12/0,7 15a
25209	0
25219	PM692
25236	PM598
25238	12/0,8
25239	0
25242	PM198 0
25242	
25246	0
25249	M043
25249	M043 12/1,0
25250	0
25253	M210 0
25255	
25257	12/0,7
25260	PM598 0
25265	PM598 0
25266	M210 0
25270	M159
25270	M159 12/0,7 15a
25271	M030 12/0,7
25271	M030 12/0,7
25272	M030 12/0,7
25276	0
25277	0
25281	0
25282	M049
25282	M152 12/1,1
25282	M049 12/1,1
25283	M210 0
25285	M196 12/0,8
25286	12/0,7
25287	

MARELLI RMA $\frac{V}{Kw - !}$

25288	0
25289	M030 12/0,7
25289	M030 12/0,7
25290	0
25291	M210 0
25292	M096 12/0,8
25292	M096 12/0,8
25294	0
25295	0
25326	M082 12/0,8
25326	M076 12/0,8
25329	M391 0
25330	0
25331	0
25332	M082 12/0,8
25332	M082 12/0,8
25333	0
25334	M082 0
25335	M159 12/0,7 15a
25335	M159 12/0,7 15a
25337	M159 12/0,7 15a
25338	M076 12/0,8
25338	M137 12/0,8
25338	M082 12/0,8
25339	M061 12/1,1
25344	M082 12/0,8
25344	M082 12/0,8
25345	12/0,8
25348	0
25349	M106 12/0,8 15a
25349	M106 12/0,8 15a
25350	M106 12/0,8 15a
25350	M106 12/0,8 15a
25351	M106 12/0,8 15a
25355	M113 12/1,1
25355	M113 12/1,1
25356	0
25357	M159 12/0,7 15a
25357	M159 12/0,7 15a
25360	0
25362	0
25365	12/1,1
25366	0
25368	0

MARELLI RMA $\frac{V}{Kw -!}$

25369	
25370	0
25372	0
25375	PM249 0
25376	0
25379	0
25382	0
25383	M076 12 0,8
25387	PM249 0
25388	0
25397	M136 12 0,8
25398	0
25400	0
25404	M082 12 0,8
25411	PM249 0
25512	0
25524	0
25533	0
25593	0
25603	0
25605	0
25612	0
25616	PM686 0
25620	0
25626	0
25631	0
25632	0
25642	0
25647	0
25648	M030 12 0,7
25654	PM686 0
25660	PM686 0
25668	0
25674	0
25678	0
25681	M305
25683	0
25684	RM094 0
25685	M305 0
25689	0
25692	0
25696	M305 12 1,4
25701	0
25704	0

MARELLI RMA $\frac{V}{Kw -!}$

25707	0
25712	M049
25712	M049 12 1,1
25714	0
25716	12 1,1
25717	0
25719	0
25720	0
25728	0
25732	0
25734	0
25735	M049 12 1,1
25745	0
25749	0
25755	M304 12 1,4
25756	M304 12 1,4
26071	PM688
26125	0
26126	0
26132	
26133	PM688 0
26137	M294
26140	0
26143	PM688
26145	PM147 12 2,0
26147	M294
26148	M309 0
26150	12 2,1
26151	
26151	PM333 0
26153	PM690
26154	PM147 12 2,0
26156	0
26157	
26163	0
26164	0
26165	0
26166	PM690
26167	PM688 0
26173	PM688 0
26180	RM094 0
26183	0
26186	PM147
26189	M294 0

MARELLI RMA $\frac{V}{Kw -!}$

26193	
26196	M309 12 2,4
26197	12 2,1
26198	
26198	PM333 0
26200	PM147 12 2,0
26211	M294 12 2,8
26213	M294 12 2,8
26219	PM334 0
26220	PM147 12 2,0
26227	M294 12 2,8
26242	PM162
26246	
26251048	M328
26252	0
26256	PM335 0
26259	PM335 0
26264	PM147 12 2,0
26265	PM130 0
26266	0
26267	M305 0
26271	PM334 0
26273	PM224 0
26274	PM645 0
26278	PM688 0
26280	12 2,1
26281	PM333 0
26283	M309 12 2,4
26284	PM162 0
26285	
26286	PM690 0
26288	PM688 0
26290	PM150
26291	M294 12 2,8
26294	PM689 0
26295	RM096 0
26301	0
26302	0
26304	0
26310	0
26311	PM130 0
26312	M059
26316	M294 12 2,8
26320	0

MOTORINI

MARELLI

MARELLI **RMA** $V \sqrt{Kw} -!$

26321	PM335 0/
26323	PM645 0/
26329	M294 12/ 2,8
26330	M294 12/ 2,8
26336	PM129 12/ 1,7
26336	PM129 12/ 1,7
26338	M294 12/ 2,8
26339	M294 12/ 2,8
26341	PM130 0/
26342	PM162 0/
26343	0/
26345	PM645 0/
26349	RM095 12/ 2,1
26351	M294 12/ 2,8
26352	M294 12/ 2,8
26355	M059 12/ 2,5
26356	M059 0/
26357	PM689 0/
26358	RM096 0/
26359	M027 0/
26364	M294 12/ 2,8
26365	PM224 /
26366	PM645 0/
26369	M027 0/
26371	PM779 0/
26373	0/
26374	RM096 /
26375	M309 12/ 2,4
26376	0/
26379	RM099 0/
26381	0/
26386	M295 12/ 2,8
26388	M059 12/ 2,5
26390	PM150 12/ 3,5
26391	PM147 0/
26394	M406 0/
26395	M294 12/ 2,8
26396	M223 0/
26398	PM263 0/
26398	PM263 0/
26398	PM263 0/
26398	PM263 0/
26399	M294 /
26400	PM779 0/

MARELLI **RMA** $V \sqrt{Kw} -!$

26405	0/
26406	PM645 0/
26407	M059 12/ 2,5
26408	RM096 0/
26410	PM645 0/
26411	PM224 0/
26412	PM147 12/ 2,0
26413	PM334 0/
26414	PM691 0/
26416	RM095 0/
26417	PM128 0/
26418	/
26420	RM095 /
26422	M309 12/ 2,4
26428	PM129 /
26430	M059 0/
26430A	M059 0/
26430D	M059 0/
26431	PM130 0/
26432	PM162 /
26433	PM129 0/
26436	RM096 /
26457	M436 0/
26587	M134 12/ 0,8
26600	M137 12/ 0,8
26600	M137 12/ 0,8
26601	M137 12/ 0,8
26601	M137 12/ 0,8
26602	M308 12/ 0,8
26604	M106 12/ 0,8 15a
26605	PM558 0/
26606	M106 0/
26607	M223 12/ 0,9
26609	PM325 0/
26613	0/
26614	M308 12/ 0,8
26616	PM558 0/
26616	PM558 0/
26617	M223 0/
26618	M308 12/ 0,8
26618	M308 12/ 0,8
26619	M308 12/ 0,8
26622	M308 12/ 0,8
26624	M082 12/ 0,8

MARELLI **RMA** $V \sqrt{Kw} -!$

26624	M082 12/ 0,8
26624	M082 12/ 0,8
26626	0/
26628	M260 12/ 1,4
26628	M260 12/ 1,4
26628	M260 12/ 1,4
26629	0/
26631	PM692 0/
26645	PM326 0/
26647	M106 0/
26648	0/
26649	/
26649	0/
26649	0/
26654	0/
26654	0/
26655	0/
26656	0/
26657	0/
26657	0/
26660	M406 0/
26660	M406 0/
26664	0/
26667	M338 12/ 1,0
26678	M134 12/ 0,8
26678	M134 12/ 0,8
26678D	M134 0/
26679	M137 12/ 0,8
26679	M137 12/ 0,8
26679	M137 12/ 0,8
26680	M260 12/ 1,4
26681	PM558 0/
26682	M223 0/
26686	0/
26688	0/
26689	M217 12/ 1,4
26689	M217 0/
26689	M217 12/ 1,4
26690	M406 0/
26692	M223 12/ 0,9
26693	M406 0/
26694	M406 0/
26695	M235 12/ 1,4
26696	M223 12/ 0,9

MARELLI	RMA $V_{Kw} -!$
26698	PM558 0
26699	PM558 0
26701	0
26702	M223 12/0,9
26707	0
26715	M441 0
26717	M223 12/0,9
26719	0
26721	0
26722	M223 12/0,9
26800	PM029 0
26801	M305 12/1,4
26802	M359 12/1,1
26803	0
26804	M318 12/1,4 15a
26805	M243 12/1,4
26806	M243 0
26807	M243 0
26809	M311 12/1,4
26810	M312 12/1,4
26811	M223
26812	M223X 12/0,9
26813	M201 12/1,4
26814	PM520 0
26815	M311 12/1,4
26816	M311 0
26819	M243 12/1,4
26820	M243 12/1,4
26823	M311 12/1,4
26824	M312 12/1,4
26826	M243 0
26827	M243 0
26829	M243 0
26830	M311 12/1,4
26831	M311 12/1,4
26832	M312 0
26833	M312 12/1,4
26834	M201 12/1,4
26835	M223X
26836	M311 12/1,4
26837	M312 12/1,4
26838	M243 12/1,4
26839	0
26841	M201 12/1,4

MARELLI	RMA $V_{Kw} -!$
26842	M318 12/1,4 15a
26845	M201 12/1,4
26847	M223X
26904	0
26908	M436 0
26909	0
26910	PM454
26912	PM464 0
26913	M214 12/1,7
26913	M214 12/1,7
26914	M214 12/1,7
26917	PM688
26920	
26921	PM250 12/1,8
26923	0
26925	PM645
26925056	
26925159A	M446
26925159B	M446
26927	0
26929	PM250 12/1,8
26929	PM250 12/1,8
26932	0
26935	M214 12/1,7
26935	M214 12/1,7
26936	PM250 12/1,8
26936	PM250 12/1,8
26937	M436 0
26938	PM250 0
26941	M214 12/1,7
26942	M214 12/1,7
26943	M058 0
26945	M058X 12/1,8
27002	M190 0
27002	M190 0
27004	M235 12/1,4
27005	M082 12/0,8
27005	M137 12/0,8
27006	M137 12/0,8
27007	PM332 0
27008	M082 12/0,8
27008	M082 12/0,8
27009	0
27010	M260 0

MARELLI	RMA $V_{Kw} -!$
27011	PM025 0
27013	M137 12/0,8
27013	M082 12/0,8
27014	M137 12/0,8
27014	M134 12/0,8
27016	PM558 0
27017	M134 0
27018	PM692
27022	M338 12/1,0
27024	M308 12/0,8
27026	12/0,8
27029	M106 0
27034	M406 0
27035	M106 0
27035	M406 0
27037	M223 12/1,0
27037	M338 12/1,0
27041	0
27043	M338 0
27043	M338 0
27044	M223 0
27045	M223 0
27047	M338 12/1,0
27048	0
27049	0
27050	0
27051	M338
27058	0
2707130	
27305	PM166 0
27309	PM165 0
27311	PM165 0
27315	PM165 0
27400	M079 12/2,0
27400	M079 12/2,0
27401	M027 12/2,5
27402	M153 0
27407	0
27408	PM147 12/2,0
27409	PM147 0
27409	PM147 12/2,0
27412	0
27412	0
27413	PM688 0

MOTORINI

MARELLI

MARELLI **RMA** $V_{Kw} -!$

27415	PM333	0
27416		12 2,1
27417	M309	12 2,4
27419	PM690	0
27420		0
27421	PM147	0
27422		0
27423	PM688	
27424		0
27425	M277	0
27426	M294	12 2,8
27427		0
27428		0
27430	M091	12 3,5
27431	PM779	0
27432	PM147	12 2,0
27433	PM334	0
27435	M309	12 2,4
27436		0
27440	M074	0
27443	RM095	12 2,5
27446	PM335	0
27448		0
27454	M079	12 2,0
27455	M254	12 2,0
27456	M171	12 2,1
27457		0
27459	PM147	12 2,0
27460	M277	0
27463	PM688	0
27464	PM333	
27465	PM690	0
27467	M309	12 2,4
27468	PM335	0
27469	PM147	12 2,0
27470	PM147	12 2,0
27472	M309	12 2,4
27473		
27473	PM333	0
27474	PM147	12 2,0
27475		0
27476	PM690	
27477		0
27478	M309	12 2,4

MARELLI **RMA** $V_{Kw} -!$

27479	PM333	0
27480	PM147	0
27481		0
27482		0
27485		0
27486	M309	12 2,4
27487	PM333	0
27488	PM147	0
27489		0
27490		0
27500	M294	12 2,8
27501	M059	12 2,5
27502		0
27503		0
27504		
27507		
27508	PM129	0
27510	PM645	0
27511	PM130	0
27512	PM162	0
27513		0
27515	PM645	0
27516		0
27518	PM689	0
27519	RM096	
27520	PM689	0
27522	PM224	0
27523	PM645	
27523		0
27524	PM689	
27526		0
27528	RM099	0
27529	PM645	
27531	M059	12 2,5
27533	PM263	0
27537	RM096	0
27539	PM645	0
27540	PM224	0
27541	PM691	0
27543	RM095	12 2,1
27544	PM128	0
27545	RM095	
27547	PM691	
27553	M059	0

MARELLI **RMA** $V_{Kw} -!$

27554	PM130	0
27556		
27556	PM129	0
27557	M059	0
27558	PM129	0
27559	RM096	0
27563		0
27564	PM599	0
27565	PM691	0
27567	M059	12 2,5
27567	M059	0
27568	PM691	0
27569	M294	0
27570	PM689	0
27571	PM224	0
27572	PM645	0
27573		0
27574		0
27575	PM129	0
27576		0
27577	M059	12 2,5
27578	PM645	0
27582	PM224	
27583	PM645	0
27584	PM224	0
27585	PM689	0
27586	PM129	0
27587	PM162	0
27588	PM689	0
27590	PM691	0
27592	PM689	0
27593	PM224	
27594	PM645	
27594		0
27595	PM599	0
27596	PM689	0
27598	PM691	0
27599	PM691	0
27601	PM263	
27602	PM691	
27604	PM129	0
27606	PM645	
27608	PM691	0
27626	PM691	

MARELLI	RMA $\sqrt{\text{Kw}} -!$	MARELLI	RMA $\sqrt{\text{Kw}} -!$	MARELLI	RMA $\sqrt{\text{Kw}} -!$
27707	0	4294495		4713807	M028
30000	M406	4377759	PM135	4716062	PM144
30000A	M406 0	4392461		4719664	M027
30001A	M406 0	43924610		4728682	PM150
30002A	M406 0	441289	M028	4732241	PM202
30003A	M406 0	4421708		4732242	PM194
30180187		4448694	M028	4737756	PM146
30180187		4469985		4737758	
30180246		4469986		4741699	M028
30180280		4469987		4755108	PM138
30180280		4470118		4755109	M091
30180285		4470377		4755110	PM135
30180287		4470378		4755112	
30180289		4470378	M131	4755113	PM142
30180289		4474762		4759929	PM150
30180304	M028	4474763		4780974	PM223
30180309		4475130		4782801	
30180309	M027	4475131		4782802	PM202
30180342		4622477	PM138	4782803	PM194
30280103	PM138	46231505	M270	4784745	PM207
30281003		46414831	M200	4784747	
30281004		46430721	M058X	47920141	
30281004	PM138	46430784	M384	50232991	PM247
30281012	PM142	46430785	M268	50246218	M116 0
30281012	PM142	46446291	M058	50246416	M258 0
30281013		46468696	M382	50246532	M283 0
30281013	PM138	46473784	M384	50246648	M283 0
30281017	PM142	46518059	M268	54022264	
30281017	PM142	46791692	M382	54293284	PM689
30281018		4682996		54293704	M223
30281018	PM155	4682998	PM150	54293817	M223
30281020	PM146	4682999	PM138	54294945	M058X ¹² / _{1,8}
30281020	PM146	4691200	PM155	54294945	M058X ¹² / _{1,8}
30281027	PM142	4699705	M091	5885182	M048X
30380301	M091	4701920	PM138	5984563	M045
30380319	PM150	4702248	M091	5985265	M053
3708000		4703751	M091	5997307	
3708000	M114	4706008	PM146	60504218	
4169096	M091	4706720	PM142	60512969	M151
4169096	M091	4706931	PM155	60512969	M151
4172113	PM150	4710224	PM150	60521584	
4179626	PM202	4711699	M027	60522387	M062
4269114	PM138	4713806	PM135	60562973	M013
4294494		4713806	PM135	60562974	M013X

MARELLI RMA $\frac{V}{Kw -!}$

60585343	M200	
60655876	M200	
60777242	M062X	
60800295	M057	
60813460	M200	
60814706	M200	
60814911	M384	
60925032	PM598	
61227993		
61924015	PM150	
61924031	PM146	
61924050	PM122	
61924051	PM137	
61924100	M193	
61924101	M425	
62925042	PM686	
63101000	PM231	0
63101002	M268	$\frac{12}{0,8}$
63101003	M408	0
63101007	PM314	0
63101008	M408	0
63101015	M401	0
63101018	M401	0
63101022	M408	0
63101023	M408	0
63102000	PM301	0
63102003	M405	0
63102004	PM231	0
63102007	M268	0
63102008	M269	$\frac{12}{0,9}$
63102014	PM302	0
63102018	M401	0
63102020	M401	0
63102021	PM302	0
63102022	PM304	
63103002	M131	
63103002	M283	$\frac{12}{0,9}$
63103003	M409	0
63103007	M283X	0
63103008	M409	0
63103015	PM305	0
63103017	PM306	0
63103017	PM306	0
63103022	M283	0

MARELLI RMA $\frac{V}{Kw -!}$

63103023	PM307	0
63103024	PM305	0
63103025	PM306	0
63103026	PM308	0
63103028	PM309	0
63103031	M401X	
63111000	M402X	0
63111001	M413	0
63111005	M402	0
63111006	M185X	0
63111006	M185X	0
63111007	M402	0
63111008	M410	0
63111009	M409	0
63111016	M410	0
63111017	M409	0
63111018	M410	
63111027	PM310	0
63111033	PM311	0
63111036	M410	0
63111037	M410	0
63112003	PM312	0
63113001	PM687	
63113002	M384	0
63113003	PM241	0
63114008	M411	0
63114010	M411	0
63114014		
63114014	M400	0
63187051	PM244	
63191001	PM313	0
63191007	PM314	0
63192000	PM301	0
63193001	PM315	0
63194012	PM316	0
63200703	M033	0
63201000	M039	$\frac{12}{0,5}$
63201001	M039	$\frac{12}{0,5}$
63201004	M039	$\frac{12}{0,5}$
63201005	M039	$\frac{12}{0,5}$
63201100	M039	$\frac{12}{0,5}$
63201101	M039	$\frac{12}{0,5}$
63206002		0
63211001	PM313	0

MARELLI RMA $\frac{V}{Kw -!}$

63213815	M091	$\frac{12}{3,5}$
63213853	M091	0
63213855	M091	
63214308	PM142	0
63214308	PM142	
63214308	PM142	
63214333	PM142	0
63214371	PM142	
63214376	PM317	0
63216701	PM138	
63216701	PM138	0
63216702	PM142	
63216702	PM142	0
63216703	PM146	0
63216703	PM146	0
63216704	PM138	0
63216706	PM318	0
63216725	PM138	0
63216726	PM138	0
63216727	PM138	0
63216731	PM138	0
63216733	PM142	0
63216738	PM318	0
63216740	PM146	0
63216740	PM146	0
63216741	PM146	0
63216741	PM146	0
63216747	PM138	0
63216748	PM138	0
63216763	PM318	0
63216800	M091	$\frac{12}{3,5}$
63216802	PM319	0
63216808	M028	
63216808	M028	$\frac{12}{2,0}$
63216814	PM119	0
63216815	PM247	0
63216816	PM159	
63216818	PM122	0
63216825	M091	
63216825	M091	$\frac{12}{3,5}$
63216826	M091	
63216826	M091	$\frac{12}{3,5}$
63216827	M091	$\frac{12}{3,5}$
63216831	M091	$\frac{12}{3,5}$

MARELLI	RMA $V_{Kw} -!$	MARELLI	RMA $V_{Kw} -!$	MARELLI	RMA $V_{Kw} -!$
63216833	PM319 0/	63217225	PM155 0/	63220735	12/ 0,8
63216851	PM247 0/	63217226	PM155 0/	63220736	M097 12/ 0,8
63216852	PM321 0/	63217226	PM155 0/	63220741	M032 12/ 0,8
63216859	PM322 0/	63217402	PM116 0/	63220743	M033 /
63216873	PM135 0/	63217410	M027X 12/ 2,5	63220743	M033 12/ 0,8
63216874	M091 0/	63217410	M027X 12/ 2,5	63220743	M033 12/ 0,8
63216876	PM119 0/	63217433	PM116 0/	63220744	M035 12/ 0,8
63216884	PM119 0/	63220107	12/ 0,5	63220746	M097 12/ 0,8
63216896	M246 /	63220137	12/ 0,5	63220800	/
63216896	PM135 0/	63220400	0/	63220806	12/ 0,6
63216898	PM135 0/	63220402	0/	63220834	M097 0/
63217101	PM150 /	63220408	0/	63220901	M166 12/ 0,8
63217101	PM150 0/	63220409	12/ 0,6	63220902	0/
63217104	M027 /	63220409	0/	63220902	12/ 0,6
63217104	M027 /	63220432	0/	63220931	M166 12/ 0,8
63217104	M027 12/ 2,5	63220439	12/ 0,6	63220932	0/
63217104	M027 12/ 2,5	63220439	0/	63221005	M039 0/
63217105	M028 /	63220502	M067 0/	63221103	M097 0/
63217105	M028 12/ 2,0	63220505	M067 12/ 0,6	63221300	M018 12/ 0,8 15a
63217106	PM117 0/	63220506	M110 12/ 0,7	63221302	M013 12/ 0,7
63217110	PM116 0/	63220507	M033 12/ 0,8	63221303	M012 12/ 0,7
63217116	M028 12/ 2,0	63220508	M035 12/ 0,8	63221304	M016 12/ 0,8 15a
63217118	M028 /	63220535	M067 12/ 0,6	63221304	M016 12/ 0,8 15a
63217118	M028 12/ 2,0	63220535	M067 12/ 0,6	63221305	M107 12/ 0,8 15a
63217121	PM323 0/	63220536	M110 12/ 0,7	63221305	M107 12/ 0,8 15a
63217125	PM150 /	63220537	M033X 12/ 0,8	63221306	M107 12/ 0,8 15a
63217125	PM150 0/	63220537	M033X 12/ 0,8	63221306	M107 12/ 0,8 15a
63217126	PM150 0/	63220538	M035 12/ 0,8	63221307	M107 12/ 0,8 15a
63217138	PM117 0/	63220700	0/	63221307	M107 12/ 0,8 15a
63217138	M044 0/	63220701	M032 12/ 0,8	63221308	M044 12/ 1,0
63217147	M027 12/ 2,5	63220703	M033 12/ 0,8	63221330	M018 12/ 0,8 15a
63217147	M027 12/ 2,5	63220703	M033 12/ 0,8	63221332	M013 12/ 0,7
63217148	M027 12/ 2,5	63220704	M035 12/ 0,8	63221333	M012 12/ 0,7
63217148	M027 12/ 2,5	63220705	12/ 0,8	63221334	M016 12/ 0,8 15a
63217154	M028 12/ 2,0	63220706	M097 12/ 0,8	63221334	M016 12/ 0,8 15a
63217156	PM111 0/	63220713	M033 12/ 0,8	63221335	M107 0/
63217158	M355 12/ 2,5	63220721	M032 12/ 0,8	63221335	M034 0/
63217163	PM117 0/	63220723	M033 12/ 0,8	63221338	M044 12/ 1,0
63217173	PM116 0/	63220723	M033 12/ 0,8	63221400	/
63217180	0/	63220724	M035 12/ 0,8	63221400	M011 12/ 0,9
63217201	PM155 /	63220726	M097 12/ 0,8	63221400	M011 12/ 0,9
63217201	PM155 0/	63220731	M032 12/ 0,8	63221401	/
63217201	PM155 0/	63220733	M033 12/ 0,8	63221401	M131 /
63217225	PM155 0/	63220734	M035 12/ 0,8	63221401	M023 12/ 0,8

MARELLI RMA $\frac{V}{Kw - !}$

63221403	M011	12 / 0,9	
63221404	M044	12 / 1,0	
63221405	M379	12 / 1,1	
63221406		12 / 1,1	
63221407	M016	0 /	
63221407	M016	0 /	
63221408	M025	12 / 1,0	
63221430	M011	12 / 0,9	
63221431	M023	12 / 0,8	
63221433	M011	0 /	
63221434	M044	0 /	
63221434	M044	0 /	
63221435	M379	12 / 1,1	
63221437	M016	12 / 0,8	15a
63221437	M016	12 / 0,8	15a
63221500	M061	12 / 1,1	
63221502	M301	12 / 1,1	
63221503	M113	/	
63221503	M113	12 / 1,1	
63221504	M100	12 / 0,8	
63221505	M034	12 / 0,8	
63221506		0 /	
63221508	M046	12 / 0,9	
63221509	M046	12 / 0,9	
63221530	M061	12 / 1,1	
63221532	M301	12 / 1,1	
63221533	M113	12 / 1,1	
63221533	M113	12 / 1,1	
63221534	M100	12 / 0,8	
63221535	M034	12 / 0,8	
63221536		0 /	
63221538	M046	12 / 0,9	
63221539	M046	12 / 0,9	
63221600		/	
63221600	M281	12 / 1,1	
63221601		/	
63221607	M131	12 / 0,8	
63221630	M281	12 / 1,1	
63221631	M046	12 / 0,9	
63221632	M011	12 / 0,9	
63221637	M131	12 / 0,8	
63221639	M046	12 / 0,9	
63221731	M046	12 / 0,9	
63221800	M056	12 / 0,9	

MARELLI RMA $\frac{V}{Kw - !}$

63221801	M045	12 / 2,2	
63221830	M056	12 / 0,9	
63221831	M045	12 / 2,2	
63221832	M055	12 / 1,0	
63221834	M265	/	
63221834	M265	12 / 0,8	
63221890	M056	/	
63221890	M056	12 / 0,9	
63221892	M055	12 / 1,0	
63222000	M048	12 / 2,2	
63222001	M053	12 / 2,2	
63222005	PM236	12 / 2,2	
63222030	M048	12 / 2,2	
63222031	M053	12 / 2,2	
63222033	M053	12 / 2,2	
63222034	M228	12 / 2,2	
63222035	M037	12 / 2,2	30h
63222035	M037	12 / 2,2	30h
63222036	M045	12 / 2,2	
63222038	M048X	12 / 2,2	
63222038	M048X	12 / 2,2	
63222039	M053	12 / 2,2	
63222085	M037	12 / 2,2	30h
63222085	M037	12 / 2,2	30h
63222130	M048	12 / 2,2	
63222131	M316	12 / 2,2	
63222133	M045	12 / 2,2	
63222134	M048X	12 / 2,2	
63222134	M048X	12 / 2,2	
63222135	M048X	12 / 2,2	
63222136	M053	12 / 2,2	
63222138	M228	12 / 2,2	
63222203	M316	12 / 2,2	
63222204	M404	12 / 2,2	
63222206	M316	12 / 2,2	
63222206010	M316	/	
63222230	M045	0 /	
63222301		0 /	
63222400	M047	/	
63222400	M047	12 / 1,3	
63222401		0 /	
63222405	M114	12 / 0,8	
63222406		0 /	
63222408	M114	12 / 0,8	

MARELLI RMA $\frac{V}{Kw - !}$

63222408	M114	12 / 0,8	
63222409	M047	/	
63222409	M047	12 / 1,3	
63222430	M047	/	
63222430	M048X	12 / 1,3	
63222431		0 /	
63222435	M114	12 / 0,8	
63222436	M114	12 / 0,8	
63222438	M114	/	
63222438	M114	12 / 0,8	
63222438	M114	12 / 0,8	
63222439	M048X	12 / 1,3	
63222439	M047	0 /	
63222501	M044	12 / 1,0	
63222502	M047	/	
63222502	M048X	12 / 1,3	
63222506	M114	0 /	
63222531	M044	0 /	
63222532	M047	/	
63222532	M047	12 / 1,3	
63222536		0 /	
63222700		0 /	
63222703	M406	0 /	
63222730		0 /	
63222806	M270	12 / 0,8	
63222831	M131	12 / 0,8	
63222833	M131	12 / 0,8	
63222834	M271	12 / 1,0	
63222835	M271	12 / 1,0	
63222836	M270	12 / 0,8	
63222837	M270	12 / 0,8	
63222837	M270	12 / 0,8	
63222888	M265	12 / 0,8	
63222889	M268	12 / 0,8	
63222897	M270	/	
63222897	M270	12 / 0,8	
63222900	M269	12 / 0,9	
63222901	M409	0 /	
63222904	M405	0 /	
63222905	M270	12 / 0,8	
63222908	M270	12 / 0,8	
63222909	PM324	0 /	
63222936	M268	0 /	
63223001	M131	12 / 0,8	

MARELLI	RMA \sqrt{Kw} -!	MARELLI	RMA \sqrt{Kw} -!	MARELLI	RMA \sqrt{Kw} -!
63223031	M131 $\frac{12}{0,8}$	63223434	M116 $\frac{12}{1,4}$ 15a	63226839	M243 $\frac{0}{0}$
63223031	M131 $\frac{12}{0,8}$	63223435	M185 $\frac{12}{1,4}$ 30h	63226842	M318 $\frac{12}{1,4}$ 15a
63223033	M283 $\frac{0}{0}$	63223436	M219 $\frac{12}{1,4}$	63226845	PM688 $\frac{12}{1,4}$
63223033	M131 $\frac{12}{0,8}$	63223436	M219 $\frac{12}{1,4}$	63226849	PM328 $\frac{0}{0}$
63223034	M271 $\frac{12}{1,0}$	63223436	M219 $\frac{0}{0}$	63226908	M436 $\frac{0}{0}$
63223035	M131 $\frac{12}{0,8}$	63223438	PM026 $\frac{0}{0}$	63226909	$\frac{0}{0}$
63223039	M255 $\frac{0}{0}$	63223494	M116 $\frac{12}{1,4}$ 15a	63226912	$\frac{0}{0}$
63223085	M362 $\frac{12}{0,9}$	63223530	M219 $\frac{12}{1,4}$	63226920	$\frac{0}{0}$
63223091	M283 $\frac{0}{0}$	63223531	M219 $\frac{12}{1,4}$	63226923	$\frac{0}{0}$
63223101	M283 $\frac{12}{0,9}$	63223532	M057 $\frac{12}{1,4}$	63226927	$\frac{0}{0}$
63223103	M406 $\frac{0}{0}$	63223533	M407 $\frac{0}{0}$	63226937	$\frac{0}{0}$
63223104	M406 $\frac{0}{0}$	63223534	M402X $\frac{0}{0}$	63226939	M244 $\frac{0}{0}$
63223106	PM301 $\frac{0}{0}$	63223535	M382 $\frac{0}{0}$	63226941	M214 $\frac{0}{0}$
63223108	PM227 $\frac{0}{0}$	63223537	M185X $\frac{12}{1,4}$ 30h	63226942	M214 $\frac{12}{1,7}$
63223109	PM324 $\frac{0}{0}$	63223537	M185X $\frac{12}{1,4}$ 30h	63226945	M058X $\frac{12}{1,8}$
63223182	M223 $\frac{0}{0}$	63223538	M403 $\frac{0}{0}$	63226946	PM330 $\frac{0}{0}$
63223200	M268 $\frac{12}{0,8}$	63223639	M402X $\frac{0}{0}$	63226948	$\frac{0}{0}$
63223203	M026 $\frac{12}{1,6}$	63223730	M402 $\frac{0}{0}$	63226948	$\frac{0}{0}$
63223206	M026 $\frac{0}{0}$	63224000	$\frac{0}{0}$	63226949	M244 $\frac{0}{0}$
63223207	M026 $\frac{0}{0}$	63224009	$\frac{0}{0}$	63226950	PM331 $\frac{0}{0}$
63223209	PM325 $\frac{0}{0}$	63224170	PM138 $\frac{0}{0}$	63227004	M235X $\frac{12}{1,4}$
63223233	M026 $\frac{12}{1,6}$	63224170	PM138 $\frac{0}{0}$	63227005	M134 $\frac{0}{0}$
63223236	M026 $\frac{12}{1,6}$	63224580	PM138 $\frac{0}{0}$	63227005	M134 $\frac{0}{0}$
63223237	M026 $\frac{12}{1,6}$	63224580	PM138 $\frac{0}{0}$	63227006	M134 $\frac{0}{0}$
63223239	PM325 $\frac{0}{0}$	63224600	PM150 $\frac{0}{0}$	63227007	PM332 $\frac{0}{0}$
63223300	M026 $\frac{12}{1,6}$	63224600	PM150 $\frac{0}{0}$	63227008	M136 $\frac{0}{0}$
63223303	M362 $\frac{12}{0,9}$	63226301	$\frac{0}{0}$	63227009	$\frac{0}{0}$
63223303	M283 $\frac{12}{0,9}$	63226391	$\frac{0}{0}$	63227012	$\frac{0}{0}$
63223330	M026 $\frac{12}{1,6}$	63226609	PM325 $\frac{0}{0}$	63227014	M137 $\frac{12}{0,8}$
63223332	M026 $\frac{12}{1,6}$	63226629	$\frac{0}{0}$	63227016	$\frac{0}{0}$
63223401	M219 $\frac{12}{1,4}$	63226631	$\frac{0}{0}$	63227017	M217 $\frac{0}{0}$
63223401	M219 $\frac{0}{0}$	63226645	PM326 $\frac{0}{0}$	63227018	$\frac{0}{0}$
63223402	M057 $\frac{12}{1,4}$	63226664	$\frac{0}{0}$	63227024	M308 $\frac{0}{0}$
63223402	M057 $\frac{12}{1,4}$	63226680	$\frac{0}{0}$	63227026	M300 $\frac{12}{0,8}$
63223403	M175 $\frac{12}{1,4}$ 30h	63226686	$\frac{0}{0}$	63227029	$\frac{0}{0}$
63223404	M116 $\frac{12}{1,4}$ 15a	63226689	M261 $\frac{0}{0}$	63227034	M406 $\frac{0}{0}$
63223405	M185 $\frac{12}{1,4}$ 30h	63226715	PM327 $\frac{0}{0}$	63227035	M406 $\frac{0}{0}$
63223408	PM026 $\frac{0}{0}$	63226722	M223 $\frac{12}{0,9}$	63227037	M223 $\frac{12}{1,0}$
63223430	M113X $\frac{12}{1,4}$	63226800	PM029 $\frac{0}{0}$	63227041	$\frac{0}{0}$
63223431	M219 $\frac{12}{1,4}$	63226801	M305 $\frac{12}{1,4}$	63227043	M338 $\frac{12}{1,0}$
63223431	M219 $\frac{12}{1,4}$	63226803	$\frac{0}{0}$	63227044	M223 $\frac{0}{0}$
63223432	M057 $\frac{12}{1,4}$	63226836	M311 $\frac{12}{1,4}$	63227045	M223 $\frac{0}{0}$
63223432	M057 $\frac{12}{1,4}$	63226837	M312 $\frac{12}{1,4}$	63227049	PM025 $\frac{0}{0}$
63223433	M175 $\frac{12}{1,4}$ 30h	63226838	M243 $\frac{12}{1,4}$	63227051	M338 $\frac{12}{1,0}$

MARELLI	RMA $V_{Kw} -!$	MARELLI	RMA $V_{Kw} -!$	MARELLI	RMA $V_{Kw} -!$
63227052	0	63227593	PM224 0	7658554	M048X
63227058	0	63227594	0	7674733	M053
63227061	0	63227596	PM689	77028560	M027
63227413	PM688 0	63227598	PM691 0	77040560	
63227415	PM333 0	63227599	PM691 0	77040561	PM138
63227416	12 2,1	63227601	0	77050262	PM146
63227433	PM334 0	63227602	0	77050561	PM155
63227460	M277 0	63227603	0	77050562	PM146
63227468	PM335 0	63227604	0	77065560	PM142
63227470	PM147 12 2,0	63227606	0	7706908	M045
63227478	PM689	63227609	0	77080560	PM155
63227480	PM224	63230001	M406 0	77080560	PM138
63227484	0	63230003	M406 0	77080561	PM155
63227485	0	63251871	0	77097430	PM142
63227486	PM689 12 2,4	63252291	0	77130560	PM142
63227487	PM333 0	63253010	M136 12 0,9 15a	77138430	
63227488	PM224 0	63253020	M214 12 1,7	77138430	M047
63227489	PM690 0	63253050	M059 12 2,5	7716766	M058
63227490	0	63253403	M175 12 1,4 30h	77167660	M058
63227491	0	63280001	M235X 0	77194430	M047
63227501	M059 12 2,5	63280002	PM027 0	77211430	
63227502	0	63280005	0	77211430	M047
63227508	PM115	63280010	PM264 0	7727486	M053
63227512	PM162 0	63291405	M202 0	7727487	M053
63227512	PM162 0	63292005	0	7727534	
63227520	PM689	63293039	M255	77305430	M056
63227528	PM688 0	63293039	M255 0	7731823	M048X
63227533	0	63293104	M406 0	7740560	PM138
63227541	PM691	63293104	M406 0	77414430	PM138
63227543	0	63293537	M185X 12 1,4 30h	77414431	PM138
63227553	PM263 0	63293538	M403 0	77444430	PM138
63227554	PM130 0	63296357	PM689	77444530	
63227564	0	66925072		77445430	PM138
63227565	PM691	66925087		77515430	M028
63227568	PM691 0	66925191	PM692	8122161	PM193
63227569	M294 0	66925238		8662534	PM142
63227576	0	673251139		88205006	M091
63227585	PM689	7541569	M057	88205018	
63227586	PM129 0	7580192	M058	8862534	PM142
63227587	0	7587118	M026	8961386	PM142
63227588	PM689	75891510	M228	8962534	PM142
63227590	PM691	7597118	M026	9151139080	
63227591	0	7613744	M045	932223730	M382
63227592	0	7621040		943102003	M405 0

MARELLI	RMA $V_{Kw} -!$	MARELLI	RMA $V_{Kw} -!$	MARELLI	RMA $V_{Kw} -!$
943102008	M384 0	943221335	M107 0	943223101	
943110000		943221431	M283 0	943223233	M026 0
943111005	M402	943221431	M023 0	943223236	M058 0
943112431		943221433		943223332	M058 0
943114008	M411	943221434	M044 12 1,0	943223430	M113 0
943114010	M411	943221530	M061 0	943223433	M175 12 1,4 30h
943141075	0	943221533	M113	943223435	M185
943192000	PM301	943221533	M113 0	943223435	M185 0
943201005	M039 0	943221534	M100 12 0,8	943223436	0
943201059	M121X 0	943221535	M107 12 0,8 15a	943223438	PM026 0
943201113	0	943221535	M034 12 0,8 15a	943223530	0
943213853	M091 0	943221538	M011 0	943223532	M046 0
943214376	0	943221539	M046 0	943223639	
943216731	PM138 0	943221630	M281 12 1,1	943223730	M382 0
943216818	PM122 0	943221801	M045 12 2,2	9432252075	PM689
943216831	M091 0	943221831	M045 12 2,2	943226366	PM689
943216876		943221832	M055 12 1,0	943226391	0
943217147	M027 0	943221890	M056 0	943226624	
943217147	M027 0	943222000	M048 12 2,2	943226628	M222
943217154	M028 0	943222030	M048 0	943226629	0
943217163		943222031	M053 0	943226645	PM326 0
943217226	PM155 0	943222034	M228 0	943226719	0
943217433	PM116 0	943222035	M037 12 2,2 30h	943226721	0
943220439	0	943222035	M037 12 2,2 30h	943226838	M243 0
943220439	0	943222035	M037 12 2,2 30h	943226839	0
943220439	0	943222036		943226904	0
943220526	M289 12 1,8	943222038	M048X 0	943226932	0
943220535	M067 12 0,6	943222039	M053 0	943226937	M436 0
943220536	M110 0	943222130	M048 0	943227005	M138 0
943220537	M033 0	943222203	M316 0	943227006	M137 0
943220537	M033 0	943222204		943227007	PM332 0
943220538	M035 0	943222438	M114 0	943227008	M137 0
943220723	0	943222438	M114 0	943227010	0
943220735	12 0,8	943222439	0	943227011	0
943220741	M032 0	943222536	0	943227012	0
943220746	M097 12 0,8	943222836	M270 0	943227014	
943220931	M166 0	943222837	M270 12 0,8	943227015	0
943220932	0	943222889	M268 0	943227016	0
943221072	M078	943222905	0	943227017	0
943221332	M013 0	943222909		943227024	M300 0
943221333	M012 0	943223031	M283 0	943227026	M300 0
943221334	M016 12 0,8 15a	943223031	M283 0	943227034	0
943221334	M016 12 0,8 15a	943223033	M283 0	943227048	0
943221335	M107 0	943223034	M271 0	943227050	0

MARELLI	RMA $\frac{V}{Kw -!}$	MARELLI	RMA $\frac{V}{Kw -!}$	MARELLI	RMA $\frac{V}{Kw -!}$
943227052	0/	943241049	PM498 0/	943241148	PM216 0/
943227446	/	943241050	PM469 0/	943241158	0/
943227559	0/	943241051	PM015 0/	943241161	0/
943227567	0/	943241054	M335 0/	943241163	PM094 0/
943227568	0/	943241055	0/	943241166	PM268 0/
943227573	0/	943241056	0/	943241167	0/
943227574	0/	943241058	0/	943241170	0/
943227584	PM224 0/	943241060	M262 0/	943251005	M039 0/
943227610	0/	943241061	PM053 0/	943251007	M158 $\frac{12}{0,8}$
943230001	M406 0/	943241062	0/	943251008	M038 $\frac{12}{1,0}$
943241000	PM026 0/	943241063	0/	943251014	M049 $\frac{12}{1,1}$
943241001	M128 0/	943241064	0/	943251014	M049 $\frac{12}{1,1}$
943241003	0/	943241067	0/	943251015	M159 $\frac{12}{0,7}$ 15a
943241005	PM296 0/	943241070	0/	943251015	M159 $\frac{12}{0,7}$ 15a
943241007	0/	943241071	0/	943251048	M094 $\frac{12}{0,6}$
943241008	M151 0/	943241073	0/	943251050	M077 $\frac{12}{0,6}$
943241008	M151 0/	943241074	0/	943251050	M077 $\frac{12}{0,6}$
943241009	M392 0/	943241077	0/	943251052	PM908 $\frac{12}{0,6}$
943241012	0/	943241080	0/	943251052	M192 $\frac{12}{0,6}$
943241013	0/	943241081	0/	943251054	M119 $\frac{12}{1,0}$
943241015	0/	943241083	M128 0/	943251054	M119X $\frac{12}{1,0}$
943241016	0/	943241086	PM404 0/	943251055	M075X $\frac{12}{0,8}$
943241019	/	943241088	M304 0/	943251055	M075X $\frac{12}{0,8}$
943241020	0/	943241092	0/	943251056	M084X $\frac{12}{0,9}$
943241023	0/	943241094	PM356 0/	943251056	M084X $\frac{12}{0,9}$
943241024	0/	943241096	0/	943251057	M021 $\frac{12}{1,0}$
943241025	0/	943241099	0/	943251058	M124X
943241026	0/	943241100	M129 0/	943251058	M124X $\frac{12}{1,0}$
943241027	0/	943241102	0/	943251059	M121X $\frac{12}{2,9}$
943241028	0/	943241104	0/	943251059	M121X $\frac{12}{2,9}$
943241031	M380 0/	943241107	M423 0/	943251060	M096 $\frac{12}{0,8}$
943241033	M381 0/	943241114	0/	943251060	M096 $\frac{12}{0,8}$
943241035	M099 0/	943241119	PM215 0/	943251061	M093 $\frac{12}{1,0}$
943241036	0/	943241124	M426 0/	943251062	M067 0/
943241037	M442 0/	943241125	0/	943251062	M067 0/
943241038	M437 0/	943241127	M427X 0/	943251063	M118 0/
943241039	0/	943241128	0/	943251064	M280 $\frac{12}{1,1}$
943241040	M334 $\frac{12}{0,6}$	943241132	0/	943251065	M010 0/
943241042	0/	943241133	M143 0/	943251065	M010 0/
943241043	0/	943241136	M313 0/	943251066	/
943241044	0/	943241137	0/	943251067	M010 0/
943241046	0/	943241141	PM265 0/	943251067	M010 0/
943241047	PM455 0/	943241142	M344 0/	943251068	M119X $\frac{12}{1,0}$
943241048	M325 0/	943241143	M320 0/	943251070	$\frac{12}{0,7}$

MARELLI	RMA $V_{Kw} -!$	MARELLI	RMA $V_{Kw} -!$	MARELLI	RMA $V_{Kw} -!$
943251072	M078 $12/0,7$	943251225	M256 $12/1,8$	943251403	M010 $12/0,8$
943251072	M078 $12/0,7$	943251226	M394 $0/$	943251405	M124X $12/1,0$
943251074	M118 $12/0,8$	943251227	$0/$	943251408	M197 $12/1,5$
943251075	M079 $12/2,0$	943251228	M396 $0/$	943251408	M197 $12/1,5$
943251079	M161 $12/2,2$	943251266	M200 $12/1,4$	943251409	M119X $12/1,0$
943251080	M117 $12/1,1$	943251268	M200 $0/$	943251410	M108 $12/0,8$ 15a
943251085	M101 $12/1,5$	943251269	$0/$	943251410	M108 $12/0,8$ 15a
943251099	M157 $12/2,2$	943251272	M155 $0/$	943251412	$12/0,7$
943251099	M157 $12/2,2$	943251273	M013X $0/$	943251413	M043 $12/1,0$
943251101	M156 $12/2,0$	943251274	M062 $0/$	943251413	M043 $12/1,0$
943251103	PM894 $12/2,5$	943251275	M058 $0/$	943251414	M109 $12/1,1$ 15a
943251107	M017 $12/0,8$	943251277	$0/$	943251415	M066 $12/2,2$
943251107	M017X $12/0,8$	943251287	$0/$	943251415	M258 $12/2,2$
943251109	M102 $12/0,8$	943251288	$0/$	943251416	M069X $12/1,4$
943251110	M075X $12/0,8$	943251296	M039 $0/$	943251416	M069X $12/1,4$
943251111	M104 $12/0,9$	943251300	M246 $12/2,2$	943251417	M112 $12/0,9$ 15a
943251112	M029 $12/1,0$	943251301	PM555 $0/$	943251418	M115 $12/1,0$ 15a
943251113	M120 $12/1,9$	943251302	M247 $12/2,2$	943251419	M299X $12/1,7$ 30h
943251113	M120X $12/1,9$	943251305	M120X $12/1,9$	943251419	M299 $12/1,7$ 30h
943251114	M119X $12/0,9$	943251307	M121X $12/2,9$	943251420	M375 $12/1,4$ 30h
943251114	M192 $12/0,9$	943251314	$0/$	943251421	M276 $12/3,1$
943251115	$12/0,9$	943251316	M305 $12/1,4$	943251422	M195 $12/1,4$
943251116	M297 $12/2,5$	943251317	M244 $0/$	943251423	M102 $0/$
943251117	M137 $12/0,6$	943251320	M275 $12/3,1$	943251423	M102 $0/$
943251117	M081 $12/0,6$	943251322	M306 $0/$	943251424	M062X $12/1,4$
943251121	M010 $0/$	943251323	M069 $0/$	943251426	M240 $12/1,4$
943251122	M254 $12/2,0$	943251324	PM048 $0/$	943251427	$12/0,7$
943251124	$12/1,2$	943251325	M099X $0/$	943251428	M295 $12/2,8$
943251125	M124X $12/1,0$	943251326	M248 $0/$	943251429	M022 $12/0,9$
943251127	M103 $0/$	943251327	M236 $0/$	943251430	M250 $12/1,7$
943251127	M103 $12/1,7$	943251328	M034 $0/$	943251430	M250 $12/1,7$
943251136	M176 $12/1,0$	943251329	M105 $0/$	943251431	$0/$
943251136	M222 $12/1,0$	943251330	M282 $0/$	943251433	M238 $12/1,4$
943251138	M088X $0/$	943251333	M227 $0/$	943251434	M191 $12/1,0$
943251138	M088X $0/$	943251334	M314 $0/$	943251435	M191 $12/1,0$
943251139	M099 $12/1,4$	943251335	M217 $0/$	943251436	M251 $12/0,9$
943251143	$0/$	943251336	M125 $12/2,2$	943251437	PM050 $0/$
943251144	M105 $12/1,7$	943251337	M307 $0/$	943251438	M015 $12/1,7$
943251144	M105 $12/1,7$	943251338	PM089 $0/$	943251438	M015 $12/1,7$
943251165	$12/0,7$	943251340	M255 $0/$	943251439	M143 $12/0,9$
943251220	M152 $12/0,8$ 15a	943251344	$12/2,8$	943251440	M433 $0/$
943251221	M059 $12/2,5$	943251401	$12/2,8$	943251441	M278 $12/3,1$
943251223	M172 $12/1,1$	943251402	M157 $12/2,2$		
943251223	M172 $12/1,1$	943251403	M010 $12/2,2$		

MARELLI	RMA $V_{Kw} -!$
943251442	M297X $12/2,5$
943251443	M089 $0/$
943251444	M164 $12/1,5$
943251445	$0/$
943251446	M140 $12/1,5$ 15a
943251447	$0/$
943251448	M089 $0/$
943251449	PM088 $0/$
943251450	PM051 $0/$
943251451	PM051 $0/$
943251452	M089 $0/$
943251453	M021 $0/$
943251454	M202 $0/$
943251454	M017X $12/0,9$
943251454	M202 $12/0,9$
943251455	M049 $0/$
943251456	M243 $12/1,4$
943251457	M285 $12/2,2$
943251457	M285 $12/2,2$
943251458	M260 $12/1,4$
943251459	M261 $12/1,4$
943251459	M261 $12/1,4$
943251460	M190 $12/1,0$
943251461	PM021 $0/$
943251462	M190 $12/1,0$
943251463	M105 $0/$
943251464	PM020 $0/$
943251465	$0/$
943251466	M102X $12/1,1$
943251467	PM024 $0/$
943251471	M201 $12/1,4$
943251472	M338 $0/$
943251472	M338 $0/$
943251485	M299 $12/1,5$
943251486	$12/0,8$
943251487	M284 $0/$
943251488	M102X $0/$
943251489	M017X $12/1,2$
943251501	M066X $12/2,2$
943251502	$0/$
943251534	M025 $12/1,0$
943251549	$12/1,1$
943251568	PM223 $0/$
943251569	PM170 $0/$

MARELLI	RMA $V_{Kw} -!$
943251571	M383 $0/$
943251572	M310 $12/1,8$
943251573	M235 $12/1,4$
943251574	$0/$
943251576	M143 $0/$
943251606	M076 $12/0,8$
943251606	M076 $12/0,8$
943251607	M096 $12/1,0$ 15a
943251607	M096 $12/1,0$ 15a
943251609	M073 $12/1,1$
943251610	M180 $0/$
943251610	M180 $0/$
943251613	M095 $12/0,7$
943251617	M109 $12/1,1$ 15a
943251619	M024 $12/0,8$
943251619	M024 $12/0,8$
943251623	M041 $12/1,1$
943251623	M041 $12/1,1$
943251624	M106 $12/0,8$ 15a
943251624	M106 $12/0,8$ 15a
943251625	M158 $12/0,8$
943251626	M051 $12/1,5$
943251626	M051 $12/1,5$
943251627	$0/$
943251628	$12/0,8$ 15a
943251632	M136 $12/0,9$ 15a
943251632	M136 $12/0,9$ 15a
943251633	M031 $12/0,7$
943251634	M065 $12/2,0$
943251635	M064 $12/2,0$
943251636	M153 $12/2,0$
943251637	M072 $12/1,5$
943251640	M051 $12/1,7$
943251640	M051 $12/1,7$
943251641	PM025 $0/$
943251644	M180 $12/0,8$
943251644	M180 $12/0,8$
943251646	M149 $12/0,8$
943251646	M145 $12/0,8$
943251648	M109 $12/1,1$ 15a
943251648	M109 $12/1,1$ 15a
943251649	M063 $0/$
943251650	M087 $12/1,5$
943251651	M165 $12/1,5$

MARELLI	RMA $V_{Kw} -!$
943251652	M063 $12/1,5$
943251652	M063 $12/1,5$
943251655	M014 $12/1,7$
943251656	M264 $12/1,7$
943251658	M030 $12/0,7$
943251658	M030 $12/0,7$
943251659	M052 $12/1,7$
943251659	M052 $12/1,7$
943251660	M068 $12/0,9$
943251661	M296 $12/0,8$
943251663	M150 $12/0,9$ 15a
943251664	M088X $12/2,2$
943251664	M088X $12/2,2$
943251664	M088X $12/2,2$
943251665	$0/$
943251669	M116 $12/1,4$ 15a
943251670	M251 $0/$
943251671	M111 $12/0,8$ 15a
943251671	M111 $12/0,8$ 15a
943251674	M140 $12/1,5$
943251674	M140 $12/1,5$
943251675	M218 $12/1,7$
943251683	M040 $12/2,2$
943251685	M134 $0/$
943251685	M134 $0/$
943251686	M148 $12/0,9$ 15a
943251686	M148 $12/0,9$ 15a
943251687	M037 $12/2,2$ 30h
943251687	M037X $12/2,2$ 30h
943251688	M137 $12/0,8$
943251688	M136 $12/0,8$
943251689	M137 $12/0,9$
943251689	M138 $12/0,9$
943251690	M260 $0/$
943251690	M260 $0/$
943251691	M263 $12/1,4$
943251692	M243 $12/1,4$
943251693	M214 $12/1,7$
943251693	M214 $12/1,7$
943251694	M083X $12/1,4$
943251694	M083 $12/1,4$
943251695	M216 $12/1,7$
943251697	M162 $12/2,2$
943251698	$0/$

MARELLI RMA \sqrt{Kw} -!

943251699	M237	12/1,4
943251700	M066X	0/
943251700	M066X	0/
943251701	M257	12/1,7
943251803	M044	0/
943251815		0/
943251833	M057	12/1,4
943251833	M057	12/1,4
943251856	M058	12/1,7
943251862	RM039	0/
943251870		0/
943251871	M213	12/0,6
943251875		0/
943251876		0/
943251877	M423	0/
943251878		0/
943251881		0/
943251882	M332	0/
943251885	M433	0/
943251887		0/
943251889	PM456	0/
943251890		0/
943251893		0/
943251894		0/
943251895	M330	0/
943251896	M320	0/
943251897		0/
943251898		0/
943251905		0/
943251906		0/
943251908	M128	0/
943251909	M320	0/
943251910		0/
943251911		0/
943251915	M415	0/
943251916	M017E	0/
943251917	M327	0/
943251918		0/
943251919	PM092	0/
943251920	PM094	0/
943251921	M417	0/
943251923	PM028	0/
943251924	M280	0/
943251926	M419	0/

MARELLI RMA \sqrt{Kw} -!

943251945	PM221	0/
943251946	PM184	0/
943251971		0/
943252012	PM184	0/
943252039	PM116	0/
943252045	PM221	0/
943252046	PM184	0/
943252046	PM184	0/
943252063		0/
943252064		0/
943252065	PM173	0/
943252067	M309	12/2,4
943252069		0/
943252070	PM691	0/
943252071	PM122	12/2,4
943252072	PM333	0/
943252073		12/2,1
943252074		0/
943252077		0/
943252077		0/
943252078		0/
943252122	M253	12/2,0
943252129	PM186	0/
943252132	PM181	0/
943252187	PM189	0/
943252188	PM188	0/
943252189	PM193	0/
943252190	PM201	0/
943252191	PM206	0/
943252194		0/
943252197	PM190	0/
943252198	PM192	0/
943252201		0/
943252203	PM195	0/
943252204	PM122	0/
943252205	PM137	0/
943252206	PM128	0/
943252207	PM136	0/
943252208	PM110	0/
943252210	PM204	0/
943252212		0/
943252213	PM143	0/
943252215	PM156	0/
943252216	PM158	0/

MARELLI RMA \sqrt{Kw} -!

943252217	PM148	12/2,4
943252220	PM199	0/
943252221	PM194	0/
943252222		0/
943252223	M089	12/2,0
943252227	PM146	0/
943252228	PM146	0/
943252229	PM155	0/
943252230	PM202	0/
943252231	PM198	0/
943252232	PM133	0/
943252233	PM134	0/
943252234	PM144	0/
943252235		0/
943252236		0/
943252237	PM205	0/
943252238		0/
943252239	PM145	0/
943252240	PM167	0/
943252241		0/
943252242		0/
943252243	PM213	0/
943252244	PM128	0/
943252245		0/
943252247		0/
943252249		0/
943252250	PM204	0/
943252252	PM165	0/
943252253	PM185	0/
943252254	PM210	0/
943252256	PM121	0/
943252257	PM263	0/
943252273	PM120	0/
943252273	PM120	0/
943252274	PM108	0/
943252275	PM118	0/
943252276	PM149	0/
943252277	PM115	0/
943252278	PM139	0/
943252281	PM112	0/
943252282	PM126	0/
943252283	PM132	0/
943252284	PM169	0/
943252290	PM141	0/

MARELLI	RMA $V_{Kw -!}$	MARELLI	RMA $V_{Kw -!}$	MARELLI	RMA $V_{Kw -!}$
943252291	0	943254033	M416 0	MSN104	PM325
943252294	PM127 0	943254040	0	MSN105	M308
943252295	PM121 0	943254043	M120X 0	MSN106	
943252297	PM130 0	943254050	M399 0	MSN111	
943252298	PM125 0	943254065	0	MSN112	
943252299	PM176 0	943254066	PM282 0	MSN118	
943252680	PM123 0	943254070	M416 0	MSN120	M137
943252690	PM217 0	943254075	0	MSN122	PM558 0
943252858	M054 12 2,2	943254076	0	MSN123	PM025 0
943253101	M105X 0	943254077	0	MSN124	
943253102	M317 0	943254078	0	MSN127	M223
943253103	M389 0	943254079	0	MSN128	M406
943253104	0	943254082	M143 0	MSN129	M406
943253105	0	943254083	0	MSN131	M223
943253106	M385 0	943254084	PM482 0	MSN136	PM327
943253107	M315 0	943281886	M037 12 2,2 30h	MSN137	M223
943253108	M289 0	943293104		MSN138	PM029
943253111	M387 0	943552236	0	MSN139	M305
943253112	0	9611705880	PM094	MSN140	
943253113	M319 0	961301578	M102X	MSN141	M318
943253114	0	9613022580	M102X	MSN146	M243 0
943253115	M391 0	96130225800	M102X	MSN147	
943253116	PM072 0	9625382480	PM094	MSN148	M312
943253118	PM042 0	9629473280	M102X	MSN157	M201
943253119	PM071 0	9947830	M105	MSN159	M436
943253256	PM247 0	B7605/12C	M039 0	MSN160	
943254002	0	B7605/12S	M039 0	MSN161	
943254003	0	E10013/12V11	M044	MSN163	
943254004	0	E10013/12V8	M114 0	MSN165	M214 0
943254007	PM015 0	E70R11/12	M116	MSN165	M214 0
943254008	PM491 0	E7605/12SV9	0	MSN166	M244 0
943254015	PM476 0	E8011/12V		MSN175	
943254018	M195 0	E8408/12V1	M032 0	MSN176	
943254020	PM488 0	E8408/12V3	M033 0	MSN177	
943254022	M428X 0	E8408/12V4	M035 0	MSN178	PM333
943254023	0	E8408/12V5	0	MSN179	
943254024	0	E9509/12/V4	M016	MSN180	PM689
943254025	0	E9509/12V/V5	M107	MSN181	
943254026	0	E9509/12V2	M013	MSN182	M277
943254027	0	E9509/12V3	M012	MSN183	PM335
943254028	0	E9511/12	M113	MSN184	PM147
943254029	0	M1253/12	M091	MSN185	
943254030	PM472 0	M125M3Z93/1	M091 0	MSN186	
943254031	M105 0	MSN103	M223	MSN188	

MARELLI RMA $\frac{V}{Kw -!}$

MSN189		
MSN190	PM162	0
MSN191	PM689	
MSN192		
MSN195	PM263	0
MSN196	PM130	0
MSN198		
MSN199		
MSN202	M294	
MSN203		
MSN206	PM115	0
MSN207	M059	0
MSN208	M410	
MSN209	PM312	
MSN213	PM138	0
MSN214	PM142	0
MSN215	PM138	
MSN216	PM318	
MSN219	M091	0
MSN220	PM319	
MSN221	PM247	0
MSN222	PM322	
MSN224	PM135	
MSN226	PM323	
MSN227	PM150	0
MSN229	M027	0
MSN229	M027	0
MSN230	M028	0
MSN232	M355	
MSN233	PM117	
MSN234	PM116	
MSN237	PM155	0
MSN242	M027	0
MSN252	M346	
MSN256		
MSN262	M053	0
MSN263		0
MSN264	M048X	0
MSN265	M048X	
MSN274	M283	0
MSN277	PM325	
MSN290	M033X	0
MSN290	M033	0
MSN290	M033	0

MARELLI RMA $\frac{V}{Kw -!}$

MSN291	M035	0
MSN294	M032	0
MSN296	M166	0
MSN297		
MSN298	M013	0
MSN299	M012	0
MSN3000		
MSN302	M023	0
MSN303	M011	0
MSN306	M301	
MSN314	M055	0
MSN315	M265	0
MSN316	M056	0
MSN317		0
MSN319	M228	0
MSN320	M037	0
MSN320	M037	0
MSN320	M037	0
MSN323	M114	0
MSN330	M113	0
MSN332	M046	0
MSN334	M185	0
MSN334	M185X	0
MSN400	M401	
MSN401	M401	
MSN402	PM302	
MSN403	PM308	
MSN404	PM309	
MSN405	PM311	
MSN410	PM300	
MSN416	M408	
MSN418	PM304	
MSN419	PM306	
MSN504	M235X	0
MSN518	M268	0
MSN520		
MSN521	PM146	0
MSN523		
MSN526		
MSN531		
MSN536		
MSN540	PM224	0
MSN541		
MSN554		

MARELLI RMA $\frac{V}{Kw -!}$

MSN561		
MSN565	PM334	
MSN569		
MSN600		
MSN603	M405	0
MSN604		
MSN610	M384	0
MSN611	M411	
MSN612	PM313	
MSN613	PM301	
MSN614	PM119	0
MSN616	M228	
MSN617	M404	
MSN618	M316	0
MSN620	M270	
MSN621	PM324	
MSN624	PM227	
MSN626	M026	0
MSN627	M219	
MSN628	M219	
MSN629	M407	
MSN631	M382	0
MSN634	M058X	0
MSN635	PM330	
MSN638		
MSN639	M255	0
MSN640	M406	0
MSN641	M406	0
MSN642	M185X	0
MSN643	M403	
MSN650		
MSN653		
MSN697	PM122	
MSN751	PM321	
MSN790	PM328	
MSN791	M406	
MSN797	M408	0
MSN799		
MSN800	PM314	
MSN8001	M235X	
MSN8002	PM027	
MSN8005		
MSN801	M400	
MSN8010	PM264	

MARELLI RMA $\frac{V}{Kw -!}$

MSN802	
MSN806	PM310
MSN807	M402
MSN808	PM315
MSN809	
MSN812	PM331
MSN813	
MSN816	M384
MSN819	M409
MSN820	PM316
MSN821	M410
MSN824	
MSN829	M268
MSN911	M270
MSN923	M401
MSN924	
MSN925	PM307
MSN926	PM305
MSN927	PM306
MSR051	M066X 0
MSR1001	M128
MSR1003	
MSR1005	PM296
MSR1007	
MSR1008	M151
MSR1009	M392
MSR101	M137
MSR1012	PM356
MSR1013	
MSR1015	
MSR1016	
MSR1019	
MSR102	
MSR1020	
MSR1023	
MSR1024	
MSR1025	
MSR1026	
MSR1027	
MSR1028	
MSR1031	M380
MSR1033	M381 0
MSR1035	M099 0
MSR1036	

MARELLI RMA $\frac{V}{Kw -!}$

MSR1037	M442
MSR1038	M437 0
MSR1039	
MSR1040	M334
MSR1042	
MSR1043	
MSR1044	
MSR1046	
MSR1047	PM455
MSR1048	M325
MSR1049	PM498
MSR105	
MSR1050	PM469
MSR1051	PM015
MSR1054	M335
MSR1055	
MSR1056	
MSR1058	
MSR1060	M262 0
MSR1061	PM053
MSR1062	
MSR1063	
MSR1064	
MSR1067	
MSR1070	
MSR1071	
MSR1073	
MSR1074	
MSR1077	
MSR1080	
MSR1083	M128
MSR1086	PM404
MSR1088	M304
MSR1092	
MSR1099	
MSR110	
MSR1100	M129
MSR1102	
MSR1104	
MSR1107	M423
MSR111	PM692
MSR1114	
MSR1119	PM215
MSR1124	M426

MARELLI RMA $\frac{V}{Kw -!}$

MSR1125	
MSR1127	M427X
MSR113	
MSR1136	M313
MSR1137	
MSR1141	PM265
MSR1142	M344
MSR1143	M320
MSR1148	PM216 0
MSR115	
MSR1158	
MSR1166	PM268
MSR1167	
MSR1170	
MSR121	
MSR1211	
MSR1212	
MSR122	
MSR125	
MSR128	
MSR134	
MSR135	
MSR149	
MSR158	
MSR167	M436
MSR179	
MSR194	
MSR197	
MSR199	
MSR200	
MSR2002	
MSR2003	
MSR2004	
MSR2007	PM015
MSR2008	PM491
MSR2015	PM476
MSR2018	M195
MSR2020	PM488
MSR2022	M428X
MSR2023	
MSR2024	
MSR2025	
MSR2026	
MSR2027	

MARELLI RMA $\sqrt{\text{Kw}} -!$

MSR2028	
MSR2029	
MSR2030	PM472
MSR2031	M105
MSR2033	M416
MSR2040	
MSR2043	M120X
MSR2050	M399
MSR2065	
MSR2066	PM282
MSR2075	
MSR2076	
MSR2077	
MSR2078	
MSR2079	
MSR2082	M143
MSR2083	
MSR2084	PM482
MSR212	M091
MSR218	PM122
MSR240	PM122
MSR244	PM116
MSR262	M053
MSR275	M271
MSR279	
MSR284	M039 0/
MSR287	
MSR288	M067 0/
MSR288	M067 0/
MSR289	M110
MSR291	
MSR293	
MSR295	M097
MSR298	
MSR300	M016 0/
MSR300	M016 0/
MSR301	
MSR304	M044
MSR305	M061
MSR308	M100
MSR309	M034
MSR309	M107 0/
MSR312	
MSR314	M314

MARELLI RMA $\sqrt{\text{Kw}} -!$

MSR317	M048
MSR319	
MSR324	
MSR330	M113
MSR330	M113X
MSR333	M175 0/
MSR334	M185
MSR335	PM026 0/
MSR339	M049 0/
MSR339	M049 0/
MSR340	M159 0/
MSR340	M159 0/
MSR341	M094 0/
MSR342	M119X
MSR342	M192 0/
MSR342	M192 0/
MSR343	PM908 0/
MSR344	M119
MSR344	M119X 0/
MSR344	M119X 0/
MSR345	M084 0/
MSR345	M084X 0/
MSR346	M021
MSR347	M124X 0/
MSR348	M121X 0/
MSR349	M096
MSR350	M093 0/
MSR351	M280 0/
MSR354	
MSR355	M078 0/
MSR355	M078 0/
MSR356	M118
MSR357	M079 0/
MSR358	
MSR359	M117
MSR360	M101 0/
MSR361	M157
MSR363	PM894 0/
MSR364	M017 0/
MSR365	M102 0/
MSR366	M075X
MSR367	M104 0/
MSR368	M029 0/
MSR368	M029 0/

MARELLI RMA $\sqrt{\text{Kw}} -!$

MSR369	M120
MSR370	M192
MSR371	M297 0/
MSR372	M082
MSR373	M010 0/
MSR374	M254 0/
MSR375	
MSR376	M124X 0/
MSR377	M105
MSR378	M222 0/
MSR378	M176 0/
MSR379	M099 0/
MSR379	M226
MSR380	
MSR381	
MSR382	
MSR385	M172 0/
MSR385	M172 0/
MSR386	M200 0/
MSR387	
MSR388	PM555 0/
MSR390	M125
MSR392	
MSR393	
MSR394	M197 0/
MSR394	M197 0/
MSR395	M108 0/
MSR395	M108 0/
MSR397	M043 0/
MSR397	M043 0/
MSR399	M258 0/
MSR400	M069X 0/
MSR400	M069X 0/
MSR401	M112 0/
MSR402	M115 0/
MSR403	M299X 0/
MSR404	M375 0/
MSR405	M276 0/
MSR406	M238 0/
MSR407	M102
MSR408	M062X 0/
MSR409	M240 0/
MSR410	
MSR411	

MARELLI RMA $\frac{V}{Kw -!}$

MSR412	M022	0/
MSR413	M250	0/
MSR413	M250	0/
MSR414		0/
MSR415	M238	0/
MSR416	M191	0/
MSR417	M191	0/
MSR418	M251	0/
MSR419	PM050	0/
MSR420	M015	0/
MSR420	M052	0/
MSR421	M143	0/
MSR422		0/
MSR423	M278	0/
MSR424	M297X	0/
MSR425	M089	0/
MSR426	M164	0/
MSR427		/
MSR428	M140	0/
MSR429		/
MSR430		/
MSR431	PM088	0/
MSR432	PM051	/
MSR434	M021	/
MSR435	M202	0/
MSR435	M202	0/
MSR435	M202	0/
MSR436	M049	/
MSR438	M285	0/
MSR438	M285	0/
MSR439	M260	0/
MSR439	M260	0/
MSR440	M261	0/
MSR440	M261	0/
MSR441	M190	0/
MSR442	PM021	0/
MSR443	M190	/
MSR444		/
MSR445		0/
MSR446	M102X	0/
MSR447	PM024	0/
MSR451	M299	0/
MSR452		/
MSR453	M025	/

MARELLI RMA $\frac{V}{Kw -!}$

MSR454		/
MSR455	M082	/
MSR456	M096	/
MSR457	M073	0/
MSR458	M076	0/
MSR458	M076	0/
MSR459	M095	0/
MSR460	M109	/
MSR461	M024	0/
MSR461	M024	0/
MSR462	M041	0/
MSR462	M041	0/
MSR463	M106	0/
MSR463	M106	0/
MSR464		/
MSR465		/
MSR466		0/
MSR467		/
MSR469	M031	/
MSR470	M065	0/
MSR471	M064	0/
MSR472	M254	/
MSR473	M072	0/
MSR474	M051	0/
MSR474	M051	0/
MSR476	M180	/
MSR477	M145	0/
MSR477	M149	0/
MSR478	M109	0/
MSR478	M109	0/
MSR479	M063	/
MSR480	M087	0/
MSR481	M165	0/
MSR482	M063	0/
MSR482	M063	0/
MSR483	M014	0/
MSR484	M214	/
MSR485	M030	0/
MSR485	M030	0/
MSR486	M015	0/
MSR486	M015	0/
MSR487	M148	0/
MSR487	M148	0/
MSR487	M068	/

MARELLI RMA $\frac{V}{Kw -!}$

MSR488	M296	0/
MSR489	M150	0/
MSR490	M088X	0/
MSR490	M088X	0/
MSR491	M116	0/
MSR492	M251	0/
MSR493	M111	0/
MSR493	M111	0/
MSR494	M140	0/
MSR494	M140	0/
MSR495	M218	0/
MSR496	M040	0/
MSR497	M134	/
MSR498	M148	0/
MSR498	M148	0/
MSR499	M136	/
MSR500	M138	0/
MSR500	M137	/
MSR5000	M415	/
MSR5001	M017E	0/
MSR5002	M327	/
MSR5003		/
MSR5004	PM092	0/
MSR5005	PM094	0/
MSR5006	M417	0/
MSR5007	PM028	0/
MSR5008	M280	/
MSR5009	M419	/
MSR501	M260	/
MSR502	M263	0/
MSR503	M243	0/
MSR5038		/
MSR504	M235	/
MSR505	M083	0/
MSR505	M083	0/
MSR5056	PM129	/
MSR5059	M155	/
MSR506	M216	0/
MSR5064	M320	/
MSR5066		/
MSR5068		/
MSR5069		/
MSR507	M162	0/
MSR5071		/

MARELLI RMA $\sqrt{\text{Kw}} -!$

MSR5073	PM146	
MSR5074	PM155	
MSR5075	PM176	
MSR508		0
MSR509	M237	0
MSR510	M066X	0
MSR511	M257	0
MSR512	M057	0
MSR513	M058	0
MSR514	RM039	0
MSR515	M213	
MSR516	M089	0
MSR517	M054	0
MSR521	PM146	
MSR522		
MSR523		
MSR524	PM332	
MSR527	M138	
MSR530		
MSR5301	M105X	
MSR5302	M317	
MSR5303	M389	
MSR5304		
MSR5305		
MSR5306	M385	
MSR5307	M315	
MSR5308	M289	
MSR5311	M387	
MSR5312		
MSR5313	M319	
MSR5314		
MSR5315	M391	
MSR5316	PM072	
MSR5318	PM042	
MSR5319	PM071	
MSR534		
MSR535		
MSR536	M243	
MSR537		
MSR538		
MSR604		
MSR620		
MSR627	M386	
MSR632	PM326	

MARELLI RMA $\sqrt{\text{Kw}} -!$

MSR641	M406	
MSR651	PM317	
MSR654		
MSR655	M075X	0
MSR655	M075X	0
MSR656	M156	0
MSR657		
MSR658	M256	0
MSR659	M394	0
MSR660		0
MSR661		0
MSR662	M246	0
MSR663	M247	0
MSR664	M120X	0
MSR665	M121X	
MSR666	M275	0
MSR667	M215	
MSR668	M119X	
MSR669	M089	0
MSR670	M102X	0
MSR671	M017X	
MSR672	M066X	
MSR673	PM223	0
MSR675	PM171	0
MSR676	M383	0
MSR677	M310	0
MSR679	PM221	
MSR680	PM184	0
MSR681		
MSR682	PM173	
MSR683	PM122	0
MSR684	M253	0
MSR685	PM186	
MSR686	PM181	0
MSR687	PM189	0
MSR688	PM188	0
MSR689	PM193	0
MSR690	PM201	0
MSR691	PM206	0
MSR693	PM190	0
MSR694		
MSR695	PM106	0
MSR696	PM195	
MSR697	PM122	0

MARELLI RMA $\sqrt{\text{Kw}} -!$

MSR698	PM137	0
MSR699	PM128	0
MSR700	PM136	0
MSR701	PM110	0
MSR702	PM204	0
MSR703	PM192	0
MSR704	PM143	
MSR705	PM156	0
MSR706	PM158	0
MSR707	PM148	0
MSR708	PM199	0
MSR709	PM194	0
MSR710		
MSR711	PM207	0
MSR712	PM202	0
MSR713	PM198	0
MSR714	PM133	0
MSR715	PM134	0
MSR716	PM144	0
MSR717	PM106	0
MSR718		
MSR719	PM205	0
MSR720		
MSR721	PM145	0
MSR721	PM145	0
MSR722	PM167	0
MSR724		
MSR725	PM213	0
MSR726	PM128	0
MSR727	PM106	0
MSR729	PM169	0
MSR730	PM165	0
MSR731	PM185	0
MSR732	PM210	0
MSR733	PM121	0
MSR734	PM120	
MSR735	PM108	0
MSR736	PM118	0
MSR737	PM149	0
MSR738	PM139	0
MSR739	PM112	0
MSR740	PM126	0
MSR741	PM132	0
MSR742	PM164	0

MARELLI RMA $\frac{V}{Kw - !}$

MSR743	PM141	0
MSR744		0
MSR745	PM127	0
MSR745	PM127	0
MSR746	PM121	0
MSR747	PM125	0
MSR748	PM217	
MSR766	M396	
MSR781		
MSR786	M157	
MSR790		
MSR807	PM170	
MSR808	PM184	
MSR829		
MSR900	M200	0
MSR901	M013X	
MSR902	M058	0
MSR903	M069	
MSR904	M289	
MSR905	M248	0
MSR906	M236	0
MSR907	M034	
MSR908	M314	0
MSR909	M217	0
MSR910	M307	
MSR911	M255	0
MSR913	M284	0
MSR914	M143	0
MSR915		
MSR916		
MSR922	M332	
MSR925	M433	
MSR927		
MSR929	PM456	
MSR930		
MSR931	M423	
MSR933		
MSR934		
MSR935	M330	
MSR936	M320	
MSR937		
MSR938		
MSR945		
MSR946		

MARELLI RMA $\frac{V}{Kw - !}$

MSR948	M128	
MSR949	M320	
MSR950		
MSR951		
MSR955	M062	
MSR956	M306	0
MSR957	PM048	
MSR958	M282	0
MSR960	M227	0
MSR961	PM089	
MT37C		0
MT38R		
MT38RA		
MT38TB	M091	0
MT43HA	PM142	0
MT43HA	PM142	
MT43PA	PM317	0
MT62BA	M091	0
MT67A	PM138	0
MT67AA	PM138	0
MT67AB	PM138	0
MT67AC	PM138	0
MT67AD	PM138	0
MT67B	PM142	0
MT67BA	PM142	0
MT67C	PM146	0
MT67CA	PM146	0
MT67CB	PM146	0
MT67D	PM138	0
MT67DA	PM138	0
MT67DB	PM138	0
MT67F	PM318	0
MT67FA	PM318	0
MT67FB	PM318	0
MT68A	M091	$\frac{12}{3,5}$
MT68AA	M091	$\frac{12}{3,5}$
MT68AB	M091	$\frac{12}{3,5}$
MT68AC	M091	$\frac{12}{3,5}$
MT68AD	M091	$\frac{12}{3,5}$
MT68B	PM319	0
MT68BA	PM319	0
MT68H	M028	0
MT68L	PM135	
MT68LA	PM135	0

MARELLI RMA $\frac{V}{Kw - !}$

MT68LB	PM135	0
MT68LC	PM135	0
MT68MB	M091	0
MT68P	PM119	0
MT68PA	PM119	0
MT68PB	PM119	0
MT68Q	PM247	0
MT68QA	PM247	0
MT68R	PM159	0
MT68RA	PM159	0
MT68T	PM122	0
MT71A	PM150	0
MT71AA	PM150	0
MT71AB	PM150	0
MT71CB	M355	$\frac{12}{2,5}$
MT71D	M027	$\frac{12}{2,5}$
MT71D	M027	$\frac{12}{2,5}$
MT71DA	M027	$\frac{12}{2,5}$
MT71DA	M027	$\frac{12}{2,5}$
MT71DB	M027	$\frac{12}{2,5}$
MT71DB	M027	$\frac{12}{2,5}$
MT71E	M028	$\frac{12}{2,0}$
MT71F	PM117	0
MT71FB	PM117	0
MT71G	M355	
MT71GB	M355	$\frac{12}{2,5}$
MT71HB		0
MT71L	PM116	0
MT71LA	PM116	0
MT71R	M028	0
MT71RB	M028	0
MT71T	M028	$\frac{12}{2,0}$
MT71TA	M028	$\frac{12}{2,0}$
MT71Z	M091	0
MT72A	PM155	0
MT72AA	PM155	0
MT72AB	PM155	0
MT74B	PM116	0
MT74BA	PM116	0
MT74G	PM148	0
MT74L	M027X	$\frac{12}{2,5}$
MT74L	M027X	

MITSUBA RMA $\frac{V}{Kw -!}$

SM30201	M432	0
SM30202	M432	0
SM30202	PM294	0
SM30203	M432	0
SM30204	PM295	12 1,0
SM30205	M128	0
SM30206	M130	12 1,0
SM30207	M194	12 1,0
SM30207	M194	12 1,0
SM30208	PM294	0
SM30209	M432	0
SM30210	M194	12 1,0
SM30210	M194	12 1,0
SM30211	M130	0
SM30212	M194	12 1,0
SM30212	M194	12 1,0
SM30215	M194	12 1,0
SM30215	M194	12 1,0
SM30216	PM295	12 1,0
SM30218	PM296	0
SM30219	PM336	0
SM30222	PM296	0
SM30224	PM295	12 1,0
SM30225	M194	12 1,0
SM30225	M194	12 1,0
SM30227	PM296	0
SM30228	PM296	0
SM30240	PM295	0
SM30241N	PM296	
SM30246	PM286	12 1,0
SM30248	PM286	12 1,0
SM40201	PM297	0
SM40202	PM295	
SM40203	PM693	0
SM40204	M427	0
SM40204	M427	0
SM40205	M427	0
SM40205	M427	0
SM40205	M427	0
SM40210	PM296	0
SM40211	PM296	0
SM40213	PM694	
SM40215	PM695	
SM40216	PM291	0

MITSUBA RMA $\frac{V}{Kw -!}$

SM40217	M194	0
SM40225		0
SM42209	M194	0
SM42210	RM042	
SM42211	PM696	
SM44210	M194	
SM44225	PM697	
SM44226	PM696	

MITSUBA RMA $\frac{V}{Kw -!}$

MITSUBISHI RMA $\frac{V}{Kw -!}$

	PM745 $\frac{0}{/}$
10SO41ED	PM643 $\frac{/}{/}$
30857255	PM016 $\frac{/}{/}$
AW307758	PM698 $\frac{/}{/}$
AW327819	PM699 $\frac{/}{/}$
AW336121	PM699 $\frac{/}{/}$
AW343141	$\frac{/}{/}$
JM001A74491	PM251 $\frac{/}{/}$
M001T90281	M105 $\frac{/}{/}$
M003T19871	M104 $\frac{/}{/}$
M0A01901	PM376 $\frac{/}{/}$
M0T45071ZT	M391 $\frac{/}{/}$
M0T45071ZT	M391 $\frac{/}{/}$
M0T60081	PM337 $\frac{0}{/}$
M0T60081A	PM337 $\frac{/}{/}$
M0T60181	PM700 $\frac{/}{/}$
M0T60181A	PM700 $\frac{/}{/}$
M0T70281	M338 $\frac{0}{/}$
M0T70285	M338 $\frac{0}{/}$
M0T70381	M429X $\frac{0}{/}$
M0T71681	PM339 $\frac{0}{/}$
M0T73881ZC	PM637 $\frac{/}{/}$
M0T80081	PM340 $\frac{0}{/}$
M0T80082	M105 $\frac{0}{/}$
M0T80281	PM341 $\frac{/}{/}$
M0T80281A	PM341 $\frac{/}{/}$
M0T80281AC	PM341 $\frac{/}{/}$
M0T80281B	PM341 $\frac{/}{/}$
M0T80281ZC	PM341 $\frac{/}{/}$
M0T80285	PM341 $\frac{0}{/}$
M0T80285A	PM341 $\frac{/}{/}$
M0T80381	PM342 $\frac{0}{/}$
M0T80581	PM344 $\frac{/}{/}$
M0T80783	PM701 $\frac{/}{/}$
M0T80784	PM701 $\frac{/}{/}$
M0T80881	PM343 $\frac{0}{/}$
M0T81181	PM702 $\frac{/}{/}$
M0T81281	PM344 $\frac{0}{/}$
M0T81283	PM344 $\frac{0}{/}$
M0T81284	PM344 $\frac{0}{/}$
M0T81381	PM703 $\frac{/}{/}$
M0T81681	M437 $\frac{0}{/}$
M0T81981	PM704 $\frac{/}{/}$
M0T82081	PM243 $\frac{0}{/}$

MITSUBISHI RMA $\frac{V}{Kw -!}$

M0T82281	PM705 $\frac{/}{/}$
M0T83381	PM706 $\frac{/}{/}$
M0T83981	M437 $\frac{/}{/}$
M0T84381	PM404 $\frac{/}{/}$
M0T84781	M446 $\frac{/}{/}$
M0T84881ZC	PM707 $\frac{/}{/}$
M0T85381	PM243 $\frac{/}{/}$
M0T85681	PM345 $\frac{0}{/}$
M0T85881	PM708 $\frac{/}{/}$
M0T85981	PM709 $\frac{/}{/}$
M0T86081	$\frac{/}{/}$
M0T86181	PM710 $\frac{/}{/}$
M0T86481	PM350 $\frac{/}{/}$
M0T86781	M099X $\frac{/}{/}$
M0T91181ZC	PM711 $\frac{/}{/}$
M0T91182ZC	PM711 $\frac{/}{/}$
M0T91581	PM710 $\frac{/}{/}$
M1M71881	PM274 $\frac{0}{/}$
M1M72087	M443 $\frac{0}{/}$
M1M75181	PM358 $\frac{0}{/}$
M1M75381	PM358 $\frac{0}{/}$
M1M90081	PM347 $\frac{0}{/}$
M1Q71281	PM356 $\frac{0}{/}$
M1T11172	PM402 $\frac{/}{/}$
M1T11173	PM402 $\frac{/}{/}$
M1T11174	PM402 $\frac{/}{/}$
M1T50071	M116 $\frac{12}{1,4}$ 15a
M1T50071	M116 $\frac{12}{1,4}$ 15a
M1T50171	M105 $\frac{12}{1,7}$
M1T50171	M105 $\frac{12}{1,7}$
M1T50172	M105 $\frac{12}{1,7}$
M1T50471	PM348 $\frac{0}{/}$
M1T60081	M342 $\frac{0}{/}$
M1T60181	PM349 $\frac{0}{/}$
M1T60185	PM349 $\frac{0}{/}$
M1T60281	M343 $\frac{12}{1,2}$
M1T60285	M343 $\frac{12}{1,2}$
M1T60285A	M343 $\frac{/}{/}$
M1T60286	M343 $\frac{/}{/}$
M1T60313	M343 $\frac{0}{/}$
M1T60381	M342 $\frac{12}{1,2}$
M1T60581	M447 $\frac{0}{/}$
M1T61181	M447 $\frac{0}{/}$
M1T64285	PM712 $\frac{/}{/}$

MITSUBISHI RMA $\frac{V}{Kw -!}$

M1T66081	PM713 $\frac{/}{/}$
M1T68381	PM714 $\frac{/}{/}$
M1T70181	$\frac{0}{/}$
M1T70281	PM350 $\frac{0}{/}$
M1T70283	PM350 $\frac{0}{/}$
M1T70283	PM350 $\frac{/}{/}$
M1T70283ZC	PM350 $\frac{/}{/}$
M1T70381	PM351 $\frac{0}{/}$
M1T70381A	PM351 $\frac{/}{/}$
M1T70387	PM351 $\frac{0}{/}$
M1T70465	PM384 $\frac{0}{/}$
M1T70481	M426 $\frac{0}{/}$
M1T70482	M426 $\frac{0}{/}$
M1T70483	M426 $\frac{0}{/}$
M1T70483ZC	M426 $\frac{/}{/}$
M1T70485	M426 $\frac{0}{/}$
M1T70485A	M426 $\frac{/}{/}$
M1T70781	PM352 $\frac{0}{/}$
M1T70881	PM715 $\frac{/}{/}$
M1T70881A	PM715 $\frac{/}{/}$
M1T70981	PM353 $\frac{0}{/}$
M1T70981A	PM353 $\frac{/}{/}$
M1T70982	PM353 $\frac{0}{/}$
M1T70982A	PM353 $\frac{/}{/}$
M1T70985	PM354 $\frac{0}{/}$
M1T71081	PM355 $\frac{0}{/}$
M1T71281	PM274 $\frac{/}{/}$
M1T71281	PM274 $\frac{0}{/}$
M1T71281A	PM274 $\frac{/}{/}$
M1T71281A	PM274 $\frac{/}{/}$
M1T71281AC	PM274 $\frac{/}{/}$
M1T71281B	PM274 $\frac{/}{/}$
M1T71281ZC	PM274 $\frac{/}{/}$
M1T71381	PM299 $\frac{0}{/}$
M1T71382	PM299 $\frac{0}{/}$
M1T71382ZC	PM299 $\frac{/}{/}$
M1T71388	PM299 $\frac{/}{/}$
M1T71481	PM357 $\frac{0}{/}$
M1T71481A	PM357 $\frac{/}{/}$
M1T71581	PM358 $\frac{0}{/}$
M1T71681	PM359 $\frac{0}{/}$
M1T7171481A	PM357 $\frac{/}{/}$
M1T71781	PM360 $\frac{0}{/}$
M1T71781A	PM360 $\frac{/}{/}$

MITSUBISHI RMA $\frac{V}{Kw -!}$

M1T71811	PM609	
M1T71881	PM274	0
M1T71881A	PM274	
M1T71981		0
M1T72081	PM361	0
M1T72085	M443	0
M1T72085A	M443	
M1T72086	M443	0
M1T72086A	M443	
M1T72087	M443	0
M1T72087A	M443	
M1T72088		0
M1T72181	PM355	0
M1T72181A	PM355	
M1T72182	PM355	0
M1T72182A	PM355	
M1T72281	PM362	0
M1T72281A	PM362	
M1T72285	PM362	0
M1T72385	M201	
M1T72481	M327	0
M1T72481ZC	M327	
M1T72483	M327	0
M1T72483ZC	M327	
M1T72581	PM299	0
M1T72582	PM299	
M1T72582	PM299	
M1T72583	PM299	0
M1T72583G	PM299	
M1T72681	PM360	0
M1T72781	PM362	0
M1T72781A	PM362	
M1T72781B	PM362	
M1T72981	M201	$12/1,4$
M1T72981A	M201	
M1T72985	M201	$12/1,4$
M1T72985A	M201	
M1T73271		0
M1T73281	PM363	0
M1T73283	PM363	0
M1T73371	M429	0
M1T73381	M429	0
M1T73381ZC	M429	
M1T73382	M429	0

MITSUBISHI RMA $\frac{V}{Kw -!}$

M1T73383	M429	0
M1T73383ZC	M429	
M1T73481	PM360	0
M1T73481A	PM360	
M1T73681		0
M1T73881	PM637	
M1T73881ZC	PM637	
M1T74081	PM364	0
M1T74087	PM364	0
M1T74281	M345	$12/1,2$
M1T74281ZC	M345	
M1T74283	M345	0
M1T74283ZC	M345	
M1T74286	M345	0
M1T74286ZC	M345	
M1T74287	M345	0
M1T74287ZC	M345	
M1T74381	PM365	0
M1T74481	PM716	
M1T74482	PM716	
M1T74491	PM251	0
M1T74581	M327	$12/0,7$
M1T74583	M327	$12/0,7$
M1T74781	PM717	
M1T74781A	PM717	
M1T74785	PM717	
M1T75181	PM365	0
M1T75181A	PM365	
M1T75281	PM350	
M1T75283	PM350	0
M1T75283	PM350	0
M1T75381	PM365	0
M1T75581	PM366	0
M1T75581ZC	PM366	
M1T75681	PM364	0
M1T75981	PM718	
M1T76081	PM719	
M1T76081ZC	PM719	
M1T76082ZC	PM719	
M1T76281	PM365	0
M1T76481	PM345	
M1T77081	PM367	0
M1T77181	M437	0
M1T77281	PM341	0

MITSUBISHI RMA $\frac{V}{Kw -!}$

M1T77381	PM274	0
M1T77381ZC	PM274	
M1T77581	PM720	
M1T77777	PM721	
M1T77777ZC	PM721	
M1T77781	PM721	
M1T77781ZC	PM721	
M1T78181	PM722	
M1T78381	PM723	
M1T78481	PM724	
M1T78581	PM725	
M1T78581ZC	PM725	
M1T78681	PM726	
M1T78681ZC	PM726	
M1T78691	PM726	
M1T78881	M201	0
M1T78981	PM363	
M1T79081	PM299	0
M1T79481	PM238	0
M1T79482	PM238	0
M1T79581	PM345	0
M1T79681	PM368	0
M1T79781	PM368	0
M1T80081	M105	$12/1,7$
M1T80082	M105	$12/1,7$
M1T80381	M105	0
M1T80381		
M1T80481	M105	
M1T84381ZC	M345	
M1T84481	PM364	0
M1T84883ZC	PM664	
M1T84884	PM727	
M1T84981	PM711	
M1T84981ZC	PM711	
M1T85781	PM246	0
M1T86181	PM345	
M1T86481	PM364	
M1T90081	PM347	0
M1T90081A	PM347	
M1T90281	M105	$12/1,7$
M1T92071	PM400	0
M2T10071	PM369	0
M2T10171	M424	0
M2T10271	M424	0

MITSUBISHI RMA $\frac{V}{Kw - !}$

M2T10471	PM370	0
M2T13081	M391	0
M2T13281	M430	0
M2T13581	M430	0
M2T20181	M424	0
M2T20181A	M424	
M2T20181D	M424	
M2T20182	PM371	0
M2T20182	PM371	0
M2T20281	M424	0
M2T20671	PM272	0
M2T20771		0
M2T23081	PM372	0
M2T23181	M320	$12 \frac{0,8}{0,8}$
M2T23181	M320	$12 \frac{0,8}{0,8}$
M2T23685	PM373	0
M2T25281	PM728	
M2T25282	PM728	
M2T25481	PM374	0
M2T25581	PM375	
M2T25681	PM375	0
M2T25681G	PM375	
M2T25772	PM372	0
M2T25871	M374	$12 \frac{1,2}{1,2}$
M2T27686	M330	0
M2T27781	M320	$12 \frac{0,8}{0,8}$
M2T30381	M446	0
M2T30481	M330	$12 \frac{0,8}{0,8}$
M2T30581	M330	$12 \frac{0,8}{0,8}$
M2T30586	M330	$12 \frac{0,8}{0,8}$
M2T30881	PM327	0
M2T32581	PM729	
M2T32681	PM409	0
M2T33182	M330	
M2T33183	M330	
M2T33781	M446	
M2T33785	M446	
M2T37081	M320	$12 \frac{0,8}{0,8}$
M2T37081	M320	$12 \frac{0,8}{0,8}$
M2T37281	M211	0
M2T40081	M425	0
M2T40271		0
M2T40377	PM730	
M2T41081	M425	

MITSUBISHI RMA $\frac{V}{Kw - !}$

M2T41171	M338	0
M2T41381	M446	0
M2T41581	M330	0
M2T41586	M330	$12 \frac{0,8}{0,8}$
M2T41881	M446	
M2T41885	M446	
M2T42371	M319	0
M2T42381	M330	$12 \frac{0,8}{0,8}$
M2T42881	PM013	0
M2T42981	M424	0
M2T43681	PM731	
M2T43781	PM731	
M2T43881	PM731	
M2T44081	M425X	0
M2T44681	M425X	0
M2T44781	PM411	
M2T46081	M446	
M2T46081ZE	M446	
M2T47281	M425	
M2T47382	PM732	
M2T48081	PM376	0
M2T48381	M430	$12 \frac{1,2}{1,2}$
M2T48681	M338	$12 \frac{1,0}{1,0}$
M2T49181	M330	0
M2T49189	M330	$12 \frac{0,8}{0,8}$
M2T49281	M320	
M2T49282	M320	
M2T49283	PM341	0
M2T49881	M425X	0
M2T50081		0
M2T50171	PM377	0
M2T50181	PM377	0
M2T50271	PM714	
M2T50281	PM714	
M2T50285	PM714	
M2T50371	PM378	0
M2T50381	PM378	0
M2T50391	PM378	0
M2T50481	M276	$12 \frac{3,1}{3,1}$
M2T50485	M276	$12 \frac{3,1}{3,1}$
M2T50581		0
M2T50583		0
M2T50585		0
M2T50781		0

MITSUBISHI RMA $\frac{V}{Kw - !}$

M2T50981		
M2T51082	PM273	0
M2T51083	PM273	0
M2T51085	PM379	$12 \frac{2,0}{2,0}$
M2T51180	PM380	0
M2T51181	PM380	0
M2T51185		0
M2T51281	PM381	0
M2T51282	PM381	0
M2T51486	M330	0
M2T51685	M193	$12 \frac{2,0}{2,0}$
M2T51805	PM379	0
M2T52071	PM377	0
M2T52081	PM377	0
M2T52082	PM377	0
M2T52171		0
M2T52172		0
M2T52181		0
M2T52271	PM622	
M2T52281	PM381	0
M2T52282		0
M2T52381	PM384	
M2T52382	PM384	
M2T52671		0
M2T52681	M374	0
M2T52871	M374	$12 \frac{1,2}{1,2}$
M2T52881	M374	$12 \frac{1,2}{1,2}$
M2T52882	PM733	0
M2T52981	PM383	0
M2T53081	PM384	0
M2T53082	PM384	0
M2T53083	PM384	0
M2T53085	PM384	0
M2T53086	PM384	0
M2T53281	PM384	0
M2T53282	PM384	0
M2T53681	PM734	
M2T53781	PM383	0
M2T53881	PM385	0
M2T53882	PM385	0
M2T53883	PM385	0
M2T54085	PM386	0
M2T54086	PM384	
M2T54091	PM386	0

MITSUBISHI RMA $\sqrt{\text{Kw}} -!$

M2T54371	PM387	0
M2T54372	PM387	0
M2T54571	PM261	0
M2T54572	PM261	0
M2T54771	PM275	0
M2T54871	PM388	0
M2T54881	PM388	0
M2T54882	PM388	0
M2T56071	PM389	0
M2T56072	PM389	0
M2T56082		0
M2T56171	M193	$12 \sqrt{2,0}$
M2T56181	M193	$12 \sqrt{2,0}$
M2T56182	M193	$12 \sqrt{2,0}$
M2T56185	M193	$12 \sqrt{2,0}$
M2T56271	PM391	
M2T56272	PM391	0
M2T56471	PM259	0
M2T56472	PM259	0
M2T56475	PM259	0
M2T56871	PM390	
M2T57271	M193	$12 \sqrt{2,0}$
M2T57273	M193	$12 \sqrt{2,0}$
M2T57371	M332	$12 \sqrt{2,0}$
M2T57771	M193	$12 \sqrt{2,0}$
M2T57773	M193	
M2T57871	PM390	0
M2T57881		0
M2T58381	PM392	0
M2T58481	PM393	0
M2T58581	PM368	0
M2T58681	PM368	
M2T58881	PM368	0
M2T58981	PM386	0
M2T60071	PM387	0
M2T60072	PM387	0
M2T60073	PM387	0
M2T60171	M341	$12 \sqrt{2,2}$
M2T60172	M341	$12 \sqrt{2,2}$
M2T60185	PM394	0
M2T61071	M341	$12 \sqrt{2,2}$
M2T61072	M341	$12 \sqrt{2,2}$
M2T61171	PM394	$12 \sqrt{2,2}$
M2T61172	PM275	$12 \sqrt{2,2}$

MITSUBISHI RMA $\sqrt{\text{Kw}} -!$

M2T61272	PM275	0
M2T61771	PM390	0
M2T61871	PM256	0
M2T61871A	PM256	
M2T61871B	PM256	
M2T62071A		0
M2T62271	PM260	0
M2T62771	PM394	
M2T62971	M193	$12 \sqrt{2,0}$
M2T62971	M193	$12 \sqrt{2,0}$
M2T62971	M193	$12 \sqrt{2,0}$
M2T63171	PM394	0
M2T63271	PM412	
M2T63371	PM735	
M2T63471	M445	0
M2T64271	PM736	
M2T64272	PM736	
M2T64273	M445	0
M2T64371	PM649	
M2T64372	M445	0
M2T64373	PM649	
M2T65271	PM395	0
M2T65272	PM395	0
M2T65275	PM395	
M2T66871	PM396	0
M2T66872	PM396	0
M2T66873	PM396	0
M2T66881	PM396	
M2T66882	PM396	
M2T67871	PM396	0
M2T67872	PM396	0
M2T67873	PM396	0
M2T67881	PM396	0
M2T67882	PM396	0
M2T67883	PM396	0
M2T67884	PM396	0
M2T72781	PM362	
M2T74171	M193	$12 \sqrt{2,0}$
M2T74171	PM397	$12 \sqrt{2,0}$
M2T78372	PM737	
M2T78381	PM737	
M2T78382	PM737	
M2T78383	PM737	
M2T79781	PM368	

MITSUBISHI RMA $\sqrt{\text{Kw}} -!$

M2T80081	PM738	
M2T80381	M121X	0
M2T80582	PM094	0
M2T80582		
M2T80681	PM738	
M2T84071	PM398	0
M2T84071ZT	PM398	
M2T84171	PM399	
M2T84771	PM094	0
M2T84771	PM094	
M2T87071	PM398	0
M2T87071ZT	PM398	
M2T87171	PM399	0
M2T87171ZT	PM399	
M2T87471	PM739	
M2T87671	PM235	0
M2T87971	PM398	0
M2T88071	PM399	0
M2T88271	PM398	
M2T88572	M449	
M2T88671	PM740	
M2T90071	M105	$12 \sqrt{1,7}$
M2T91172	PM381	0
M2T92071	PM400	0
M2T92071A	PM400	
M2T92171	PM401	0
M2T92172	PM401	0
M2T92172A	PM401	
M2T92471	PM381	0
M3T10071	PM402	0
M3T10072	PM741	0
M3T10081	PM742	
M3T10271	PM403	0
M3T10272	PM403	0
M3T10371	PM370	0
M3T10372	PM370	0
M3T10473	PM404	0
M3T10475	PM404	0
M3T10476	PM404	0
M3T10476D	PM404	
M3T10672	PM405	0
M3T10881	PM742	
M3T10977	PM743	
M3T11172	PM402	

MITSUBISHI RMA $V_{Kw} -!$

M3T11174	PM402	0
M3T11272	PM643	0
M3T12572	PM403	0
M3T12672	PM407	0
M3T13073	PM371	0
M3T14572	PM403	0
M3T14672	PM403	0
M3T14673	PM403	0
M3T15071	PM403	0
M3T15072	PM403	0
M3T15073	PM403	0
M3T15074	PM403	0
M3T15075	PM403	0
M3T15077	PM403	0
M3T15271	PM371	0
M3T15772	PM403	0
M3T15872	PM403	0
M3T15971	PM409	0
M3T19371	M118	12 0,8
M3T19571	M118	12 0,8
M3T19771	M104	12 0,9
M3T19871	M104	12 0,9
M3T19971	M100	12 0,8
M3T20081	PM408	0
M3T20082		0
M3T20381	PM370	0
M3T20681	PM405	0
M3T20781	PM744	0
M3T21281	PM643	0
M3T21281D	PM643	0
M3T21282	PM643	0
M3T21482	PM371	0
M3T21781	PM643	0
M3T21874	M431	0
M3T21881	PM643	0
M3T21882	PM643	0
M3T21882D	PM643	0
M3T21882D	PM643	0
M3T22081	PM408	0
M3T22173		0
M3T22381	PM370	0
M3T22488	M202	0
M3T22581	M425X	0
M3T22582	M425X	0

MITSUBISHI RMA $V_{Kw} -!$

M3T22681	PM409	0
M3T22781	PM744	0
M3T23081	PM371	0
M3T24081	PM408	0
M3T24181	M041	12 1,1
M3T24181	M041	12 1,1
M3T24432	M433	0
M3T24481	M433	0
M3T24482	M433	0
M3T24482A	M433	0
M3T24482H	M431	0
M3T24482HC	M431	0
M3T24482J	M431	0
M3T24482K	M431	0
M3T24483	M433	0
M3T24485	M433	0
M3T24486	M433	0
M3T24486A	M433	0
M3T24486H	M431	0
M3T24487	M433	0
M3T24488	M433	0
M3T24782	M327	0
M3T24917	PM409	0
M3T25081	PM408	0
M3T25181	PM643	0
M3T25281	PM371	0
M3T25282	PM371	0
M3T25781	M425X	0
M3T25782	M425	0
M3T25783	M425	0
M3T25785	M425	0
M3T25881	M425X	0
M3T25882	M425X	0
M3T25883	M425	0
M3T25885	M425	0
M3T25981	PM409	0
M3T25983		0
M3T26081	PM745	0
M3T26481		0
M3T26685	PM410	0
M3T27581	PM371	0
M3T27582	PM371	0
M3T27681	PM372	0
M3T27685	PM372	0

MITSUBISHI RMA $V_{Kw} -!$

M3T27686	PM372	0
M3T27686D	PM372	0
M3T27686H	PM372	0
M3T27686N	PM372	0
M3T27688	PM372	0
M3T27781	M320	12 0,8
M3T27781	M320	12 0,8
M3T27781D	M320	0
M3T27881	PM373	0
M3T29481	PM371	0
M3T29482	PM371	0
M3T29681	M439	0
M3T30081	PM408	0
M3T30082	PM408	0
M3T30088	PM408	0
M3T30171		0
M3T30281	M433	0
M3T30282	M433	0
M3T30285	M433	0
M3T30286	M433	0
M3T30381	PM370	0
M3T30382	PM370	0
M3T30481	M330	0
M3T30581	PM327	0
M3T30581H	PM327	0
M3T30581J	PM327	0
M3T30583	PM327	0
M3T30586	M330	0
M3T30681		0
M3T30781	PM744	0
M3T30782	PM744	0
M3T30881	M431	0
M3T30881	M431	0
M3T30981	PM746	0
M3T31471		0
M3T32081	PM408	0
M3T32082	PM408	0
M3T32281	M433	0
M3T32282	M433	0
M3T32381	PM370	0
M3T32382	PM370	0
M3T32581	M425X	0
M3T32582	M425X	0
M3T32583	M425X	0

MITSUBISHI RMA $\frac{V}{Kw - !}$

M3T32584	M425X 0
M3T32585	M425X 0
M3T32587	0
M3T32588	M425X
M3T32589	M425 0
M3T32591	M425X 0
M3T32592	M425X 0
M3T32593	M425X 0
M3T32681	PM409 0
M3T32781	PM744 0
M3T32782	PM744 0
M3T32782D	PM744
M3T32985	M202 12 0,9
M3T32986	M202 12 0,9
M3T32986	M202 12 0,9
M3T32988	M202 12 0,9
M3T32988	M017X 12 0,9
M3T32988	M202 12 0,9
M3T32989	M202 12 0,9
M3T32989	M202 12 0,9
M3T32991	M017E 12 0,9
M3T33081	PM609 0
M3T33181	M439 12 0,9
M3T33182	M330 12 0,8
M3T33183	M330 12 0,8
M3T33281	M431 0
M3T33281	M435 0
M3T33282	M431
M3T33481	PM747 0
M3T33535	M433 0
M3T33581	M433 0
M3T33582	M433 0
M3T33582A	M433
M3T33583	M431 0
M3T33585	M433 0
M3T33586	M433 0
M3T33586A	M433
M3T33586D	M431 0
M3T33587	M431 0
M3T33588	M433 0
M3T33781	M446 0
M3T33781ZC	M446
M3T33785	M446 0
M3T33871	M446 0

MITSUBISHI RMA $\frac{V}{Kw - !}$

M3T33981	M441 0
M3T33981H	M441
M3T34081	PM408 0
M3T34082	PM408 0
M3T34281	0
M3T34781	M327 12 0,7
M3T34781	M327 12 0,7
M3T34782	M327 12 0,7
M3T35081	PM408 12 0,7
M3T35082	PM408 12 0,7
M3T35088	PM408
M3T36081	PM745 0
M3T36481	0
M3T36881	M433 0
M3T36882	M433 0
M3T37081	M320 12 0,8
M3T37782	M320 0
M3T37783	PM341 0
M3T38381	0
M3T38482	PM625
M3T38483	PM625
M3T38682	PM643
M3T38881	M431 0
M3T38881	M431 0
M3T38881A	M431
M3T38881B	M431 0
M3T38881C	M431
M3T38882	M431 0
M3T38882	M431 0
M3T38882A	M431
M3T38882B	M431
M3T38882C	M431
M3T38883	M431 0
M3T38884	M431 0
M3T38885	M431 0
M3T38981	M327 12 0,7
M3T38981	M327 12 0,7
M3T39385	M433 0
M3T39481	M433 0
M3T39581	M070 12 0,8
M3T39781	M104 12 0,9
M3T39881	M104 12 0,9
M3T39981	M431 0
M3T40081	M425 0

MITSUBISHI RMA $\frac{V}{Kw - !}$

M3T40371	M222 0
M3T40371	M176 0
M3T40471	M442 0
M3T40671	0
M3T41081	M425 0
M3T41081	M425 0
M3T41083	M425 0
M3T41083	M425 0
M3T41088	M425
M3T41181	PM643
M3T41185	PM632 0
M3T41281	M425 0
M3T41282	M425 0
M3T41285	M425 0
M3T41381	PM372 0
M3T41481	M441 0
M3T41581	PM327 0
M3T41681	PM371 0
M3T41781	M327 12 0,7
M3T41881	M446 0
M3T41885	M446
M3T42281	PM372 0
M3T42581	M017X
M3T42781	PM376 0
M3T42781ZC	PM376
M3T42881	PM409 0
M3T43381	PM257 0
M3T43481	PM376 0
M3T43581	M431 0
M3T44081	PM411 0
M3T44081ZT	PM411
M3T44181	PM411 0
M3T44281	M446 0
M3T44481	PM748
M3T47281	M425X
M3T48081	PM376 0
M3T48181	M431 0
M3T48382	M442 0
M3T49281	M442 0
M3T49282	M442 0
M3T49282	M442
M3T49381	M431 0
M3T49381	M431
M3T49381	M431 0

MITSUBISHI RMA $\sqrt{Kw - !}$

M3T49481	M431	
M3T49581	M431	0
M3T49585	M433	0
M3T49781	M431	0
M3T50171	PM650	
M3T52071	PM736	
M3T53085	PM384	0
M3T54071	PM395	
M3T54072	PM395	0
M3T56071	PM667	0
M3T56072	PM667	0
M3T56074	PM667	0
M3T56082	PM667	
M3T56084	PM667	
M3T56174	PM749	
M3T56181	PM749	
M3T56182	PM749	
M3T57371	M332	0
M3T61071	M193	$12 \frac{2,0}{2,0}$
M3T61071	M193	$12 \frac{2,0}{2,0}$
M3T61171	PM391	0
M3T64071	PM387	0
M3T64172	PM259	
M3T66071	PM387	
M3T66072	PM387	
M3T66074	PM387	
M3T70081	PM744	0
M3T70381	PM750	
M3T70382	PM750	
M3T80071	M016	$12 \frac{0,8}{0,8}$ 15a
M3T80071	M016	$12 \frac{0,8}{0,8}$ 15a
M3T80571	M148	0
M3T88371	M106	
M3T90071	PM751	
M3T90072	PM751	0
M3T95071	PM666	
M3T95072	PM666	
M3T95073	PM666	
M3T95081	PM666	
M3T95082	PM666	
M3Y24482	M431	
M4T14572	M324	$12 \frac{1,2}{1,2}$
M4T14673	M324	0
M4T14771	M324	$12 \frac{1,2}{1,2}$

MITSUBISHI RMA $\sqrt{Kw - !}$

M4T14772	M425	
M4T14872	M324	0
M4T15771	M324	0
M4T16071	PM745	0
M4T18171		0
M4T18187		0
M4T26081	PM745	0
M4T50073	PM667	
M4T55076	PM666	
M4T70485	M426	0
M4T71281	PM274	0
M4T95481	PM752	0
M5T22072	PM390	
M5T22171	PM261	
M5T22175	PM261	
M5T23172	PM259	
M5T23871	PM390	
M5T27671	PM395	
M6T10673	PM667	
M7T03774	PM753	0
M7T03777	PM753	0
M8T43181	M437	
M8T50071	PM754	
M8T50171	PM755	
M8T70071	PM386	
M8T70971	PM756	
M8T71371	PM757	
M8T71471	PM758	
M8T75071	PM412	0
M8T75071A	PM412	
M8T75371	PM757	
M8T80071	PM759	
M8T80071A	PM759	
M8T85071	PM759	
M9T60371	PM760	
M9T60671	PM215	
M9T61171	PM219	
M9T80271	PM761	
M9T80472		
M9T80473		
MC109018	M425	
MCA010	PM369	0
MCA0102	PM369	0
MCA0103	PM369	0

MITSUBISHI RMA $\sqrt{Kw - !}$

MCA011	PM369	0
MCA020	M424	0
MCA021	M424	0
MCA022	M424	0
MCA030	M424	0
MD001133	M425	0
MD001155	PM403	0
MD001333	M425X	0
MD001550	PM403	0
MD001552	PM403	0
MD001553	PM403	0
MD001555	M425X	0
MD003550	PM403	0
MD003551	PM403	0
MD006761	PM403	0
MD011553	PM416	
MD016920	M425X	0
MD016921	M425	0
MD017649	PM023	
MD021665	PM403	0
MD021666	M324	$12 \frac{1,2}{1,2}$
MD021670	PM403	0
MD021674	M425	0
MD021678	M425X	0
MD021685	PM403	0
MD021866	M324	$12 \frac{1,2}{1,2}$
MD023578		0
MD023738		0
MD023746	PM384	0
MD023758	PM384	0
MD027380	PM384	0
MD027381	PM384	0
MD027382	PM384	0
MD027400	M425	0
MD027401	M425	0
MD027585	PM384	0
MD027832	PM384	0
MD034120	M425X	0
MD034121	M425X	0
MD034212	PM403	0
MD050200	M193	$12 \frac{2,0}{2,0}$
MD050205	M193	$12 \frac{2,0}{2,0}$
MD050205	M193	$12 \frac{2,0}{2,0}$
MD061154	M193	$12 \frac{2,0}{2,0}$

MITSUBISHI RMA $\frac{V}{Kw - !}$

MD061154	M193	$\frac{12}{2,0}$
MD066761	M425	$\frac{0}{/}$
MD069166	M193	$\frac{12}{2,0}$
MD069166	M193	$\frac{12}{2,0}$
MD070933	PM380	$\frac{0}{/}$
MD070934	M193	$\frac{12}{2,0}$
MD070934	M193	$\frac{12}{2,0}$
MD072585	PM384	$\frac{0}{/}$
MD072654	M341	$\frac{12}{2,2}$
MD073654	M341	$\frac{0}{/}$
MD081567	M425X	$\frac{0}{/}$
MD081568	M425X	$\frac{0}{/}$
MD084414	M193	$\frac{12}{2,0}$
MD085730		$\frac{0}{/}$
MD085731	M425	$\frac{0}{/}$
MD091567	M425	$\frac{0}{/}$
MD095865	M341	$\frac{12}{2,2}$
MD099667	PM698	$\frac{0}{/}$
MD099667	M426	$\frac{0}{/}$
MD100431	M425	$\frac{0}{/}$
MD100431	M425	$\frac{0}{/}$
MD101219	M425	$\frac{0}{/}$
MD107615	M425	$\frac{0}{/}$
MD112625	PM299	$\frac{0}{/}$
MD115514	PM409	$\frac{0}{/}$
MD121581	PM394	$\frac{0}{/}$
MD122625	PM299	$\frac{0}{/}$
MD136933	PM299	$\frac{0}{/}$
MD140190	M193	$\frac{12}{2,0}$
MD140190	PM397	$\frac{12}{2,0}$
MD156986	M193	$\frac{12}{2,0}$
MD156986	M193	$\frac{12}{2,0}$
MD156987	PM394	$\frac{0}{/}$
MD156989	M341	$\frac{12}{2,2}$
MD161437	M425X	$\frac{0}{/}$
MD162389	PM384	$\frac{0}{/}$
MD162836	M425X	$\frac{0}{/}$
MD162837	M425	$\frac{0}{/}$
MD162838	PM376	$\frac{0}{/}$
MD162839	M426	$\frac{0}{/}$
MD162840	M429	$\frac{0}{/}$
MD162842	PM299	$\frac{0}{/}$
MD162843	PM299	$\frac{0}{/}$
MD162975	M193	$\frac{12}{2,0}$

MITSUBISHI RMA $\frac{V}{Kw - !}$

MD162975	M193	$\frac{12}{2,0}$
MD164975	M193	$\frac{12}{2,0}$
MD164975	M193	$\frac{12}{2,0}$
MD164976	M193	$\frac{12}{2,0}$
MD164976	PM397	$\frac{12}{2,0}$
MD164977	M341	$\frac{12}{2,2}$
MD164978	PM394	$\frac{0}{/}$
MD171228	PM368	$\frac{0}{/}$
MD172860	M426	$\frac{0}{/}$
MD172861	M429	$\frac{0}{/}$
MD172863	PM299	$\frac{0}{/}$
MD172863	PM299	$\frac{0}{/}$
MD172864	PM363	$\frac{0}{/}$
MD174482	M429X	$\frac{0}{/}$
MD174483	M426	$\frac{0}{/}$
MD177596	PM394	$\frac{0}{/}$
MD180238	M425X	$\frac{0}{/}$
MD180239	PM376	$\frac{0}{/}$
MD188720	PM339	$\frac{0}{/}$
MD188721	PM358	$\frac{0}{/}$
MD189054	PM409	$\frac{0}{/}$
MD191433	M193	$\frac{12}{2,0}$
MD191433	M193	$\frac{12}{2,0}$
MD191433R	M193	$\frac{0}{/}$
MD191435	M193	$\frac{12}{2,0}$
MD191435	M193	$\frac{12}{2,0}$
MD191437	PM394	$\frac{0}{/}$
MD192227	PM257	$\frac{0}{/}$
MD192228	PM376	$\frac{0}{/}$
MD194976		$\frac{0}{/}$
MD301348	PM411	$\frac{0}{/}$
MD301348G	PM411	$\frac{0}{/}$
MD301350	PM411	$\frac{0}{/}$
MD301351	PM344	$\frac{0}{/}$
MD3013581	PM344	$\frac{0}{/}$
MD306997	PM724	$\frac{0}{/}$
MD306998	PM723	$\frac{0}{/}$
MD308088	PM252	$\frac{0}{/}$
MD309471	PM299	$\frac{0}{/}$
MD309472	PM363	$\frac{0}{/}$
MD312857	PM398	$\frac{0}{/}$
MD312858	PM398	$\frac{0}{/}$
MD313327	PM299	$\frac{0}{/}$
MD315547	PM399	$\frac{0}{/}$

MITSUBISHI RMA $\frac{V}{Kw - !}$

MD315548	PM399	$\frac{0}{/}$
MD316001	M425X	$\frac{0}{/}$
MD318086	PM368	$\frac{0}{/}$
MD320618	PM368	$\frac{0}{/}$
MD321445	PM411	$\frac{0}{/}$
MD328235	PM702	$\frac{0}{/}$
MD329260	M120X	$\frac{12}{1,9}$
MD329260	M120X	$\frac{0}{/}$
MD332022	PM344	$\frac{0}{/}$
MD335584	PM748	$\frac{0}{/}$
MD344182	PM398	$\frac{0}{/}$
MD344183	PM399	$\frac{0}{/}$
MD348221	PM398	$\frac{0}{/}$
MD351508	PM701	$\frac{0}{/}$
MD356104	PM344	$\frac{0}{/}$
MD356178	PM664	$\frac{0}{/}$
MD360368	PM344	$\frac{0}{/}$
MD362207	PM709	$\frac{0}{/}$
MD362910	PM727	$\frac{0}{/}$
MD363633	PM701	$\frac{0}{/}$
MD667539	PM376	$\frac{0}{/}$
MDR775		$\frac{0}{/}$
ME001565	PM390	$\frac{0}{/}$
ME012995	PM759	$\frac{0}{/}$
ME013007	PM759	$\frac{0}{/}$
ME017001	PM736	$\frac{0}{/}$
ME017004	PM736	$\frac{0}{/}$
ME017034	PM396	$\frac{0}{/}$
ME017035	PM396	$\frac{0}{/}$
ME017036	PM396	$\frac{0}{/}$
ME017056	PM396	$\frac{0}{/}$
ME017061	PM396	$\frac{0}{/}$
ME017085	PM396	$\frac{0}{/}$
ME037150	PM667	$\frac{0}{/}$
ME037330	PM667	$\frac{0}{/}$
ME037465	PM667	$\frac{0}{/}$
ME037636	PM667	$\frac{0}{/}$
ME057200	PM666	$\frac{0}{/}$
ME057350	PM666	$\frac{0}{/}$
ME057845	PM666	$\frac{0}{/}$
ME057985	PM666	$\frac{0}{/}$
ME057990	PM666	$\frac{0}{/}$
ME067611	PM667	$\frac{0}{/}$
ME077048	PM667	$\frac{0}{/}$

MITSUBISHI RMA \sqrt{Kw} -!

ME077407	PM667	/
ME087507	PM737	/
ME087589	PM737	/
ME087590	PM737	/
ME088390	PM737	/
ME110JA	M433	0/
ME200206	PM412	/
ME201650	PM412	0/
ME204424	PM412	/
ME224425		/
MEA010	PM402	0/
MEA010	PM402	0/
MEA011	PM741	0/
MEA0112		0/
MEA0113		0/
MEA012AR	PM402	/
MEA030	PM407	0/
MEA0302	PM403	0/
MEA0303	PM403	0/
MEA031	PM407	0/
MEA032	PM403	/
MEA034	PM403	0/
MEA040	PM370	0/
MEA04023		0/
MEA041	PM370	0/
MEA04123		0/
MEA046	PM370	0/
MEA061	PM405	0/
MEA070	PM405	0/
MEA071	PM405	0/
MEA0711	PM405	0/
MEA1007	PM743	/
MEA107	PM743	/
MEA121	PM741	0/
MEA131	PM643	0/
MEA132	PM643	0/
MEA152	M210	$\sqrt{12}$ 0,9
MEA160	M210	$\sqrt{12}$ 0,9
MEA161	M210	$\sqrt{12}$ 0,9
MEA162	M210	$\sqrt{12}$ 0,9
MEA163	M210	$\sqrt{12}$ 0,9
MEA241	PM407	0/
MEA950	PM371	0/
MEA951		0/

MITSUBISHI RMA \sqrt{Kw} -!

MEB020	M210	$\sqrt{12}$ 0,9
MEC010	PM371	0/
MEC011	PM371	0/
MEC012	PM371	0/
MEC042	PM371	/
MED020	PM403	0/
MED021	PM643	0/
MED022	PM643	0/
MED030		0/
MED031	PM407	0/
MED032	PM403	0/
MED033	PM403	0/
MED034	PM403	0/
MED042	PM371	0/
MEO01565		0/
MEO040		0/
MEO041		0/
MEO07517		0/
MEO07655		0/
MEO17004	PM396	0/
MEO17034	PM396	0/
MEO17035	PM396	0/
MEO17036	PM396	0/
MEO17056	PM396	0/
MEO17061	PM396	0/
MEO17085	PM396	0/
MEO17088	PM396	0/
MEO17089	PM396	0/
MEO37465		0/
MEO37636		0/
MEO77048		0/
MEO77407		0/
MES071	PM405	/
MEWR	PM403	/
MEY1R	PM643	0/
MEY3R	PM643	0/
MG250302		0/
MM115513	PM409	0/
MM115514	PM409	0/
MM115517	PM409	0/
MM115518	PM368	0/
MM115519	PM368	/
MM409410	PM378	/
MM409411	PM391	0/

MITSUBISHI RMA \sqrt{Kw} -!

MM409413	PM391	/
MM409414	PM378	0/
MQJ1R	PM405	0/
MQJ2R	PM405	0/
MQJ6R	PM405	0/
MQJR	PM405	0/
MR994325	PM344	/
MW2R		0/
MW8R	PM369	0/
MW9R	PM369	0/
MWC2R	M424	0/
MWV10R	PM369	0/
MWV10R	PM369	/
MWV11R	PM369	0/
MWV11R	PM369	/
MWV3R	M424	0/
MWV3R	M424	/
MWV4R	M424	0/
MWV4R	M424	/
MWV8R	PM369	0/
MWV9R	PM369	0/
MXR	PM643	0/
RD021866	M324	/

MOTORCRAFT RMA $\frac{V}{Kw -!}$

5271BA	M235	$\frac{12}{1,4}$
6231AA	M420	$\frac{0}{}$
6239AA	M420	$\frac{0}{}$
6247CA	M235	$\frac{12}{1,4}$
6261CA	M235	$\frac{12}{1,4}$
6263BA	M420	$\frac{0}{}$
6331BA	M420	$\frac{0}{}$
6350AA	M235	$\frac{12}{1,4}$
7051AA	M235	$\frac{12}{1,4}$
7051CA	M235	$\frac{12}{1,4}$
7078AA	M235	$\frac{12}{1,4}$
7107BA	M235	$\frac{12}{1,4}$
7150BA	M235	$\frac{12}{1,4}$
7336CA	M235	$\frac{12}{1,4}$
ESA1207R		$\frac{0}{}$
ESA1240	M190	$\frac{0}{}$
ESA1243R		$\frac{0}{}$
ESA1255	M059	$\frac{12}{2,5}$
ESA1262R	M217	$\frac{0}{}$
ESA1267R		$\frac{0}{}$
ESA1270R	M235	$\frac{12}{1,4}$
ESA1271R	PM027	$\frac{0}{}$
ESA1283R	M389	$\frac{0}{}$
ESA1284R		$\frac{0}{}$
ESA1285	M387	$\frac{0}{}$
ESA1290R	M235X	$\frac{0}{}$
ESA200	M214	$\frac{0}{}$
ESA200	M214	$\frac{0}{}$
ESA200R	M214	$\frac{0}{}$
ESA201	M082	$\frac{12}{0,8}$
ESA201	M136	$\frac{12}{0,8}$
ESA201R	M082	$\frac{12}{0,8}$
ESA205	M261	$\frac{0}{}$
ESA205	M261	$\frac{0}{}$
ESA205R	M261	$\frac{0}{}$
ESA206	M261	$\frac{12}{1,4}$
ESA206	M261	$\frac{12}{1,4}$
ESA206R	M261	$\frac{12}{1,4}$
ESA208R		$\frac{0}{}$
ESA208R		$\frac{0}{}$
ESA209	M043	$\frac{12}{1,0}$
ESA209R	M043	$\frac{12}{1,0}$
ESA210	M263	$\frac{12}{1,4}$
ESA210R	M263	$\frac{12}{1,4}$

MOTORCRAFT RMA $\frac{V}{Kw -!}$

ESA212	M243	$\frac{0}{}$
ESA212R	M243	$\frac{0}{}$
ESA214R	PM558	$\frac{0}{}$
ESA215	M260	$\frac{12}{1,4}$
ESA215	M260	$\frac{12}{1,4}$
ESA215R	M260	$\frac{12}{1,4}$
ESA218	PM021	$\frac{0}{}$
ESA218R	PM021	$\frac{0}{}$
ESA219	M153	$\frac{12}{2,0}$
ESA219R	M153	$\frac{12}{2,0}$
ESA221	M285	$\frac{12}{2,2}$
ESA221	M285	$\frac{12}{2,2}$
ESA221R	M285	$\frac{12}{2,2}$
ESA223R	M243	$\frac{0}{}$
ESA224	M190	$\frac{12}{1,0}$
ESA224R	M190	$\frac{12}{1,0}$
ESA225	M260	$\frac{12}{1,4}$
ESA225R	M260	$\frac{12}{1,4}$
ESA226	M244	$\frac{12}{1,8}$
ESA226R	M244	$\frac{12}{1,8}$
ESA229	M137	$\frac{12}{0,8}$
ESA229	M137	$\frac{12}{0,8}$
ESA229R	M138	$\frac{0}{}$
ESA232	PM089	$\frac{12}{0,8}$
ESA232R	PM089	$\frac{12}{0,8}$
ESA233	M214	$\frac{12}{1,7}$
ESA233	M214	$\frac{12}{1,7}$
ESA233R	M214	$\frac{12}{1,7}$
ESA234	M307	$\frac{12}{2,2}$
ESA234R	M307	$\frac{12}{2,2}$
ESA235	M134	$\frac{12}{0,8}$
ESA235R	M134	$\frac{0}{}$
ESA235R	M137	$\frac{0}{}$
ESA235R	M134	$\frac{0}{}$
ESA236R	M137	$\frac{12}{0,8}$
ESA236R	M137	$\frac{12}{0,8}$
ESA237	M261	$\frac{12}{1,4}$
ESA237	M261	$\frac{12}{1,4}$
ESA237R	M261	$\frac{12}{1,4}$
ESA240	M190	$\frac{12}{1,0}$
ESA240R	M190	$\frac{12}{1,0}$
ESA241	M244	$\frac{12}{1,8}$
ESA241R	M244	$\frac{12}{1,8}$
ESA242	PM089	$\frac{0}{}$

MOTORCRAFT RMA $\frac{V}{Kw -!}$

ESA242R	PM089	$\frac{0}{}$
ESA243	M243	$\frac{12}{1,4}$
ESA243R	M243	$\frac{12}{1,4}$
ESA244	M285	$\frac{12}{2,2}$
ESA244	M285	$\frac{12}{2,2}$
ESA244R	M285	$\frac{12}{2,2}$
ESA245	M260	$\frac{12}{1,4}$
ESA245R	M260	$\frac{12}{1,4}$
ESA246R	M263	$\frac{12}{1,4}$
ESA247	M307	$\frac{12}{2,2}$
ESA247R	M307	$\frac{12}{2,2}$
ESA248R	PM598	$\frac{0}{}$
ESA249	M137	$\frac{12}{0,9}$
ESA249	M138	$\frac{12}{0,9}$
ESA249R	M138	$\frac{12}{0,9}$
ESA250	M243	$\frac{0}{}$
ESA254	PM025	$\frac{0}{}$
ESA254R	PM025	$\frac{0}{}$
ESA255	M059	$\frac{12}{2,5}$
ESA255R	M059	$\frac{12}{2,5}$
ESA262	M217	$\frac{12}{1,4}$
ESA262R	M217	$\frac{12}{1,4}$
ESA267R	PM025	$\frac{0}{}$
ESA268R	M214	$\frac{12}{1,7}$
ESA268R	M214	$\frac{12}{1,7}$
ESA268R	M214	$\frac{12}{1,7}$

NIKKO	RMA $\sqrt{\text{Kw}} -!$	NIKKO	RMA $\sqrt{\text{Kw}} -!$	NIKKO	RMA $\sqrt{\text{Kw}} -!$
0210001460	PM669	0230000062	PM767	0230003010	PM279
0210002660	PM762 $\sqrt{0}$	0230000063	PM767	0230003160	PM772
0210003291	PM279	0230000130	PM413 $\sqrt{0}$	0230003170	PM772
0210003410	PM762 $\sqrt{0}$	0230000150	PM768 $\sqrt{0}$	0230003180	PM773 $\sqrt{0}$
0210003411	PM762	0230000240	PM677	0230003184	PM773 $\sqrt{0}$
0210003433	PM678	0230000241	PM677	0230003185	PM773 $\sqrt{0}$
0210003490	PM763 $\sqrt{0}$	0230000260	PM413 $\sqrt{0}$	0230003290	PM774
0210003491	PM763 $\sqrt{0}$	0230000261	PM413	0230003291	PM279 $\sqrt{0}$
0210003600	PM279	0230000262	PM413 $\sqrt{0}$	0230003292	PM774
0210003640	PM669	0230000270	PM768	0230003661	PM279 $\sqrt{0}$
0210003641	PM669	0230000271	PM768 $\sqrt{0}$	0230006340	PM775
0210003650	PM279	0230000272	PM768	0230006341	PM775
0210003651	PM669	0230000278	PM768 $\sqrt{0}$	0230006342	PM775
0210003660	PM279	0230000330	PM767	0230006343	PM775
0210003661	PM279	0230000331	PM767	0230006510	PM772 $\sqrt{0}$
0210003790	PM764 $\sqrt{0}$	0230000332	PM767	0230006513	PM772
0210004110	PM765	0230000333	PM767	0230006530	PM776
0210004132	PM766	0230000727	PM768 $\sqrt{0}$	0230006531	PM776
0210004230	PM270	0230001030	PM279 $\sqrt{0}$	0230006532	PM776
0210004231	PM270 $\sqrt{0}$	0230001031	PM279 $\sqrt{0}$	0230006533	PM776
0210004231	PM270	0230001032	PM279	0230006590	PM772
0210004470	PM279	0230001033	PM279	0230007020	PM776
0210004471	PM279	0230001070	PM668	0230007021	PM776
0210004471	PM279	0230001071	PM668	0230007022	PM776
0210004850	PM766 $\sqrt{0}$	0230001230	PM769 $\sqrt{0}$	0230007731	PM777
0210004851	PM766 $\sqrt{0}$	0230001231	PM769 $\sqrt{0}$	0230007910	PM772
0210004880	PM765 $\sqrt{0}$	0230001260	PM680 $\sqrt{0}$		
0210004881	PM765 $\sqrt{0}$	0230001270	PM769 $\sqrt{0}$		
0210004934	PM678	0230001290	PM770 $\sqrt{0}$		
0210004935	PM678	0230001292	PM770 $\sqrt{0}$		
0210005230	PM270 $\sqrt{0}$	0230001310	PM680 $\sqrt{0}$		
0210005231	PM270	0230001410	PM770		
0230000030	PM677	0230001550	PM770		
0230000031	PM677	0230001581	PM666		
0230000032	PM677	0230001670	PM279		
0230000040	PM767	0230001700	PM680 $\sqrt{0}$		
0230000041	PM767	0230001750	PM770		
0230000042	PM767	0230001752	PM770		
0230000050	PM767	0230002040	PM771		
0230000051	PM767	0230002100	PM680 $\sqrt{0}$		
0230000052	PM767	0230002201	PM680 $\sqrt{0}$		
0230000053	PM767	0230002201	PM680		
0230000060	PM767	0230002541	PM680		
0230000061	PM767	0230002570	PM769		

NISSAN	RMA $\sqrt{\text{Kw}} -!$	NISSAN	RMA $\sqrt{\text{Kw}} -!$	NISSAN	RMA $\sqrt{\text{Kw}} -!$
1195016E10	RM064	233000W010	PM700	233001E400	PM637
230054A01RE	PM265	233000W011	PM700	233001E410	PM637
231000C401	PM619	233000Y000	M336 0	233001F700	PM544
23100R9000	PM643	233000Y001	M336	233001F705	PM544 0
2330000H00	PM643 0	233000Y005	M336 0	233001F705	PM544
2330000H10	PM632 0	2330010605	PM616	233001F710	PM013 0
23300018016	M424 0	2330010615	PM616	233001F715	PM013 0
2330001B00	PM526 0	2330010G02	M434 0	233001F715	PM013
2330001E00	PM327 0	2330010T01	M336X 0	233001F770	PM889
2330001E10	PM327 0	2330010T01	M336X 0	233001M211	PM341
2330001E11	PM327 0	2330010T02	M336X 0	233001M212	PM341
2330001E12	PM327 0	2330011M00	PM512 0	233001M215	PM341 0
2330001E13	PM327 0	2330011M01	PM512 0	233001M216	PM341 0
2330001N00	PM509 0	2330011M02	PM512 0	233001S710	PM337 0
2330001Y10	PM354 0	2330012G02	PM513	233001S711	PM337 0
2330001Y11	PM354 0	2330012G03	PM513 0	233001S715	PM750
2330003E00	M441 0	2330012G05	PM513	233001S716	PM750
2330003E01	M441	2330015800	PM643 0	233001S900	PM269 0
2330003E10	M441 0	2330015805	PM643 0	2330020H12	PM392 0
2330003E11	M441 0	2330015810	PM643 0	2330020P00	PM632 0
2330003J00	PM510 0	2330015815	PM643 0	2330020P05	PM632
2330004A07	0	2330015A00	PM514 0	2330020R11	PM355 0
2330004E00	PM383 0	2330015A06	PM527	2330021000	PM405 0
2330004E01	PM383 0	2330016E01	PM629	2330021005	PM405 0
2330004E02	PM383 0	2330016E02	PM629	2330021006	PM405 0
2330004E10	PM383 0	2330016E03	PM629	2330021007	PM405 0
2330005E00	PM379 0	2330016E04	PM629	2330021008	PM405 0
2330005E10	PM379 0	2330017C00	PM625	2330021009	PM405 0
2330005P01	PM516 0	2330017C05	PM625	2330021010	PM405 0
2330006E00	PM327 0	2330017C60	M374 0	2330021015	PM405 0
2330006E10	PM327 0	2330018000	M424 0	2330021016	PM405 0
2330006W61	M374 0	2330018005	M424 0	2330021017	PM405 0
2330007G00	0	2330018015	M424 0	2330021800	PM272 0
23300084A01	0	2330018016	M424 0	2330022P00	PM516 0
2330009600	PM615	2330018C00	PM625	233002F000	PM301 0
2330009601	PM615	2330018C01	PM625	233002F000	
2330009E00	M332 0	2330018C02	PM625	233002F200	M413 0
2330009E10	M332 0	2330018C03	PM625	233002J201	PM517
2330000B711	PM712	2330018C06	PM405 0	233002J260	PM517 0
233000C010	PM374 0	2330018C55	M374 0	233002J261	PM517 0
233000D0200	M443 0	2330018C60	M374 0	233002J262	PM517
233000M210	PM341	2330018C65	M374 0	233002T700	M336X 0
233000M301	M443 0	2330018C70	PM733	233002Y900	PM518
233000M302	M443 0	2330018V10	PM372 0	2330030F10	PM357 0

NISSAN RMA $\sqrt{\text{Kw}} -!$

2330030F11	PM357 0/
2330030P14	PM362 0/
2330030P15	PM728 /
2330030P16	PM728 /
2330030P17	PM728 /
2330030R01	PM362 0/
2330030R02	PM362 0/
2330030R12	PM362 0/
2330030R13	PM362 0/
2330031U00	PM518 0/
2330031U01	PM518 0/
2330031U02	PM518 0/
2330031W00	PM272 0/
2330031W01	0/
2330031W02	PM272 0/
2330031W03	0/
2330031W04	PM272 0/
2330036A00	PM385 0/
2330036A10	PM385 0/
2330036A11	PM385 0/
2330037503	PM272 0/
2330037508	PM272 0/
2330037553	PM272 0/
2330037A00	PM410 0/
2330037A01	PM410 0/
2330037A10	PM410 0/
2330037J00	PM510 0/
2330037J05	PM510 0/
233003M000	PM256 0/
233003M010	PM256 /
2330040500	PM371 0/
2330040501	PM371 0/
2330040510	PM371 0/
2330040511	PM371 0/
2330040512	PM371 0/
2330040513	PM371 0/
2330040700	PM371 0/
2330040710	PM371 0/
2330041B15	M320 /
2330041B71	PM013 0/
2330043G01	M336X 0/
2330044R10	PM355 0/
2330044R11	PM355 0/
2330047500	PM377 0/

NISSAN RMA $\sqrt{\text{Kw}} -!$

2330047501	PM377 0/
2330047502	PM377 0/
2330047510	PM377 0/
2330047511	PM377 0/
2330047601	PM615 0/
2330048301	PM615 0/
2330048L10	0/
233004E100	PM637 /
233004E210	M201 0/
233004J606	PM519 0/
233004Y00	M320 /
2330050Y00	M443 0/
2330050Y01	M443 0/
2330050Y02	M338 0/
2330050Y10	M443 0/
2330050Y11	M443 0/
2330050Y12	M338 0/
2330050Y14	M338 0/
2330051E10	PM355 0/
2330051E11	PM355 0/
2330052F00	M447 0/
2330052F01	M447 /
2330052F05	M447 0/
2330052F10	M447 0/
2330052H00	PM510 0/
2330053F10	0/
2330053F11	PM362 0/
2330053J00	PM349 /
2330053J11	M201 0/
2330053J12	M201 0/
2330053Y00	M338 0/
2330053Y01	M338 0/
2330054A00	PM265 0/
2330054A01	PM265 0/
2330054A05	PM265 0/
2330054C00	PM349 0/
2330054T00	PM269 0/
2330057J00	PM256 0/
2330057J05	PM256 0/
2330057J11	PM256 /
2330057J13	PM256 0/
2330057M05	M441 0/
2330057M60	PM359 0/
2330057M70	PM359 0/

NISSAN RMA $\sqrt{\text{Kw}} -!$

2330060S10	PM632 0/
2330060U10	PM717 /
2330060U11	PM717 /
2330060U12	PM717 /
2330062C00	PM385 0/
2330062C10	PM341 0/
2330062C10	PM385 /
2330063J00	PM349 0/
2330063J01	PM349 0/
2330063J02	PM349 /
2330063J10	M201 0/
2330063J11	M201 0/
2330065F05	M447 0/
2330065F10	M447 0/
2330065N50	M336X /
2330065N51	M336X 0/
2330065Y00	M443 0/
2330065Y01	M443 /
2330065Y10	M338 /
233006T000	M336X /
233006T001	M336X /
233006T001	M336X 0/
2330070J00	PM520 0/
2330070J00	M338 /
2330070J01	PM520 /
2330070J01	M338 0/
2330070J02	M338 0/
2330070J03	M201 0/
2330070J10	M201 0/
2330070J11	M201 0/
2330070J12	0/
2330070J12	M201 /
2330070Y00	PM341 0/
2330070Y01	PM341 0/
2330070Y10	PM341 0/
2330072F10	PM362 /
2330073C00	PM341 /
2330073C10	PM341 /
2330073C10	M338 0/
2330073Y00	M338 0/
2330073Y01	PM341 0/
2330073Y01	M338 /
2330074Y00	PM341 0/
2330074Y10	PM361 0/

NISSAN	RMA $\sqrt{\text{Kw -!}}$	NISSAN	RMA $\sqrt{\text{Kw -!}}$	NISSAN	RMA $\sqrt{\text{Kw -!}}$
2330074Y10	PM341	2330090060	PM280	23300B5010	PM616
2330077A01	PM361 0	2330090067	PM269 0	23300B5011	PM616
2330077A11	PM361 0	2330090069	PM269 0	23300BG3G1	0
2330078503	PM405 0	2330091N10	M443 0	23300C0600	PM617
2330078504	PM405 0	2330092350	PM301 0	23300C6800	PM281 0
2330078505	PM349 0	2330094850	M320	23300C6801	PM282 0
2330079E10	PM349 0	2330094850	M320	23300C8601	PM281 0
233007C600	M252	2330094850	M320 0	23300C8703	PM281 0
233007C600	M252	2330094850	M320 0	23300C8704	PM281
233007C625	M252 0	2330094851	PM013	23300D0100	PM372 0
233007F400	PM405 0	2330094851	PM013	23300D0110	PM372 0
2330080100	PM405 0	2330094851	PM013 0	23300D0111	PM372 0
2330080200	M320 0	2330097E00	PM638	23300D0200	PM372 0
2330080G00	M336X 0	2330097E01	PM638	23300D0210	PM372 0
2330080G00	M336X 0	2330099B00	M320 0	23300D0211	PM372 0
2330080G01	M336X 0	2330099B00	M320 0	23300D0212	PM372 0
2330080G10	M343	2330099B00	M320 0	23300D0213	PM372 0
2330081N00	M443 0	2330099B00	M320 0	23300D0214	PM372 0
2330081N00	M443 0	2330099B05	M320X 0	23300D0300	PM523 0
2330081N01	M443	2330099B06	M320X 0	23300D0301	PM523 0
2330081N01	M443 0	2330099B06	M320	23300D0302	PM523 0
2330081N10	M443 0	2330099B10	PM013 0	23300D0310	PM523 0
2330081N11	M443 0	2330099B10	PM013 0	23300D0511	PM353 0
2330081W00	PM405 0	2330099B10	PM013 0	23300D0512	PM353 0
233008310	PM373	2330099B15	PM013 0	23300D0513	PM353 0
2330083W00	PM385 0	2330099B16	PM013	23300D0514	PM372 0
2330084A01	PM385 0	2330099B16	PM013 0	23300D1700	PM372 0
2330084A07	M443 0	233009C600	M252 0	23300D8700	RM076 0
2330084A11	PM385 0	233009C600	M252 0	23300D870A	RM076
2330084A17	M443 0	233009F600	PM069 0	23300D9700	M252 0
2330084A18	M443	233009F600	PM069 0	23300D9701	M252 0
2330085A11	0	233009F660	PM069	23300D9702	M252 0
2330085E00	PM521 0	233009F661	PM069	23300D9702	M252
2330085E01	PM521 0	23300A3200	PM643 0	23300DO300	PM523
2330085E02	0	23300AA000	0	23300DO302	PM523
2330086G10	M343 0	23300AA010	PM351 0	23300E3000	PM371 0
2330086G11	M343 0	23300AA020	PM364 0	23300E3001	PM371 0
2330086G12	M343 0	23300AA40A	M437	23300E3010	PM371 0
2330087709	M129 0	23300B03G0	M320 0	23300E3011	PM371 0
2330088G00	PM522 0	23300B03G0	M320 0	23300E3100	PM371 0
2330088G01	PM522 0	23300B0700	PM615	23300E3101	PM371 0
233008H300	PM642	23300B5000	PM616 0	23300E3101	PM371 0
233008H801	PM758	23300B5001	PM616	23300G2403	M380 0
233008X800	RM030 0	23300B5002	PM616	23300G2404	M380 0

NISSAN	RMA $\sqrt{\text{Kw}} -!$	NISSAN	RMA $\sqrt{\text{Kw}} -!$	NISSAN	RMA $\sqrt{\text{Kw}} -!$
23300G2405	M380 0/	23300M0111	PM369 0/	23300N5902	PM377 0/
23300G2406	M380 0/	23300M0112	PM369 0/	23300N5903	PM377 0/
23300G2406	M380 0/	23300M0113	PM369 0/	23300N5910	PM377 0/
23300G7003	PM272 0/	23300M1500	PM369 0/	23300N5911	PM377 0/
23300G8400	PM633 /	23300M1501	PM369 0/	23300P0611	PM643 0/
23300G8401	PM633 /	23300M1502	PM369 0/	23300P0612	PM643 0/
23300G9900	M252X 0/	23300M1503	PM369 0/	23300P0613	PM643 0/
23300G9900	M252X 0/	23300M1510	PM369 0/	23300P0614	PM643 0/
23300H0100	M424 0/	23300M1511	PM369 0/	23300P1114	PM643 0/
23300H0101	M424 0/	23300M4900	PM369 0/	23300P5110	PM643 0/
23300H3900	M424 0/	23300M8000	M320 0/	23300P5111	PM643 0/
23300H5000	M424 0/	23300M8000	M320 0/	23300P5112	PM643 0/
23300H5001	M424 0/	23300M8001	M320 0/	23300P5113	PM643 0/
23300H5002	M424 0/	23300M8010	M320 0/	23300P5114	PM632 0/
23300H5003	M424 0/	23300M8010	M320 0/	23300Q9000	M441 0/
23300H5004	M424 0/	23300M8011	M320 0/	23300R2000	PM377 0/
23300H5010	M424 0/	23300M8011	M320 0/	23300R2010	PM377 0/
23300H5011	M424 0/	23300M8100	PM526 0/	23300R8300	PM650 /
23300H5012	M424 0/	23300M8101	PM526 0/	23300R9000	PM643 0/
23300H5013	M424 0/	23300M8110	PM373 0/	23300S0500	PM405 0/
23300H5014	M424 0/	23300M8111	PM373 0/	23300S0510	PM405 0/
23300H5015	M424 0/	23300M8200	M320 0/	23300T3400	PM650 /
23300H6900	M424 0/	23300M8200	M320 0/	23300T3402	PM650 /
23300H6901	M424 0/	23300M8201	M320 0/	23300T3470	PM272 0/
23300H6902	M424 0/	23300M8201	M320 0/	23300T5070	PM643 0/
23300H6903	M424 0/	23300M8202	M320 0/	23300T7200	PM650 /
23300H6904	M424 0/	23300M8210	M320 0/	23300T7201	PM650 /
23300H7301	M424 0/	23300M8210	M320 0/	23300T9000	PM649 /
23300H9101	PM377 /	23300M8211	M320 0/	23300T9005	PM649 /
23300H9112	PM377 /	23300M8211	M320 0/	23300T9007	PM649 /
23300K9160	M342 0/	23300M8212	M320 0/	23300T9009	PM649 /
23300KA470	M211 0/	23300M8300	PM526 0/	23300T9010	PM649 /
23300KA471	M211 0/	23300M8301	PM526 0/	23300U0100	PM405 0/
23300L1110	PM643 0/	23300M8500	PM527 0/	23300U0101	PM405 0/
23300L1111	PM643 0/	23300M8501	PM527 0/	23300U0102	PM405 0/
23300L1800	PM272 0/	23300M8502	PM527 0/	23300U0110	PM405 0/
23300L2910	0/	23300N2N00	M336X 0/	23300U0111	PM405 0/
23300L2911	PM643 0/	23300N3300	PM405 0/	23300U0112	PM405 0/
23300L2912	PM643 0/	23300N3301	PM405 0/	23300U0113	PM405 0/
23300L6000	PM280 0/	23300N3302	PM405 0/	23300U0114	0/
23300L6810	PM393 0/	23300N3303	PM405 0/	23300U6000	PM405 0/
23300M0100	PM369 0/	23300N3304	PM405 0/	23300U6001	PM405 0/
23300M0101	PM369 0/	23300N5900	PM377 0/	23300U6002	PM405 0/
23300M0110	PM369 0/	23300N5901	PM377 0/	23300U6003	PM405 0/

NISSAN	RMA $\sqrt{\text{Kw}} -!$	NISSAN	RMA $\sqrt{\text{Kw}} -!$	NISSAN	RMA $\sqrt{\text{Kw}} -!$
23300U6004	PM405 0/	23300W1701	PM273 0/	3446620102	PM395 0/
23300U6006	PM405 0/	23300W1702	PM273 0/	3446620201	PM259 /
23300U6007	PM405 0/	23300W1711	PM273 0/	3476610903	PM749 /
23300U7500	PM377 0/	23300W1712	PM273 0/	3476620900	PM749 /
23300U7501	PM377 0/	23300W1800	PM388 0/	772000050	/
23300U7502	PM377 0/	23300W1810	PM388 0/	772000082	/
23300U7510	PM377 0/	23300W1811	PM388 0/	772000120	/
23300U7511	PM377 0/	23300W2500	PM273 0/	77200120	RM005 /
23300V0600	PM272 0/	23300W2801	PM273 0/	8200466758	PM539 /
23300V0600	PM272 0/	23300W2802	PM273 0/	997267	RM075 /
23300V0602	PM272 0/	23300W2803	PM275 0/	997280	/
23300V0603	PM272 0/	23300W2804	PM275 0/	997281	/
23300V0605	PM272 0/	23300W2811	PM275 0/	B330M01E00EX	PM327 /
23300V0606	PM272 0/	23300W3410	PM275 0/	B330M01E13EX	PM327 /
23300V0607	PM272 0/	23300W9810	M342 0/	B330M03E00EX	M441 /
23300V0700	PM388 0/	23300WD000	PM757 /	B330M04E02EX	PM383 /
23300V0706	PM388 0/	23300WD001	PM757 /	B330M10T02EX	M336X /
23300V0711	PM388 0/	23300Y0102	PM405 0/	B330M31W04EX	PM272 /
23300V4361	M116 0/	23300Y0500	PM371 0/	B330M36A00EX	PM385 /
23300V4362	M116 0/	23300Y0501	PM371 0/	B330M54A01EX	PM265 /
23300V5302	PM516 0/	23300Y0510	PM371 0/	B330M70J00EX	M338 /
23300V7200	M336 0/	23300Y0511	PM371 0/	B330MD1700EX	PM372 /
23300V7260	M336 0/	23300Y0512	PM371 0/	B330MM8011EX	M320 /
23300V8200	M320 0/	23300Y0513	PM371 0/	B330MM8011EX	M320 /
23300VB300	M336 0/	23300Y0700	PM371 0/	B330MM8200EX	M320 /
23300VB3C0	M336 0/	23300Y0701	PM371 0/	B330MM8200EX	M320 /
23300W0400	PM371 0/	23300Y0702	PM405 0/	B330MM8502EX	M320 /
23300W0401	0/	23300Y0710	PM371 0/	B330MN5903EX	PM377 /
23300W0402	PM371 0/	23300Y0711	PM371 0/	B330MU6007EX	PM405 /
23300W0403	PM371 0/	23300Y0712	PM371 0/	B330MW1011EX	M374 /
23300W0410	PM371 0/	23300Y0713	PM371 0/	B330MY0701EX	PM405 /
23300W0411	PM371 0/	23300Y0714	PM371 0/		
23300W0412	PM371 0/	23300Y0715	PM371 0/		
23300W0413	PM371 0/	23300Y9700	M252 0/		
23300W0414	0/	23300Z5000	PM280 /		
23300W0415	0/	23300Z5005	PM280 /		
23300W0416	0/	23300Z5504	PM280 0/		
23300W0602	0/	23300Z5505	PM280 0/		
23300W0606	0/	23300Z5507	PM280 /		
23300W1000	M374 0/	23300Z5508	PM280 0/		
23300W1001	M374 0/	23300Z5509	PM280 0/		
23300W1002	M374 0/	23300Z5514	PM280 0/		
23300W1010	M374 0/	23300Z5515	PM280 0/		
23300W1011	M374 0/	23330001Y10	PM354 /		

OPEL	RMA \sqrt{Kw} -!	OPEL	RMA \sqrt{Kw} -!	OPEL	RMA \sqrt{Kw} -!
09000700	M143	1202004		1202102	
09000756	M143	1202005	M099	1202103	M094
09115190	M143X	1202006	M093	1202103	
09117031	M143	1202007	M094	1202104	M093
09117691	RM086	1202007		1202105	M093
09119796	M423	1202008	M096	1202108	
09119797	M344	1202009	M423X	1202109	M095
09119798	M314	1202010	M099	1202110	M095
09130838	M143	1202011	M143	1202113	M180
09133598	M143	1202013		1202118	M052
09163638	M421	1202013	M052	1202125	M099
09163850	M093	1202014	M423	1202125	
09163851	M180	1202015	M340	1202126	M095
09163853		1202016	M015	1202127	M143
09163854	M340	1202016		1202127	M143
09163856	M143	1202017	PM268	1202128	M143
09163858	M095	1202018	M064	1202129	M095
09163859	M064	1202019	M095	1202130	M099
09163860	M143	1202020	M095	1202131	M143
09193455	M052	1202021	M096	1202132	
09198701	M143	1202024	PM032	1202132	M094
09198701	M099X	1202026	M423	1202133	M093
09200961	M314	1202027	M180	1202134	M094
09200962	M385	1202028	M180	1202135	M093
09512040	M094	1202029	M314	1202136	M423
09512045	M093	1202030	M093	1202137	M143
09512046	M180	1202033	M344	1202138	M099X
09512048		1202034	M096	1202139	PM031
09512049	M340	1202035	M096	1202139	PM031
09512051	M143	1202036	M052	1202141	M037
09512053	M095	1202036		1202142	M143
09512054	M064	1202037	M094	1202143	M015
09512055	M143	1202040	M093	1202143	
09512152	M421	1202045	M015	1202144	M099X
09512269	M344	1202045		1202145	M314
09512270	M314	1202045		1202146	M423
09512277	M423	1202047	M094	1202147	PM268
09512420	M052	1202048	M162	1202148	M385
1202000	M099	1202048		1202149	M340
1202000	M095	1202049	M096	1202152	PM268
1202001	M095	1202049		1202154	PM277
1202001	M143	1202100	M096	1202156	M015
1202002	M095	1202101	M096	1202157	M421
1202002	M095	1202102	M094	1202158	M314

OPEL	RMA \sqrt{Kw} -!	OPEL	RMA \sqrt{Kw} -!	OPEL	RMA \sqrt{Kw} -!
1202159	M314	24406133	M143	4414332	PM239
1202160	PM459	24422258	RM086	4414402	PM239
1202161	M344	24422258	RM086	4502489	PM926
1202162	PM031	24422272	M314	4506175	PM240
1202163	PM268	24422273	M385	55351257	M143X
1202166	PM043	24436877	M143X	55351508	M143X
1202167	M340	24436877	M143X	55351608	M143X
1202168	M037	24437136	M143	55351608	M143X
1202169	PM032	24437136	M143	55351608	M143X
1202172	M143	24437136	M143	55351630	M385
1202173	M143	24454172	M037X	55351630	M385
1202174	M143	24454172	RM012	55351631	PM067
1202179	RM086	24454431	M385	55351631	PM067
1202184	PM268	24460703	PM068	55351638	M314
1202950	M094	24460703	PM068	55351638	M314
1202950		24460703	PM068	55353257	M143X
1202950		3471143	M094	6202000	PM641
1202950		3471150	M095	6202001	PM277
1202951	M096	3471154		6202004	RM093
1202952	M093	3471155	M180	6202006	PM068
1202953	M095	3471163	M094	6202008	M314
1202954	M180	3471165		6202009	M385
1202954		3471169	M143	6202011	M143
1202955		3471170		6202013	M143X
1202955		3471171	M094	6202014	M385
1202955		3471172	M095	6202016	M143
1202955	M180	3471173	M143	6202017	M037X
1202956	M052	3471174		6202020	M143X
1202956	M052	3471176		6202021	PM068
1202956		3471366	M095	6202039	M385
1202956		3471375		6202040	PM032
1202957	M096	3471377	M180	6202042	RM086
1202958	M099	3471381	M094	6202043	PM641
1202958		3471390	M094	6202046	
1202958		3471393	M095	6202047	PM031
1202959	M143	3471394	M180	6202048	PM043
1202960		3471395	M064	6202049	M143
1202961	M143	3471396	M052	6202050	M143X
1202962	M143	3471850		6202051	PM067
1202963	M094	3491190		6202052	PM068
1203002	M095	3771390		6202053	M314
12564088	RM093	4313543	PM459	6202054	M037X
24 454431	M385	4411195	PM239	6202060	M385
24406133	M143	4411319	PM240	6202061	M143X

OPEL	RMA $\sqrt{\text{Kw}} -!$	OPEL	RMA $\sqrt{\text{Kw}} -!$	OPEL	RMA $\sqrt{\text{Kw}} -!$
6202064	M143X	90337026		90508036	M143
6202066	M314	90337028	M143	90508037	M314
6202071	M143X	90337030	M052	90511841	M015
6202079	M143X	90341777	M143	90512188	M099X
6261061	M143X	90348290	M099	90512188	M099X
900019308		90348290		90512189	M314
90008257		90348290		90512467	M385
90008257		90348291	M095	90518627	M314
90008258		90348292	M064	90518628	M099X
90008258		90348292	M143	90518628	M099X
9000961	M314	90349285		90519331	M385
90019307	M096	90349285		90519332	
90019308	M094	90349285		90519332	
90019367	M096	90349352	M094	90535261	M143
90053962	M094	90349353	M093	90535261	M143
90055368	M180	90357730	PM031	9053962	
90055369	M052	90357730	PM031	90540586	M015
9007007	PM068	90371765	M314	90541527	PM031
9007007	PM068	90371766	M314	90541527	PM031
90091379		90371773	M421	90542411	M340
90091379	M095	90376895		90542417	M094
90093899	M064	90379385	PM032	90542532	PM032
90094133		90398044	M093	90542967	PM032
90094133	M095	90398044		90542967	PM032
900962	M385	90421121	M095	90543871	M143
90102212	M064	90421876	M095	90543872	M143
90140179	M180	90421877	M143	90563736	PM031
90166122	M052	90443488	M015	90563736	PM031
90175902	M143	90443488		90566073	PM032
90196710		90444192	PM031	90566073	PM032
90197192		90444192	PM031	90586910	RM086
90243160		90444193	M099X	90586916	RM086
90243160		90444193	M099X	90875582	M093
90246853	M143	90449689	M314	9110602	PM926
90272669		90451825	M314	9112221	PM240
90272669		90458462	M099X	9112233	PM240
90273370	M095	90458462	M099X	9115190	M143X
90273370		90465731	M037	9115192	
90273370	M095	90487345	M314	9115197	M143X
90277394		90487546	PM032	9115197	M143
90277933	M093	90490356		91154217	PM043
90277934	M099	90490771		91167270	PM239
90297846	M099	90490771		91167474	PM239
90337026	M094	90508036	M143	91167635	PM240

OPEL	RMA \sqrt{Kw} -!	OPEL	RMA \sqrt{Kw} -!	OPEL	RMA \sqrt{Kw} -!
9117031	M143	93174030	PM032	93184538	
9117031	M143	93174033	RM086	93184539	PM067
9117691	RM086	93174034	PM641	93186246	M143X
9119792	M423	93174202	PM240	93186246	M143X
9119793	M344	93174341	PM926	94332586	M340
9119794	M314	93174342	PM926	94371833	PM459
9120559	PM459	93175881		94386328	M423
9120560	PM268	93175882	PM031	94412142	PM459
9120561	PM268	93175883	PM043	94454891	M423X
9120565	PM268	93175884	M143	94469496	M333
9130838	M143	93175885	M143X	9512644	PM239
9133598	M143	93175886	PM067	9512655	M385
9146359	PM067	93175887	PM068	9512656	PM032
91463599	PM067	93175888	M314	9512658	RM086
9190838	M143	93175889	M037X	9512659	PM641
9198701	M143	93175899		9512668	PM240
9199321	M143X	93175900	PM031	9512675	PM926
9200610	PM067	93175902	M143	9512763	
9200890	PM068	93175903	M143X	9512764	PM031
9200960	RM086	93175904	PM067	9512765	PM043
9200960	RM086	93175905	PM068	9512766	M143
9200961	M314	93175906	M314	9512768	PM067
9200962	M385	93175907	M037X	9512769	PM068
9201825	PM240	93175996	M143X	9512770	M314
9224108		93175996	M143X	9512771	M037X
9224108	PM068	93176034	M385	97112549	PM268
93150902		93176034	M385	97117769	M340
93160655	PM239	93176034	M385	97117770	M423
93160667	PM240	93176051	M143X	97133369	M344
93171526	M385	93176051	M143X	97136688	PM277
93171936	M143X	93176051	M143X	97150203	M423
93171936	M143	93176056	PM067	97150204	M421
93171936	M143	93176056	PM067	97189118	PM641
93171945	M037X	93176061	M314	97255390	PM268
93171950	M143X	93176061	M314	R1540005	M385
93172020	PM068	93177175		R1540010	PM641
93172020	PM068	93178138	M143X		
93174002	PM239	93178167	M143		
93174017	M385	93178167	M143		
93174022	PM032	93184533	M143		
93174025	M143	93184534	M143		
93174027	RM086	93184535	M143X		
93174028	PM641	93184535	M143X		
93174029	M385	93184536	RM086		

P.RHONE=VA RMA $\frac{V}{Kw -!}$ P.RHONE=VA RMA $\frac{V}{Kw -!}$ P.RHONE=VA RMA $\frac{V}{Kw -!}$
LEO LEO LEO

PEUGEOT RMA $\sqrt{\text{Kw}} -!$

1475489080	PM094
493934	M067
494430	M067
5417601	
5426014	M078
5426014	M078
5426014	M078
5433495	M078
5433495	M078
5490011	
5490308	M078
5490308	M078
5490422	
5490926	M161
5491077	
5491077	
5491163	M067
5491163	M067
5491448	M078
5491448	M078
5491588	
555801	M010
555804	M079
555806	M179
555807	M010
555809	
555813	PM894
555818	M100
555821	M101
555832	M161
555833	M254
555836	M105
555838	M102
555840	M297
555845	M075X
555848	
555893	M010
555896	M156
558001	M010
558004	M079
558006	M179
558007	M010
558009	
558013	PM894

PEUGEOT RMA $\sqrt{\text{Kw}} -!$

558018	M100
558021	
558028	M075X
558033	M254
558040	M297
558093	M010
558096	M156
580193	M010
580193	
580201	M010
580204	M079
580206	M179
580207	M010
580208	M075X
580209	
580211	
580213	PM894
580214	M156
580215	M079
580216	
580218	M100
580221	
580222	M101
580223	
580226	M124X
580228	M075X
580233	M254
580236	M105
580238	M102
580238	
580239	M102
580240	M297
580242	M010
580243	M075X
580244	M179
580245	M075X
580245	
580246	M075X
580247	M124X
580248	
580250	M105
580250	M105
580252	M104
580253	M104

PEUGEOT RMA $\sqrt{\text{Kw}} -!$

580256	M010
580258	M100
580261	M079
580262	
580264	PM894
580265	M156
580266	M101
580267	M124X
580268	M075X
580270	M075X
580271	M161
580272	M254
580275	M104
580281	M010
580282	M010
580285	M157
580286	M075X
580287	M075X
580288	M102X
580289	M297
580289	M297X
580289	M297
580290	M124X
580291	M010
580292	M105
580293	M157
580297	M079
580298	M222
5802A0	M222
5802A2	PM248
5802A3	M156
5802A4	M254
5802A6	M105
5802A6	M105
5802A7	M297X
5802A8	PM024
5802A9	PM024
5802A9	PM024
5802A9	PM024
5802AQ	RM017
5802AS	RM014
5802C0	M102X
5802C0	M102X
5802C1	M102X

PEUGEOT	RMA $\sqrt{\text{Kw}} -!$	PEUGEOT	RMA $\sqrt{\text{Kw}} -!$	PEUGEOT	RMA $\sqrt{\text{Kw}} -!$
5802C1	M102X	5802F9	M102X	5802M6	
5802C2	M222	5802F9	M102X	5802M6	PM028
5802C3	M105	5802G0	M105	5802M9	M222
5802C4	M105*	5802G2	M195	5802M9	M222
5802C4	M105	5802G4		5802N0	M222
5802C5	RM029	5802G9	M105	5802N2	M222
5802C9	M222	5802H3	PM028	5802N3	M222
5802E0	PM024	5802H4	M102X	5802N4	PM233
5802E1	M102X	5802H5	PM094	5802N7	M067
5802E1	M102X	5802H6	PM094	5802P3	M102
5802E1	M102X	5802H7	M105*	5802P4	M075X
5802E2	M105	5802H8	M105	5802P5	M010
5802E2	M105	5802H9	M102X	5802P6	M124X
5802E2	M105	5802J0	M102X	5802P7	M157
5802E2	M105	5802J1	M222	5802P8	M222
5802E3	M228	5802J2	PM024	5802Q0	PM024
5802E3	M228	5802J4	M105	5802Q1	M222
5802E4	M102X	5802J5	M195	5802Q2	M102X
5802E4	M102X	5802J6	M010	5802Q3	M195
5802E5	M102X	5802J8	M100	5802Q4	M078
5802E5	M102X	5802J9	M079	5802Q7	M391
5802E5	M102X	5802K1	PM894	5802Q9	M391
5802E5	M102X	5802K2	M156	5802R8	M200
5802E6	PM028	5802K3	M101	5802V4	M284
5802E6	PM028	5802K4	M124X	5802V4	M284
5802E6	M382	5802K5	M075X	5802V7	PM243
5802E6	PM028	5802K6	M161	5802V9	
5802E7	M176	5802K7	M254	5802W0	
5802E8	M222	5802K8	M104	5802W5	M390
5802E9	M195	5802K8	M104	5802W5	
5802E9	M195	5802K9		5802W5	
5802F0	M102X	5802L0	M102	5802W6	PM897
5802F0	M102X	5802L1	M297X	5802W7	PM094
5802F1	PM028	5802L2	M124X	5802W7	
5802F3	M195	5802L3	M010	5802W8	M390
5802F5	M102X	5802L3	M010	5802Y4	PM899
5802F5	M102X	5802L4	M105	5802Y9	M400
5802F5	M102X	5802L5	M157	5802Z0	PM102
5802F6	PM094	5802L7		68656488	PM024
5802F6	PM094	5802L9	M195	75491453	M067
5802F6	PM094	5802M0	M195	75491615	
5802F6	PM094	5802M3	M105	75491623	
5802F7	PM094	5802M4	M105	75491668	
5802F7	PM094	5802M5	PM094	75491723	M078

PEUGEOT	RMA $\sqrt{\text{Kw}} -!$	PEUGEOT	RMA $\sqrt{\text{Kw}} -!$	PEUGEOT	RMA $\sqrt{\text{Kw}} -!$
75492269		91508525	M102	95495248	
75492472	M067	91508644		95495299	M161
75492566	M078	9150864480	M102	95495509	
75492638		9150864480		95495849	M157
77000705204	M075X	9150864580	M102	95496952	
7700705204	M075X	9151058680	M100	95508644	M102
7700705204	M075X	9151082480		95514125	M105
7702105793	M075X	915113080		95536160	M275
7910004942	M010	9151139080	M010	95580161	M078
7910014193	M179	9151394980	M075X	95580164	M075X
7910014193		9151394980	M075X	95580164	M075X
7910014194	M179	91514125	M105	95580165	
7910014194		91514125	M105	95580166	M067
7910014197	M075X	91514245	M075X	95580167	M075X
7910014197	M075X	9151431280	M105	95580171	M275
7910014197	M075X	9151789380	M100	95580174	
7910014198	M075X	9151798380		95580180	M161
7910014198	M075X	91518794	M075X	95580181	M161
7910014198	M075X	91518794	M075X	95580182	
7910027938	M010	91520222	M075X	95580183	M124X
7910027938		9152063180	M010	95583854	M157
7910245613		91521310	M276	95583854	M157
7910246983		91535130	M075X	9558385480	M157
7932567913	M101	91535771	M157	9558385480	M157
9 1514245		91536044	M105	95591701	M156
91040098	M105	91536044	M105	95607229	M102
91040098	M105	91536044	M105	95607230	M075X
91040098	M105	91536241	M222	95607233	M010
91040098	M105	9153624180		95607234	M105
91040098	M105	91536242	M222	95619181	M161
9104009880	M105	95041033	M102X	95619195	M124X
9150136780	M100	95155198		95619196	M276
9150136780		95492868	M067	95619197	M157
9150457580		95493014	M161	95624960	
9150475180	M010	95493072	M161	95643763	M275
9150475180	M010	95493097		95656487	M102X
9150516480	M079	95493129		95656487	M102X
915074477		95493159	M156	95656488	PM024
91507477	M102	95493755		95656488	PM024
9150747780	M102	95493934	M067	95656489	M105X
91507478	M102	95494247	M078	95656490	M195
9150747880		95494263		95658487	M102X
9150803080	M254	95494430	M067	95667752	
91508524	M102	95495248		95667753	

PEUGEOT RMA $\sqrt{\text{Kw}} -!$

95667754	M102X
95667755	M176
9600282180	
96014184	M102X
96017849	M195
96017849	M195
96024261	M275
96028857	
96035033	M102X
96035034	M102X
96035034	M102X
96035035	M105
96035035	M105X
96035035	M105
96035036	M105X
9604831	RM029
96052193	
96052193	M222
9605219380	
9605219380	M222
96054384	M105
96054384	M105
96079833	PM028
96079834	PM028
96079834	PM028
96087192	
9608719280	
96087193	M195
96087193	M195
96087193	M195
96087193	M195
96092340	PM024
96092340	PM024
96092340	PM024
96092384	M102X
96092384	PM024
96092384	PM029
96092384	M102X
96092384	PM024
96093132	
96093132	M222
9609313280	M222
96095132	
96102058	M102X

PEUGEOT RMA $\sqrt{\text{Kw}} -!$

9610205880	
96125588	M105X
9613015980	M102X
96130225	M195
96130225	M102X
96130225	M195
96130225	M102X
9613022580	M102X
9613022580	M102X
9614592	M102X
96147592	M102X
96147592	M102X
96147592	M102X
96155198	M102X
96155198	
96155198	M102X
9615519880	RM083
96251686	RM084
9625168680	M102X
9625168680	
96253824	PM094
9625382480	PM094
96253825	M390
96253825	M390
96253825	
96253825	
96262614	M391
9626261480	M391
9626261480	PM157
96288707	M195
96288707	M195
96325689	M120X
9633292480	M222
96343143	M102X
96343143	M102X
96356597	PM094
96356597	
96365597	PM094
96365597	
96398467	PM094
96398467	
9640825280	PM899
96481116	
96481116	

PEUGEOT RMA $\sqrt{\text{Kw}} -!$

9751377680	M104
97517545	M104
97530824	
97530824	M222
GX0610501B	
GX0610501BR	
GX0610502A	
GX0610502AR	
ND53301A	PM181
V7540897	RM001

R.M.A

RMA $\frac{V}{Kw -!}$

R.M.A

RMA $\frac{V}{Kw -!}$

R.M.A

RMA $\frac{V}{Kw -!}$

PM529

M175

R.M.A.	RMA $\sqrt{\frac{V}{Kw}}$ -!	R.M.A.	RMA $\sqrt{\frac{V}{Kw}}$ -!	R.M.A.	RMA $\sqrt{\frac{V}{Kw}}$ -!
M450	M401				
PM041	M384				
PM060	PM013				
PM086	M066X				
PM101	PM099				
PM208	PM204				
PM212	PM204				
PM214	PM190				
PM220	PM216				
PM228	PM027				
PM298X	M427X				
PM303	M401				
PM320	PM122				
PM338	M429X				
PM382	M374				
PM418	M370				
PM439	PM466				
PM451	PM416				
PM478	PM364				
PM483	PM419				
PM484	M335X				
PM486	M428X				
PM515	M374				
PM525	M252				

RENAULT	RMA $\sqrt{\text{Kw}} -!$	RENAULT	RMA $\sqrt{\text{Kw}} -!$	RENAULT	RMA $\sqrt{\text{Kw}} -!$
0000431120	M017	5000789048	PM184	5010090371	PM120
0000431120		5000789304	PM145	5010090683	PM108
0000434120	M017	5000791210	PM171	5010090684	PM120
0000434120		5000791210	PM171	5010090911	PM171
0025841022	PM184	5000791211	PM108	5010090911	PM171
0025841025	PM184	5000791383	PM215	5010096027	PM215
0025841042	PM120	5000793515	PM215	5010115452	RM032
0025841044	PM108	5000804191	PM206	5010217215	PM192
0028115048		5000804191	PM206	5010217215	PM192
0028115089	PM215	5000806878	PM189	5010217532	
0122946900	RM035	5000811448	PM223	5010217950	
0325339011	PM181	5000816041	PM189	5010217956	RM088
0855159400		5000816041	PM189	5010306143	PM108
0855787900		5000820624	PM145	5010306412	PM589
5000041221		5000822346	PM204	5010306413	
5000049122	PM127	5000822346	PM204	5010306413	PM108
5000049124	PM120	5001000061	PM204	5010306533	PM760
5000049532	PM127	5001000061	PM204	5010306777	PM215
5000049532	PM127	5001000127	PM184	5010306910	PM215
5000080750	PM184	5001000127	PM184	5010508443	PM108
5000082919		5001014187	PM120	5010559682	RM033
5000084535	PM127	5001014196	PM215	51262017042	PM206
5000084765	PM145	5001014200		5171736000	
5000094406	PM145	5001014203	PM184	5172369500	
5000138298	RM031	5001014209	PM247	5830000132	PM215
5000138533		5001014215	PM184	5830000632	PM215
5000241737	RM036	5001014221	PM108	6000102270	PM122
5000241777	PM189	5001014227	PM215	6000102394	PM122
5000242222		5001014230	M246	6001040105	M120X
5000270909	PM191	5001014233	PM145	6005003155	PM122
5000270909		5001014236	PM127	6005003156	PM122
5000383929	PM165	5001822955	RM092	6005007548	PM224
5000393154	PM247	5001823247	PM127	6005011729	
5000499961	PM120	5001825905		6005016395	PM122
5000559254		5001831086		6005700082	PM224
5000559361	PM120	5001831090	RM088	6005701125	
5000589041	PM111	5001853707	PM215	6021330030	
5000592182	PM184	5001853710	PM215	700859823	PM092
5000612741	PM247	5010050904	PM215	700859823	PM092
5000683929	PM165	5010058895	PM171	700860915	M415
5000785288	PM215	5010058895	PM171	700865719	M017X
5000785288	PM215	5010058895	PM171	700866505	M120X
5000785288	PM215	5010058981	RM090	700868184	M246
5000789048	PM184	5010090370	PM108	7700026780	PM149

RENAULT	RMA $\sqrt{\text{Kw -!}}$	RENAULT	RMA $\sqrt{\text{Kw -!}}$	RENAULT	RMA $\sqrt{\text{Kw -!}}$
7700026780	PM149	7700352049	M017X	7700750305	M119X
7700046893		7700377051		7700750306	M192
7700100647	M017X	7700377051	PM099	7700751200	M029
7700102000	M262	7700501670		7700751495	M280
7700102800	M120X	7700509355	M119X	7700757741	M215
7700102800	M120X	7700509855	M119X	7700758172	M029
7700103386	M262	7700519797	PM149	7700758217	M017
7700103386	M262	7700525064		7700759283	M124X
7700104344	PM234	7700525547	PM126	7700759289	M124X
7700104346	PM093	7700543483	M119X	7700759861	PM251
7700104674	PM237	7700561416	PM908	7700761416	M120X
7700105080	M017X	7700569256	M119	7700764429	M121X
7700105080	M017X	7700569257	M119	7700777478	M120X
7700106209	M120X	7700572689	M192	7700796488	M017X
7700106426	M120X	7700621108	M021	7700851490	M215
7700106426	M415	7700621302	PM908	7700851491	M124X
7700106426	M415	7700622528	M075X	7700852853	M120X
7700106763	M415	7700622529	M075X	7700853827	M017X
7700113207	M415	7700622748	M021	7700854954	M415
7700113208	M415	7700622951	M119	7700854955	M017X
7700113209	M120X	7700625428	M124X	7700856260	M417
7700113227	M415	7700633995	M021	7700856291	PM056
7700113227	M120X	7700638420	M119	7700857114	M419
7700113622	PM239	7700650287	M192	7700857114	M419
7700113627	M415	7700665613	M121X	7700858114	PM093
7700114428	M200X	7700669221	M021	7700858375	PM093
7700114428	M200	7700680639	M021	7700858442	M017E
7700115294		7700681068	M084X	7700858442	M017E
7700115294	PM010	7700694096	M119X	7700859823	PM092
7700116260	PM239	7700703490		7700860915	M415
7700116282	PM246	7700703490	M017	7700861013	M120X
7700260505	M280	7700705204		7700862838	PM251
7700260710	PM251	7700705204	M075X	7700864608	M319
7700268275	M280	7700709922		7700864634	M120X
7700272482	M202	7700709922	M021	7700865213	M120X
7700273783	M430	7700715102	M124X	7700865719	M017X
7700274178	M430	7700723189	M246	7700865985	M416
7700274303	M430	7700723189	M246	7700866505	M120X
7700274351	M430	7700730756	M246	7700866785	PM251
7700300501	PM251	7700730756	M246	7700867631	M417
7700301993	M246	7700735712	M120X	7700868184	M246
7700301993	M246	7700740076	M124X	7700870951	M417
7700313447	PM235	7700747741	M215	7700871055	PM254
7700315522	PM926	7700749770	M280	7700871057	M017X

RENAULT RMA $\sqrt{\text{Kw}} -!$

7700872450	PM010
7700875450	PM010
7701003914	
7701019038	PM111
7701019590	
7701024176	
7701024176	M021
7701028780	PM224
7701030289	PM224
7701348278	M084X
7701348343	M075X
7701348482	M124X
7701348605	
7701348605	M021
7701348746	PM908
7701348805	M021
7701348880	
7701348880	M075X
7701348964	M119
7701349264	
7701349264	M017
7701349265	
7701349265	M017
7701349542	
7701349542	M021
7701349588	M084X
7701349591	M192
7701351026	M121X
7701351027	M017
7701351120	M280
7701351390	M017X
7701351391	M120X
7701351392	M120X
7701351393	PM908
7701351394	M119X
7701351395	M075X
7701351396	M029
7701351397	M084X
7701351398	M124X
7701351523	M119X
7701351772	M017X
7701351794	M120X
7701352049	M017X
7701352050	M415

RENAULT RMA $\sqrt{\text{Kw}} -!$

7701352055	M121
7701352126	M417
7701352210	M017E
7701352256	PM092
7701352305	PM251
7701352350	M415
7701353827	M017X
7701381629	PM247
7701381632	PM908
7701381633	M119X
7701381640	M280
7701381644	M121X
7701381647	M246
7701449651	M319
7701499199	PM908
7701499200	M119
7701499201	M075X
7701499202	M021
7701499219	M084X
7701499220	M124X
7701499229	M120X
7701499232	M280
7701499233	M124X
7701499234	M124X
7701499246	M121X
7701499247	M017
7701499468	M119X
7701499478	M280
7701499479	M124X
7701499480	M124X
7701499482	M202
7701499484	M029
7701499484	M084X
7701499545	M419
7701499601	M120X
7701499616	RM096
7701499648	M075X
7701499649	M119X
7701853827	M017X
7702004621	M119
7702007262	M119
7702046211	M119
7702082972	M017E
7702102137	M119

RENAULT RMA $\sqrt{\text{Kw}} -!$

7702106485	
7702111083	M119
7702146495	M120X
7702180318	
7702180318	M017
7708758173	M029
7709758174	
7709758174	M017
7711134302	
7711134530	PM237
7711134794	PM012
8200018818	PM240
8200021396	PM710
8200049826	PM237
8200050150	PM010
8200050150	PM010
8200054336	PM239
8200064465	PM239
8200069377	PM012
8200069377	PM012
8200075362	PM239
8200082782	PM237
8200106788	PM240
8200130624	PM240
8200182178	PM912
8200186144	PM010
8200186144	PM010
8200186144	PM010
8200186148	PM012
8200186148	PM012
8200199737	PM539
8200227092	PM710
8200331251	PM239
8200369521	M319
8200466744	PM010
8200466754	PM012
8200466754	PM012
8200466761	PM010
8200466763	M120X
8200466763	M120X
820053977	PM897
8953002125	
8953002577	M121X
9627267180	PM233

MOTORINI

RENAULT

RENAULT **RMA** $\sqrt{V/Kw -!}$

RENAULT **RMA** $\sqrt{V/Kw -!}$

RENAULT **RMA** $\sqrt{V/Kw -!}$

DM2120	
DM2130	M074
DM2134	M074
DM2138*	M091
DM2140	
DM2140	
DM92140	M119

ROVER	RMA $\sqrt{\text{Kw}} -!$	ROVER	RMA $\sqrt{\text{Kw}} -!$	ROVER	RMA $\sqrt{\text{Kw}} -!$
1489994		GEU4445	PM598	NAD100380	PM044 0
1489994		GEU4527	M308	NAD100390	M277 0
1489995		GEU4529	M308	NAD100390	M277
1489995	PM538	GEU463	0	NAD100390	M277X
ADU1233	0	GNU4538	M111	NAD100400	PM029 0
ADU1239	M318	GNU4541	M223	NAD100410	M223 0
ADU1595	M406 0	GNU4542	M318	NAD100420	M223 0
ADU4417	0	GNU4558	PM454	NAD10046	M263
ADU7406	0	GNU4563	M406	NAD100480	PM044
ADU7408	0	GNU4595	M223	NAD100480	M263 0
ADU7457	0	GNU4607	M406	NAD10050	M223X
ADU8919	M308 0	GNU4608	M406	NAD100580	PM454 0
ADU8993	0	GNU4611	M223	NAD100740	M406 0
ADU9356	M106 0	GNU4737	PM289	NAD100750	M406 0
ADU9357	M106 0	GNU4771	M223X	NAD100790	PM499 0
ADU9362	M223 0	GNU4773	M427	NAD101070	M406 0
ADU9363	M223 0	GNU4814	M406 0	NAD101080	M406
ADU9537	0	GNU4820	PM288	NAD10119	PM044 0
ADU9703	M308 0	GNU4900	M406	NAD101190	PM044
ADU9800	M308 0	GXE4441	PM686	NAD101190	PM044 0
ADU9801	M308 0	GXE4527	M308	NAD101240	PM242
ADZ91211	PM268	GXE4529	M308	NAD101260	M406 0
AMR2165	RM007 0	GXE4534	M223	NAD101260	M406
AUU1140	0	GXE4541	M223	NAD101340	PM543
AUU1233	0	GXE4542	M318	NAD101340	PM543 0
AUU1237	0	GXE4558	PM454	NAD101470	PM011 0
AUU1239	0	GXE4585	M308	NAD101471	
AUU1595	M406 0	GXE4595	M223	NAD101471	PM011 0
DRC2418	0	GXE4596	M318	NAD101481	
ERR5009	M277	GXE9445	PM598	NAD101481	M421 0
ERR5009	M277X 0	GXE9464		NAD101490	PM044
ERR5009	M277	NA500220	PM583	NAD101490	PM044 0
ERR5021	PM583 0	NAD000130	PM583	NAD50021	M277
ERR5445	M037 0	NAD000200	M406	PRC3032	M277 0
ERR5693	M244 0	NAD100010	M223	PRC5658	PM044 0
ERR5693	RM019	NAD100020	M223	PRC5669	M288 0
ERR6087	PM044	NAD100030	M223X	PRC5669	M288
ERR6087	PM044 0	NAD100110	M223	PRC6578	PM044 0
ESR2191	PM044 0	NAD10022	0	PRC6613N	PM029
ESR2192	PM044	NAD100300	M223 0	PRC6613N	PM029
ESR52192	PM044 0	NAD100330	M406 0	RTC5225	0
GEU420	0	NAD100340	M406 0	RTC5228	PM044 0
GEU441	PM686	NAD100370	M037 0	RTC5249	M277 0
GEU4441	PM686	NAD100380	PM044	RTC6061N	M305

S1334 RMA $v \diagup$ Kw -! S1334 RMA $v \diagup$ Kw -! S1334 RMA $v \diagup$ Kw -!

0001106001 M111 0

SKODA

RMA $\sqrt{\text{Kw}} -!$

SKODA

RMA $\sqrt{\text{Kw}} -!$

SKODA

RMA $\sqrt{\text{Kw}} -!$

02914207	M293	$\sqrt{12}$ 0,8
02T911023C	PM081	$\sqrt{0}$
09914207	M293	$\sqrt{12}$ 0,8
11490400	M293	$\sqrt{12}$ 0,8
441040092196	PM076	$\sqrt{0}$
441040092206		$\sqrt{\quad}$
441040092206	PM076	$\sqrt{\quad}$
441040092206	PM076	$\sqrt{0}$
443115142071	M293	$\sqrt{12}$ 0,8
443115142110	M293	$\sqrt{12}$ 0,8
443115142112	M293	$\sqrt{12}$ 0,8
6U0911023A	PM076	$\sqrt{\quad}$
6U0911023B	PM684	$\sqrt{\quad}$

SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$
11111	M013	11151	M203	11204	M039
11111	M013X	11151	M118	11205	M048
11112	M012	11151	M070	11206	
11113	M040	11153	M105X	11208	M053
11114	M025	11153	M105	11209	M048X
11115	M182	11154	M102	11209	M045
11116	M057	11154	M102X	11211	M097
11118	M065	11156	M161	11213	M047
11119	M109	11157	M078	11214	M011
11120	M024	11158	M067	11215	M032
11120	M016	11159	M275	11216	
11122	M063	11161	M075X	11217	M026
11124	M024	11162	PM024	11218	M283
11124	M148	11163	M102X	11218	M023
11124	M068	11164	M105X	11218	M131
11126		11164	M105*	11219	M035
11127	M069X	11166	PM248	11221	M114
11128	M145	11169	M074	11223	M296
11128	M107	11169	M176	11223	M285
11128	M149	11169	M222	11224	M295
11128	M034	11170	M124	11226	M153
11128	M149	11170	M215	11227	M254
11128	M108	11170	M124X	11228	M214
11129	M258	11171	M117	11228	M264
11130	M112	11172	M010	11229	M043
11130	M227	11173	M010	11229	M030
11131	M115	11174		11229	M159
11132		11178	M104	11230	M260
11134	M116	11179	M075X	11231	M138
11135	M308	11179	M075	11231	M137
11139		11180	M195	11231	M136
11140		11191		11231	M082
11142	M033X	11192	PM780	11231	M076
11142	M033	11193	PM603	11232	M214
11143	M056	11194	PM600	11234	M138
11144	M072	11195	M127	11234	M082
11144	M158	11196	PM424	11234	M134
11146	M038	11198	M301	11234	M137
11147	M073	11199	M046	11234	M076
11148	M037	11200	M018	11235	M043
11150	M196	11201	M270	11236	M152
11150	M118	11202	M166	11237	M049
11150	M070	11203	M061	11238	M243
11150	M118	11203	M166	11241	M263

SO.CO.	RMA \sqrt{Kw} -!	SO.CO.	RMA \sqrt{Kw} -!	SO.CO.	RMA \sqrt{Kw} -!
11243	M082	11298	PM526	11344	M077
11243	M081	11299	PM369	11344	M192
11245	M128	11300	PM405	11344	M119X
11247	PM293	11301	PM371	11346	PM908
11247	M128	11302	M424	11348	M017X
11249	M425X	11303	M424	11348	M017
11250	RM039	11306	M094	11348	M202
11255		11307	M095	11349	M120X
11256	M044	11307	M143	11350	M021
11258	M044	11307	M067	11353	M280
11259	M174	11308	M052	11354	M084
11259	M096	11309	M015X	11354	M084X
11260	M150	11309	M052	11355	M346
11260	M248	11309	M015	11355	M121X
11260	M111	11310	M180	11356	M088
11261		11311	M099	11357	M120
11262		11312		11357	M120X
11264	M277	11313	M096	11358	M124X
11264	M277X	11314	M162	11361	M121
11265	PM402	11315	M093	11361	M121X
11266	PM370	11316	M064	11362	M029
11268	PM408	11321		11363	M192
11272	M129	11322		11363	M119X
11273	M433	11323		11365	M237
11274	PM370	11324	M100	11366	M041
11275	M087	11325	M297X	11367	M033
11275	M140	11325	M297	11367	M270
11276	M083X	11326		11367	M055
11276	M083	11327	M103	11368	M077
11277	M088X	11328		11368	M293
11277	M088	11330	M101	11369	PM351
11278	PM088	11331	M079	11370	M330
11279	M165	11332	M070	11380	PM443
11279	M164	11332	M072	11381	M439
11284	M216	11332	M072	11387	PM415
11285	PM051	11332	M299	11392	PM434
11286	PM446	11333	M278	11393	PM431
11289	PM403	11335	M276	11393	PM431
11290	PM380	11336		11397	M251
11293	M425X	11337	M109	11398	M014
11294	M028	11338		11400	
11295	PM372	11339	PM020	11402	M106
11296	M320	11341		11403	M031
11297	PM377	11344	M119	11405	M034

SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$
11405	M149	11475	PM405	11539	
11405	M108	11476	PM643	11540	M156
11405	M107	11478		11546	
11405	M145	11481	M252	11550	M064
11406	M440	11481	M314	11562	M327
11406	M102X	11482	PM273	11566	
11407	M218	11483	PM327	11571	M305
11408	M022	11486	PM512	11574	M376
11409	M238	11487	PM425	11588	M215
11410	M089	11488	PM785	11590	M021
11411	M051	11490	PM778	11593	PM432
11414		11494	PM419	11595	
11415		11495	PM600	11597	M193
11420	M172	11496	M325X	11608	PM335
11423	M066X	11496	M325	11611	M223
11423	M066	11497	M200	11617	M058
11424	M240	11498	PM796	11618	PM379
11427	M113X	11498	PM796	11619	PM455
11427	M113	11501	M151	11625	M222
11428	M110	11502	PM435	11625	M195
11430	M051	11503	PM423	11627	M062
11431		11504	PM602	11630	PM433
11433	M059	11506	PM437	11633	PM410
11435	M197	11508	M446	11634	PM523
11437	M027	11509	M334X	11635	PM287
11438	PM247	11510	M095	11636	PM381
11439	M246	11510	M143	11637	PM282
11444	M250	11511	M211	11639	M390
11447	M308	11513	PM787	11639	M105
11448	RM094	11514	PM788	11640	M175
11452	PM444	11514	PM351	11643	M228
11455	PM459	11515	M118	11646	PM429
11456	PM283	11515	M070	11647	PM454
11457	M432	11515	M203	11648	M213
11459	M194	11517	M172	11651	M406
11462	PM400	11518	M219	11652	M305
11467	M425	11520	M283	11653	M027X
11467	M425X	11520	M131	11654	PM684
11468	M341	11525	M120X	11655	PM050
11469	PM407	11527	M202	11656	M191
11470	PM384	11527	M017X	11656	M306
11471	PM281	11531	M257	11658	M375
11473	PM272	11533	M297X	11659	M299X
11474	M434	11534	M157	11660	M185

SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$
11662	M261	11701	M227	11743	PM609
11663	M260	11702	PM036	11744	PM401
11663	M190	11703	M255	11745	PM365
11664	M244	11703	M034	11746	PM274
11666	M423	11704	M431	11747	M374
11666	M423X	11705	M338	11748	PM268
11667	M239	11706	M236	11749	PM464
11668	M334	11707	PM252	11750	PM376
11669	M176	11708	PM466	11751	M437
11670	M417	11709	PM456	11752	M284
11671	M013X	11710	M426	11753	PM298
11672	M214	11711	PM383	11753	M427
11672	M307	11712	PM385	11754	M336
11673	M261	11713	PM555	11755	M428X
11674	M017E	11714		11756	PM336
11675	PM251	11715		11757	PM364
11676	PM023	11716	M089	11758	PM458
11677	PM049	11717	M392	11759	PM430
11678	M271	11718	M256	11760	PM299
11679	M265	11719	M394	11761	M337
11679	M268	11719	M396	11762	PM461
11680	M362	11720	PM062	11763	M255
11680	M283	11720	PM065	11764	PM052
11681	M269	11721	PM558	11765	PM357
11682	M058X	11722	M386	11766	PM516
11684	M048X	11723	M282	11767	PM521
11685	M340	11724		11768	M314
11686	PM249	11725		11769	PM094
11687	M235X	11728	M370	11770	M404
11688	M289X	11729	PM623	11772	PM089
11688	M282	11730	PM459	11773	M243
11688	M313	11731	M441	11774	M185
11688	M289	11732	M336X	11774	M185X
11689	PM517	11733	PM445	11775	M403
11690	M306	11734	PM676	11776	PM026
11691	M099	11735	PM465	11777	M255
11691	M099X	11736	PM459	11778	M317
11692	PM274	11737	M442	11780	PM499
11693	PM359	11738	PM015	11781	PM527
11694	M318	11739	PM469	11781	PM373
11697	M313	11740	PM296	11782	M328
11698	M343	11741	M325X	11783	PM092
11699	M304	11742	M440	11784	PM270
11700	M333	11742	M428	11785	M128X

SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$
11786	M419	11838	M310	11885	M408
11787	M420	11839	M150	11886	PM082
11788	PM233	11839	M111	11887	PM566
11790	PM058	11839	M248	11888	PM083
11791	PM031	11841	M399	11891	M447
11793	PM277	11842		11892	PM343
11794	M402	11843	PM397	11892	PM366
11796	PM057	11843	M193	11893	PM513
11797	M319	11844	PM466	11894	PM522
11798	M311	11845	M383	11895	M409
11799	M381	11846	PM022	11896	PM491
11800	M335	11848	PM236	11899	PM027
11801	PM684	11849	PM473	11900	M429
11802	PM076	11850	PM535	11902	PM496
11803	M416	11851		11903	
11804	PM093	11853	M414	11904	PM069
11805	M396	11854	M400	11907	PM254
11806	M315	11856	M391	11909	PM087
11807	M387	11857	M385	11910	PM099
11808	M384	11859	PM037	11911	PM073
11809	M083X	11860	PM063	11912	PM080
11810	M405	11861	PM498	11913	PM641
11811	M421	11861	PM017	11914	PM010
11813	M328	11862	M388	11915	PM012
11814	M443	11864	PM477	11915	PM539
11817	PM231	11865	PM479	11916	PM235
11818	PM341	11867	PM362	11917	
11819	PM354	11868	PM070	11918	PM043
11820	PM324	11871	PM237	11920	PM243
11821		11874	PM032	11922	PM239
11823	PM055	11875	PM394	11923	PM240
11824	M336X	11876	PM398	11928	M430
11825	M444	11879	M397	11931	M393
11827	PM353	11879	PM095	11934	PM097
11828	M345	11880	PM454	11935	PM042
11829	PM355	11880	PM454	11936	PM045
11829	PM355	11881	PM044	11937	PM066
11831	PM487	11883	M408	11938	PM100
11833	M412	11883	M268	11939	PM072
11834	PM265	11883	PM305	11940	PM081
11835	PM518	11883	M401	11941	M397
11836	PM253	11883	M401	11942	PM244
11837	M352	11883	M401	11943	PM034
11838	PM091	11884	PM071	11944	PM258

SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$	SO.CO.	RMA $\sqrt{\text{Kw}} -!$
11945	M395	33399		33532	PM207
11946	PM242	33401	M253	33533	PM210
11947	M410	33403	PM128	33545	M054
11948	PM241	33404	PM141	33546	PM198
11949	PM229	33406	PM139	33550	PM164
11950	PM605	33408	PM120	33552	PM132
11951	PM288	33409		33555	PM223
11953	PM013	33413	M010	33573	PM161
11954	PM301	33413	PM333	33576	PM215
11955	RM086	33416	M091	33578	PM115
11956	RM093	33418	PM121	33582	PM195
11961	PM710	33419	PM184	33595	PM181
11963	PM912	33420	PM149	33596	PM202
11967	PM918	33421	PM148	33596	PM194
33333	PM156	33430		33599	PM190
33334	PM122	33432	PM108	33599	
33335	PM137	33436	PM134	33606	PM192
33340	PM135	33437	PM130	33621	PM779
33341	PM150	33440	PM193	33629	PM226
33342	M091	33452	M059	33631	PM199
33342	PM150	33453	PM167	33649	PM203
33345	PM155	33455	PM118	33696	PM121
33346	PM191	33457	PM204	33723	PM124
33349	PM138	33457	PM204	33726	PM747
33355	PM188	33457	PM204	33729	PM420
33357		33459	PM189	33736	M277
33358	PM106	33459	PM127	33736	M277X
33358	PM106	33461	PM119	33755	PM395
33364	PM689	33473	PM691	33765	PM271
33367	RM096	33475	PM224	33783	PM162
33368	PM158	33478		33786	M044
33370	PM123	33503		33799	M288
33375	PM125	33505		33806	PM391
33376	PM206	33507	PM192	33809	M445
33377	PM192	33513	PM149	33818	PM764
33379	M294	33515	PM753	33824	PM426
33380	PM147	33516	PM621	33825	M247
33385	PM752	33517	PM213	33834	M309
33388		33518	PM136	33861	PM263
33391	M214	33521	PM162	33869	PM436
33391	PM129	33524	PM143	33870	PM427
33394	PM645	33525	PM110	33871	PM421
33395	PM334	33530	PM190	33873	PM644
33396	PM688	33531	PM202	33874	PM255

SO.CO.	RMA \sqrt{Kw} -!	SO.CO.	RMA \sqrt{Kw} -!	SO.CO.	RMA \sqrt{Kw} -!
33875					
33876					
33880	PM409				
33882	PM751				
33883	PM389				
33885	PM176				
33890	PM770				
33895	PM216				
33897	PM170				
33898	PM140				
33899	PM169				
33901	PM404				
33904	PM218				
33905					
33906	PM159				
33907	PM599				
33908	PM627				
33910	PM396				
33912	PM157				
33913	PM197				
33915	PM690				
33917	PM368				
33918	PM457				
33919	PM447				
33921	PM422				
33922	PM824				
33923	PM450				
33924	PM180				
33927	PM378				
33929	PM279				
33930	PM386				
33931	PM416				
33938	PM428				
33939	PM448				
33943	PM103				
33946	PM217				
33947	PM105				

MOTORINI

SUBARU

SUBARU **RMA** $\frac{V}{Kw -!}$

2107050200	PM619 /
2107050210	PM619 /
23300AA000	PM788 0 /
23300AA010	PM351 0 /
23300AA020	PM364 0 /
23300AA030	PM788 0 /
23300AA031	PM788 0 /
23300AA040	PM351 0 /
23300AA050	PM364 0 /
23300AA100	M211 12 0,8 /
23300AA180	PM351 0 /
23300AA190	PM364 0 /
23300AA200	M437 0 /
23300AA210	PM364 0 /
23300AA220	M437 0 /
23300AA221	M437 0 /
23300AA230	PM364 0 /
23300AA270	M437 0 /
23300AA280	M437 0 /
23300AA300	PM364 0 /
23300AA351	PM703 /
23300AA380	M437 0 /
23300AA381	M437 /
23300AA390	PM364 0 /
23300KA010	M442 0 /
23300KA020	M442 0 /
23300KA030	M211 12 0,8 /
23300KA031	M211 12 0,8 /
23300KA032	M211 0 /
23300KA040	M211 0 /
23300KA100	M211 /
23300KA120	M442 /
23300KA120	M442 0 /
23300KA140	M442 0 /
23300KA190	M442 0 /
23300KA210	M442 /
23300KA210	M442 0 /
23300KA220	M442 0 /
23300KA221	M442 0 /
23300KA250	M442 0 /
23300KA270	M442 0 /
23300KA280	M442 0 /
23300KA290	M442 0 /
23300KA370	M442 /

SUBARU **RMA** $\frac{V}{Kw -!}$

23300KA370	M442 0 /
23300KA430	M442 0 /
311007810	0 /
422917210	PM351 0 /
429915900	M211 0 /
429916100	M211 12 0,8 /
429916200	M442 0 /
429916400	M442 0 /
429916500	M442 0 /
429916710	M442 0 /
429917000	PM787 0 /
429917100	PM788 0 /
429917110	PM351 0 /
429917120	PM788 0 /
429917130	PM788 0 /
429917200	0 /
429917210	PM351 0 /
429917220	PM351 0 /
429917300	PM364 0 /
429917310	PM364 0 /
429917500	PM364 0 /
429917700	PM787 0 /
42991AA010	PM351 0 /
4299AA010	0 /
829914120	0 /
829916100	M334X 0 /
829918600	M334X 0 /

SUBARU **RMA** $\frac{V}{Kw -!}$

SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$
11111	M013 $12/0,7$	11133	M109 $12/1,1$ 15a	11157	M078 $12/0,7$
11112		11134	M116	11158	M067
11112	M012 $12/0,7$	11134	M116 $12/1,4$ 15a	11158	M067 $12/0,6$
11113	M040	11135	M308	11159	
11113	M040 $12/2,2$	11135	M300 $12/0,8$	11159	M275 $12/3,1$
11114	M025	11136	M106	11160	
11114	M025 $12/1,0$	11136	M106 $12/0,8$ 15a	11161	M075X
11115		11137	M106	11161	M075X $12/0,8$
11115	$12/1,1$	11137	M106 $12/0,8$ 15a	11162	
11116	M057	11138		11163	M102X
11116	M057 $12/1,4$	11139		11163	M102X $12/1,1$
11117		11140		11164	M105X
11117	$12/0,9$	11140	$12/0,8$	11164	M105X $12/2,0$
11118	M065	11141		11165	M157
11118	M065 $12/2,0$	11142	M033X	11165	M157 $12/2,2$
11119	M109	11142	M033 $12/0,8$	11166	
11119	M109 $12/1,1$ 15a	11143	M056	11167	M102X
11120	M016	11143	M056 $12/0,9$	11167	M102X $12/1,1$
11120	M016 $12/0,8$ 15a	11144		11169	M222
11121		11144	M158 $12/0,8$	11169	M074 $12/0,9$
11121	M024 $12/0,8$	11145	M072	11170	
11122	M063	11145	M072 $12/1,5$	11170	$12/2,2$
11122	M063 $12/1,5$	11146	M038	11170	M124 $12/0,9$
11123	M109	11146	M038 $12/1,0$	11171	M117
11123	M109 $12/1,1$ 15a	11147	M073	11171	M117 $12/1,1$
11124	M148	11147	M073 $12/1,1$	11172	
11124	M148 $12/0,9$ 15a	11148	M037	11172	M010 $12/0,8$
11125		11148	M037 $12/2,2$ 30h	11173	
11125	M068 $12/0,9$	11149		11173	M010 $12/0,8$
11126		11150		11174	
11126	$12/0,8$	11150	M196 $12/0,8$	11174	$12/0,7$
11127		11151		11175	M125
11127	M069 $12/1,4$	11151	M203 $12/0,8$	11175	M125 $12/2,2$
11128		11151	M070 $12/0,8$	11176	M124X
11128	M107 $12/0,8$ 15a	11152	M196	11176	M124 $12/0,9$
11129	M258	11153		11176	M124X $12/1,0$
11129	M258 $12/2,2$	11153	M105 $12/1,7$	11177	
11130		11154	M102	11178	M104
11130	M112 $12/0,9$ 15a	11154	M102 $12/0,8$	11178	M104 $12/0,9$
11131	M115	11155	M156	11179	M179
11131	M115 $12/1,0$ 15a	11155	M156 $12/2,0$	11179	M179 $12/0,7$
11132	M108	11156	M161	11180	M195
11132	M108 $12/0,8$ 15a	11156	M161 $12/2,2$	11180	M195 $12/1,4$
11133	M109	11157	M078	11181	

SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$
11182	M075X	11209	M045	11231	M082 $12/0,8$
11182	M075 $12/0,8$	11209	M316 $12/1,8$	11231	M138 $12/0,9$
11183	M075	11209	M045 $12/2,2$	11232	M214
11183	M075 $12/0,8$	11210		11232	M214 $12/1,7$
11184		11210	$12/0,5$	11233	M082
11185	M117	11211	M097	11233	M136 $12/0,9$ 15a
11185	M117 $12/1,1$	11211	M097 $12/0,8$	11233	M082 $12/0,8$
11186	M161	11212		11234	M134
11186	M161 $12/2,2$	11212	$12/0,6$	11234	M134 $12/0,8$
11187		11213	M047	11234	M082 $12/0,8$
11187	$12/2,8$	11213	$12/1,3$	11235	
11188		11214		11235	M043 $12/1,0$
11189		11214	M011 $12/0,9$	11236	M152
11189	$12/2,8$	11215	M032	11236	M152 $12/0,8$ 15a
11191		11215	M032 $12/0,8$	11237	
11191	$12/2,8$	11216		11237	M049 $12/1,1$
11192		11216	$12/0,8$	11238	M243
11193		11217	M026	11239	M152
11194		11217	M026 $12/1,6$	11240	M260
11195		11218	M023	11240	M260 $12/1,4$
11195	M127 $12/0,8$	11218	M023 $12/0,8$	11241	M263
11196		11219	M035	11241	M263 $12/1,4$
11197	M058	11219	M035 $12/0,8$	11242	M076
11198	M301	11220	M011	11242	M076 $12/0,8$
11198	M301 $12/1,1$	11220	$12/1,3$	11243	M081
11199	M046	11221		11243	M081 $12/0,6$
11199	M046 $12/0,9$	11221	M114 $12/0,8$	11245	
11200		11223	M296	11246	
11200	M018 $12/0,8$ 15a	11223	M296 $12/0,8$	11247	M128
11201	M033X	11224	M295	11247	M128 $12/1,0$
11201	M270 $12/0,8$	11224	M295 $12/2,8$	11248	M128
11201	M033X $12/0,8$	11225		11249	M425
11202	M166	11226	M153	11250	
11202	M166 $12/0,8$	11226	M153 $12/2,0$	11251	M114
11203	M061	11227	M254	11253	
11203	M061 $12/1,1$	11227	M254 $12/2,0$	11253	M145 $12/0,8$
11204	M039	11227	$12/2,5$	11255	
11204	M039 $12/0,5$	11228		11256	M044
11205	M048	11228	M264 $12/1,7$	11256	M044 $12/1,0$
11205	M048 $12/2,2$	11229		11257	M347 $12/1,7$
11206		11229	M030 $12/0,7$	11258	M044
11207	M046	11230	M260	11258	M044 $12/1,0$
11208	M053	11231	M134	11258	M044 $12/1,0$
11208	M053 $12/2,2$	11231	M137 $12/0,8$	11259	M096

SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$
11259	M096 $12/0,8$	11294	M028 $12/2,0$	11322	
11260	M111 $12/0,8$	11294	M028 $12/2,2$	11323	
11260	M111 $12/0,8$ 15a	11295		11323	$12/1,2$
11261		11296		11324	M100 $12/0,8$
11262		11296	M320 $12/0,8$	11324	M100 $12/0,8$
11262	$12/0,7$	11297		11325	M297 $12/2,5$
11264	M277 $12/3,1$	11298		11325	M297 $12/2,5$
11264	M277 $12/3,1$	11299		11326	
11265		11300		11327	M103 $12/1,7$
11266		11301		11327	M103 $12/1,7$
11267		11302	M424 $12/1,7$	11328	
11268		11303	M424 $12/1,7$	11328	$12/1,5$
11269		11304	M424 $12/1,7$	11329	M102 $12/1,5$
11271	M127 $12/0,8$	11306	M094 $12/0,6$	11330	M101 $12/1,5$
11272	M129 $12/0,8$	11306	M094 $12/0,6$	11330	M101 $12/1,5$
11272	$12/0,8$	11307	M095 $12/0,7$	11331	M079 $12/1,5$
11272	$12/0,8$	11307	M095 $12/0,7$	11332	M299 $12/1,5$
11273	M433 $12/1,5$	11308	M052 $12/1,7$	11332	M299 $12/1,5$
11274		11308	M052 $12/1,7$	11333	
11275	M140 $12/1,5$ 15a	11309	M015 $12/1,7$	11333	M278 $12/3,1$
11275	$12/1,5$	11309	M015 $12/1,7$	11334	
11276	M083 $12/1,4$	11309	M015 $12/1,7$	11335	M276 $12/1,5$
11276	M083 $12/1,4$	11310	M180 $12/0,8$	11336	
11277	M088 $12/2,2$	11310	M180 $12/0,8$	11337	
11277	M088 $12/2,2$	11311	M226 $12/1,0$	11337	$12/0,7$
11278		11311	M226 $12/1,0$	11338	
11279	M164 $12/1,5$	11311	M099 $12/1,4$	11339	
11279	M164 $12/1,5$	11312	M226 $12/0,6$	11340	
11280	M087 $12/1,5$	11312	$12/0,6$	11341	
11280	M140 $12/1,5$	11313	M174 $12/1,0$ 15a	11342	
11281	M140 $12/1,5$	11314	M162 $12/2,2$	11343	
11281	M140 $12/1,5$	11315	M093 $12/1,0$	11344	M119 $12/0,9$
11282		11315	M093 $12/1,0$	11344	M192 $12/0,9$
11284	M216 $12/1,7$	11316	M064 $12/2,0$	11345	
11284	M216 $12/1,7$	11316	M064 $12/2,0$	11346	$12/0,6$
11285		11318	M094 $12/0,6$	11346	$12/0,6$
11286		11319		11347	M021 $12/1,0$
11287		11320		11347	M021 $12/1,0$
11288		11321		11348	M017 $12/0,8$
11289				11348	M017 $12/0,8$
11290				11349	
11291				11349	M120X $12/1,9$
11292				11350	M021 $12/1,0$
11293	M425 $12/1,0$			11350	M021 $12/1,0$

SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$
11351	M119X	11380		11411	M051 $12/1,5$
11351	M119 $12/0,8$	11381		11414	
11352	M077	11382		11415	
11352	M077 $12/0,6$	11383		11418	
11352	M119 $12/0,8$	11385		11419	M202
11353		11386		11420	M172
11354		11387		11421	
11354	M084 $12/0,9$	11388		11422	M172
11355	M121	11389		11422	M172 $12/1,1$
11355	M121 $12/2,2$	11390		11423	M066X
11356	M084X	11391		11423	M066X $12/2,2$
11356	M084X $12/0,9$	11392		11423	M066 $12/2,0$
11357	M120	11393		11424	
11357	M120 $12/1,9$	11394		11424	M240 $12/1,4$
11358	M124X	11397	M251	11425	
11359	M202	11397	M251 $12/0,9$	11427	
11359	M202 $12/0,9$	11398		11427	$12/1,1$
11360		11398	M014 $12/1,7$	11427	M113 $12/1,4$
11360	$12/1,1$	11398	M310 $12/1,8$	11427	M359 $12/1,1$
11361	M121X	11399	M150	11428	M110
11361	M121X $12/2,9$	11399	M150 $12/0,9$ 15a	11428	M110 $12/0,7$
11362	M029	11399	M248 $12/1,1$	11429	
11362	M029 $12/1,0$	11400		11430	M051
11363	M192	11401	M063	11430	M051 $12/1,7$
11363	M192 $12/0,9$	11401	M063 $12/1,5$	11431	
11364		11402	M106	11432	
11364	M119X $12/1,0$	11402	M106 $12/0,8$ 15a	11433	M059
11365	M237	11403	M031	11433	M059 $12/2,5$
11365	M237 $12/1,4$	11403	M031 $12/0,7$	11434	
11366	M041	11404		11434	$12/2,5$
11366	M041 $12/1,1$	11405	M034	11435	M197
11367	M055	11405	M034 $12/0,8$	11435	M197 $12/1,5$
11367	M055 $12/1,0$	11405	M034 $12/0,8$	11436	
11368	M293	11406	M102X	11437	M027
11368	M293 $12/0,8$	11406	M102X $12/1,1$	11437	M027 $12/2,5$
11369		11407	M218	11438	
11370	M330	11407	M218 $12/1,7$	11439	M246
11370	M330 $12/0,8$	11408		11439	M246 $12/2,2$
11371		11408	M022 $12/0,9$	11441	M326
11372		11409	M238	11441	M236 $12/1,1$
11373		11409	M238 $12/1,4$	11442	
11374		11410	M089	11442	M329 $12/0,8$
11375		11410	M089 $12/2,0$	11443	
11376		11411	M051	11444	M250

SUDEST	RMA $\sqrt{\frac{V}{Kw}}$ -!	SUDEST	RMA $\sqrt{\frac{V}{Kw}}$ -!	SUDEST	RMA $\sqrt{\frac{V}{Kw}}$ -!
11444	M250 $\frac{12}{1,7}$	11496	M325 $\frac{12}{0,8}$	11531	M257
11446	M370	11497	M200	11531	M257 $\frac{12}{1,7}$
11446	M370 $\frac{24}{3,1}$	11497	M200 $\frac{12}{1,4}$	11532	
11447	M308	11498		11532	M149 $\frac{12}{0,8}$
11447	M308 $\frac{12}{0,8}$	11501	M151	11533	
11448		11501	M151 $\frac{12}{2,2}$	11533	$\frac{12}{2,5}$
11449		11502		11534	M157
11450		11503		11534	M157 $\frac{12}{2,2}$
11450	$\frac{12}{0,8}$	11504		11536	M117 $\frac{12}{1,1}$
11451		11505		11537	M078
11451	M159 $\frac{12}{0,7}$ 15a	11505	M165 $\frac{12}{1,5}$	11538	
11452		11506		11538	$\frac{12}{0,7}$
11455		11508		11539	
11456		11509		11539	$\frac{12}{0,8}$ 15a
11457	M432	11509	M334 $\frac{12}{0,6}$	11540	M156
11459		11510	M095	11541	M307
11459	M194 $\frac{12}{1,0}$	11510	M095 $\frac{12}{0,7}$	11542	
11460		11511	M211	11543	M100
11462		11511	M211 $\frac{12}{0,8}$	11544	
11465		11513		11545	M379
11467		11514		11545	M379 $\frac{12}{1,1}$
11468	M341	11515	M118	11547	M038
11468	M341 $\frac{12}{2,2}$	11515	M118 $\frac{12}{0,8}$	11547	M039 $\frac{12}{0,5}$
11469		11516	M118	11548	M038
11470		11517	M172	11549	
11471		11517	M172 $\frac{12}{1,1}$	11550	M064
11473		11518		11550	M064 $\frac{12}{2,0}$
11474		11518	M219 $\frac{12}{1,4}$	11553	
11475		11519		11554	M223
11476		11519	M057 $\frac{12}{1,4}$	11554	M223 $\frac{12}{0,9}$
11478	M424	11520	M283	11555	
11481		11520	M283 $\frac{12}{0,9}$	11559	
11481	M252 $\frac{12}{2,2}$	11520	M283 $\frac{12}{0,8}$	11559	$\frac{12}{0,6}$
11482		11520	M131	11560	
11483		11521	M176	11561	
11486		11521	M176 $\frac{12}{1,1}$	11562	M327
11487		11524	M423	11562	M327 $\frac{12}{0,7}$
11488		11525		11563	
11490		11525	M120X $\frac{12}{1,9}$	11565	
11491		11527	M017X	11567	
11494		11527	M017X $\frac{12}{1,2}$	11568	
11494	M335 $\frac{12}{2,0}$	11528		11569	
11495		11529		11569	$\frac{12}{1,1}$
11496	M325	11530		11570	

SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$	SUDEST	RMA $V_{Kw} -!$
11571	M305	11622	M171	11659	
11572		11622	M171 $12/2,1$	11659	M299 $12/1,7$ 30h
11573		11625	M222	11659	M299X $12/1,7$ 30h
11574	M376	11625	M222 $12/1,0$	11660	M185
11574	M376 $12/1,2$	11627	M062	11660	M185 $12/1,4$ 30h
11576		11627	M062 $12/1,4$	11661	M261
11577		11627	M062X $12/1,4$	11661	M261 $12/1,4$
11580		11629		11662	
11580	M276 $12/3,1$	11630		11663	
11581		11632		11663	M190 $12/1,0$
11584		11633		11664	M244
11585		11634		11664	M244 $12/1,8$
11586		11635		11665	M143
11587		11636		11665	M143 $12/0,9$
11589	M215	11637		11666	M344
11589	M215 $12/1,5$	11638		11667	M239
11590		11639		11667	M239 $12/1,4$
11591		11639	M105 $12/1,7$	11668	M334
11593		11640	M175	11669	
11594		11640	M175 $12/1,4$ 30h	11670	M417
11595		11643	M228	11671	
11596		11643	M228 $12/2,2$	11671	M013X $12/1,1$
11596	$12/1,4$	11643	M228 $12/2,2$	11672	M307
11597	M193	11644		11672	M307 $12/2,2$
11597	M193 $12/2,0$	11645		11673	M217
11598		11646		11673	M217 $12/1,4$
11599		11648	M213	11674	M202
11603		11648	M213 $12/0,6$	11675	
11606	M084X	11649	M285	11676	
11606	M084X $12/0,9$	11649	M285 $12/2,2$	11677	
11608		11650		11678	M271
11609		11651	M406	11678	M271 $12/1,0$
11610	M210	11652		11679	
11610	M210 $12/0,9$	11652	M305 $12/1,4$	11679	M265 $12/0,8$
11611	M223	11653	M027X	11679	M268 $12/0,8$
11615		11653	M027X $12/2,5$	11680	M283
11615	M012 $12/0,7$	11654		11680	M283 $12/0,9$
11616		11655		11681	M269
11617		11656	M191	11681	M269 $12/0,9$
11617	M058 $12/1,7$	11656	M191 $12/1,0$	11682	
11618		11657	M306	11682	M058X $12/1,8$
11618	M332 $12/2,0$	11657	M306 $12/1,1$	11683	
11619		11658	M375	11683	M316 $12/2,2$
11620		11658	M375 $12/1,4$ 30h	11684	M048X

SUDEST	RMA $\sqrt{\frac{V}{Kw}}$ -!	SUDEST	RMA $\sqrt{\frac{V}{Kw}}$ -!	SUDEST	RMA $\sqrt{\frac{V}{Kw}}$ -!
11684	M048X $\frac{12}{2,2}$	11712		11750	
11684	M048X $\frac{12}{2,2}$	11713		11751	M437
11684	M048X $\frac{12}{2,2}$	11713	$\frac{12}{2,8}$	11752	M284
11685	M340	11714		11752	M284 $\frac{12}{2,2}$
11685	M340 $\frac{12}{1,4}$	11715		11753	M427
11686		11716		11754	
11687	M235	11717	M392	11754	$\frac{12}{2,0}$
11687	M235 $\frac{12}{1,4}$	11718	M256	11755	
11688	M289	11718	M256 $\frac{12}{1,8}$	11756	
11688	M289 $\frac{12}{1,8}$	11719	M394	11757	
11689	M201	11720		11758	
11689	M201 $\frac{12}{1,4}$	11721		11759	
11690	M306	11722	M386	11760	
11691	M099X	11723	M282	11761	M337
11692		11723	M282 $\frac{12}{1,7}$	11762	
11693		11724		11763	M255
11694		11725		11763	M255 $\frac{12}{1,1}$
11694	M318 $\frac{12}{1,4}$ 15a	11726	M324	11764	
11695	M106	11726	M324 $\frac{12}{1,2}$	11765	
11696		11727		11766	
11697	M313	11727	M380 $\frac{12}{2,5}$	11767	
11697	M313 $\frac{12}{1,8}$	11728		11768	M314
11698	M343	11729		11768	M314 $\frac{12}{1,0}$
11698	M343 $\frac{12}{1,2}$	11730		11769	
11699	M304	11731	M441	11770	
11699	M304 $\frac{12}{1,4}$	11732		11770	$\frac{12}{2,2}$
11700	M333	11733		11771	M402X
11700	M333 $\frac{12}{2,0}$	11734		11772	
11701	M227	11735		11773	M243
11701	M227 $\frac{12}{1,1}$	11736		11773	M243 $\frac{12}{1,4}$
11702	M262	11737	M442	11774	M185X
11702	M262 $\frac{12}{1,4}$	11738		11775	M403
11703		11739		11776	
11704	M431	11740		11777	M255
11705	M338	11741		11778	M317
11705	M338 $\frac{12}{1,0}$	11742	M440	11778	M317 $\frac{12}{1,4}$
11705	M338 $\frac{12}{1,0}$	11743		11779	M121X
11706	M236	11744		11780	
11706	M236 $\frac{12}{1,1}$	11745		11781	
11707		11746		11782	M328
11708		11747		11783	
11709		11747	M374 $\frac{12}{1,2}$	11784	
11710		11748		11785	M128X
11711		11749		11786	

MOTORINI

SUDEST

SUDEST RMA $V_{Kw} -!$

11787	M420	
11788		
11789		
11790		
11791		
11792		
11793		
11794	M382	
11795	M099	
11796		
11797	M319	
11797	M319	$12/0,7$
11798		
11798	M312	$12/1,4$
11798	M311	$12/1,4$
11799	M381	
11800	M335	
11802		
11803	M416	
11804		
11805	M396	
11806	M315	
11806	M315	$12/1,8$
11807	M387	
11808	M384	
11809	M083X	
11810	M405	
11811	M421	
11812		
11813		
11813		$12/0,6$
11814		
11815		
11816		
11817		
11818		
11819		
11820		
11821		
11823		
11824		
11825	M444	
11826		
11827		

SUDEST RMA $V_{Kw} -!$

11828	M345	
11828	M345	$12/1,2$
11829		
11830		
11831		
11833	M412	
11834		
11835		
11836		
11837	M352	
11837	M352	$12/2,2$
11838	M310	
11838	M310	$12/1,8$
11839	M248	
11840		
11841		
11842		
11843		
11844		
11845	M383	
11846		
11847		
11848		
11849		
11850		
11851		
11852		
11853	M414	
11854	M400	
11855	M195	
11856	M391	
11857	M385	
11858	M408	
11859		
11860		
11861		
11862	M388	
11863		
11864		
11865		
11866	M415	
11867		
11868		
11869		

SUDEST RMA $V_{Kw} -!$

11870		
M382		

SUZUKI RMA $\sqrt{\text{Kw}} -!$

3100080X51	M330	
3100082631	M446	0
3100085010	M328	0
3110040B01	PM655	
3110051A90	M334	0
3110051X50	M334	0
3110060A10		
3110060A11	M327	12 0,7
3110060A12	M327	0
3110060A20	M327	
3110060A22	M327	
3110060AB2	M327	
3110060AC2	M327	0
3110060B50	PM350	0
3110060B51	M446	0
3110060G10	M446	0
3110060G11	M446	
3110062030	M446	0
3110064B10	PM350	
3110064B12	PM350	0
3110064G00	M446	0
3110067D20	PM345	
3110073010	M439	0
3110073030	M439	0
3110073031	M330	12 0,8
3110073033	M330	12 0,8
3110073034	M330	12 0,8
3110073035	M330	12 0,8
3110073036	M330	12 0,8
3110073071	M439	0
3110073090	M439	0
3110075F01	PM704	
3110075F10	PM704	
3110077E10	PM345	
3110077E20	PM345	0
3110077E22	PM345	0
3110078010	M334X	0
3110078021	M334	0
3110078310		0
3110078320		0
3110078480	PM787	0
3110078611	M328	12 0,6
3110079610	M328	12 0,6
3110079610L	M328	

SUZUKI RMA $\sqrt{\text{Kw}} -!$

3110079611	M328	12 0,6
3110079620	M328	0
3110079621	M328	0
3110079628	M328	0
3110079630	M328	0
3110079631	M328	0
3110079650	M328	12 0,6
3110079660	M328	12 0,6
3110079661	M328	12 0,6
3110079680	M328	12 0,6
3110080091	M330	12 0,8
3110080092	M330	12 0,8
3110080094	M330	12 0,8
3110080E00	M446	
3110080G00	PM887	
3110080X51	M330	12 0,8
3110081010	M334	0
311008201	M446	
3110082010	M446	0
3110082011	M446	0
3110082016	M446	0
3110082021	M327	12 0,7
3110082030	M446	0
31100820D1	M446	0
3110082610	M446	0
3110082611	PM350	0
3110082612	M446	0
3110082641	PM350	0
31100826A0	M446	0
31100826A1	M446	0
3110083010	M327	12 0,7
3110083010	M327	12 0,7
3110083011	M327	12 0,7
3110083020	M327	12 0,7
3110083020	M327	12 0,7
3110083021	M327	0
311008303	M327	
3110083030	M327	12 0,7
3110083031	M327	12 0,7
3110083421	M327	12 0,7
3110083E0	M446	
3110084210		0
3110084221		0
3110084350	M334	0

SUZUKI RMA $\sqrt{\text{Kw}} -!$

3110085010	M328	0
3110085020	M328	0
3110085021	M328	
3110085291	M328	12 0,6
3110086030	PM350	0
3110086032	PM350	0
3110086033	PM350	
3110086033	PM350	
31100860D2	PM350	0
3110086130	M446	0
3110088011		0
3110092330	M446	0
31100A7303	M330	0
31100A83010	M327	12 0,7
31100A83031	M327	12 0,7
31100M70F00	M446	0
31100M81110	M334	
31100M82011	M446	0
31100M82020	M446	
31100M82021	M446	0
31100T79J00	RM016	
31100W0100		
32A6600101		

TOYOTA RMA $\sqrt{\text{Kw -!}}$

20100Y020	
210000D130	M317
2810001030	
2810001030	PM015 0
2810002040	
2810002040	PM015 0
2810002050	
2810002050	PM838
2810002060	
2810002060	PM487 0
2810002080	
2810002080	PM015 0
2810003030	
2810003030	M440 0
2810003070	
2810003070	M428 0
2810003100	
2810003100	PM505 0
2810007010	
2810007010	PM857
2810008010	
2810008010	PM095
2810008010	
2810008010	PM095 0
2810008010	PM095 0
2810008040	
2810008040	PM494 0
281000B010	
281000B010	M397 0
281000B020	PM095
281000B020	
281000B020	M397 0
281000C010	
281000C010	PM490
281000C060	
281000C060	PM890
281000D020	
281000D020	PM880
281000D030	
281000D030	
281000D030	PM018 0
281000D130	
281000D130	
281000D130	PM551

TOYOTA RMA $\sqrt{\text{Kw -!}}$

281000E010	
281000E010	
281000E010	
281000E010	PM017 0
281000G010	M397
281000G010	
281000G010	M397 0
281000G030	
281000J020	PM888
281000L070	
281000L070	PM891
281000N010	RM003
281000Q021	RM062
281000T030	RM061
2810010020	
2810010020	M325X 0
2810010021	
2810010021	M325X 0
2810010030	
2810010030	M325 0
2810010040	PM456 0
2810011010	M325 0
2810011020	PM828
2810011060	PM497 0
2810011080	PM496 0
2810011090	PM859
2810011100	PM498 0
2810011140	PM496 0
2810011160	PM498 0
2810012030	M439 0
2810012040	M439 0
2810013010	PM424 0
2810013020	PM600 0
2810013030	PM600 0
2810013050	PM424 0
2810013060	PM600 0
2810013061	PM600 0
2810013080	PM424 0
2810014014	PM603 0
2810014020	PM785 0
2810014021	PM785 0
2810015010	PM785 0
2810015011	PM785 0
2810015020	PM425 0

TOYOTA RMA $\sqrt{\text{Kw -!}}$

2810015040	0
2810015050	PM785 0
2810015050	PM785 0
2810015060	PM601 0
2810015070	PM431 0
2810015110	PM796 0
2810015120	PM797
2810015130	PM796 0
2810015140	PM601 0
2810015150	PM796 0
2810015160	PM796 0
2810015170	PM796 0
2810015180	PM796 0
2810015190	PM472 0
2810016010	PM460 0
2810016020	PM015 0
2810016040	PM460 0
2810016041	PM460 0
2810016070	PM460 0
2810016071	PM460 0
2810016080	PM469 0
2810016090	PM469 0
2810016110	PM015 0
2810016130	PM015 0
2810016140	PM015 0
2810016150	PM489 0
2810016160	PM488 0
2810016170	PM015 0
2810016180	PM487 0
2810016190	PM489 0
2810016210	PM015 0
2810016220	PM838
2810016230	
2810016230	PM488 0
2810016230	PM488 0
2810016270	PM487 0
2810017020	PM479 0
2810017030	PM479 0
2810017040	PM836
2810017050	PM504 0
281002040	
2810020540	PM602 0
281002055071	PM416
2810020551	PM416 0

TOYOTA	RMA $\sqrt{\text{Kw -!}}$	TOYOTA	RMA $\sqrt{\text{Kw -!}}$	TOYOTA	RMA $\sqrt{\text{Kw -!}}$
281002055171	PM416 0/	2810024100	PM600 0/	2810027060	PM434 0/
2810020552	PM416 0/	2810024100	PM600 0/	2810027070	PM789 /
281002055271	PM416 0/	2810025010	PM780 0/	281002880	/
281002055371	PM416 0/	2810025011	PM780 0/	2810031020	PM603 0/
2810020557	PM416 /	2810025012	PM780 0/	2810031021	PM603 0/
2810020571	PM416 0/	2810025012	PM780 0/	2810031022	PM603 0/
2810020572	PM416 0/	2810025020	PM780 0/	2810031030	PM603 0/
2810021020	PM532 /	2810025021	PM780 0/	2810031625	PM433 /
2810021030	PM532 0/	2810025030	PM780 0/	281003162571	PM433 0/
2810021142	PM780 0/	2810025031	PM780 0/	281003162572	0/
2810022000	PM416 0/	2810025032	0/	281003162574	0/
2810022010	M439 0/	2810026020	PM780 0/	2810033010	PM602 0/
2810022011	M439 0/	2810026021	PM780 0/	2810033011	PM602 0/
2810022012	M439 0/	2810026022	PM780 0/	2810033020	PM602 0/
2810022020	M439 0/	2810026031	PM780 0/	2810034010	PM602 0/
2810022021	M439 0/	2810026040	M326 0/	2810034020	PM602 0/
2810022022	M439 0/	2810026041	M326 0/	2810034040	PM416 /
2810022030	PM893 /	2810026042	M326 0/	2810034042	PM416 0/
2810022040	PM018 /	2810026043	M326 0/	2810034043	PM416 0/
2810022050	PM884 /	2810026050	M326X /	2810034044	PM416 0/
281002206071	PM422 0/	2810026051	M326X /	2810034052	PM416 0/
281002206171	PM422 0/	2810026052	M326X /	2810034053	PM416 0/
2810022071	PM422 /	2810026053	M326X 0/	2810034060	PM423 0/
2810023010	PM603 0/	2810026060	M326 0/	2810034070	PM602 0/
2810023011	PM603 0/	2810026061	M326 0/	2810034080	PM423 0/
2810023020	PM827 /	2810026062	M326 0/	2810034090	PM602 0/
2810023030	PM508 0/	2810026063	M326 0/	2810034100	PM423 /
281002366071	PM856 /	2810026070	M326 0/	2810035020	PM416 0/
281002380071	PM824 0/	2810026071	M326 0/	2810035030	PM423 0/
281002381071	PM423 0/	2810026080	PM780 0/	2810035040	PM416 0/
2810024000	PM600 0/	2810026090	M326 0/	2810035060	PM416 0/
2810024010	PM600 0/	2810026100	M326X 0/	2810035080	PM493 0/
2810024012	PM600 0/	2810026110	0/	2810035090	PM494 0/
2810024020	PM600 0/	2810026120	M326 0/	2810035100	PM845 /
2810024021	PM600 0/	2810026130	PM780 0/	2810035140	PM416 /
2810024022	PM600 0/	2810026141	PM780 0/	2810036020	PM602 0/
2810024023	PM789 0/	2810026142	PM780 0/	2810036030	PM602 0/
2810024030	PM600 0/	2810026150	PM780 0/	2810036040	PM602 0/
2810024031	PM600 0/	2810026160	PM789 0/	2810036050	PM602 0/
2810024060	PM600 0/	2810027010	M326 /	2810036051	PM602 0/
2810024070	PM600 0/	2810027020	PM789 0/	2810036060	PM602 0/
2810024080	PM600 0/	2810027030	PM434 0/	2810036070	PM602 0/
2810024081	PM600 0/	2810027040	0/	2810036090	PM602 0/
2810024090	PM600 0/	2810027050	PM434 0/	2810037010	PM602 0/

TOYOTA	RMA $\sqrt{\text{Kw -!}}$	TOYOTA	RMA $\sqrt{\text{Kw -!}}$	TOYOTA	RMA $\sqrt{\text{Kw -!}}$
2810037011	PM602 0/	2810045032	PM415 0/	2810054310	M335X 0/
281003701171	PM602 0/	2810045033	PM415 0/	2810054320	PM419 0/
2810037040	0/	2810045050	PM415 0/	2810054340	M335X 0/
2810040010	PM603 0/	2810045061	PM419 0/	2810054370	PM419 0/
2810040011	PM603 0/	2810046030	PM786 0/	2810054380	M335X 0/
2810040012	PM603 0/	2810046090	PM471 0/	2810054390	PM419 0/
2810040013	PM603 0/	2810046100	PM471 0/	2810054400	M335 0/
2810040014	PM603 0/	2810046120	PM471 0/	2810054410	M335X 0/
2810040015	PM603 0/	2810046140	PM840 0/	2810054470	PM419 0/
2810040040	PM602 0/	2810047030	0/	2810056030	M370 0/
2810040041	PM602 0/	2810047040	PM429 0/	2810056060	M370 0/
2810040050	PM602 0/	2810047050	PM429 0/	2810056070	M370 0/
2810040060	PM602 0/	2810047060	0/	2810056071	M370 0/
2810040061	PM602 0/	2810047070	PM792 0/	2810056100	M370 0/
2810040100	PM603 0/	2810047080	PM792 0/	2810056180	PM458 0/
2810040110	PM603 0/	2810047090	PM433 0/	2810056181	PM458 0/
2810040120	PM603 0/	2810047091	PM433 0/	2810056220	PM457 0/
2810040130	PM603 0/	2810050020	PM820 0/	2810056221	PM457 0/
2810040140	PM603 0/	2810050060	PM862 0/	2810056260	PM457 0/
2810040290	PM800 0/	2810050061	PM862 0/	2810057070	PM457 0/
281004029171	PM800 0/	2810050062	PM862 0/	2810060010	PM778 0/
2810041010	PM415 0/	2810050070	PM862 0/	2810060040	PM778 0/
2810041011	PM415 0/	2810051450	PM419 0/	2810060041	PM778 0/
2810041012	PM415 0/	2810054010	PM419 0/	2810060042	PM778 0/
2810041013	PM415 0/	2810054011	PM419 0/	2810060051	0/
2810041020	PM415 0/	2810054032	PM419 0/	2810060060	PM778 0/
2810041030	PM415 0/	2810054042	PM419 0/	2810060061	PM778 0/
2810041060	PM435 0/	2810054051	PM419 0/	2810060062	PM778 0/
2810042010	PM415 0/	2810054052	PM419 0/	2810060070	PM437 0/
2810042011	PM415 0/	2810054061	PM419 0/	2810060080	0/
2810042020	0/	2810054070	M335 0/	2810062010	PM462 0/
2810042021	PM415 0/	2810054080	0/	2810062011	PM462 0/
2810042040	PM470 0/	2810054090	PM419 0/	2810062020	M440 0/
2810042050	PM471 0/	2810054100	M335 0/	2810062021	M440 0/
2810044010	PM435 0/	2810054140	PM419 0/	2810062030	PM860 0/
2810044040	PM435 0/	2810054150	PM419 0/	2810062050	PM857 0/
2810044041	PM435 0/	2810054170	M335 0/	2810063020	PM437 0/
2810044050	PM415 0/	2810054180	M335 0/	2810063021	PM437 0/
2810045020	PM415 0/	2810054190	PM419 0/	2810063030	0/
2810045021	PM415 0/	2810054220	PM419 0/	2810063040	PM533 0/
2810045022	PM415 0/	2810054250	PM419 0/	2810063050	PM455 0/
2810045023	PM415 0/	2810054270	M335X 0/	2810064010	PM443 0/
2810045030	PM415 0/	2810054290	M335 0/	2810064020	PM466 0/
2810045031	PM415 0/	2810054300	PM419 0/	2810064040	PM466 0/

TOYOTA	RMA $\sqrt{Kw - !}$	TOYOTA	RMA $\sqrt{Kw - !}$	TOYOTA	RMA $\sqrt{Kw - !}$
2810064070	PM443 0/	2810074070	M440 0/	2810087721	0/
2810064070	PM443 0/	2810074090	M440 0/	2810087725	M129 0/
2810064100	PM443 0/	2810074100	M440 0/	2810087727	M129 0/
2810064110	PM443 0/	2810074120	PM462 0/	2810087730	0/
2810064130	PM481 0/	2810074130	M428X 0/	2810087731	PM430 0/
2810064140	PM466 0/	2810074140	M428 0/	2810087883	M127 /
2810064180	PM466 0/	2810074200	PM495 0/	281008Y002	/
2810064190	PM466 0/	2810074230	PM870 /	28100U210071	PM494 /
2810064200	PM481 0/	2810074240	M428 0/	28100YA020	/
2810064210	PM466 0/	2810074250	PM495 /	28100YB010	/
2810064230	0/	2810074260	PM505 /	28100YD010	/
2810064280	PM466 0/	2810074270	PM871 /		
2810064290	PM466 0/	2810075010	PM470 0/		
2810064310	PM095 0/	2810075030	PM475 0/		
2810064340	PM500 0/	2810075050	PM475 0/		
2810064350	PM501 0/	2810075070	PM491 0/		
2810064430	PM095 /	2810075090	PM490 0/		
2810065010	PM468 0/	2810075110	PM853 /		
2810065020	PM467 0/	2810075130	PM490 /		
2810065080	PM848 /	2810075140	PM861 /		
2810065090	PM492 0/	2810076050	PM476 0/		
2810065100	PM849 /	2810076060	PM477 0/		
2810066050	PM837 /	2810076070	PM477 0/		
2810066060	PM837 /	2810076081	PM476 0/		
2810066180	0/	2810076091	PM476 /		
2810067050	PM502 0/	2810076101	PM476 0/		
2810067070	PM503 0/	2810077090	PM417 0/		
2810072010	PM444 0/	2810087202	0/		
2810072020	PM445 /	2810087203	0/		
2810072030	PM444 0/	2810087204	0/		
2810072060	PM444 0/	2810087207	0/		
2810072070	PM445 0/	2810087505	0/		
2810072080	PM444 0/	2810087510	M444 0/		
2810072090	PM445 0/	2810087517	M444 0/		
2810072100	PM444 0/	2810087601	PM429 0/		
2810072110	PM445 0/	2810087700	M129 0/		
2810072120	PM445 0/	2810087701	M127 0/		
2810072130	PM444 /	2810087702	M127 0/		
2810074010	PM462 0/	2810087704	M127 0/		
2810074011	PM462 0/	2810087706	M127 0/		
2810074020	M440 0/	2810087708	M129 0/		
2810074021	M440 0/	2810087709	M337 0/		
2810074050	M440 0/	2810087710	PM446 0/		
2810074060	PM462 0/	2810087713	PM446 0/		

VALEO	RMA $\sqrt{Kw - !}$	VALEO	RMA $\sqrt{Kw - !}$	VALEO	RMA $\sqrt{Kw - !}$
073042	PM120	310032Y	M021	432532	M125 $12/2,2$
076517	PM108	310033Z	M084X	432534	
076571	PM184	310118Z		432534	$12/2,8$
095423	PM127	310213V	M102	432535	M161
097224	PM134	310216Y	M254	432536	M278
098209	PM215	310218A	M192	432536	M254 $12/3,1$
10047	RM018	310229E	M280	432537	M297 $12/3,1$
105495	PM145 0	310465	PM215 0	432537	M297X $12/3,1$
105808	M276 0	432231	0	432538	M121X $12/2,9$
184202	PM134	432502	$12/0,7$	432538	M121X $12/2,9$
184456	$12/2,2$	432503	M033 $12/0,8$	432543	$12/0,7$
185249	M150 $12/0,9$	432503	M033 $12/0,8$	432544	M010 0
186214	M379 $12/1,1$	432505	M044 0	432545	M104 $12/0,9$
186502	M222 $12/1,0$	432506	M012 $12/0,7$	432546	M102 $12/0,8$
186848	M222 $12/1,0$	432507	M276	432547	M119X $12/1,0$
1EM0051		432507	M117 0	432548	M084X $12/0,9$
1EM0064		432508	M046	432549	M029
1EM0087		432508	M048	432549	M029 $12/1,0$
1EM0088		432508	M114	432550	M124X
1EN0026		432508	M031	432550	M084X $12/0,9$
2010001005		432508	M011 $12/0,9$	432551	M075X
2010001006		432509	M044 $12/1,0$	432551	M192
2010001011		432510	M202 0	432551	M179
2010001014		432510	M017X $12/0,9$	432551	M075X $12/0,8$
2518035		432511	M100 $12/0,8$	432552	M119X
2541139		432512	M010 $12/0,8$	432552	M077
2541263		432515	0	432552	M119
2565994		432517	M013 $12/0,7$	432552	M192 $12/0,9$
2565995		432520	M101 $12/1,5$	432552	M192 $12/0,9$
2940349		432522	M109 $12/1,1$	432553	M280 $12/1,1$
2940353		432522	M109 $12/1,1$	432554	M124X $12/1,0$
2940356		432524	$12/2,2$	432555	M124X $12/0,9$
2940357		432524	$12/2,2$	432556	M118
2940361		432524	M121X	432556	M203
2940426		432524	M124X 0	432556	M196 $12/0,8$
2940782		432526	M021 $12/1,0$	432557	PM908
2941097		432526	M021 $12/1,0$	432558	M078 $12/0,7$
2EA0520		432527	M120X $12/1,9$	432558	M078 $12/0,7$
2EA0606		432528	M017X $12/1,2$	432559	M067 $12/0,6$
310021U	M100	432529	M079 $12/2,0$	432560	$12/1,2$
310023W	M010	432530	M156 $12/2,0$	432560	$12/1,2$
310024X	M156	432531	PM894 $12/2,5$	432561	M105 $12/2,0$
310030W	PM908	432532	M307	432562	
310031X	M119X	432532	M255	432563	M157 $12/2,2$

VALEO RMA $V_{Kw} -!$

432564	M055	12/2,0
432565	M192	
432565	M119X	12/1,0
432565	M119	12/1,0
432566	M017	12/0,8
432566	M202	
432566	M017	12/0,8
432569	PM149	0/
432571		12/2,0
432572	PM149	0/
432573	M102	12/0,8
432574	M277X	
432574	M277	12/3,1
432575	M176	12/1,1
432576	M176	12/1,1
432577		
432580	M121	
432580	M121X	12/2,9
432581	M017	12/0,9
432581	M017	
432581	M017	12/0,9
432581	M202	12/0,9
432581	M202	0/
432582	M120X	
432582	M120	
432582	M415	
432582	M120X	12/1,9
432584	M075X	12/0,8
432584	M075	12/0,8
432586	M376	12/1,2
432587	M275	12/3,1
432588	M102	12/1,1
432590	M017X	12/1,2
432590	M017	12/1,2
432591	M074	
432591	M176	12/1,1
432592	M102X	
432593	PM024	0/
432594	M327	12/0,7
432595	M105X	12/2,0
432596	M102X	12/1,1
432598	M176	12/1,1
432599	PM906	
432601	M270	

VALEO RMA $V_{Kw} -!$

432601	M055	
432601	M033X	12/0,8
432601	M033	12/0,8
432602	M158	
432602	M072	12/1,5
432603	M110	12/0,7
432604	M175	
432604	M073	12/1,1
432605	M106	
432605	M248	
432605	M051	
432605	M111	
432605	M022	
432605	M106	
432605	M150	12/0,9 15a
432606	M148	
432606	M068	12/0,9
432607	M089	12/2,0
432609	M285	12/2,2
432609	M285	12/2,2
432610	M104	
432610	M104	12/0,9
432612	M064	0/
432613	M195	12/1,4
432614	M017	12/0,9
432614	M202	12/0,9
432621	M415	
432621	M202	12/0,9
432622	M017X	
432622	M017X	12/1,2
432622	M017X	12/1,2
432623	M190	
432623	M222	12/1,0
432623	M176	12/1,0
432624	M102X	12/1,1
432625	M094	12/0,6
432626		0/
432627	M088X	12/2,2
432627	M088X	12/2,2
432628	M017	12/1,2
432628	M202	0/
432628	M017	12/1,2
432629	M120	
432629	M120X	12/1,9

VALEO RMA $V_{Kw} -!$

432630	M103	12/1,7
432630	M105	12/1,7
432631	M417	0/
432632	M143	12/0,9
432633	M032	0/
432635	PM909	12/1,2
432636	M102	
432636	M102X	
432637	M120X	
432637	M120X	
432638	PM251	
432639	M419	
432639	M105	
432643	M268	
432644	M399	
432644	M088X	12/2,2
432644	M088X	12/2,2
432650	M056	
432651	M046	12/0,9
432652	M159	12/0,7 15a
432652	M159	12/0,7 15a
432653	M137	
432653	M136	
432653	M081	
432653	M076	
432653	M082	
432654	M149	
432654	M107	
432654	M149	
432654	M145	
432654	M034	
432655	M024	
432655	M148	
432655	M016	12/0,8 15a
432655	M016	12/0,8 15a
432656	M106	12/0,8 15a
432656	M106	12/0,8 15a
432657	M024	12/0,8
432657	M024	12/0,8
432658	M034	
432658	M149	
432658	M108	
432658	M145	
432658	M107	

VALEO RMA $V_{Kw} -!$

432659	M283	/
432659	M023	/
432659	M131	/
432659	M301	/
432661	M093	/
432661	M096	$12/0,8$
432661	M096	$12/0,8$
432662	M180	/
432662	M180	$12/0,8$
432662	M180	$12/0,8$
432663	M032	/
432663	M032	$12/0,8$
432664	M094	$12/0,6$
432665	M095	/
432665	M095	/
432665	M095	/
432666	M195	/
432668	M105X	/
432668	M105	/
432670	M416	/
432672	M120X	$12/1,9$
432673		/
432674	M262	$12/1,4$
432675	M083X	/
432675	M083	/
432684	M120X	/
432685	M319	/
432700		/
432765		/
432804		/
432829		/
432836		/
433007		0/
433016	M148	0/
433022	M102X	0/
433036		/
433045		/
433052		/
433054		/
433056		/
433057		/
433135		/
433200	M078	$12/0,7$
433201	M075	0/

VALEO RMA $V_{Kw} -!$

433201	M075X	0/
433202	M179	$12/0,8$
433202	M075X	$12/0,8$
433203	M075	$12/0,8$
433203	M075	$12/0,8$
433204	M075X	$12/0,8$
433204	M075X	$12/0,8$
433205	M102	0/
433206	M067	$12/0,6$
433207		$12/0,7$
433208	M124	0/
433208	M124X	0/
433209	M124X	0/
433213	M117	0/
433214		0/
433215	M157	0/
433215	M161	0/
433216	M125	0/
433217		$12/2,8$
433218		$12/2,8$
433219	M156	$12/2,8$
433219	M156	$12/2,8$
433220		0/
433221		0/
433223	M010	$12/0,8$
433223	M010	$12/0,8$
433224		0/
433225		0/
433226	M100	$12/0,8$
433226	M100	$12/0,8$
433227	M101	$12/1,5$
433227	M101	$12/1,5$
433228	M079	$12/2,0$
433229	M254	$12/2,0$
433229	M254	$12/2,0$
433230		0/
433231	M010	0/
433232		0/
433233	PM894	$12/2,5$
433234	M297	0/
433235	M078	0/
433236		0/
433237	M118	0/
433237	M118	$12/0,8$

VALEO RMA $V_{Kw} -!$

433237	M118	$12/0,8$
433238	M196	$12/0,8$
433243	PM908	$12/0,6$
433244	M077	$12/0,6$
433244	M077	$12/0,6$
433245	M119X	$12/1,0$
433245	M119X	$12/1,0$
433246	M192	$12/0,9$
433246	M192	$12/0,9$
433247	M192	$12/0,9$
433247	M192	$12/0,9$
433247	M119X	$12/0,9$
433247	M119	$12/0,9$
433248	M120	$12/1,9$
433249	M017	$12/0,9$
433249	M202	$12/0,9$
433252	M021	0/
433253	M021	$12/1,0$
433254	M029	0/
433254	M029	0/
433255	M084X	$12/0,9$
433255	M084X	$12/0,9$
433256	M121X	$12/2,2$
433257	M280	0/
433257	M280	0/
433259	M012	$12/0,7$
433260	M013	$12/0,7$
433261	M107	$12/0,8$ 15a
433261	M107	$12/0,8$ 15a
433262	M109	$12/1,1$ 15a
433262	M109	$12/1,1$ 15a
433262	M109	$12/1,1$ 15a
433263	M149	$12/0,8$
433263	M034	0/
433264	M024	$12/0,8$
433264	M148	$12/0,8$
433265	M016	$12/0,8$ 15a
433265	M016	$12/0,8$ 15a
433266	M106	$12/0,8$ 15a
433266	M106	$12/0,8$ 15a
433267	M051	$12/1,5$
433267	M051	$12/1,5$
433268	M051	$12/1,7$
433268	M051	$12/1,7$

VALEO	RMA $V_{Kw} -!$	VALEO	RMA $V_{Kw} -!$	VALEO	RMA $V_{Kw} -!$
433269	12 / 0,7	433309	M017 12 / 0,9	433341	M082 0 /
433272	12 / 0,8	433309	M202 12 / 0,9	433342	M110 12 / 0,7
433273	0 /	433309	M017 12 / 0,9	433343	M113 12 / 1,1
433274	M038 12 / 1,0	433310	M121X 12 / 2,9	433343	M113 12 / 1,1
433276	M033 12 / 0,8	433310	M121X 12 / 2,9	433344	M052 12 / 1,7
433276	M033X 12 / 0,8	433311	M176 12 / 1,1	433344	M052 12 / 1,7
433277	M035 12 / 0,8	433313	PM127 0 /	433346	M166 12 / 0,8
433278	M032 12 / 0,8	433314	PM149 0 /	433347	M137 12 / 0,8
433279	M114 0 /	433315	PM149 0 /	433347	M137 12 / 0,8
433279	M114 0 /	433315	PM149 0 /	433348	M048X 12 / 2,2
433282	M028 12 / 2,0	433316	PM645 0 /	433348	M045 12 / 2,2
433283	M039 12 / 0,5	433316	PM645 0 /	433349	M025 0 /
433285	12 / 0,6	433317	PM048 0 /	433357	0 /
433285	12 / 0,6	433318	0 /	433358	M097 0 /
433286	M159 12 / 0,7 15a	433319	M084X 12 / 0,9	433363	0 /
433287	M076 12 / 0,8	433320	M017X 12 / 1,2	433370	PM121 0 /
433287	M076 12 / 0,8	433320	M017X 12 / 1,2	433372	0 /
433287	M082 12 / 0,8	433321	PM024 0 /	433373	M091 0 /
433288	M082 12 / 0,8	433322	M102X 12 / 1,9	433377	0 /
433288	M082 12 / 0,8	433322	M102X 12 / 1,9	434050	M010 0 /
433289	M043 /	433323	M195 12 / 1,4	436000	M072 12 / 1,5
433289	M043 12 / 1,0	433324	M105 12 / 2,0	436000	M072 12 / 1,5
433289	M043 12 / 1,0	433324	M105 12 / 2,0	436001	M073 12 / 1,1
433292	M059 12 / 2,5	433325	M056 12 / 0,9	436002	M088 12 / 2,2
433293	M197 12 / 1,5	433326	M157 12 / 2,2	436002	M088 12 / 2,2
433293	M197 12 / 1,5	433326	M157 12 / 2,2	436002	M088 12 / 2,2
433294	M089 12 / 2,0	433327	M275 12 / 3,1	436003	M083X 12 / 1,4
433295	M253 12 / 2,0	433328	M046 12 / 0,9	436003	M083 12 / 1,4
433296	M094 12 / 0,6	433329	M153 12 / 2,0	436004	M140 12 / 1,5
433297	M095 12 / 0,7	433331	M044 12 / 1,0	436004	M140 12 / 1,5
433298	M096 12 / 0,8	433332	M120X 12 / 1,9	436005	M140 12 / 1,5
433298	M096 12 / 0,8	433333	M055 12 / 1,0	436005	M087 12 / 1,5
433299	M064 12 / 2,0	433334	M218 12 / 1,7	436006	M164 0 /
433300	M084X 12 / 0,9	433335	M251 0 /	436006	M165 0 /
433301	M011 12 / 0,9	433336	M257 12 / 1,7	436007	M023 12 / 0,8
433301	M011 12 / 0,9	433337	M030 12 / 0,7	436008	M026 12 / 1,6
433303	M102 12 / 0,8	433337	M030 12 / 0,7	436009	M152 12 / 0,8 15a
433304	M104 12 / 0,9	433338	M063 12 / 1,5	436010	M049 12 / 1,1
433305	M105 12 / 1,7	433339	M285 12 / 2,2	436010	M049 12 / 1,1
433305	M105 12 / 1,7	433339	M285 12 / 2,2	436011	M093 12 / 1,0
433306	M297 12 / 2,5	433339	M296 12 / 2,2	436012	M174 12 / 1,0 15a
433306	M297X 12 / 2,5	433340	M214 12 / 1,7	436013	M180 12 / 0,8
433307	M124X 12 / 1,0	433340	M214 12 / 1,7	436013	M180 12 / 0,8
433309	M202 12 / 0,9	433340	M214 12 / 1,7	436014	M116 0 /

VALEO	RMA $\frac{V}{Kw} -!$	VALEO	RMA $\frac{V}{Kw} -!$	VALEO	RMA $\frac{V}{Kw} -!$
436015	M068 $\frac{12}{0,9}$	436042	M066X $\frac{0}{}$	436081	M017X $\frac{12}{1,2}$
436015	M148 $\frac{12}{0,9}$	436042	M066X $\frac{0}{}$	436082	M041 $\frac{12}{1,1}$
436016	M148 $\frac{12}{0,9}$	436043	M258 $\frac{12}{2,2}$	436082	M041 $\frac{12}{1,1}$
436016	M068 $\frac{12}{0,9}$	436044	M246 $\frac{12}{2,2}$	436083	M237 $\frac{12}{1,4}$
436017	M063 $\frac{0}{}$	436045	M054 $\frac{12}{2,2}$	436084	M017X $\frac{12}{0,9}$
436017	M063 $\frac{0}{}$	436046	PM555 $\frac{0}{}$	436084	M202 $\frac{12}{0,9}$
436017	M063 $\frac{0}{}$	436047	M238 $\frac{12}{1,4}$	436084	M202 $\frac{12}{0,9}$
436018	$\frac{0}{}$	436048	M069X $\frac{12}{1,4}$	436084	M202 $\frac{12}{0,9}$
436019	M111 $\frac{12}{0,8}$ 15a	436048	M069X $\frac{12}{1,4}$	436085	M240 $\frac{12}{1,4}$
436019	M111 $\frac{12}{0,8}$ 15a	436049	M026 $\frac{0}{}$	436086	PM106 $\frac{0}{}$
436020	M014 $\frac{12}{1,7}$	436049	M058 $\frac{0}{}$	436087	M297X $\frac{0}{}$
436021	M149 $\frac{12}{0,8}$	436050	PM050 $\frac{0}{}$	436089	$\frac{12}{1,2}$
436021	M145 $\frac{12}{0,8}$	436051	M120X $\frac{12}{1,9}$	436090	M176 $\frac{0}{}$
436022	M150 $\frac{12}{0,9}$ 15a	436052	M277 $\frac{12}{3,1}$	436091	PM120 $\frac{0}{}$
436022	M150 $\frac{12}{0,9}$ 15a	436053	M327 $\frac{12}{0,7}$	436092	$\frac{0}{}$
436023	$\frac{12}{0,8}$	436054	M158 $\frac{12}{0,8}$	436093	$\frac{0}{}$
436024	M031 $\frac{12}{0,7}$	436055	M089 $\frac{0}{}$	436095	PM215 $\frac{0}{}$
436025	M172 $\frac{12}{1,1}$	436056	M143 $\frac{12}{0,9}$	436096	PM108 $\frac{0}{}$
436025	M172 $\frac{12}{1,1}$	436056	M143 $\frac{12}{0,9}$	436097	PM215 $\frac{0}{}$
436026	M018 $\frac{0}{}$	436056	M143 $\frac{12}{0,9}$	436098	PM215 $\frac{0}{}$
436027	M040 $\frac{12}{2,2}$	436058	M202 $\frac{12}{0,9}$	436099	PM145 $\frac{0}{}$
436028	M053 $\frac{12}{2,2}$	436058	M017 $\frac{12}{0,9}$	436099	PM145 $\frac{0}{}$
436029	M048 $\frac{12}{2,2}$	436059	M202 $\frac{12}{0,9}$	436565	PM405 $\frac{0}{}$
436030	M112 $\frac{12}{1,0}$ 15a	436059	M017 $\frac{12}{0,9}$	436602	M072 $\frac{0}{}$
436031	M048X $\frac{12}{2,2}$	436060	M017X $\frac{12}{1,2}$	438011	$\frac{0}{}$
436031	M048X $\frac{12}{2,2}$	436061	M121X $\frac{12}{2,2}$	438013	$\frac{0}{}$
436031	M048X $\frac{12}{2,2}$	436062	M176 $\frac{12}{1,1}$	438014	M099 $\frac{0}{}$
436032	M057 $\frac{12}{1,4}$	436062	M222 $\frac{12}{1,1}$	438014	M099X $\frac{0}{}$
436032	M057 $\frac{12}{1,4}$	436063	PM248 $\frac{0}{}$	438014	M162 $\frac{0}{}$
436033	M283 $\frac{12}{0,8}$	436064	M102X $\frac{12}{1,1}$	438014	M064 $\frac{0}{}$
436034	M099 $\frac{12}{1,4}$	436065	M102X $\frac{12}{1,1}$	438014	M099 $\frac{0}{}$
436034	M226 $\frac{12}{1,4}$	436066	M104 $\frac{12}{0,9}$	438014	M226 $\frac{0}{}$
436034	M099X $\frac{12}{1,4}$	436068	M105X $\frac{12}{1,7}$	438015	$\frac{0}{}$
436035	M219 $\frac{12}{1,4}$	436070	PM121 $\frac{0}{}$	438019	PM234 $\frac{0}{}$
436035	M219 $\frac{12}{1,4}$	436073	M091 $\frac{0}{}$	438021	PM288 $\frac{0}{}$
436037	M027 $\frac{12}{2,5}$	436074	PM150 $\frac{0}{}$	438022	$\frac{0}{}$
436037	M027 $\frac{12}{2,5}$	436075	PM125 $\frac{0}{}$	438023	M427 $\frac{0}{}$
436038	M065 $\frac{12}{2,0}$	436076	$\frac{0}{}$	438024	M418 $\frac{0}{}$
436039	M106 $\frac{0}{}$	436077	PM115 $\frac{0}{}$	438027	M414 $\frac{0}{}$
436040	M037 $\frac{12}{2,2}$ 30h	436077	PM122 $\frac{0}{}$	438029	PM902 $\frac{0}{}$
436040	M037 $\frac{12}{2,2}$ 30h	436078	M280 $\frac{12}{1,1}$	438030	$\frac{0}{}$
436040	M037 $\frac{12}{2,2}$ 30h	436079	M417 $\frac{12}{1,2}$	438052	M283 $\frac{0}{}$
436041	M162 $\frac{0}{}$	436080	PM092 $\frac{0}{}$	438052	M362 $\frac{0}{}$
436041	M162 $\frac{0}{}$	436081	M202 $\frac{12}{1,2}$	438052	M131 $\frac{0}{}$

VALEO	RMA $\sqrt{\text{Kw}} -!$	VALEO	RMA $\sqrt{\text{Kw}} -!$	VALEO	RMA $\sqrt{\text{Kw}} -!$
438053	M058 $12/1,7$	438101	PM930	438166	PM919
438054		438102	PM928	438167	PM921
438054		438103	PM929	438168	M143X
438060		438104	PM274 0	438168	PM895
438061	PM027	438105	M425 0	438169	M352
438063	M217	438110		438171	PM569
438063	M261	438111	PM901	438172	PM563
438064	M387	438112	M415	438173	
438065		438113	PM365	438174	PM568
438068	M105	438114	PM932	438175	
438069	M105	438115		438176	PM573
438070		438116		438177	PM896
438071		438117	PM400	438178	M421
438072	M069	438118		438183	PM907
438073	PM918	438119		438184	PM923
438074	M415	438120		438186	PM094
438075	M310	438121	PM927	439178	
438075	M313	438122		439179	
438076	M289	438123		439337	M307
438076	M289X	438131	M314	439403	
438077	M396	438132	PM911	439405	
438078	PM924	438133	PM899	439412	
438079		438134	PM237	439508	
438079	M414	438135	PM913	439509	
438081	M430	438136	PM915	453007	$12/0,6$
438082	PM903	438137	PM069	453009	M072 $12/1,5$
438083	PM904	438138	PM070	453012	0
438084	PM905	438141	M336X	453013	M021 0
438086	M222	438144	PM916	453014	M021 $12/1,0$
438086	M195	438145	M393	453015	PM908 $12/0,6$
438087		438146	*****	453016	M010 $12/0,8$
438088		438147	PM917	453017	M156 $12/2,0$
438089	PM910	438151	PM920	453021	M078 $12/0,7$
438090		438152		453022	M079 $12/2,0$
438091	M390	438154		453022	M079 $12/2,0$
438092		438156	PM914	453025	M179 $12/0,7$
438093	M391	438157	PM925	453027	M119 $12/0,8$
438094	PM898	438158	PM240	453027	M119 $12/0,8$
438095	PM239	438159	PM341	453028	M119 $12/0,8$
438096	PM239	438161	PM049	453028	M119 $12/0,8$
438097		438162		453028	M192 $12/0,8$
438098	PM376	438163	PM912	453030	0
438099	PM931	438164	PM922	453030	0
438100		438165		453031	M075X $12/0,8$

VALEO	RMA $V_{Kw} -!$	VALEO	RMA $V_{Kw} -!$	VALEO	RMA $V_{Kw} -!$
453031	M075X $12/0,8$	455504	PM184 $0/$	455546	PM195 $0/$
453031	M075X $12/0,8$	455505	PM184 $0/$	455547	M034 $0/$
453033	M124 $12/0,9$	455507	PM127 $0/$	455547	M034 $0/$
453033	M124X $0/$	455508	M246 $12/2,2$	455548	M248 $12/1,1$
453034	$0/$	455509	PM215 $0/$	455549	M215 $0/$
453035	M100 $12/0,8$	455511	M056 $0/$	455550	M120X $0/$
453035	M100 $12/0,8$	455512	M102X $12/1,1$	455551	PM251 $0/$
453036	M067 $12/0,6$	455514	M105 $12/1,7$	455552	M419 $0/$
453039	$12/0,7$	455514	M105 $12/1,7$	455553	M268 $12/0,8$
453040	M084 $12/0,9$	455516	PM137 $0/$	455554	M088X $12/2,2$
453041	M118 $0/$	455517	PM138 $0/$	455555	PM403 $0/$
453045	M196 $0/$	455518	PM146 $0/$	455557	PM370 $0/$
453046	M117 $12/1,1$	455518	PM146 $0/$	455557	PM370 $0/$
453048	M161 $12/2,2$	455519	PM156 $0/$	455558	PM408 $0/$
453051	M013 $12/0,7$	455520	PM155 $0/$	455559	PM780 $0/$
453051	M013 $12/0,7$	455520	PM155 $0/$	455560	PM385 $0/$
453052	M017 $12/0,8$	455521	PM142 $0/$	455560	PM341 $0/$
453052	M017 $12/0,8$	455521	PM142 $0/$	455561	M425 $0/$
454347	M222 $0/$	455522	PM207 $0/$	455561	M425X $0/$
454348	M017X $0/$	455523	PM194 $0/$	455561	M425 $0/$
454400	M222 $0/$	455524	PM202 $0/$	455562	M425 $0/$
454401	M017X $0/$	455525	PM139 $0/$	455562	M425X $0/$
454432	PM024 $0/$	455526	$0/$	455563	PM380 $0/$
454462	M248 $0/$	455526	PM195 $0/$	455564	M424 $0/$
454490	M017X $0/$	455527	PM128 $0/$	455564	M424 $0/$
454506	M222 $0/$	455528	PM106 $0/$	455565	PM405 $0/$
454524	M222 $0/$	455529	PM106 $0/$	455566	PM371 $0/$
454632	M222 $0/$	455530	PM189 $0/$	455567	PM512 $0/$
454638	M222 $0/$	455531	PM204 $0/$	455567	PM512 $0/$
454654	M222 $0/$	455532	PM164 $0/$	455568	PM372 $0/$
454657	M222 $0/$	455533	PM136 $0/$	455569	M320 $12/0,8$
454718	M248 $0/$	455534	PM190 $0/$	455570	PM377 $0/$
454730	M248 $0/$	455534	PM190 $0/$	455571	PM281 $0/$
454748	M248 $0/$	455535	PM198 $0/$	455572	PM273 $0/$
454762	M248 $0/$	455536	PM110 $0/$	455573	M128 $0/$
455174	PM693 $0/$	455537	PM226 $0/$	455574	PM272 $0/$
455392	M017X $0/$	455538	PM170 $0/$	455574	PM272 $0/$
455431	PM204 $0/$	455539	PM192 $0/$	455575	M013 $0/$
455441	M017X $0/$	455540	PM192 $0/$	455575	M128 $12/1,0$
455451	M017X $0/$	455541	PM213 $0/$	455576	M128 $0/$
455500	PM247 $0/$	455542	PM210 $0/$	455576	M130 $0/$
455501	PM171 $0/$	455543	PM192 $0/$	455577	PM294 $0/$
455502	PM215 $0/$	455544	PM192 $0/$	455577	M432 $0/$
455503	RM090 $0/$	455545	PM133 $0/$	455578	PM295 $12/1,0$

VALEO	RMA $V_{Kw} -!$	VALEO	RMA $V_{Kw} -!$	VALEO	RMA $V_{Kw} -!$
455578	M194 $12/1,0$	455613	M325 $12/0,8$	455691	M105 $0/$
455578	M194 $12/1,0$	455614	PM141 $0/$	455691	M105 $0/$
455579	PM294 $0/$	455615	PM184 $0/$	455693	M416 $0/$
455579	M432 $0/$	455616	PM199 $0/$	455694	M120 $0/$
455580	M432 $0/$	455618	PM106 $0/$	455695	M120X $0/$
455580	M432 $0/$	455619	$0/$	455696	M052 $0/$
455581	M201 $0/$	455621	PM128 $0/$	455696	M015 $0/$
455582	M433 $0/$	455622	$0/$	455697	PM252 $0/$
455583	PM520 $12/1,0$	455623	PM204 $0/$	455698	PM254 $0/$
455584	PM381 $0/$	455624	M247 $12/2,2$	455699	M143 $0/$
455585	PM603 $12/1,0$	455625	M251 $12/0,9$	455700	M095 $0/$
455586	PM600 $0/$	455626	M228 $0/$	455702	RM088 $0/$
455587	PM296 $0/$	455627	PM216 $0/$	455704	RM092 $0/$
455588	PM287 $0/$	455628	M256 $12/1,8$	455713	PM295 $0/$
455589	PM286 $0/$	455629	M394 $0/$	455714	PM693 $0/$
455590	PM424 $12/0,8$	455630	$0/$	455715	M427 $0/$
455591	PM437 $0/$	455632	M376 $0/$	455716	M427 $0/$
455591	PM437 $0/$	455634	M388 $0/$	455717	PM289 $0/$
455592	PM400 $0/$	455638	PM431 $0/$	455719	M120X $0/$
455593	PM274 $0/$	455661	M134 $0/$	455720	M399 $0/$
455594	PM796 $0/$	455665	M433 $0/$	455720	M399 $0/$
455595	PM419 $0/$	455669	PM135 $0/$	455720	M399 $0/$
455595	PM419 $0/$	455671	M185 $12/1,4$ 30h	455721	M010 $0/$
455596	PM443 $0/$	455671	M185 $12/1,4$ 30h	455722	M319 $0/$
455596	PM443 $0/$	455672	M236 $12/1,1$	455723	PM761 $0/$
455597	M127 $12/0,8$	455673	M191 $12/1,1$	455724	M235X $0/$
455598	M129 $12/0,8$	455674	M216 $12/1,7$	455725	M307 $0/$
455599	$0/$	455675	M383 $0/$	455726	$0/$
455600	PM480 $0/$	455676	M175 $12/1,4$ 30h	455727	M310 $0/$
455600	PM430 $0/$	455677	M299X $12/1,7$ 30h	455728	M255 $0/$
455601	M337 $12/0,8$	455678	RM039 $0/$	455731	M308 $0/$
455603	$0/$	455679	$0/$	455732	M223 $0/$
455604	PM423 $0/$	455680	M227 $12/1,1$	455733	RM040 $0/$
455605	PM400 $0/$	455681	M299 $12/1,5$	455734	PM233 $0/$
455606	M433 $0/$	455682	M375 $12/1,4$ 30h	455736	M099X $0/$
455606	M433 $0/$	455683	M250 $12/1,7$	455737	PM288 $0/$
455607	M425 $0/$	455683	M250 $12/1,7$	455738	M017X $0/$
455607	M425X $0/$	455684	M260 $12/1,4$	455739	PM535 $0/$
455608	PM327 $0/$	455685	PM025 $0/$	455740	PM536 $0/$
455609	M433 $0/$	455685	PM025 $0/$	455741	PM234 $0/$
455610	PM408 $0/$	455686	M243 $12/1,4$	455743	M423 $0/$
455611	PM603 $0/$	455687	M195 $0/$	455744	M340 $0/$
455611	PM602 $0/$	455688	$0/$	455745	PM093 $0/$
455612	PM444 $0/$	455690	M017E $0/$	455746	M214 $0/$

VALEO	RMA $\sqrt{\text{Kw}} -!$	VALEO	RMA $\sqrt{\text{Kw}} -!$	VALEO	RMA $\sqrt{\text{Kw}} -!$
455747	M414 0/	455905	M193 0/	455940	M421 0/
455748	M222 0/	455906	PM396 0/	455942	M306 0/
455749		455907	PM299 0/	455942	M306 0/
455749	M105 0/	455908	PM643 0/	455943	M120X 0/
455774		455909	PM527 0/	455943	M120X 0/
455807	M318 0/	455909	PM526 0/	455947	M083X 0/
455823	M137 0/	455910	PM643 0/	455947	M083 0/
455840	PM250 0/	455910	PM632 0/	455949	M414 0/
455871	PM218 0/	455910	PM643 0/	455950	M430 0/
455872	M046 0/	455911	M336X 0/	455954	PM240 0/
455873	M026 0/	455912	M336 0/	455955	M195 0/
455873	M026 0/	455913	M441 0/	455956	PM897 0/
455876	PM237 0/	455914	M332 0/	455957	PM926 0/
455877	M311 0/	455915	PM274 0/	455959	PM239 0/
455878	M312 0/	455916	PM351 0/	455960	M390 0/
455879	M314 0/	455917	M442 0/	455962	M391 0/
455881	M314 0/	455917	M442 0/	455964	PM376 0/
455884	M338 0/	455918	M437 0/	455971	PM239 0/
455885	PM032 0/	455918	M437 0/	455972	PM239 0/
455885	PM032 0/	455919	M437 0/	455973	M143 0/
455886	M423 0/	455922	PM602 0/	455974	PM237 0/
455886	M423 0/	455923	PM456 0/	455976	M415 0/
455887	M344 0/	455924	PM015 0/	455977	PM684 0/
455888	PM031 0/	455925	PM432 0/	455978	M244 0/
455889	M037 0/	455926	PM184 0/	455979	M392 0/
455889	M037 0/	455927	M289X 0/	455981	M255 0/
455890	0/	455928	M105 0/	455982	PM899 0/
455891	0/	455929	M105 0/	455983	PM237 0/
455891	0/	455930	M313 0/	455985	PM889 0/
455891	PM027 0/	455931	PM288 0/	457930	M313 0/
455891	PM027 0/	455932	M418 0/	458041	M396 0/
455892	0/	455933	M069 0/	458116	M317 0/
455893	M235X 0/	455934	PM918 0/	458117	M317 0/
455894	M387 0/	455934	PM918 0/	458117	M317 0/
455895	M420 0/	455934	PM918 0/	458118	M307 0/
455896	M214 0/	455935	M260 0/	458159	PM069 0/
455897	M305 0/	455935	M260 0/	458160	PM070 0/
455899	PM094 0/	455936	M415 0/	458161	M336X 0/
455900	PM094 0/	455936	M415 0/	458163	M393 0/
455901	M327 0/	455937	M102X 0/	458166	PM920 0/
455902	M328 0/	455937	M440 0/	458167	PM080 0/
455903	M261 0/	455939	M289 0/	458168	M406 0/
455903	M261 0/	455939	M289 0/	458169	M385 0/
455904	M138 0/	455940	M421 0/	458172	PM240 0/

VALEO	RMA $\sqrt{\text{Kw}} -!$	VALEO	RMA $\sqrt{\text{Kw}} -!$	VALEO	RMA $\sqrt{\text{Kw}} -!$
458173	PM341	458473	PM055	458622	PM446
458174	PM179	458484	M282	458625	PM021
458175	RM091	458487		458627	M271
458176	PM180	458488	PM051	458629	M334
458177	PM105	458491	M193	458632	PM023
458178		458492	M315	474745	0
458179	PM912	458494	PM052	499004	M010
458181	PM049	458502		499007	M192 0
458184	M314	458504	M284	499007	M192 0
458185	PM919	458507	PM097	499013	M082 0
458188	M143	458515	PM501	499013	M076 0
458189	PM010	458517	M381	499014	M095 0
458190	M262	458519	PM020	499016	M104 0
458192	M352	458520	PM374	499025	M056 0
458194	M062	458523	M151	499027	M150 0
458195	M200	458526	M380	516038BC	
458196	PM012	458528	PM058	518035	
458197	M013X	458529	M333	530006	M013 0
458202	PM089	458532	PM695	532000	M021 12/1,0
458203	M308	458537	PM521	532001	M021 12/1,0
458204	M265	458539	PM087	532002	M119 12/0,8
458206	M201	458540		532002	M119X 12/0,8
458207	PM274	458541	M211	532002	M119X 12/0,8
458208	PM099	458545	M304	532003	M124X 12/0,9
458211		458546	M426	532003	M124 12/0,9
458212	M384	458548	PM094	532004	M124X 12/0,9
458213	PM569	458555	PM045	532004	M124 12/0,9
458214	PM563	458560	PM459	532005	M010 0
458215	PM564	458563	PM088	532007	M118 12/0,8
458216	PM568	458569		532007	M070 12/0,8
458217	PM572	458570		532008	M021 12/1,0
458218	PM573	458573	M412	532008	M021 12/1,0
458219	PM641	458590	PM491	532009	M084X 12/0,9
458220	PM042	458591	PM785	532009	M084 12/0,9
458221	PM071	458593	M048X	532010	M119 12/0,8
458222	M099	458595		532010	M119X 12/0,8
458223	PM066	458598	PM425	532011	M100 12/0,8
458224	RM086	458599	PM416	532012	M067 12/0,6
458230	M405	458607	PM454	532014	M075X 12/0,8
458461	PM078	458608	PM516	532014	M075X 12/0,8
458462	PM063	458611	PM429	532014	M075 12/0,8
458463	PM013	458615	M223	532016	12/0,7
458464	PM026	458616	M044	532017	M077 12/0,6
458469		458621	PM423	532017	M119X 12/0,6

VALEO	RMA \sqrt{Kw} -!	VALEO	RMA \sqrt{Kw} -!	VALEO	RMA \sqrt{Kw} -!
532018	M084X $12/0,9$	534047	M192 $12/0,9$	6155	0
532018	M084 $12/0,9$	534048	M075X $12/0,8$	6160	0
532020	M075X $12/0,7$	534048	M075X $12/0,8$	6161	M203 $12/0,8$
532020	M075X $12/0,7$	534049	M100 $12/0,8$	6162	0
532020	M179 $12/0,7$	534050	M010 $12/0,8$	6172	M119 $12/0,6$
532021	PM908 $12/0,6$	534053	M056 $12/0,9$	6172	M077 $12/0,6$
532023	PM908 $12/0,6$	534054	M074 $12/0,9$	6174	0
532024	M033 $12/0,8$	534054A	M222	6176	0
532024	M033 $12/0,8$	534055	M074 $12/0,9$	6177	0
532027	M055 $12/1,0$	534056	M046 $12/0,9$	6178	$12/1,5$
533000	M044 $12/1,0$	534057	M017 $12/0,8$	6180	PM334 0
533001	M100 $12/0,8$	536001	M117 $12/1,1$	618074	0
533002	M010 $12/0,8$	536611	M013 0	618076	0
533003	0	536611	M013 0	618077	M010 $12/0,8$
533004	0	538000	M125 $12/2,2$	618078	M010 $12/0,8$
533051	M013 0	538001	M161 $12/2,2$	618089	M079 $12/2,0$
533051	M013 0	538002	M161 $12/2,2$	618091	M179 $12/0,7$
533052	M013 0	538003	M125 $12/2,2$	6181	0
533052	M013 0	538005	$12/2,8$	6182	0
534002	M012 $12/0,7$	538006	M161 $12/2,8$	6183	M021 $12/1,0$
534003	M118 $12/0,8$	538008	0	618358	M179 $12/0,7$
534004	M118 $12/0,8$	538050	0	6184	0
534005	M118 $12/0,8$	538500	M059 0	618482	0
534007	M118 $12/0,8$	538501	M294 0	6185	PM908 $12/0,6$
534009	M117 $12/1,1$	538502	PM645 0	618538	M179 $12/0,7$
534015	0	583028	M100 $12/0,8$	618565	M010 $12/0,8$
534023	M084X $12/0,9$	583045		618595	M010 0
534027	M011 $12/0,9$	583045	M100 $12/0,8$	6187	M077 $12/0,6$
534028	M011 $12/0,9$	6010	0	6187	M119 $12/0,6$
534029	M017 $12/0,8$	6020	0	6187	M010 $12/0,6$
534031	M202 $12/0,9$	6035	0	618795	
534031	M017 $12/0,9$	6056	0	618795	M010 $12/0,8$
534032	M192 $12/1,0$	6081	0	6189	M010 $12/0,8$
534032	M119X $12/1,0$	6092	0	6190	M010 $12/0,8$
534035	M044 0	6099	0	6192	M156 $12/2,0$
534036	M044 $12/1,0$	6109	M156 $12/2,0$	6193	0
534039	M102 $12/0,8$	6112	0	6195	0
534042	M017 $12/0,8$	6127	PM147 0	6200	0
534043	M202 $12/0,9$	6128	M119 $12/0,6$	6201	0
534043	M102 $12/0,8$	6128	M077 $12/0,6$	6202	M078 $12/0,7$
534043	M202 $12/0,9$	6134	0	6202A	M078 0
534044	M084X $12/0,9$	6135	0	6202B	M078 0
534045	M100 $12/0,8$	6136	PM908 $12/0,6$	6202C	M078 0
534046	M010 $12/0,8$	6139	PM908 0	6202D	M078 0

VALEO	RMA $V_{Kw} -!$	VALEO	RMA $V_{Kw} -!$	VALEO	RMA $V_{Kw} -!$
6202F	M078 0	6236	M117 12/1,1	D10E66	M215 12/1,5
6203	M077 12/0,6	6237	0	D10E72	M101 12/1,5
6206	12/0,7	6237A	0	D10E73	12/1,5
6207	M079 12/2,0	6237C	0	D10E74	M215 12/1,5
6208	M078 12/0,7	6237D	0	D10E75	M109 12/1,1 15a
6211	M119 0	6237E	0	D10E75	M109 12/1,1 15a
6211	M192 0	6237F	0	D10E76	0
6212	M010 12/0,8	6238	0	D10E79	12/2,2
6215	0	6238	0	D10E80	M021 0
6216	M179 12/0,7	6238A	0	D10E81	M109 12/1,1 15a
6217	12/0,7	6238B	0	D10E81	M109 12/1,1 15a
6217A	0	6238C	0	D10E83	M109 12/1,1 15a
6217B	0	6238D	0	D10E83	M109 12/1,1 15a
6217C	0	6239	M117 12/1,1	D10E85	M120 12/1,9
6217D	0	6240	M010 12/0,8	D10E87	M280 12/1,1
6217E	0	6241	M078 12/0,7	D10E87	M280 12/1,1
6217F	0	6242		D10E88	M215 12/2,2
6217G	0	6242	M010 12/0,8	D10E881	M215 12/2,2
6217H	0	6244	M070 12/0,8	D10E882	M215 12/2,2
6219	PM908 12/0,6	6245	M196 12/0,8	D10E882	M215 12/2,2
6220	M075 12/0,8	6246	M013 12/0,7	D10E89	M215 12/2,2
6220	M075 12/0,8	6247	M075 12/0,8	D10E92	M120 12/1,9
6220	M075 12/0,8	6247	M075 12/0,8	D10E921	M120 12/1,9
6221	M119 12/0,8	6247	M075 12/0,8	D10E922	M120 12/1,9
6221	M192 12/0,8	632020	M179 12/0,7	D11E104	PM120 0
6221	M192 12/0,8	8293	M102 12/0,8	D11E105	0
6222	M013 12/0,7	8294	M102 12/0,8	D11E109	M156 12/2,0
6223	M070 12/0,8	93BB11000HC		D11E110	0
6224	M021 12/1,0	93BB11000JC		D11E118	PM127
6225	0	95675	M118	D11E118	PM127
6226	M203 12/0,8	D10E41	0	D11E118	PM127 0
6227	M119 12/0,6	D10E43	M021 0	D11E119	PM120 0
6227	M077 12/0,6	D10E47	12/1,5	D11E119T	PM120
6230	M125 12/2,2	D10E48	M021 0	D11E120	PM149 0
6231	M119 12/0,8	D10E52	0	D11E122	PM108 0
6231	M119 12/0,8	D10E54	0	D11E122T	PM108 0
6231	M119 12/0,8	D10E55	0	D11E123	0
6231A	M119 0	D10E57	0	D11E126	M079 12/2,0
6231B	M119 0	D10E59	M280 12/1,1	D11E131	PM149 0
6231C	M119 0	D10E59	M280 12/1,1	D11E135	0
6231D	M119 0	D10E63	M021 12/1,0	D11E137	PM645 0
6232	PM147 0	D10E63	M021 12/1,0	D11E139	PM145 0
6233	PM334 0	D10E64	0	D11E139T	PM145
6236	M117 12/1,1	D10E65	0	D11E141	PM147 12/2,0

VALEO RMA $\frac{V}{Kw - !}$

D11E142	M156 $\frac{12}{2,0}$
D11E143	$\frac{0}{}$
D11E146	PM127 $\frac{0}{}$
D11E148	$\frac{12}{2,5}$
D11E153	PM127 $\frac{0}{}$
D11E153T	PM127 $\frac{0}{}$
D11E154	PM645 $\frac{0}{}$
D11E155	PM147 $\frac{12}{2,0}$
D11E156	M079 $\frac{12}{2,0}$
D11E158	PM149 $\frac{0}{}$
D11E159	M156 $\frac{12}{2,0}$
D11E15H	PM645 $\frac{0}{}$
D11E161	PM894 $\frac{12}{2,5}$
D11E163	M161 $\frac{12}{2,2}$
D11E164	M125 $\frac{12}{2,2}$
D11E165	$\frac{0}{}$
D11E167	PM134 $\frac{0}{}$
D11E167T	PM134 $\frac{0}{}$
D11E169	M161 $\frac{12}{2,8}$
D11E170	M156 $\frac{12}{2,0}$
D11E172	M121 $\frac{12}{2,2}$
D11E173	$\frac{12}{2,8}$
D11E174	$\frac{0}{}$
D11E176	M161 $\frac{12}{2,8}$
D11E177	M161 $\frac{12}{2,2}$
D11E179	M254 $\frac{0}{}$
D11E184	M254 $\frac{12}{2,0}$
D11E184	M254 $\frac{12}{2,0}$
D11E187	$\frac{12}{2,8}$
D11E188	M297 $\frac{12}{2,5}$
D11E191	M254 $\frac{12}{2,0}$
D11E192	M297 $\frac{12}{2,5}$
D11E193	PM145 $\frac{0}{}$
D11E195	M079 $\frac{12}{2,0}$
D11E195	M079 $\frac{12}{2,0}$
D11E198	$\frac{0}{}$
D11E198	RM029 $\frac{0}{}$
D11E272	M121 $\frac{12}{2,2}$
D11E35	PM688 $\frac{0}{}$
D11E59	PM688 $\frac{0}{}$
D11E61	PM127 $\frac{0}{}$
D11E79	$\frac{0}{}$
D11E84	PM147 $\frac{12}{2,0}$
D11E93	PM127 $\frac{0}{}$

VALEO RMA $\frac{V}{Kw - !}$

D11E93	PM127 $\frac{0}{}$
D11E97	$\frac{0}{}$
D11E99	PM108 $\frac{0}{}$
D11E99T	PM108 $\frac{0}{}$
D13E105	$\frac{0}{}$
D13E107	PM215 $\frac{0}{}$
D13E107TE	PM215 $\frac{0}{}$
D13E110	PM215 $\frac{0}{}$
D13E110TE	PM215 $\frac{0}{}$
D13E111	PM215 $\frac{0}{}$
D13E117	PM215 $\frac{0}{}$
D13E117TE	PM215 $\frac{0}{}$
D13E118	PM215 $\frac{0}{}$
D13E118TE	PM215 $\frac{0}{}$
D13E119	PM215 $\frac{0}{}$
D13E119TE	PM215 $\frac{0}{}$
D13E120TE	RM090 $\frac{0}{}$
D13E121TE	$\frac{0}{}$
D13E123	PM215 $\frac{0}{}$
D13E123TE	PM215 $\frac{0}{}$
D13E63	PM184 $\frac{0}{}$
D13E63T	PM184 $\frac{0}{}$
D13E69	PM184 $\frac{0}{}$
D13E69T	PM184 $\frac{0}{}$
D13E81	PM184 $\frac{0}{}$
D13E81T	PM184 $\frac{0}{}$
D13E95	$\frac{0}{}$
D13HP601	RM040 $\frac{0}{}$
D13HP605	$\frac{0}{}$
D13HP607	RM088 $\frac{0}{}$
D13HP613	PM761 $\frac{0}{}$
D13HP702	RM092 $\frac{0}{}$
D13HP703	PM215 $\frac{0}{}$
D13HP709	PM761 $\frac{0}{}$
D15E30	$\frac{0}{}$
D15E30T	$\frac{0}{}$
D15E30TE	$\frac{0}{}$
D6G1	M143X $\frac{0}{}$
D6G1	PM895 $\frac{0}{}$
D6G2	PM896 $\frac{0}{}$
D6G3	M222 $\frac{0}{}$
D6G32	M143X $\frac{0}{}$
D6G5	$\frac{0}{}$
D6GS11	PM569 $\frac{0}{}$

VALEO RMA $\frac{V}{Kw - !}$

D6GS12	PM563 $\frac{0}{}$
D6GS13	PM564 $\frac{0}{}$
D6GS14	PM568 $\frac{0}{}$
D6RA10	M176 $\frac{12}{1,1}$
D6RA100	M222 $\frac{12}{1,4}$
D6RA101	M415 $\frac{0}{}$
D6RA104	M415 $\frac{0}{}$
D6RA105	M415 $\frac{0}{}$
D6RA107	PM897 $\frac{0}{}$
D6RA108	PM898 $\frac{0}{}$
D6RA109	M102X $\frac{0}{}$
D6RA11	PM255 $\frac{0}{}$
D6RA110	PM899 $\frac{0}{}$
D6RA112	PM900 $\frac{0}{}$
D6RA115	M415 $\frac{0}{}$
D6RA12	PM024 $\frac{0}{}$
D6RA12	PM024 $\frac{0}{}$
D6RA13	M327 $\frac{12}{0,7}$
D6RA132	M143 $\frac{0}{}$
D6RA133	M017X $\frac{12}{1,2}$
D6RA137	PM901 $\frac{0}{}$
D6RA138	M393 $\frac{0}{}$
D6RA141	M417 $\frac{0}{}$
D6RA15	M376 $\frac{12}{1,2}$
D6RA16	M102X $\frac{12}{1,1}$
D6RA161	M102X $\frac{0}{}$
D6RA162	M143 $\frac{0}{}$
D6RA163	M143 $\frac{0}{}$
D6RA165	PM902 $\frac{0}{}$
D6RA167	PM903 $\frac{0}{}$
D6RA168	M083X $\frac{12}{1,4}$
D6RA168	M083X $\frac{12}{1,4}$
D6RA17	PM528 $\frac{12}{2,2}$
D6RA18	M102X $\frac{12}{1,1}$
D6RA180	PM904 $\frac{0}{}$
D6RA181	PM905 $\frac{0}{}$
D6RA185	PM902 $\frac{0}{}$
D6RA187	PM901 $\frac{0}{}$
D6RA188	M393 $\frac{0}{}$
D6RA19	M379 $\frac{12}{1,1}$
D6RA20	M176 $\frac{12}{1,1}$
D6RA21	PM906 $\frac{0}{}$
D6RA210	PM906 $\frac{0}{}$
D6RA22	M388 $\frac{0}{}$

VALEO RMA $\frac{V}{Kw - !}$

D6RA23	PM537	$\frac{12}{1,1}$
D6RA23	PM537	$\frac{12}{1,1}$
D6RA249	M143	
D6RA25	M175	$\frac{12}{1,1}$
D6RA25	M175	$\frac{12}{1,1}$
D6RA26	M110	$\frac{12}{0,7}$
D6RA28	M072	$\frac{12}{1,5}$
D6RA29	M379	
D6RA293	PM907	
D6RA30	M270	$\frac{12}{0,8}$
D6RA30	M033	$\frac{12}{0,8}$
D6RA31	M094	$\frac{12}{0,6}$
D6RA32	M143	$\frac{12}{0,9}$
D6RA33	M017X	$\frac{12}{1,2}$
D6RA34	M379	$\frac{12}{1,1}$
D6RA35	M176	$\frac{0}{}$
D6RA37	M222	$\frac{12}{1,0}$
D6RA38	M102X	$\frac{12}{1,1}$
D6RA38	M102X	$\frac{12}{1,1}$
D6RA39	M056	$\frac{12}{0,9}$
D6RA40	PM255	$\frac{0}{}$
D6RA41	M417	$\frac{0}{}$
D6RA42	PM908	$\frac{12}{0,6}$
D6RA421	PM908	
D6RA43	M078	$\frac{12}{0,7}$
D6RA431	M078	
D6RA44	M067	$\frac{12}{0,6}$
D6RA441	M067	
D6RA45	PM251	$\frac{0}{}$
D6RA46	M017X	$\frac{12}{1,2}$
D6RA47	M011	$\frac{12}{0,9}$
D6RA47	M011	$\frac{12}{0,9}$
D6RA48	M143	$\frac{0}{}$
D6RA49		$\frac{0}{}$
D6RA5	M176	$\frac{12}{1,1}$
D6RA50	M379	$\frac{12}{1,1}$
D6RA51	M176	$\frac{12}{1,1}$
D6RA511	M176	$\frac{12}{1,1}$
D6RA52	M388	$\frac{0}{}$
D6RA53	PM251	$\frac{0}{}$
D6RA54	M379	$\frac{12}{1,1}$
D6RA55	PM909	
D6RA56	M017X	$\frac{12}{1,2}$
D6RA57	M222	$\frac{12}{1,0}$

VALEO RMA $\frac{V}{Kw - !}$

D6RA571	M222	$\frac{12}{1,0}$
D6RA572	M222	$\frac{12}{1,0}$
D6RA59	M268	$\frac{12}{0,8}$
D6RA6	M017X	$\frac{12}{1,2}$
D6RA60	PM531	$\frac{12}{2,2}$
D6RA61	M017X	$\frac{12}{1,2}$
D6RA62	M143	$\frac{12}{0,9}$
D6RA63	M416	$\frac{0}{}$
D6RA64	PM537	$\frac{12}{1,1}$
D6RA65	PM902	
D6RA66	M102X	$\frac{12}{1,1}$
D6RA661	M102X	$\frac{12}{1,1}$
D6RA67	PM288	$\frac{0}{}$
D6RA68	M083	$\frac{12}{1,4}$
D6RA68	M083X	$\frac{12}{1,4}$
D6RA7	M376	$\frac{12}{1,2}$
D6RA72	PM024	$\frac{0}{}$
D6RA721	PM024	$\frac{0}{}$
D6RA73	M017X	$\frac{0}{}$
D6RA74	PM243	$\frac{0}{}$
D6RA75	PM909	
D6RA76	PM252	$\frac{0}{}$
D6RA78	PM535	$\frac{0}{}$
D6RA79	PM536	$\frac{0}{}$
D6RA8	M102X	$\frac{12}{1,1}$
D6RA80	PM288	$\frac{0}{}$
D6RA80	PM288	
D6RA80	PM288	$\frac{0}{}$
D6RA81	M418	$\frac{0}{}$
D6RA81	M418	
D6RA81	M418	
D6RA82	M099X	$\frac{12}{1,4}$
D6RA82	M099X	$\frac{12}{1,4}$
D6RA83	M414	$\frac{0}{}$
D6RA84	PM902	
D6RA85	PM902	
D6RA87	PM910	
D6RA9	M176	$\frac{12}{1,1}$
D6RA91	PM911	
D6RA92	M314	
D6RAD183	*****	
D6RAD183	M414	
D6RAP404	PM897	
D7E1	M319	$\frac{12}{0,7}$

VALEO RMA $\frac{V}{Kw - !}$

D7E15	M430	$\frac{0}{}$
D7E16	M222	
D7E18	M414	
D7E19	PM237	$\frac{0}{}$
D7E2	M222	$\frac{12}{1,0}$
D7E20	M430	
D7E22	PM237	$\frac{0}{}$
D7E23	M222	
D7E25	M176	$\frac{0}{}$
D7E26	PM237	
D7E27	PM912	
D7E29	PM913	
D7E30	PM889	
D7E31	PM069	$\frac{0}{}$
D7E31		
D7E31	PM069	$\frac{0}{}$
D7E32	PM914	
D7E39	M319	
D7E4	M414	$\frac{0}{}$
D7E40	PM915	
D7E42	PM914	
D7E47	PM912	
D7E5	M222	$\frac{12}{1,0}$
D7E51	M176	$\frac{0}{}$
D7E52	PM916	
D7E6	PM237	$\frac{0}{}$
D7E7	M391	$\frac{0}{}$
D7E71	M391	$\frac{0}{}$
D7E8	M414	$\frac{0}{}$
D7ED28	*****	
D7ED28	PM917	
D7EP12	M143	
D7ES2	PM918	$\frac{0}{}$
D7ES4	PM918	
D7ES5	PM070	
D7G11	PM240	
D7G3	PM919	
D7G4	PM920	
D7G6	PM049	
D7G6	PM049	
D7GS10	PM573	
D7GS10	PM573	
D7GS17	PM921	
D7GS7	PM922	

VALEO RMA $\frac{V}{Kw - !}$

D7GS8	PM572	
D7GS9	PM923	
D7R1	M195	$\frac{12}{1,4}$
D7R1	M195	$\frac{12}{1,4}$
D7R11	M195	$\frac{12}{1,4}$
D7R12	M105	$\frac{12}{1,7}$
D7R13	M120X	$\frac{12}{1,9}$
D7R14		
D7R15	M195	$\frac{12}{1,4}$
D7R151	M195	0
D7R16	PM254	$\frac{12}{1,4}$
D7R16	PM254	$\frac{12}{1,4}$
D7R17	PM233	0
D7R18	M120X	$\frac{12}{1,9}$
D7R19	M399	$\frac{12}{2,2}$
D7R19+KIT		
D7R2	M105	$\frac{12}{1,7}$
D7R2	M105	$\frac{12}{1,7}$
D7R20	M105	0
D7R22	PM234	0
D7R23	PM093	0
D7R24	M105	0
D7R25	M120X	$\frac{12}{1,9}$
D7R25	M120X	$\frac{12}{1,9}$
D7R26	M105	0
D7R27	M105	0
D7R28	M399	$\frac{12}{2,2}$
D7R28	M399	$\frac{12}{2,2}$
D7R28	M399	$\frac{12}{2,2}$
D7R281	M399	0
D7R3	M195	$\frac{12}{1,4}$
D7R33	M069	0
D7R34	PM240	0
D7R35	M120X	0
D7R36	PM924	
D7R37	PM925	
D7R4	M105	$\frac{12}{1,7}$
D7R40	PM926	
D7R41	M246	
D7R42	M058	0
D7R43	M088X	
D7R43	M088X	
D7R44	PM239	0
D7R46	M088X	

VALEO RMA $\frac{V}{Kw - !}$

D7R47	PM239	0
D7R48	PM239	
D7R49	PM239	
D7R5	M120X	$\frac{12}{1,9}$
D7R53	PM240	
D7R57	PM094	
D7R61	M352	
D7R7	M058	$\frac{12}{1,7}$
D7R8	M105	$\frac{12}{1,7}$
D7R8	M105	$\frac{12}{1,7}$
D7RP123	M088X	0
D7RP158		0
D7RP204	PM240	
D7RP82	PM233	0
D7RS1	PM295	0
D7RS129	M313	
D7RS130	M289X	
D7RS130	M289	
D7RS131	M396	
D7RS150		
D7RS150	PM080	
D7RS29	M313	0
D7RS30	M289X	0
D7RS31	M396	0
D7RS50	PM080	
D7RS7	PM289	0
D7RSA10	M427	0
D7RSA10	M427	0
D7RSA11	M427	0
D7RSA2	PM295	0
D7RSA3	PM693	
D7RSA4	M427	0
D7RSA5	M427	0
D7RSA7	PM289	0
D7RSA8	PM295	0
D7RSA9	PM693	
D8E102		0
D8E103		$\frac{12}{0,7}$
D8E104	M010	0
D8E106		0
D8E107	M179	$\frac{12}{0,7}$
D8E108		$\frac{12}{0,9}$
D8E109	M012	$\frac{12}{0,7}$

VALEO RMA $\frac{V}{Kw - !}$

D8E111	PM908	$\frac{12}{0,6}$
D8E112	M070	$\frac{12}{0,8}$
D8E113		0
D8E114	M070	$\frac{12}{0,8}$
D8E115	M070	$\frac{12}{0,8}$
D8E116	M078	$\frac{12}{0,7}$
D8E117	M075	$\frac{12}{0,8}$
D8E117	M075	$\frac{12}{0,8}$
D8E119		0
D8E120	M070	$\frac{12}{0,8}$
D8E121	M119	$\frac{12}{0,8}$
D8E121	M119	$\frac{12}{0,8}$
D8E122	M010	$\frac{12}{0,8}$
D8E123		0
D8E124	M010	$\frac{12}{0,8}$
D8E125		$\frac{12}{0,9}$
D8E126	M012	$\frac{12}{0,7}$
D8E129	M021	$\frac{12}{1,0}$
D8E130	PM908	$\frac{12}{0,6}$
D8E131	PM908	$\frac{12}{0,6}$
D8E132	M280	$\frac{12}{1,1}$
D8E132	M280	$\frac{12}{1,1}$
D8E133	M070	$\frac{12}{0,8}$
D8E134	M196	$\frac{12}{0,8}$
D8E136		0
D8E137	M075	$\frac{12}{0,8}$
D8E137	M075	$\frac{12}{0,8}$
D8E139	M021	$\frac{12}{1,0}$
D8E14		0
D8E140	M124	$\frac{12}{0,9}$
D8E142	M084	$\frac{12}{0,9}$
D8E144	M100	$\frac{12}{0,8}$
D8E145	M012	$\frac{12}{0,7}$
D8E147	M070	$\frac{12}{0,8}$
D8E147	M070	$\frac{12}{0,8}$
D8E148	M078	$\frac{12}{0,7}$
D8E151	M075	$\frac{12}{0,8}$
D8E151	M075	$\frac{12}{0,8}$
D8E152	M119	$\frac{12}{0,8}$
D8E152	M119	$\frac{12}{0,8}$
D8E153	M107	$\frac{12}{0,8}$ 15a
D8E153	M107	$\frac{12}{0,8}$ 15a
D8E154	M067	$\frac{12}{0,6}$
D8E155		$\frac{12}{0,7}$

VALEO RMA $V_{Kw} -!$

D8E157	M107	$12/0,8$	15a
D8E157	M107	$12/0,8$	15a
D8E158		$12/0,7$	
D8E21		$0/$	
D8E22		$0/$	
D8E26		$0/$	
D8E31		$0/$	
D8E34		$0/$	
D8E37		$0/$	
D8E40	M203	$12/0,8$	
D8E41	M119	$12/0,8$	
D8E41	M119	$12/0,8$	
D8E42		$0/$	
D8E43		$0/$	
D8E44		$0/$	
D8E45	M203	$12/0,8$	
D8E49	M021	$0/$	
D8E50		$0/$	
D8E51		$0/$	
D8E52	M203	$12/0,8$	
D8E54	PM908	$12/0,6$	
D8E57		$0/$	
D8E58		$0/$	
D8E59		$0/$	
D8E60	M077	$12/0,6$	
D8E60	M119	$12/0,6$	
D8E63	M021	$0/$	
D8E64	M077	$12/0,6$	
D8E64	M077	$12/0,6$	
D8E66	M077	$12/0,6$	
D8E66	M077	$12/0,6$	
D8E69		$0/$	
D8E70	PM908	$12/0,6$	
D8E71	M021	$12/1,0$	
D8E74	PM908	$12/0,6$	
D8E75	M077	$12/0,6$	
D8E75	M077	$12/0,6$	
D8E76	M010	$12/0,8$	
D8E77	M070	$12/0,8$	
D8E78	M203	$12/0,8$	
D8E81	M119	$12/0,8$	
D8E81	M119	$12/0,8$	
D8E82		$0/$	
D8E83		$0/$	

VALEO RMA $V_{Kw} -!$

D8E84	M021	$0/$	
D8E85		$0/$	
D8E86	PM908	$12/0,6$	
D8E87	M070	$12/0,8$	
D8E88		$0/$	
D8E89		$0/$	
D8E90		$0/$	
D8E94		$0/$	
D8E95		$0/$	
D8E96	M010	$12/0,8$	
D8E97		$0/$	
D8E99	M078	$12/0,7$	
D8E99	M078	$12/0,7$	
D8R1		$0/$	
D8R27		$0/$	
D9E100	M280	$12/1,1$	
D9E100	M280	$12/1,1$	
D9E101	M010	$0/$	
D9E102		$0/$	
D9E104		$0/$	
D9E107	M159	$12/0,7$	15a
D9E107	M159	$12/0,7$	15a
D9E108	M082	$12/0,8$	
D9E108	M082	$12/0,8$	
D9E109	M107	$12/0,8$	15a
D9E109	M107	$12/0,8$	15a
D9E11		$12/1,2$	
D9E110	M016	$12/0,8$	15a
D9E110	M016	$12/0,8$	15a
D9E111	M106	$12/0,8$	15a
D9E111	M106	$12/0,8$	15a
D9E113	M024	$12/0,8$	
D9E113	M024	$12/0,8$	
D9E114	M145	$12/0,8$	
D9E114	M149	$12/0,8$	
D9E119	M102	$12/0,8$	
D9E12	M192	$12/1,0$	
D9E12	M119X	$12/1,0$	
D9E12	M119X	$12/1,0$	
D9E120		$0/$	
D9E123	M023	$12/0,8$	
D9E124	M096	$12/0,8$	
D9E124	M096	$12/0,8$	
D9E125	M180	$12/0,8$	

VALEO RMA $V_{Kw} -!$

D9E125	M180	$12/0,8$	
D9E127	M032	$12/0,8$	
D9E128	M094	$12/0,6$	
D9E129	M095	$12/0,7$	
D9E131	M104	$12/0,9$	
D9E132	M104	$12/0,9$	
D9E136	M148	$12/0,9$	15a
D9E136	M148	$12/0,9$	15a
D9E137	M202	$12/0,9$	
D9E137	M202	$12/0,9$	
D9E138	M202	$12/0,9$	
D9E14		$0/$	
D9E14		$0/$	
D9E140	M150	$12/0,9$	15a
D9E15		$0/$	
D9E152	M124X	$12/1,0$	
D9E152	M124X	$12/1,0$	
D9E16	M117	$12/1,1$	
D9E167	M159	$0/$	
D9E17	M041	$0/$	
D9E18	M118	$12/0,8$	
D9E19	M118	$12/0,8$	
D9E20	M192	$12/0,9$	
D9E20	M192	$12/0,9$	
D9E200	M280	$12/1,1$	
D9E200	M280	$12/1,1$	
D9E200	M280	$12/1,1$	
D9E21	M117	$12/1,1$	
D9E22	M192	$12/0,9$	
D9E22	M192	$12/0,9$	
D9E237	M202	$12/0,9$	
D9E237	M202	$12/0,9$	
D9E238	M202	$12/0,9$	
D9E239		$0/$	
D9E243	M362	$12/0,9$	
D9E26	M084X	$12/0,9$	
D9E27	M010	$12/0,8$	
D9E27	M010	$12/0,8$	
D9E276	M202	$12/0,9$	
D9E278	M192	$12/1,0$	
D9E278	M119X	$12/1,0$	
D9E278	M119X	$12/1,0$	
D9E28	M118	$12/0,8$	
D9E300	M280	$12/1,1$	

VALEO RMA $V_{Kw} -!$

D9E300	M280	12/1,1
D9E31	M118	12/0,8
D9E31	M118	12/0,8
D9E32	M118	12/0,8
D9E34	M192	12/0,9
D9E34	M192	12/0,9
D9E35	M192	12/0,9
D9E35	M192	12/0,9
D9E36	M010	12/0,8
D9E37	M084X	12/0,9
D9E38	M010	0/
D9E39	M017	12/0,8
D9E40	M117	12/1,1
D9E41	M084X	12/0,9
D9E43	M104	12/0,9
D9E44	M104	12/0,9
D9E45		12/1,2
D9E46	M192	12/0,9
D9E46	M192	12/0,9
D9E48	M102	12/0,8
D9E49	M102	12/0,8
D9E51		0/
D9E52	M017	12/0,9
D9E52	M202	12/0,9
D9E53	M075X	12/0,8
D9E53	M075X	12/0,8
D9E54	M010	12/0,8
D9E55	M192	12/0,9
D9E55	M192	12/0,9
D9E56	M084X	12/0,9
D9E57		/
D9E57	M100	12/0,8
D9E57	M100	12/0,8
D9E58		0/
D9E61	M010	12/0,8
D9E62	M010	12/0,8
D9E64	M075X	12/0,8
D9E64	M075X	12/0,8
D9E66	M084X	12/0,9
D9E68	M119X	12/1,0
D9E68	M119X	12/1,0
D9E69	M029	12/1,0
D9E7		12/1,2
D9E70	M124X	12/1,0

VALEO RMA $V_{Kw} -!$

D9E701	M124X	12/1,0
D9E701	M124X	12/1,0
D9E702	M124X	12/1,0
D9E702	M124X	12/1,0
D9E72	M017	12/0,8
D9E74	M084X	12/0,9
D9E75	M075X	12/0,8
D9E75	M075X	12/0,8
D9E76	M017	12/0,8
D9E76	M017	12/0,8
D9E761	M202	/
D9E77	M017	12/0,8
D9E77	M017	12/0,8
D9E771	M202	12/0,9
D9E771	M202	12/0,9
D9E772	M202	12/0,9
D9E772	M202	12/0,9
D9E772	M202	12/0,9
D9E772	M202	12/0,9
D9E773	M202	12/0,9
D9E773	M202	12/0,9
D9E773	M202	12/0,9
D9E773	M202	12/0,9
D9E774	M202	12/0,9
D9E774	M202	12/0,9
D9E776	M202	/
D9E776	M202	12/0,9
D9E776	M202	12/0,9
D9E78	M119X	12/1,0
D9E78	M119X	12/1,0
D9E79	M119X	12/0,9
D9E79	M192	12/0,9
D9E81	M280	12/1,1
D9E81	M280	12/1,1
D9E82	M118	12/0,8
D9E83	M104	12/0,9
D9E85	M124X	12/1,0
D9E851	M124X	12/1,0
D9E852	M124X	12/1,0
D9E86	M124X	12/1,0
D9E861	M124X	12/1,0
D9E87	M118	12/0,8
D9E9	M010	12/0,8
D9E92	PM908	12/0,6
D9E93	M078	12/0,7
D9E94	M067	12/0,6

VALEO RMA $V_{Kw} -!$

D9E95		12/1,2
D9E98	M100	0/
D9EP119	M102	12/1,9
D9R105	M079	12/2,0
D9R1050	M153	0/
D9R106	M156	12/2,0
D9R112	M120X	12/1,9
D9R116	PM226	0/
D9R118	M297X	12/3,1
D9R119	M088	12/2,2
D9R119	M088	12/2,2
D9R121	M105X	12/2,0
D9R122	M105X	12/2,0
D9R134	M121X	12/2,9
D9R135	M285	12/2,2
D9R135	M285	12/2,2
D9R139	M162	12/2,2
D9R141	M089	12/2,0
D9R142	M419	0/
D9R144	PM226	0/
D9R149	M088X	12/2,2
D9R149	M088X	12/2,2
D9R237	M202	0/
D9R73	M121X	12/2,9
D9R84	M105X	12/2,0
D9R89	M278	12/3,1
D9R90	M157	12/2,2
D9R90+PC	M157	/
D9R91	M277X	12/3,1
D9R96	M276	12/3,1
D9R97	M275	12/3,1
D9R97+PC		/
D9R99	PM248	0/
D9RP160	M088	0/
D9RP256	M120X	0/
ND001		12/0,7
ND002	M033	12/0,8
ND002	M033X	12/0,8
ND005	M012	12/0,7
ND007	M011	12/0,9
ND007	M031	12/0,9
ND008	M044	12/1,0
ND010	M100	12/0,8
ND011	M010	12/0,8

VALEO RMA V/Kw -!

ND015	M013	12/0,7	
ND018	M101	12/1,5	
ND020	M109	12/1,1	15a
ND020	M109	12/1,1	15a
ND022	M215	12/1,5	
ND025	M120X	12/1,9	
ND027	M079	12/2,0	
ND030	M125	12/2,2	
ND032		12/2,8	
ND033	M161	12/2,2	
ND034	M254	12/2,0	
ND034	M254	12/2,0	
ND035	M297X	12/2,5	
ND036	M121X	12/2,2	
ND036	M121	12/2,2	
ND039	M010	0/	
ND040	M104	12/0,9	
ND043	M084X	12/0,9	
ND044	M029	12/1,0	
ND045	M084X	12/0,9	
ND046	M075X	12/0,8	
ND046	M075	12/0,8	
ND047	M124X	12/0,9	
ND048	M070	12/0,8	
ND048	M203	12/0,8	
ND048	M196	12/0,8	
ND048	M118	12/0,8	
ND049	PM908	12/0,6	
ND050	M078	12/0,7	
ND051	M067	12/0,6	
ND052		12/1,2	
ND053	M105	12/2,0	
ND055	M157	12/2,2	
ND057	M119X	12/0,6	
ND057	M119X	12/0,6	
ND057	M119	12/0,6	
ND058	M017	12/0,8	
ND059	M056	12/0,9	
ND060	M046	12/0,9	
ND061	M159	12/0,7	15a
ND061	M159	12/0,7	15a
ND062	M082	12/0,8	
ND062	M137	12/0,8	
ND063	M107	12/0,8	15a

VALEO RMA V/Kw -!

ND063	M107	12/0,8	15a
ND064	M016	12/0,8	15a
ND064	M016	12/0,8	15a
ND065	M022	12/0,9	
ND068	M192	12/0,9	
ND068	M192	12/0,9	
ND069	M124X	12/1,0	
ND070	M280	12/1,1	
ND073	M202	12/0,9	
ND073	M202	12/0,9	
ND073	M202	0/	
ND073	M202	12/0,9	
ND074	M120	12/1,9	
ND078	M277	12/3,1	
ND079		12/2,0	
ND086	M121	12/2,2	
ND086	M121X	12/2,9	
ND087	M024	12/0,8	
ND088	M102X	12/1,1	
ND090	M023	0/	
ND091	M032	12/0,8	
ND094	M095	12/0,7	
ND094	M095	12/0,7	
ND095	M180	12/0,8	
ND095	M180	12/0,8	
ND096	M149	12/0,8	
ND096	M145	12/0,8	
ND099	PM145	0/	
ND099	PM145	0/	
ND108	M176	12/0,9	
ND108	M074	12/0,9	
ND110	M176	12/1,1	
ND111	M102X	12/1,1	
ND113	M376	12/1,2	
ND114	M202	12/0,9	
ND114	M202	12/0,9	
ND115		12/2,2	
ND119	M033	12/0,8	
ND119	M033X	12/0,8	
ND120	M110	12/0,7	
ND121	M017X	12/1,2	
ND122	M327	12/0,7	
ND123	M105X	12/2,0	
ND124	M158	12/0,8	

VALEO RMA V/Kw -!

ND124	M072	12/1,5	
ND125	M073	12/1,1	
ND127	M104	12/0,9	
ND127	M104	/	
ND129	M195	12/1,4	
ND130	M017	0/	
ND130	M017X	0/	
ND131	M222	12/1,0	
ND131	M176	12/1,0	
ND134	M143	12/0,9	
ND134	M143	12/0,9	
ND135	M088X	12/2,2	
ND135	M088X	12/2,2	
ND136	M202	0/	
ND136	M017X	12/1,2	
ND136	M202	12/1,2	
ND137	M120X	12/1,9	
ND138	M105	12/1,7	
ND138	M103	12/1,7	
ND139	M379	12/1,1	
ND140	M105	/	
ND141	M150	12/0,9	15a
ND145	M202	12/0,9	
ND147	PM134	0/	
ND151	M017X	12/1,2	
ND152	M120X	12/1,9	
ND155	M417	0/	
ND156	M017X	12/1,2	
ND157	M110	12/0,7	
ND158	M283	12/0,8	
ND158	M023	12/0,8	
ND159	M268	12/0,8	
ND160	M083	12/1,4	
ND161	M105	/	
ND162	M399	12/2,2	
ND163	M120X	12/1,9	
ND164	M416	0/	
ND165	M319	12/0,7	
ND166	M362	12/0,9	
ND166	M283	12/0,8	
ND167	M058	12/1,7	
ND168		/	
ND169	M120X	12/1,9	
ND170	M099	12/1,4	

VALEO RMA $\frac{V}{Kw -!}$

ND171	M017X	0
ND172	PM761	0
ND195		
ND196	M105	12 1,7
ND204		
ND209	M414	
ND210		
ND211	M195	
ND213	PM251	
ND214	PM234	0
ND215		
ND216	PM237	
ND217		
ND218		12 1,4
S114808		
TM000A03801	PM274	
TM000A03901	M433	
TM000A04001	M426	
TM000A04101	PM299	
TM000A04201	M429	
TM000A04301	PM363	
TM000A04801	PM365	
TM000A06001	PM396	
TM000A06101	M193	
TM000A06201	PM927	
TM000A06701	PM400	
TM000A07901	PM928	
TM000A08401	PM929	
TM000A08701	PM667	
TM000A10401	PM930	
TM000A13701	PM664	
TM000A13901	PM931	
TM000A14301	PM663	
TM000A17401	PM932	
TM000A19400	M336X	
TM000A27301	PM660	
TM000A27601	PM661	
TM000A31001	PM659	
TM000A31201		
TM000A33801	PM341	
TM000A34101	PM399	
TM000A34101	PM399	
U0100	PM405	0
VA132	M078	0

VALEO RMA $\frac{V}{Kw -!}$

VA153	M119X	0
VS101	M082	0
VS102		0
VS103	M017	0
VS104	M277X	0
VS104	M277X	0
VS106	M136	0
VS106		0
VS107		0
VS108		0
VS109		0
VS110	M106	0
VS111		0
VS112	M084X	0
VS114	M180	0
VS115	M095	0
VS117	M102	0
VS118	M124X	0
VS119	M214	0
VS120	M264	0
VS121		0
VS122	M029	0
VS123	M134	0
VS124		0
VS125	M308	0
VS126	M145	0
VS127	M161	0
VS128	M059	0
VS129	M010	0
VS129	M010	0
VS131	M096	0
VS132	M078	0
VS134	M084X	0
VS136	PM249	0
VS137	M159	0
VS138	M134	0
VS139	M032	0
VS140	M105	0
VS141	M049	0
VS142	M119X	0
VS143	M119X	0
VS144	M075X	0
VS145	M033	0
VS146	M118	0

VALEO RMA $\frac{V}{Kw -!}$

VS147	M100	0
VS148	M089	0
VS149	M116	0
VS150	M308	0
VS152	M094	0
VS153	M016	0
VS154		0
VS156	M056	0
VS158		0
VS162	M021	0
VS163	M075X	0
VS164	M318	0
VS166	M035	0
VS168	M121X	0
VS169	M114	0
VS172	M254	0
VS173	M162	0
VS174	M052	0
VS175	PM048	0
VS177	M049	0
VS177	M243	0
VS179	M305	0
VS182	M033	0
VS183	M293	0
VS184	M106	0
VS188		0
VS189	M031	0
VS191	M223	0
VS192	M285	0
VS193		0
VS194	M081	0
VS194	M082	0
VS195	M052	0
VS197	M104	0
VS199	M223	0
VS201	M064	0
VS202	M117	0
VS204	M172	0
VS205	M143	0
VS205	M143	0
VS206	M124X	0
VS207	M159	0
VS208	PM250	0
VS209	M424	0

VALEO	RMA $\sqrt{\text{Kw}} - !$	VALEO	RMA $\sqrt{\text{Kw}} - !$	VALEO	RMA $\sqrt{\text{Kw}} - !$
VS210	PM405 0/	VS271	M197 0/	VS32	M124X 0/
VS211	PM600 0/	VS272	M222 0/	VS320	M017 0/
VS212	PM405 0/	VS275	M013 0/	VS321	M124X 0/
VS215	PM372 0/	VS276	M012 0/	VS322	PM251 0/
VS217	M130 0/	VS277	M112 0/	VS324	M417 0/
VS218	M320 0/	VS278	M148 0/	VS325	M280 0/
VS219	M433 0/	VS279	M195 0/	VS326	M120X 0/
VS220	PM408 0/	VS280	M195 0/	VS328	M237 0/
VS221	M441 0/	VS282	M176 0/	VS329	M248 0/
VS222	PM327 0/	VS283	M105 0/	VS330	M026 0/
VS224	M330 0/	VS283	M105 0/	VS333	M327 0/
VS225	M328 0/	VS284	PM024 0/	VS334	PM437 0/
VS226	0/	VS285	M105 0/	VS335	PM443 0/
VS226	M425X 0/	VS285	M105 0/	VS336	PM601 0/
VS226	0/	VS286	M011 0/	VS337	PM780 0/
VS227	M046 0/	VS287	M268 0/	VS338	PM602 0/
VS228	PM287 0/	VS288	M023 0/	VS340	M236 0/
VS229	PM459 0/	VS289	M045 0/	VS341	M034 0/
VS230	M433 0/	VS290	M048 0/	VS342	M218 0/
VS231	M150 0/	VS291	M058 0/	VS343	M257 0/
VS232	M419 0/	VS292	M228 0/	VS344	M240 0/
VS232	M055 0/	VS293	M028 0/	VS345	M017X 0/
VS233	PM444 0/	VS294	M136 0/		
VS235	M260 0/	VS295	M296 0/		
VS236	M176 0/	VS296	M260 0/		
VS238	PM464 0/	VS297	M243 0/		
VS239	M226 0/	VS298	M243 0/		
VS240	M325 0/	VS300	M432 0/		
VS241	M283 0/	VS300	PM294 0/		
VS244	M201 0/	VS301	PM296 0/		
VS247	PM295 0/	VS302	M027 0/		
VS247	M194 0/	VS305	M431 0/		
VS249	M185 0/	VS305	M431 0/		
VS251	PM135 0/	VS306	PM274 0/		
VS252	PM247 0/	VS307	M088 0/		
VS254	M150 0/	VS308	M216 0/		
VS255	M014 0/	VS309	M140 0/		
VS259	PM684 0/	VS311	M332 0/		
VS261	M217 0/	VS312	PM526 0/		
VS262	M214 0/	VS313	PM512 0/		
VS263	M134 0/	VS316	M102 0/		
VS264	M134 0/	VS316	M102X 0/		
VS265	M260 0/	VS318	M017X 0/		
VS270	M120X 0/	VS319	M017X 0/		

VW	RMA $\sqrt{\text{Kw}} -!$	VW	RMA $\sqrt{\text{Kw}} -!$	VW	RMA $\sqrt{\text{Kw}} -!$
0003974104		020911023DX	M313 0/	020911024C	M313 /
001911023	RM020 /	020911023F	PM070 /	025911023	/
001911023	PM566 /	020911023F	PM071 /	025911023	M251 12/ 0,9
001911023	PM566 0/	020911023F	PM070 /	025911023	M251 12/ 0,9
001911023	PM566 0/	020911023F	PM070 /	025911023A	/
001911023C	RM021 /	020911023F	PM070 0/	025911023A	/
001911023C	M313 /	020911023F	PM070 0/	025911023A	M251 /
001911023X	PM566 0/	020911023F	PM070 0/	025911023A	M251 12/ 0,9
003911023A	M109 12/ 0,7	020911023FX	PM070 /	025911023A	M251 12/ 0,9
003911023B	M109 12/ 0,7	020911023FX	PM070 /	025911023AX	M251 0/
003911023BX	12/ 0,7	020911023FX	PM070 0/	025911023AY	M251 0/
003911023C	0/	020911023H	PM081 /	025911024A	M313X /
003911023D	0/	020911023J	M248 /	026911023	/
003911023D	0/	020911023J	M248 12/ 1,1	026911023	/
003911023DX	0/	020911023L	M248 /	026911023	M148 /
003911023E	/	020911023L	M248 /	026911023	M148 /
003911023E	/	020911023L	M111 /	026911023	M148 12/ 0,9 15a
003911023E	0/	020911023L	M111 12/ 0,8 15a	026911023	M148 12/ 0,9 15a
003911023E	0/	020911023L	M248 12/ 0,8 15a	0269110233	RM069 /
003911023EX	0/	020911023M	M248 /	026911023A	/
004053778	0/	020911023M	M248 12/ 1,1	026911023A	/
012911023	PM541 0/	020911023M	M111 12/ 1,1	026911023A	M016 /
012911023C	PM560 0/	020911023MX	M111 /	026911023A	M024 /
012911023E	PM571 0/	020911023MX	M248 /	026911023A	M016 12/ 0,8
012911023F	PM571 /	020911023MX	M111 0/	026911023A	M024 12/ 0,8
012911023F	PM571 /	020911023N	M248 /	026911023AX	M024 12/ 0,8
012911023G	RM025 /	020911023N	M248 /	026911023AX	M024 12/ 0,8
016016104	RM004 /	020911023N	M248 12/ 1,1	026911023B	M148 /
020911012P	M313 /	020911023P	M313 /	026911023B	M148 12/ 0,9 15a
020911012P	M313 0/	020911023P	M313 /	026911023B	M148 12/ 0,9 15a
020911023	/	020911023P	M313 12/ 1,8	026911023BX	M148 12/ 0,9 15a
020911023	M150 12/ 1,1	020911023P	M313 0/	026911023BX	M148 12/ 0,9 15a
020911023	M248 12/ 1,1	020911023PX	M313 /	026911023C	M112 /
020911023A	M248 12/ 1,1	020911023PX	M313 /	026911023C	M112 12/ 0,9 15a
020911023AX	M248 12/ 1,1	020911023PX	M313 /	026911023C	M112 12/ 0,9 15a
020911023B	M310 /	020911023PX	M313 0/	026911023CX	M112 12/ 0,9 15a
020911023B	M310 12/ 1,8	020911023PX	M313 0/	026911023E	M115 12/ 1,0 15a
020911023B	M310 12/ 1,8	020911023R	M313 0/	026911023E	M115 12/ 1,0 15a
020911023C	0/	020911023S	PM562 /	026911023EX	M115 12/ 1,0 15a
020911023D	M313 /	020911023T	PM562 /	026911023F	M115 12/ 1,0 15a
020911023D	M313 /	020911023T	PM562 /	026911023FX	M115 12/ 1,0 15a
020911023D	M313 /	020911023T	PM562 /	026911023G	M112 12/ 0,9 15a
020911023D	M313 12/ 1,8	020911024A	M313 /	026911023G	M112 12/ 0,9 15a
020911023D	M313 12/ 1,8	020911024A	M313 /	026911023GX	M112 12/ 0,9 15a

VW	RMA \sqrt{Kw} -!	VW	RMA \sqrt{Kw} -!	VW	RMA \sqrt{Kw} -!
026911023X	M148 $\frac{12}{0,9}$ 15a	02A911023L	PM071 /	02B911023L	M396 /
026911023X	M148 $\frac{12}{0,9}$ 15a	02A911023L	PM071 0	02B911023L	M396 /
026911026C	M112 /	02A911023L	PM071 0	02B911023LX	M396 /
026911026C	M313 /	02A911023Q	M282 /	02B911023M	RM027 /
027911023	/	02A911023Q	M282 $\frac{12}{1,7}$	02E911023H	PM574 /
027911023	/	02A911023Q	M282 $\frac{12}{1,7}$	02E911023H	PM574 /
027911023	/	02A911023R	M289 $\frac{12}{1,8}$	02E911023H	PM574 /
027911023	0	02A911023R	M289 $\frac{12}{1,8}$	02E911023J	PM572 /
027911023	0	02A911023RX	M289 /	02M 911023P	PM573 /
027911023X	0	02A911023RX	M289 0	02M911023	PM074 /
027911023X	0	02A911023S	PM577 /	02M911023A	/
028911023A	M012 0	02A911023T	M236 /	02M911023A	PM080 0
02A911023	M191 $\frac{12}{1,0}$	02A911023T	M236 /	02M911023A	PM080 0
02A911023	M191 $\frac{12}{1,0}$	02A911023T	M236 $\frac{12}{1,1}$	02M911023C	PM080 /
02A911023	M191 $\frac{12}{1,0}$	02A911023X	M191 $\frac{12}{1,0}$	02M911023D	PM080 /
02A911023A	M191 $\frac{12}{1,0}$	02A911024	M289X $\frac{12}{1,8}$	02M911023F	/
02A911023A	M191 $\frac{12}{1,0}$	02A911024	M289X $\frac{12}{1,8}$	02M911023F	PM080 /
02A911023A	M191 $\frac{12}{1,0}$	02A911024B	M289 0	02M911023G	PM568 /
02A911023AX	M191 0	02A911024D	M289X /	02M911023G	PM568 0
02A911023AX	M191 0	02A911024D	M289X /	02M911023M	PM568 /
02A911023B	M392 /	02A911024D	M289X /	02M911023N	PM573 /
02A911023B	PM050 0	02A911024E	PM577 /	02M911023P	PM573 /
02A911023B	PM050 0	02A911024E	PM577 /	02M911023P	PM573 /
02A911023B	PM050 0	02A911024G	M289X /	02M911023Q	PM579 /
02A911023BX	PM050 0	02A911024X	M289X /	02M911023Q	PM579 /
02A911023C	M282 $\frac{12}{1,7}$	02A911024X	M289X 0	02M911023R	PM080 /
02A911023D	M306 $\frac{12}{1,1}$	02A911042	M310 0	02M911023S	RM024 /
02A911023DX	M306 $\frac{12}{1,1}$	02A911203	/	02M911023T	PM564 /
02A911023E	M306 $\frac{12}{1,1}$	02B911023A	M394 0	02M911EA	PM074 /
02A911023EX	M306 $\frac{12}{1,1}$	02B911023AX	M394 0	02T911023B	PM567 /
02A911023F	M236 /	02B911023AX	M396 0	02T911023B	PM567 /
02A911023F	M236 /	02B911023B	M392 /	02T911023B	PM567 0
02A911023F	M236 $\frac{12}{1,1}$	02B911023B	M392 0	02T911023C	RM058 /
02A911023FX	M236 $\frac{12}{1,1}$	02B911023BX	M392 0	02T911023C	PM081 /
02A911023G	M383 /	02B911023C	M256 $\frac{12}{1,8}$	02T911023C	PM081 0
02A911023G	M383 0	02B911023C	M256 $\frac{12}{1,8}$	02T911023E	/
02A911023GX	M383 0	02B911023CX	M256 $\frac{12}{1,8}$	02T911023E	PM073 0
02A911023H	M282 /	02B911023D	M396 0	02T911023E	PM073 0
02A911023H	M282 $\frac{12}{1,7}$	02B911023D	M396 0	02T911023G	PM561 /
02A911023H	M282 $\frac{12}{1,7}$	02B911023E	PM079 0	02T911023G	PM561 0
02A911023HX	M282 $\frac{12}{1,7}$	02B911023E	PM079 0	02T911023H	/
02A911023J	M289X $\frac{12}{1,8}$	02B911023F	/	02T911023H	/
02A911023JX	M289X $\frac{12}{1,8}$	02B911023F	PM072 0	02T911023H	PM081 /
02A911023L	PM071 /	02B911023F	PM072 0	02T911023H	PM081 /

VW	RMA $\sqrt{Kw - !}$
02T911023M	PM564
02T911023M	PM564 0
02T911023R	PM563
02T911023R	PM563
02T911023R	PM563
02T911023S	PM563
02T911023T	PM564
02T911024	PM575
02T911024	PM575
02Z911023E	PM569
02Z911023E	PM569
02Z911023E	PM569
02Z911023E	PM569 0
02Z911023F	PM572
02Z911023F	PM572 0
02Z911023G	PM569
02Z911023H	PM572
02Z911023J	RM023
02Z911023L	RM026
031911023	M238
031911023	M238
031911023	M238
031911023	M238 0
031911023A	M238
031911023A	M238 0
031911023AX	M238 0
031911023X	M238 0
034911023	M116
034911023	M116 0
034911023A	M116 0
034911023X	M116 0
035911023	
035911023	
035911023	M109
035911023	M109
035911023	M109 12/1,1 15a
035911023	M109 12/1,1 15a
035911023A	M109 12/1,1 15a
035911023A	M109 12/1,1 15a
035911023B	M109 0
035911023C	M109 12/1,1 15a
035911023C	M109 12/1,1 15a
035911023D	M116 12/1,4 15a
035911023D	M116 12/1,4 15a

VW	RMA $\sqrt{Kw - !}$
035911023E	
035911023E	
035911023E	M109
035911023E	M109
035911023E	M109 12/1,1 15a
035911023E	M109 12/1,1 15a
035911023EX	M109
035911023EX	M109 12/1,1 15a
035911023EX	M109 12/1,1 15a
035911023F	M109 12/1,1 15a
035911023F	M109 12/1,1 15a
035911023J	M109 12/1,1 15a
035911023J	M109 12/1,1 15a
035911023JX	M109 12/1,1 15a
035911023JX	M109 12/1,1 15a
035911023K	M116
035911023K	M116 12/1,4 15a
035911023K	M116 12/1,4 15a
035911023K	M116 12/1,4 15a
035911023KX	M116 12/1,4 15a
035911023KX	M116 12/1,4 15a
035911023KX	M116 12/1,4 15a
035911023L	M116
035911023L	M116 12/1,4 15a
035911023L	M116 12/1,4 15a
035911023L	M116 12/1,4 15a
035911023LX	M116 12/1,4 15a
035911023LX	M116 12/1,4 15a
035911023LX	M116 12/1,4 15a
035911023M	M116 12/1,4 15a
035911023M	M116 12/1,4 15a
035911023M	M116 12/1,4 15a
035911023N	M116
035911023N	M116
035911023N	M116 12/1,4 15a
035911023N	M116 12/1,4 15a
035911023N	M116 12/1,4 15a
035911023O	M116 0
035911023P	M116
035911023P	M116 12/1,4 15a
035911023P	M116 12/1,4 15a
035911023P	M116 12/1,4 15a
035911023Q	M116
035911023Q	M116 12/1,4 15a

VW	RMA $\sqrt{Kw - !}$
035911023Q	M116 12/1,4 15a
035911023Q	M116 12/1,4 15a
035911023QX	M116 12/1,4 15a
035911023QX	M116 12/1,4 15a
035911023QX	M116 12/1,4 15a
035911023X	M109 12/1,1 15a
035911023X	M109 12/1,1 15a
036911023	M107
036911023	M107
036911023	M107
036911023	M107 12/0,8 15a
036911023	M107 12/0,8 15a
036911023A	M149 12/0,8
036911023B	M107 12/0,8 15a
036911023B	M107 12/0,8 15a
036911023BX	M107 12/0,8 15a
036911023C	M107 12/0,8 15a
036911023C	M107 12/0,8 15a
036911023D	M107 12/0,8 15a
036911023D	M107 12/0,8 15a
036911023E	M149 12/0,8
036911023E	M034
036911023E	M034 0
036911023F	M108 12/0,8 15a
036911023F	M108 12/0,8 15a
036911023FX	M108 12/0,8 15a
036911023FX	M034 12/0,8 15a
036911023G	M034 12/0,8
036911023G	M034
036911023G	M034 12/0,8
036911023GH	
036911023GX	M034 12/0,8
036911023GX	M034 12/0,8
036911023H	M034 12/0,8
036911023H	M034
036911023H	M034 12/0,8
036911023HX	M034 12/0,8
036911023HX	M034 12/0,8
036911023J	M149
036911023J	M145 12/0,8
036911023J	M149 12/0,8
036911023K	M034 12/0,8
036911023K	M034 12/0,8
036911023KX	M034 12/0,8

VW	RMA \sqrt{Kw} -!	VW	RMA \sqrt{Kw} -!	VW	RMA \sqrt{Kw} -!
036911023KX	M034 $\frac{12}{0,8}$	046911023X	M109 $\frac{12}{1,1}$ 15a	055911023B	M106 $\frac{12}{0,8}$ 15a
036911023M	M034 $\frac{12}{0,8}$	047911023A	PM020 $\frac{12}{0,8}$	055911023B	M106 $\frac{12}{0,8}$ 15a
036911023MX	M034 $\frac{12}{0,8}$	047911023B	PM918 $\frac{12}{0,8}$	055911023BX	M106 $\frac{12}{0,8}$ 15a
036911023MX	M034 $\frac{12}{0,8}$	047911023C	PM934 $\frac{12}{0,8}$	055911023BX	M106 $\frac{12}{0,8}$ 15a
036911023N	M034 $\frac{12}{0,8}$	047911023G	PM934 $\frac{12}{0,8}$	055911023D	M022 $\frac{12}{0,9}$
036911023N	M034 $\frac{12}{0,8}$	047911024A	PM020 $\frac{12}{0,8}$	055911023DX	M022 $\frac{12}{0,9}$
036911023P	M034 $\frac{12}{0,8}$	049911023	$\frac{12}{0,8}$	055911023E	M111 $\frac{12}{0,8}$ 15a
036911023P	M034 $\frac{12}{0,8}$	049911023A	$\frac{12}{0,8}$	055911023F	M150 $\frac{12}{0,9}$ 15a
036911023P	M034 $\frac{12}{0,8}$	049911023A	$\frac{12}{0,8}$	055911023F	M150 $\frac{12}{0,9}$ 15a
036911023P	M034 $\frac{12}{0,8}$	049911023D	M024 $\frac{12}{0,8}$	055911023F	M150 $\frac{12}{0,9}$ 15a
036911023PX	M034 $\frac{12}{0,8}$	049911023D	M024 $\frac{12}{0,8}$	055911023G	M386 $\frac{12}{0,9}$ 15a
036911023Q	M255 $\frac{12}{0,8}$	049911023DX	M024 $\frac{12}{0,8}$	055911023G	M386 $\frac{12}{0,9}$ 15a
036911023Q	M255 $\frac{12}{0,8}$	049911023DX	M024 $\frac{12}{0,8}$	055911023GX	M386 $\frac{12}{0,9}$
036911023Q	M255 $\frac{12}{0,8}$	049911023E	M024 $\frac{12}{0,8}$	055911023H	M111 $\frac{12}{0,8}$ 15a
036911023QX	M255 $\frac{12}{0,8}$	049911023E	M024 $\frac{12}{0,8}$	055911023H	M111 $\frac{12}{0,8}$ 15a
036911023QX	M255 $\frac{12}{0,8}$	049911023G	$\frac{12}{0,8}$	055911023H	M111 $\frac{12}{0,8}$ 15a
036911023R	M034 $\frac{12}{0,8}$	049911023G	$\frac{12}{0,8}$	055911023HX	M111 $\frac{12}{0,8}$ 15a
036911023R	M034 $\frac{12}{0,8}$	049911023G	$\frac{12}{0,8}$	055911023HX	M111 $\frac{12}{0,8}$ 15a
036911023R	M034 $\frac{12}{0,8}$	049911023G	$\frac{12}{0,8}$	055911023HX	M111 $\frac{12}{0,8}$ 15a
036911023RX	M034 $\frac{12}{0,8}$	049911023G	M148 $\frac{12}{0,9}$ 15a	055911023J	M150 $\frac{12}{0,9}$ 15a
036911023RX	M034 $\frac{12}{0,8}$	049911023G	M148 $\frac{12}{0,9}$ 15a	055911023J	M150 $\frac{12}{0,9}$ 15a
036911023RX	M034 $\frac{12}{0,8}$	049911023G	M148 $\frac{12}{0,9}$ 15a	055911023J	M150 $\frac{12}{0,9}$ 15a
036911023RX	M034 $\frac{12}{0,8}$	049911023G	M148 $\frac{12}{0,9}$ 15a	055911023J	M150 $\frac{12}{0,9}$ 15a
036911023S	M255 $\frac{12}{0,8}$	049911023GX	M148 $\frac{12}{0,9}$ 15a	055911023JX	M150 $\frac{12}{0,9}$ 15a
036911023S	M255 $\frac{12}{0,8}$	049911023GX	M148 $\frac{12}{0,9}$ 15a	055911023JX	M150 $\frac{12}{0,9}$ 15a
036911023S	M255 $\frac{12}{0,8}$	049911023H	M148 $\frac{12}{0,8}$	055911023JX	M150 $\frac{12}{0,9}$ 15a
036911023SX	M255 $\frac{12}{0,8}$	049911023H	M024 $\frac{12}{0,8}$	055911023JX	M150 $\frac{12}{0,9}$ 15a
036911023X	M107 $\frac{12}{0,8}$ 15a	052911023	M107 $\frac{12}{0,8}$ 15a	055911023K	M111 $\frac{12}{0,8}$ 15a
036911023X	M107 $\frac{12}{0,8}$ 15a	052911023A	M149 $\frac{12}{0,8}$	055911023K	M111 $\frac{12}{0,8}$ 15a
036911025B	M255 $\frac{12}{0,8}$	052911023A	M145 $\frac{12}{0,8}$	055911023K	M111 $\frac{12}{0,8}$ 15a
037911023	M111 $\frac{12}{0,8}$	052911023AX	M145 $\frac{12}{0,8}$	055911023KX	M111 $\frac{12}{0,8}$ 15a
037911023A	$\frac{12}{0,8}$	052911023AX	M149 $\frac{12}{0,8}$	055911023KX	M111 $\frac{12}{0,8}$ 15a
039911023	$\frac{12}{0,8}$	053911023	M112 $\frac{12}{1,1}$	055911023L	M248 $\frac{12}{1,1}$
039911023	PM578 $\frac{12}{0,8}$	053911023A	M227 $\frac{12}{0,8}$	055911023M	M150 $\frac{12}{0,9}$ 15a
039911023	M109 $\frac{12}{0,8}$	053911023A	M227 $\frac{12}{0,8}$	055911023M	M150 $\frac{12}{0,9}$ 15a
03G911023	PM578 $\frac{12}{0,8}$	053911023A	M227 $\frac{12}{0,8}$	055911023M	M150 $\frac{12}{0,9}$ 15a
03G911023A	PM933 $\frac{12}{0,8}$	053911023A	M227 $\frac{12}{0,8}$	055911023M	M150 $\frac{12}{0,9}$ 15a
046911023	$\frac{12}{0,8}$	053911023AX	M227 $\frac{12}{0,8}$	055911023MX	M150 $\frac{12}{0,9}$ 15a
046911023	$\frac{12}{0,8}$	053911023B	M227 $\frac{12}{0,8}$	055911023MX	M150 $\frac{12}{0,9}$ 15a
046911023	$\frac{12}{0,8}$	053911023B	M227 $\frac{12}{0,8}$	055911023MX	M150 $\frac{12}{0,9}$ 15a
046911023	M109 $\frac{12}{0,8}$	053911023BX	M227 $\frac{12}{0,8}$	055911023R	M150 $\frac{12}{0,9}$ 15a
046911023	M109 $\frac{12}{0,8}$	05590223KX	M111 $\frac{12}{0,8}$	055911023R	M111 $\frac{12}{0,8}$
046911023	M109 $\frac{12}{0,8}$	055911023	$\frac{12}{0,8}$	055911023X	$\frac{12}{0,8}$
046911023	M109 $\frac{12}{0,8}$	055911023A	$\frac{12}{0,8}$		
046911023	M109 $\frac{12}{0,8}$	055911023A	$\frac{12}{0,8}$		
046911023B	M258 $\frac{12}{0,8}$	055911023A	$\frac{12}{0,8}$		
046911023BX	M258 $\frac{12}{0,8}$	055911023A	$\frac{12}{0,8}$		
046911023X	M109 $\frac{12}{0,8}$	055911023AX	$\frac{12}{0,8}$		

VW	RMA $V_{Kw} -!$		VW	RMA $V_{Kw} -!$		VW	RMA $V_{Kw} -!$	
056911023	M016	0	059911023R	PM936		068911023G	M014	
056911023	M016	12 / 0,8 15a	059911023S	PM937		068911023G	M014	12 / 1,7
056911023A			059911024	PM935		068911023GX	M014	12 / 1,7
056911023A	M016		060911023	M295	12 / 0,8	068911023H	M051	
056911023A	M016	12 / 0,8 15a	061911023	M295	12 / 2,8	068911023H	M051	0
056911023A	M016	12 / 0,8 15a	061911023A	M295	12 / 2,8	068911023J	M218	12 / 1,7
056911023AX	M016	12 / 0,8 15a	061911023AX	M295	12 / 2,8	068911023JX	M218	12 / 1,7
056911023AX	M016	12 / 0,8 15a	061911023V	M295	12 / 2,8	068911023L	PM048	
056911023B	M016	12 / 0,8 15a	061911023X	M295	12 / 2,8	068911023L	PM048	0
056911023B	M016	12 / 0,8 15a	062911023	M063		068911023L	PM048	0
056911023C	M016	12 / 0,8 15a	068911023	M063	12 / 1,5	068911023LX	PM048	0
056911023C	M016	12 / 0,8 15a	068911023	M063	12 / 1,5	068911023LX	PM048	0
056911023D	M016	12 / 0,8 15a	068911023A	M051	12 / 1,5	068911023M	M257	
056911023D	M016	12 / 0,8 15a	068911023A	M051	12 / 1,5	068911023M	M257	
057911023E	PM587	0	068911023AX	M051	12 / 1,5	068911023M	M257	
058911023		12 / 0,8	068911023AX	M051	12 / 1,5	068911023M	M257	
058911023A		12 / 0,8	068911023B			068911023M	M257	12 / 1,7
058911023AX		12 / 0,8	068911023B			068911023M	M257	12 / 1,7
058911023B	M227		068911023B	M250		068911023MX	M257	12 / 1,7
058911023B	M227	12 / 1,1	068911023B	M250		068911023P	M069X	
058911023BX	M227	0	068911023B	M250	12 / 1,7	068911023P	M069X	12 / 1,4
058911023C		12 / 0,8	068911023B	M250	12 / 1,7	068911023P	M069X	12 / 1,4
058911023F	PM077	0	068911023C	M063	12 / 1,5	068911023PX	M069X	12 / 1,4
058911023FX	PM077	0	068911023C	M063	12 / 1,5	068911023PX	M069X	12 / 1,4
058911023H	PM042	0	068911023CX	M063	12 / 1,5	068911023Q	PM582	0
058912023F	PM077	0	068911023CX	M063	12 / 1,5	068911023Q	PM581	0
059911023		0	068911023D			068911023Q	PM580	0
059911023B		0	068911023D	M218	12 / 1,7	068911023R	M069X	
059911023C		0	068911023D	M218	12 / 1,7	068911023R	M069X	12 / 1,4
059911023CX		0	068911023DX	M218	12 / 1,7	068911023R	M069X	12 / 1,4
059911023E	M109	12 / 1,1 15a	068911023E	M051	12 / 1,7	068911023RX	M069X	12 / 1,4
059911023F		12 / 0,8	068911023E	M051	12 / 1,7	068911023RX	M069X	12 / 1,4
059911023FX		12 / 0,8	068911023EX	M051	12 / 1,7	068911023S	M069	12 / 1,4
059911023G	M109		068911023EX	M051	12 / 1,7	068911023S	M069	12 / 1,4
059911023G	M109	0	068911023F			068911023S	M069	12 / 1,4
059911023H	PM042		068911023F			068911023SX	M069	12 / 1,4
059911023H	PM042		068911023F	M250		068911023T	M310	
059911023H	PM042	0	068911023F	M250		068911023T	M310	12 / 1,8
059911023H	PM042	0	068911023F	M250	12 / 1,7	068911023T	M310	12 / 1,8
059911023H	PM042	0	068911023F	M250	12 / 1,7	068911023TX	M310	12 / 1,8
059911023P	PM935		068911023FX	M250	12 / 1,7	068911023X	M063	0
059911023P	PM935		068911023FX	M250	12 / 1,7	068911024B	M069	12 / 1,4
059911023Q	PM935		068911023G	M014		068911024B	M069	12 / 1,4
059911023Q	PM935		068911023G	M014		068911024BX	M069	12 / 1,4
059911023Q	PM935					068911024C	M216	

VW	RMA \sqrt{Kw} -!	VW	RMA \sqrt{Kw} -!	VW	RMA \sqrt{Kw} -!
068911024C	M069 $\frac{12}{1,4}$	069911023J		078911023DX	PM037 0
068911024C	M069 $\frac{12}{1,4}$	069911023J	PM084 0	078911023X	PM026 0
068911024E	M069	069911023L		079911021B	RM011
068911024F	M069	069911023L	PM082	07C911023	PM559 0
068911024F	M069	069911023M	PM084 0	07C911023	PM559 0
068911024F	M069 $\frac{12}{1,4}$	069911023V	M065 0	07C911023D	PM942
068911024F	M069 $\frac{12}{1,4}$	06B911023	M227	07C911023E	PM941
068911024G	M069	06B911023	M227 0	07C911023F	PM943
068911024G	M069	06B911023A	PM550	07C911023G	RM009
068911024G	M069 0	06B911023A	PM550 0	07D911023	PM944
068911024G	M069 0	06B911023A	PM550 0	07D911023	PM944
068911024H	PM078	06C911023	RM002	07M911023	RM004
068911024H	PM078 0	06E911023B	PM938	07Z911023A	PM591
068911024K	M014	06E911023C	PM938	07Z911023A	PM591 0
068911024K	M014	070911023B	PM939	07Z911023B	RM006
068911024K	M014 0	070911023C	RM028	085911023	M255 0
068911024T	M069	073911023	PM555	085911023A	M315
069911023	M065 $\frac{12}{2,0}$	073911023	PM555	085911023A	M315 $\frac{12}{1,8}$
069911023A	M065 $\frac{12}{2,0}$	073911023	PM555	085911023A	M315 $\frac{12}{1,8}$
069911023AX	M065 $\frac{12}{2,0}$	073911023	PM555 0	085911023AX	M315 0
069911023B	M066X	073911023	PM555 0	085911023B	M255 $\frac{12}{1,1}$
069911023B	M066X	073911023A	PM555	085911023BX	M255 0
069911023B	M066X	073911023A	PM555	085911023E	M255 0
069911023B	M066X	073911023A	PM555	085911023F	PM077 0
069911023B	M066X $\frac{12}{2,2}$	073911023A	PM555 0	085911023F	PM077 0
069911023BX	M066X $\frac{12}{2,2}$	073911023AX	PM555 0	085911023H	PM545
069911023BX	M066X $\frac{12}{2,2}$	073911023X	PM555 0	085911023J	M255
069911023C	M258 $\frac{12}{2,2}$	073911023X	PM555 0	085911023J	M255 0
069911023CX	M258 $\frac{12}{2,2}$	075911023	M014 0	085911023K	M315
069911023CX	M258 $\frac{12}{2,2}$	076911023A	PM940	085911023L	PM945
069911023CX	M258 $\frac{12}{2,2}$	077811023	PM026	085911023M	PM946
069911023D	M258 $\frac{12}{2,2}$	077911023C	PM049	091911023	M031 $\frac{12}{0,7}$
069911023D	M258 $\frac{12}{2,2}$	077911023C	PM049	091911023A	M251 0
069911023D	M258 $\frac{12}{2,2}$	077911023C	PM049 0	091911023AX	M251 0
069911023DX	M258 $\frac{12}{2,2}$	077911023C	PM049 0	091911023B	
069911023DX	M258 $\frac{12}{2,2}$	077911023E	PM057 0	091911023B	M251 0
069911023DX	M258 $\frac{12}{2,2}$	077911023E	PM057 0	091911023B	M251 0
069911023E	PM082 0	077911023F	PM557	091911023BX	M251 0
069911023E	PM082 0	077911023J	PM921	091911023X	M031 $\frac{12}{0,7}$
069911023F	PM096	078911023	PM026 0	095911023F	PM077 0
069911023F	PM096 0	078911023A	PM026 0	098911023A	M310
069911023G	M083	078911023B	PM026 0	098911023A	M310 0
069911023G	M083X 0	078911023D	RM008	098911023B	M310
069911023H	PM083 0	078911023D	PM037 0	098911023B	M310 0

VW	RMA $\frac{V}{Kw}$ -!	VW	RMA $\frac{V}{Kw}$ -!	VW	RMA $\frac{V}{Kw}$ -!
0AH911023	PM565	176911023A	M150	97VW1100BA	M313
0AH911023	PM565	176911023A	M150 $\frac{12}{0,9}$ 15a	BAA911023B	RM078
0AH911023	PM565	176911023A	M150 $\frac{12}{0,9}$ 15a	BAA911023B	
0AH911023A	PM565	176911023A	M150 $\frac{12}{0,9}$ 15a	BAH911023B	
0AH911023B	PM576	1HS911023B	M248 $\frac{0}{}$	DAH911023A	PM565
1000911023G	M083X	211911023	$\frac{0}{}$	DAH911023B	PM576
100911023G		2119110231		J2810004010	M243
111911021B	$\frac{0}{}$	2119110231		J2810004010	M243
111911021C	$\frac{0}{}$	23300O4000	PM643	J2810054100	M335X
111911021E	$\frac{0}{}$	23300T3401	PM650	J28100728DL	M243
111911021EX	$\frac{0}{}$	3059110233		J28100728DL	M243
111911021F	$\frac{0}{}$	305911023A	RM071	T12911023	
111911021G	$\frac{0}{}$	305911023A	RM071 $\frac{0}{}$	TJG911023B	RM074
111911023	$\frac{12}{0,7}$	305911023B		TJG911023D	RM077
111911023A	$\frac{0}{}$	311911021	$\frac{0}{}$	X03972657	M026
111911023BT	$\frac{12}{0,7}$	311911021X	$\frac{0}{}$	X03972657	M058
111911023C	$\frac{0}{}$	311911023B	$\frac{12}{0,7}$	ZBA911023A	RM068
111911023D		311911023C	$\frac{12}{0,7}$		
111911023D	$\frac{0}{}$	311911023D	$\frac{12}{0,7}$		
113911021	$\frac{0}{}$	311911023D	$\frac{12}{0,7}$		
113911021B	$\frac{0}{}$	311911023DX	$\frac{12}{0,7}$		
113911021BX	$\frac{0}{}$	3259110231	RM072		
113911023	$\frac{0}{}$	377911023D	RM064		
113911023	$\frac{0}{}$	377911023E	RM065		
122911023C	$\frac{0}{}$	377911023E	RM065		
126911023A	$\frac{0}{}$	377911023G	RM062		
126911023A	$\frac{0}{}$	377911023H			
126911031	$\frac{0}{}$	377911023P			
141911021A	$\frac{0}{}$	441040092196			
141911023	$\frac{0}{}$	48764	RM069		
175911023A		547911023D	RM062		
175911023A	M051	554911023B	RM073		
175911023A	M051 $\frac{0}{}$	554991023B	RM073		
175911023B	M106	5X0911023			
175911023B	M106 $\frac{12}{0,8}$ 15a	5X0911023A			
175911023B	M106 $\frac{12}{0,8}$ 15a	5X3911023			
175911023C	M022	622679	RM068		
175911023C	M022 $\frac{12}{0,9}$	640434	RM072		
176911023	M014	6U0911023	PM684		
176911023	M014	6U0911023A			
176911023		6U0911023B	PM684		
176911023	M014	711908			
176911023	M014 $\frac{12}{1,7}$	80303	RM062		
176911023	M014 $\frac{12}{1,7}$	95560410700	PM571		